

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Bumper Reinforcement Bars (Rebars) Bearing a CAPA Quality Seal

Published: December 12, 2018

The following is a notification from Intertek that the *Hui Yih* bumper reinforcement bars (rebars) identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Reinf., Bui	Reinf., Bumper Front					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country	
Toyota	Prius	2012	Plug-In	TY44101LAH	52021470102	TO1006221	US	
Toyota	Prius	2012		TY44101LAH	52021470102	TO1006221	US	
Toyota	Prius	2013- 2015	Plug-In	TY44101LAH	5202147032	TO1006221	US	
Toyota	Prius	2013- 2015		TY44101LAH	5202147032	TO1006221	US	
Manufacturer		Hui Yih Ind	Hui Yih Industrial Co., Ltd.					
Number of Units		1,248	1,248					
Lot Numbers		07/16A, 0	07/16A, 02/17A, 05/17A, 07/17A, 01/18A, 03/18A, 06/18A					
Potential Hazard		used whe are not us for compa	The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					
Sold By		Distributo	Distributors of aftermarket parts.					
What To Do			Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Hui Yih directly.					

Page 1 of 1 Public Notice 18-01