

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Rear Bumper Bar Reinforcements (Rebars) Bearing a CAPA Quality Seal

Published: March 18, 2019

The following is a notification from Intertek that the *Hui Yih* rear bumper bar reinforcements (rebars) identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Bar, Reinforcement					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Ford	Pickup	2015-2018	F150 Crew Cab, w/Towing Pkg Medum Duty Towing, Hvy Duty Towing	FD54151AH	HL3Z17D826G	FO1106375	US
Ford	Pickup	2015-2018	F150 Extended Cab, w/Towing Pkg w/o Max Trailer Towing Pkg	FD54151AH	HL3Z17D826G	FO1106375	US
Ford	Pickup	2015-2018	F150 Regular Cab, w/Towing Pkg Medium Duty Towing, Hvy Duty Towing	FD54151AH	HL3Z17D826G	FO1106375	US

Manufacturer	Hui Yih Industrial Co., Ltd.
Number of Units	170
Lot Numbers	03/18B
Potential Hazard	The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.
Sold By	Distributors of aftermarket parts.
What To Do	Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Hui Yih directly.