

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HNS6662-1A	Hyundai Sonata, 11-14	Radiator Support	Auto Power	08/16A	641013Q200	HY1225164

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BKB029NBQ	Buick Regal eASSIST, 12-13	Bumper Cover, Front	Pro Fortune	09/16A	13243355	GM1000923
BKB029NBQ	Buick Regal, 11-13	Bumper Cover, Front	Pro Fortune	09/16A	13243355	GM1000923
STB012NCQ	Chevrolet Captiva Sport LT/LTZ, 13-15	Bumper Cover, Rear	Pro Fortune	08/16A	19167514	GM1100807
STB012NCQ	Chevrolet Captiva Sport LT/LTZ, 13-15	Bumper Cover, Rear	Pro Fortune	08/16A	22949863	GM1100807
HN2720000-000C	Hyundai Elantra Sedan, 11-13 (USA)	Bumper Cover, Front	AP-Procom	07/16A	865113Y000	HY1000185
NSB106NBQ	Nissan Rogue S/SL/SV, 08-15	Bumper Cover, Rear	Pro Fortune	08/16A	HEM22JM04H	NI1100260
DT6620000-000C	Nissan Rogue, 14-15	Bumper Cover, Front	AP-Procom	08/16A	620224BA0H	NI1000293
STB012NCQ	Saturn Vue Hybrid, , 08-09, 2.4L eng	Bumper Cover, Rear	Pro Fortune	08/16A	19167514	GM1100807
STB012NCQ	Saturn Vue Hybrid, 08-10, 2.4L eng	Bumper Cover, Rear	Pro Fortune	08/16A	22949863	GM1100807
STB012NCQ	Saturn Vue XR, 08-09	Bumper Cover, Rear	Pro Fortune	08/16A	19167514	GM1100807
STB012NCQ	Saturn Vue XR, 08-10	Bumper Cover, Rear	Pro Fortune	08/16A	22949863	GM1100807
TYB075NBQ	Toyota Corolla, 01-02	Bumper Cover, Front	Pro Fortune	01/16A	5211902908	TO1000217
TY6030870-000C	Toyota Highlander Hybrid, 14-16, w/Rear Object Sensors	Bumper Cover, Rear Upper	AP-Procom	05/16A	521590E912	TO1114101
TY-04393BBQ	Toyota Highlander, 11-13	Bumper Cover, Rear Upper	Tong Yang	09/16A	521590E907	TO1100289
TY6030870-000C	Toyota Highlander, 14-16, w/Rear Object Sensors	Bumper Cover, Rear Upper	AP-Procom	05/16A	521590E912	TO1114101
TY8040870-100C	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	AP-Procom	10/16A	521500R110	TO1100306
TY8040870-100C	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	AP-Procom	11/16A	521500R110	TO1100306
TY-04251BCQ	Toyota Tacoma, 05-11, 2.7L eng., (4WD), w/o SR5	Bumper Cover, Front	Tong Yang	07/16A	5211904040	TO1000302
TY-04251BCQ	Toyota Tacoma, 05-11, 2.7L eng., w/o SR5/Pre-Runner	Bumper Cover, Front	Tong Yang	07/16A	5211904040	TO1000302
TY20-8517	Toyota Venza Base/LE/XLE, 14-16	Bumper Cover, Rear	Tran Hung	07/16B	521590T900	TO1100277
TY20-8517	Toyota Venza Base/LE/XLE/Limited, 09-13	Bumper Cover, Rear	Tran Hung	07/16B	521590T900	TO1100277
TY-07539GAQ	Toyota Venza, 13-16	Grille	Tong Yang	03/16A	531010T020	TO1200359

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
K30-1143R-ACN	Ford F150 LD Pickup, 09-10, from 3/2/09	Headlamp Assy, R	DEPO	20160509	AL3Z13008A	FO2503287
K30-1143L-ACN	Ford F150 LD Pickup, 09-10, from 3/2/09	Headlamp Assy, L	DEPO	20160201	AL3Z13008B	FO2502287
K30-1143L-ACN	Ford F150 LD Pickup, 09-10, from 3/2/09	Headlamp Assy, L	DEPO	20160912	AL3Z13008B	FO2502287
K30-1143R-ACN	Ford F150 LD Pickup, 09-12, from 3/2/09	Headlamp Assy, R	DEPO	20160509	AL3Z13008C	FO2503287
K30-1143R-ACN	Ford F150 LD Pickup, 09-14, Chrome trim	Headlamp Assy, R	DEPO	20160509	DL3Z13008A	FO2503287
K30-1143L-ACN	Ford F150 Pickup, 09-12, from 3/2/09	Headlamp Assy, L	DEPO	20160201	AL3Z13008D	FO2502287
K30-1143L-ACN	Ford F150 Pickup, 09-12, from 3/2/09	Headlamp Assy, L	DEPO	20160912	AL3Z13008D	FO2502287
K30-1143L-ACN	Ford F150 Pickup, 09-14, Chrome trim	Headlamp Assy, L	DEPO	20160201	DL3Z13008B	FO2502287
K30-1143L-ACN	Ford F150 Pickup, 09-14, Chrome trim	Headlamp Assy, L	DEPO	20160912	DL3Z13008B	FO2502287
K30-1143R-ACN	Ford F-Series Pickup, 09-10, LD	Headlamp Assy, R	DEPO	20160509	9L3Z13008E	FO2503287
K30-1143L-ACN	Ford F-Series Pickup, 09-10, LD	Headlamp Assy, L	DEPO	20160201	9L3Z13008F	FO2502287
K30-1143L-ACN	Ford F-Series Pickup, 09-10, LD	Headlamp Assy, L	DEPO	20160912	9L3Z13008F	FO2502287



MONTHLY RECALL REPORT April 2017*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all decertifications from March 1, 2017 through March 31, 2017.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.