

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

| Manufacturer Number | Application Description | Part Description | Manufacturer | Lot | OEM Number | PartsLink Number |
|---------------------|----------------------------------|------------------|--------------|--------|---------------|------------------|
| CV-10100AQ-LH | Chevrolet Impala Limited, 06-13 | Fender L | Tong Yang | 11/16A | 89023525 | GM1240326 |
| CVIP06FL1 | Chevrolet Impala Limited, 06-13 | Fender L | Gordon | 11/16A | 89023525 | GM1240326 |
| CV-10100AQ-LH | Chevrolet Impala, 06-13 | Fender L | Tong Yang | 11/16A | 89023525 | GM1240326 |
| CVIP06FL1 | Chevrolet Impala, 06-13 | Fender L | Gordon | 11/16A | 89023525 | GM1240326 |
| S0589F100AS | Dodge Caliber, 07 | Fender L | Jui Li | 02/17A | 5115661AC | CH1240250 |
| S0589F100AS | Dodge Caliber, 07-12 | Fender L | Jui Li | 02/17A | 5115661AD | CH1240250 |
| FD-03017AQ | Ford Fusion, 06-09 | Radiator Support | Tong Yang | 10/16A | 6E5Z16138A | FO1225184 |
| S1027H000AS | Honda Accord Sedan, 13-14, 4 Cyl | Hood | Jui Li | 11/16A | 60100T2AA90ZZ | HO1230169 |
| S1027H000AS | Honda Accord Sedan, 13-16, 4 Cyl | Hood | Jui Li | 11/16A | 60100T2FA90ZZ | HO1230169 |
| S0471H000AS | Honda Ridgeline, 06-14 | Hood | Jui Li | 10/16A | 60100SJCA90ZZ | HO1230147 |
| FD-03017AQ | Lincoln Zephyr, 06 | Radiator Support | Tong Yang | 10/16A | 6E5Z16138A | FO1225184 |
| FD-03017AQ | Mercury Milan, 06-09 | Radiator Support | Tong Yang | 10/16A | 6E5Z16138A | FO1225184 |
| SB30093AH | Subaru Forester, 09-13 | Radiator Support | Hui Yih | 09/16A | 53010SC0019P | SU1225139 |
| DJ-CA15401 | Toyota Camry Hybrid, 15-17 | Hood | Da Juane | 10/16A | 5330106160 | TO1230234 |
| DJ-CA15401 | Toyota Camry, 15-17 | Hood | Da Juane | 10/16A | 5330106160 | TO1230234 |

CAPA 201 STANDARD - PLASTICS

| Manufacturer Number | Application Description | Part Description | Manufacturer | Lot | OEM Number | PartsLink Number |
|---------------------|------------------------------------------------------------------------|---------------------------|--------------|----------|---------------|------------------|
| CV-04254BDQ | Chevrolet Traverse, 09-16, w/Rear object sensor | Bumper Cover, Rear Upper | Tong Yang | 12/16B | 23190140 | GM1114103 |
| CV-04254BDQ | Chevrolet Traverse, 09-16, w/Rear object sensor | Bumper Cover, Rear Upper | Tong Yang | 12/16B | 23328041 | GM1114103 |
| CV-04254BDQ | Chevrolet Traverse, 13-14, w/Rear object sensor | Bumper Cover, Rear Upper | Tong Yang | 12/16B | 22899620 | GM1114103 |
| Y-CRBP045CA | Dodge Caliber SE/SCT/R/T, 07-08, w/fog lamps | Bumper Cover, Front | Y.C.C. | 01/17A | 5183394AB | CH1000870 |
| Y-CRBP045CA | Dodge Caliber SE/SXT/R/T, 07-09, w/fog lamps | Bumper Cover, Front | Y.C.C. | 01/17A | 5183394AC | CH1000870 |
| Y-CRBP045CA | Dodge Caliber SE/SXT/R/T, 07-10, w/fog lamps | Bumper Cover, Front | Y.C.C. | 01/17A | 5183394AD | CH1000870 |
| Y-CRBP045CA | Dodge Caliber, 07-12, w/fog lamps | Bumper Cover, Front | Y.C.C. | 01/17A | 5183394AE | CH1000870 |
| HD0900000-500C | Honda Civic Hybrid, 09-11 | Bumper Cover, Front | AP-Procom | 08/16A | 04711SNAA90ZZ | HO1000266 |
| HD0900000-500C | Honda Civic Hybrid, 09-11 | Bumper Cover, Front | AP-Procom | 10/16A | 04711SNAA90ZZ | HO1000266 |
| HD0900000-500C | Honda Civic Sedan, 09-11 | Bumper Cover, Front | AP-Procom | 08/16A | 04711SNAA90ZZ | HO1000266 |
| HD0900000-500C | Honda Civic Sedan, 09-11 | Bumper Cover, Front | AP-Procom | 10/16A | 04711SNAA90ZZ | HO1000266 |
| HYB023NAQ | Hyundai Santa Fe Sport, 13-16 | Bumper Cover, Front Lower | Pro Fortune | 01/17A | 865124Z000 | HY1015102 |
| HYB023NAQ | Hyundai Santa Fe Sport, 13-16 | Bumper Cover, Front Lower | Pro Fortune | 12/16A | 865124Z000 | HY1015102 |
| TY-04354BGQ | Lexus RX 350, 10-12, Canada Built, w/o Premium Pkg, w/o Parking Assist | Bumper Cover, Front | Tong Yang | 09/16A | 521190E906 | LX1000190 |
| Y-MZBP151CA | Mazda CX-5, 13-15 | Bumper Cover, Front | Y.C.C. | 03/16A | KD4550031BB | MA1000236 |
| DS-04343BBO | Nissan Pathfinder, 13-16 | Bumper Cover, Front | Tong Yang | 06/16B | 620223KA0H | NI1000288 |
| Y-DSBP254CA | Nissan Versa Note, 14-16 | Bumper Cover, Rear | Y.C.C. | 01/17A | HEM223VY0J | NI1100294 |
| Y-TYBP297CA | Toyota Avalon Hybrid, 13-14 w/fog lamps | Bumper Cover, Front | Y.C.C. | 01/17A | 5211907910 | TO1000396 |
| Y-TYBP297CA | Toyota Avalon, 13-14, w/fog lamps | Bumper Cover, Front | Y.C.C. | 01/17A | 5211907910 | TO1000396 |
| TY-04278BCQ | Toyota Camry Base, 08-10, (USA) | Bumper Cover, Rear | Tong Yang | 07/16B | 5215906909 | TO1100243 |
| TY-04278BCQ | Toyota Camry Base, 08-10, (USA) | Bumper Cover, Rear | Tong Yang | 07/16B | 5215906950 | TO1100243 |
| TY-04278BCQ | Toyota Camry Base/LE/XLE, 11, 2.5L eng (USA) | Bumper Cover, Rear | Tong Yang | 07/16B | 5215906950 | TO1100243 |
| TY-04278BCQ | Toyota Camry CE, 07, USA built | Bumper Cover, Rear | Tong Yang | 07/16B | 5215906950 | TO1100243 |
| TY-04278BCQ | Toyota Camry LE/XLE, 07-10, (4 cyl.) | Bumper Cover, Rear | Tong Yang | 07/16B | 5215906909 | TO1100243 |
| TY-04278BCQ | Toyota Camry LE/XLE, 07-10, (4 cyl.), USA built | Bumper Cover, Rear | Tong Yang | 07/16B | 5215906950 | TO1100243 |
| TY04253BBQ | Toyota Camry, 02-06, (USA) | Bumper Cover, Rear | TYG Products | 16/12/30 | 52159AA903 | TO1100203 |
| TY04253BBQ | Toyota Camry, 02-06, (USA) | Bumper Cover, Rear | TYG Products | 17/05/18 | 52159AA903 | TO1100203 |
| Y-TYBP271ACA | Toyota Corolla Base/CE/L, 09-10, (USA) | Bumper Cover, Rear | Y.C.C. | 06/16A | 5215902963 | TO1100264 |
| TYB084NCQ | Toyota Corolla CE/LE, 03-08 | Bumper Cover, Rear | Pro Fortune | 04/16A | 5215902911 | TO1100208 |
| Y-TYBP271CA | Toyota Corolla S/XRS, 09-10, (USA) | Bumper Cover, Rear | Y.C.C. | 01/17A | 5215902964 | TO1100265 |
| TY04548BBQ | Toyota Sienna Base/L/LE, 11-17, 3.5L Eng | Bumper Cover, Front | TYG Products | 16/12/21 | 5211908904 | TO1000369 |

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

| Manufacturer Number | Application Description | Part Description | Manufacturer | Lot | OEM Number | PartsLink Number |
|---------------------|------------------------------------------------------|---------------------|--------------|----------|------------|------------------|
| TY04548BBO | Toyota Sienna Base/L/LE, 11-17, 3.5L Eng | Bumper Cover, Front | TYG Products | 17/06/23 | 5211908904 | TO1000369 |
| TY04548BBO | Toyota Sienna XLE, 11-17, 3.5L Eng., w/o Limited pkg | Bumper Cover, Front | TYG Products | 16/12/21 | 5211908904 | TO1000369 |
| TY04548BBO | Toyota Sienna XLE, 11-17, 3.5L Eng., w/o Limited pkg | Bumper Cover, Front | TYG Products | 17/06/23 | 5211908904 | TO1000369 |
| TY04548BBO | Toyota Sienna, 11-13, 2.7L Eng | Bumper Cover, Front | TYG Products | 16/12/21 | 5211908904 | TO1000369 |
| TY04548BBO | Toyota Sienna, 11-13, 2.7L Eng | Bumper Cover, Front | TYG Products | 17/06/23 | 5211908904 | TO1000369 |

CAPA 202 STANDARD - NON-WOVEN FABRICS

| Manufacturer Number | Application Description | Part Description | Manufacturer | Lot | OEM Number | PartsLink Number |
|---------------------|-------------------------|------------------|--------------|-----|------------|------------------|
| NONE | | | | | | |

CAPA 301 STANDARD - LIGHTING

| Manufacturer Number | Application Description | Part Description | Manufacturer | Lot | OEM Number | PartsLink Number |
|---------------------|------------------------------|------------------|--------------|----------|-------------|------------------|
| 20-5124-00-9 | Chevrolet Venture, 97-05 | Headlamp Assy, L | TYC Brother | 11171410 | 10368389 | GM2502175 |
| 317-19A4R-AC | Honda Accord, 13-15, on body | Taillamp R | DEPO | 20161111 | 33500T2AA01 | HO2805101 |
| 317-19A4R-AC | Honda Accord, 13-15, on body | Taillamp R | DEPO | 20170324 | 33500T2AA01 | HO2805101 |
| 11-6282-00-9 | Jeep Grand Cherokee, 07-10 | Taillamp L | TYC Brother | 10201410 | 55079013AC | CH2800172 |
| 340-1130L-ACN | Mercedes-Benz C-Class, 08-11 | Headlamp Assy, L | DEPO | 20160509 | 2048208761 | MB2502163 |
| 340-1130R-ACN | Mercedes-Benz C-Class, 08-11 | Headlamp Assy, R | DEPO | 20160808 | 2048208861 | MB2503163 |
| 340-1130L-ACN | Mercedes-Benz C-Class, 08-11 | Headlamp Assy, L | DEPO | 20160509 | 2049065503 | MB2502163 |
| 340-1130R-ACN | Mercedes-Benz C-Class, 08-11 | Headlamp Assy, R | DEPO | 20160808 | 2049065603 | MB2503163 |
| 20-5124-00-9 | Oldsmobile Silhouette, 97-04 | Headlamp Assy, L | TYC Brother | 11171410 | 10368389 | GM2502175 |
| 20-5124-00-9 | Pontiac Montana, 99-05 | Headlamp Assy, L | TYC Brother | 11171410 | 10368389 | GM2502175 |
| 20-5124-00-9 | Pontiac Trans Sport, 97-98 | Headlamp Assy, L | TYC Brother | 11171410 | 10368389 | GM2502175 |

CAPA 501 STANDARD - BUMPER PARTS

| Manufacturer Number | Application Description | Part Description | Manufacturer | Lot | OEM Number | PartsLink Number |
|---------------------|----------------------------------------|-----------------------|--------------|--------|------------|------------------|
| GM1103177DSC | Chevrolet Silverado 1500, 14-16, Black | Bumper, Rear Assembly | PBSI-DS | 12/16A | GM1103177 | GM1103177 |

*This report includes all decertifications from August 1, 2017 through August 31, 2017.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.