

### RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

### CAPA 101 STANDARD - METALS

| Manufacturer Number | Application Description  | Part Description | Manufacturer | Lot    | OEM Number | PartsLink Number |
|---------------------|--|------------------|--------------|--------|------------|------------------|
| S0239F100AS         | Chevrolet Blazer, 92-94  | Fender L         | Jui Li       | 07/17A | 15029229   | GM1240132        |
| S0239F100AS         | Chevrolet Full Size Pickup C/K, 88-02, (Old Style)             | Fender L         | Jui Li       | 07/17A | 15029229   | GM1240132        |
| S0239F100AS         | Chevrolet Suburban, 92-00                                      | Fender L         | Jui Li       | 07/17A | 15029229   | GM1240132        |
| S0239F100AS         | Chevrolet Tahoe, 95-00   | Fender L         | Jui Li       | 07/17A | 15029229   | GM1240132        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09                                     | Fender R         | Tong Yang    | 11/17A | 68054338AA | CH1241269        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09-11                                  | Fender R         | Tong Yang    | 11/17A | 68054338AB | CH1241269        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09-12                                  | Fender R         | Tong Yang    | 11/17A | 68054338AC | CH1241269        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09-12                                  | Fender R         | Tong Yang    | 11/17A | 68054338AD | CH1241269        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09-13                                  | Fender R         | Tong Yang    | 11/17A | 68054338AE | CH1241269        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09-15                                  | Fender R         | Tong Yang    | 11/17A | 68054338AF | CH1241269        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09-15                                  | Fender R         | Tong Yang    | 11/17A | 68054338AG | CH1241269        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09-15                                  | Fender R         | Tong Yang    | 11/17A | 68054338AH | CH1241269        |
| DG-10060AQ-RH       | Dodge Ram R1500 Pickup, 09-17                                  | Fender R         | Tong Yang    | 11/17A | 68054338AI | CH1241269        |
| FDFS13FL1           | Ford Fusion Hybrid, 13-16                                      | Fender L         | Gordon       | 10/17A | DS7Z16006A | FO1240289        |
| FDFS13FL1           | Ford Fusion, 13-16   | Fender L         | Gordon       | 10/17A | DS7Z16006A | FO1240289        |
| S0239F100AS         | GMC Full Size Pickup C/K, 88-02, (Old Style)                   | Fender L         | Jui Li       | 07/17A | 15029229   | GM1240132        |
| S0239F100AS         | GMC Suburban, 92-00  | Fender L         | Jui Li       | 07/17A | 15029229   | GM1240132        |
| S0239F100AS         | GMC Yukon, 92-99, w/o Denali pkg                               | Fender L         | Jui Li       | 07/17A | 15029229   | GM1240132        |
| BZ-10064AQ-LH       | Mercedes-Benz E Class E300/E350/E350 BLUETEC/E550 Sedan, 10-16 | Fender L         | Tong Yang    | 10/17A | 2128801118 | MB1240134        |
| BZ-10064AQ-LH       | Mercedes-Benz E Class E350 Wagon, 11-16                        | Fender L         | Tong Yang    | 10/17A | 2128801118 | MB1240134        |
| BZ-10064AQ-LH       | Mercedes-Benz E Class Hybrid Sedan, 13-16                      | Fender L         | Tong Yang    | 10/17A | 2128801118 | MB1240134        |
| BZ-10064AQ-LH       | Mercedes-Benz E Class Sedan, 10-11, E350/E550                  | Fender L         | Tong Yang    | 10/17A | 2128800118 | MB1240134        |
| BZ-10064AQ-LH       | Mercedes-Benz E Class Wagon, 11                                | Fender L         | Tong Yang    | 10/17A | 2128800118 | MB1240134        |
| TYS6450A            | Toyota RAV-4, 06-12  | Radiator Support | Auto Power   | 05/17A | 532050R010 | TO1225257        |

### CAPA 201 STANDARD - PLASTICS

| Manufacturer Number | Application Description                                     | Part Description          | Manufacturer | Lot    | OEM Number    | PartsLink Number |
|---------------------|---|---------------------------|--------------|--------|---------------|------------------|
| DG3620000-000C      | Dodge Challenger, 15-18, w/Fog Lamps                        | Bumper Cover, Front       | AP-Procom    | 03/18A | 68258730AB    | CH1000A20        |
| Y-FDBP062GCA        | Ford Escape HEV, 05-07                                      | Bumper Cover, Front       | Y.C.C.       | 05/17A | 5L8Z17D957BAA | FO1000571        |
| Y-FDBP062GCA        | Ford Escape XLT, 05-07, w/o appearance pkg                  | Bumper Cover, Front       | Y.C.C.       | 05/17A | 5L8Z17D957BAA | FO1000571        |
| Y-FDGR444CPC        | Ford F150 Pickup XLT, 09-11, w/o Chrome Pkg                 | Grille, Assy              | Y.C.C.       | 10/17A | 9L3Z8200DCP   | FO1200511        |
| Y-FDGR444CPC        | Ford F150 Pickup XLT, 09-12, w/o Chrome Pkg                 | Grille, Assy              | Y.C.C.       | 10/17A | 9L3Z8200D     | FO1200511        |
| HDS60023A           | Honda Civic, 16-17, 2.0L Eng                                | Radiator Support          | Auto Power   | 12/17A | 71410TBAA01   | HO1225183        |
| HYB028NDQ           | Hyundai Sonata, 15-16, w/Rear object sensors                | Bumper Cover, Rear        | Pro Fortune  | 12/17A | 86610C2000    | HY1100206        |
| HN-04162BCQ         | Hyundai Veloster, 12-16, w/o Rear object sensors, w/o Turbo | Bumper Cover, Rear        | Tong Yang    | 01/18B | 866112V000    | HY1100186        |
| Y-KABP026CA         | Kia Optima, 14-15, Korea built                              | Bumper Cover, Front       | Y.C.C.       | 02/18A | 865112T500    | KI1000169        |
| Y-KABP009CA         | Kia Sorento, 11-13, w/o Sport Pkg                           | Bumper Cover, Front Upper | Y.C.C.       | 11/17A | 865111U000    | KI1000149        |
| LSB028NCQ           | Lexus CT 200H, 11-13, w/o Parking Aid Sensors               | Bumper Cover, Rear        | Pro Fortune  | 11/17A | 5215976900    | LX1100152        |
| MC4410030-100C      | Mercury Grand Marquis, 06-10                                | Panel, Front              | AP-Procom    | 01/18A | 6W3Z8190A     | FO1221134        |
| TYB111NBQ           | Toyota Camry Hybrid, 12-14                                  | Bumper Cover, Front       | Pro Fortune  | 02/18A | 5211906974    | TO1000378        |
| TYB111NBQ           | Toyota Camry L/LE/XLE, 12-14                                | Bumper Cover, Front       | Pro Fortune  | 02/18A | 5211906974    | TO1000378        |
| TYB129NBQ           | Toyota Corolla CE/L/LE/LE Eco, 14-16                        | Bumper Cover, Front       | Pro Fortune  | 01/18B | 5211903904    | TO1000399        |

### CAPA 202 STANDARD - NON-WOVEN FABRICS

| Manufacturer Number | Application Description | Part Description | Manufacturer | Lot | OEM Number | PartsLink Number |
|---------------------|-------------------------|------------------|--------------|-----|------------|------------------|
| NONE                |                         |                  |              |     |            |                  |

### RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

#### CAPA 301 STANDARD - LIGHTING

| Manufacturer<br>Number | Application<br>Description | Part<br>Description | Manufacturer | Lot | OEM<br>Number | PartsLink<br>Number |
|------------------------|----------------------------|---------------------|--------------|-----|---------------|---------------------|
| NONE                   |                            |                     |              |     |               |                     |

#### CAPA 501 STANDARD - BUMPER PARTS

| Manufacturer<br>Number | Application<br>Description  | Part<br>Description   | Manufacturer | Lot               | OEM<br>Number | PartsLink<br>Number |
|------------------------|---|-----------------------|--------------|-------------------|---------------|---------------------|
| GM1102558DSC           | Chevrolet Silverado 1500/2500 HD, 14-16, w/Corner step, w/o Parking aid sensors, Chrome | Bumper, Rear Face Bar | PBSI-DS      | 03/17A            | 23108142      | GM1102558           |
| CH1002396DSC           | Dodge RAM R1500 Pickup, 13-17, w/Fog Lamps, w/o Parking Sensors                         | Bumper, Front         | PBSI-DS      | 17187             | 68160853AB    | CH1002396           |
| GM1102558DSC           | GMC Sierra 1500, 14-16, w/Corner step, w/o Parking aid sensors, Chrome                  | Bumper, Rear Face Bar | PBSI-DS      | 03/17A            | 23108142      | GM1102558           |
| GM1102558DSC           | GMC Sierra 2500 HD/3500 HD, 15-16, w/Corner step, w/o Parking aid sensors, Chrome       | Bumper, Rear Face Bar | PBSI-DS      | 03/17A            | 23108142      | GM1102558           |
| TO1006208DSC           | Toyota RAV-4 Limited/Base/Sport, 09-12  | Bar, Impact           | PBSI-DS      | 11/17B,<br>11/17C | 5202142082    | TO1006208           |
| TO1006208DSC           | Toyota RAV-4, 06-08   | Bar, Impact           | PBSI-DS      | 11/17B,<br>11/17C | 5202142082    | TO1006208           |

#### CAPA 601 STANDARD - RADIATORS

| Manufacturer<br>Number | Application<br>Description | Part<br>Description | Manufacturer | Lot | OEM<br>Number | PartsLink<br>Number |
|------------------------|----------------------------|---------------------|--------------|-----|---------------|---------------------|
| NONE                   |                            |                     |              |     |               |                     |

#### CORRECTIONS

The following part lot was listed as decertified on the June, 2018 Monthly Parts Recall.

Upon further review, this part lot is not decertified.

| Manufacturer<br>Number | Application<br>Description   | Part<br>Description | Manufacturer | Lot    | OEM<br>Number | PartsLink<br>Number |
|------------------------|------------------------------|---------------------|--------------|--------|---------------|---------------------|
| GM1106663DSC           | Chevrolet Impala, 06-16      | Bar, Impact         | PBSI-DS      | 11/17A | 25865729      | GM1106663           |
| GM1106663DSC           | Chevrolet Monte Carlo, 06-16 | Bar, Impact         | PBSI-DS      | 11/17A | 25865729      | GM1106663           |

The following part lots were listed as decertified on the July, 2018 Monthly Parts Recall.

Upon further review, these part lots are not decertified.

| Manufacturer<br>Number | Application<br>Description | Part<br>Description | Manufacturer | Lot      | OEM<br>Number | PartsLink<br>Number |
|------------------------|----------------------------|---------------------|--------------|----------|---------------|---------------------|
| 335-1161R-AC2          | GMC Terrain Denali, 13-15  | Headlamp Assy, R    | DEPO         | 20170814 | 22915383      | GM2503381           |
| 335-1161R-AC2          | GMC Terrain Denali, 13-15  | Headlamp Assy, R    | DEPO         | 20171002 | 22915383      | GM2503381           |
| 335-1161R-AC2          | GMC Terrain Denali, 13-15  | Headlamp Assy, R    | DEPO         | 20180305 | 22915383      | GM2503381           |
| 335-1161R-AC2          | GMC Terrain Denali, 13-15  | Headlamp Assy, R    | DEPO         | 20170814 | 23319182      | GM2503381           |
| 335-1161R-AC2          | GMC Terrain Denali, 13-15  | Headlamp Assy, R    | DEPO         | 20171002 | 23319182      | GM2503381           |
| 335-1161R-AC2          | GMC Terrain Denali, 13-15  | Headlamp Assy, R    | DEPO         | 20180305 | 23319182      | GM2503381           |

\*This report includes all decertifications from July 1, 2018 through July 31, 2018.

All CAPA Reports including the recall report are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [jillian.rahal@intertek.com](mailto:jillian.rahal@intertek.com).