

## PUBLIC SAFETY NOTICE

### Intertek Warns of Potential Safety-Related Issue with Hood Bearing a CAPA Quality Seal

Published: December 20, 2021

The following is a notification from Intertek that the Gordon hood identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

<b>Product Description</b>		Hood					
<b>Make</b>	<b>Model</b>	<b>Years</b>	<b>Details</b>	<b>AM Part Number</b>	<b>OEM Part Number</b>	<b>PartsLink Number</b>	<b>Country</b>
Honda	Pilot	2016-2021	N/A	HDPL15HD1	60100TG7A92ZZ	HO1230180	US
<b>Manufacturer</b>		Gordon Auto Body Parts Co., Ltd.					
<b>Number of Units</b>		3,935					
<b>Lot Numbers</b>		04/16A, 01/17A, 03/17A, 12/17A, 04/18A, 06/18A, 09/18A, 12/18A, 03/19A, 06/19A, 07/19A, 10/19A, 12/19A, 02/20A, 07/20A, 12/20A, 01/21A, 03/21A, 09/21A					
<b>Potential Hazard</b>		Hood may open while vehicle is being driven.					
<b>Additional Information</b>		<p>This notification is based upon the following NHTSA Safety Recall:            NHTSA Campaign Number: 21V932000            Manufacturer: Honda (American Honda Motor Co.)            Summary: Honda is recalling certain 2016-2019 Pilot vehicles. The hood latch striker may become damaged and separate from the hood, which can result in the hood opening while driving.</p> <p>Since CAPA certification of the parts identified above is based on demonstrated comparability to the Honda parts, this notification is being issued out of an abundance of caution. To date, no complaints have been reported.</p>					
<b>Sold By</b>		Distributors of aftermarket parts					
<b>What To Do</b>		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Gordon directly.					