

**PUBLIC SAFETY NOTICE**

**Intertek Warns of Potential Safety-Related Issue with  
Bumper Impact Bars Bearing a CAPA Quality Seal**

Published: December 12, 2018

The following is a notification from Intertek that the *Hui Yih* bumper impact bars identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Bar, Impact					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Ford	Fusion	2013-2016	Energi w/o Towing Hook	FD44138BH	DG9Z17757A	FO1006263	US
Ford	Fusion	2013-2016	Hybrid w/o Towing Hook	FD44138BH	DG9Z17757A	FO1006263	US
Ford	Fusion	2013-2016	w/o Towing Hook	FD44138BH	DG9Z17757A	FO1006263	US
Ford	Fusion	2013-2016	Hybrid w/o Towing Hook	FD44138BH	DG9Z17757ACP	FO1006263	US
Ford	Fusion	2013-2016	w/o Towing Hook	FD44138BH	DG9Z17757ACP	FO1006263	US
<b>Manufacturer</b>		Hui Yih Industrial Co., Ltd.					
<b>Number of Units</b>		1,400					
<b>Lot Numbers</b>		04/17A, 08/17A, 01/18A, 07/18A, 09/18A, 09/18B					
<b>Potential Hazard</b>		The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					

<b>Sold By</b>	Distributors of aftermarket parts.
<b>What To Do</b>	Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Hui Yih directly.