

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Bumper Impact Bars Bearing a CAPA Quality Seal

Published: December 12, 2018

The following is a notification from Intertek that the *Hui Yih* bumper impact bars identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Bar, Impact					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Ford	Fusion	2013-2016	Energi w/Towing Hook	FD44138AH	DG9Z5410852A	FO1006262	US
Ford	Fusion	2013-2016	Hybrid w/Towing Hook	FD44138AH	DG9Z5410852A	FO1006262	US
Ford	Fusion	2013-2016	w/ Towing Hook	FD44138AH	DG9Z5410852A	FO1006262	US
Manufacturer		Hui Yih Industrial Co., Ltd.					
Number of Units		150					
Lot Numbers		04/17A					
Potential Hazard		The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					
Sold By		Distributors of aftermarket parts.					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Hui Yih directly.					