

**PUBLIC SAFETY NOTICE**

**Intertek Warns of Potential Safety-Related Issue with Radiator Supports Bearing a CAPA Quality Seal**

Published: February 23, 2023

The following is a notification from Intertek that the Tong Yang radiator supports identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

|                            |              |   |                          |                       |                        |                         |                |
|----------------------------|--------------|---|--------------------------|-----------------------|------------------------|-------------------------|----------------|
| <b>Product Description</b> |              | Radiator Support  |                          |                       |                        |                         |                |
| <b>Make</b>                | <b>Model</b> | <b>Years</b>  | <b>Details</b>           | <b>AM Part Number</b> | <b>OEM Part Number</b> | <b>PartsLink Number</b> | <b>Country</b> |
| Honda                      | Civic        | 2018  | Coupe, Front, EX-L, EX-T | HD-03001EQ            | 71410TBCA21            | HO1225202               | US             |
| <b>Manufacturer</b>        |              | Tong Yang Industry Co., Ltd.  |                          |                       |                        |                         |                |
| <b>Number of Units</b>     |              | 270   |                          |                       |                        |                         |                |
| <b>Lot Numbers</b>         |              | 09/19A, 03/20A, 08/20A, 02/21A, 08/21A, 11/21A, 03/22A, 06/22A, 12/22A  |                          |                       |                        |                         |                |
| <b>Potential Hazard</b>    |              | Parts may exhibit a separation of metal surrounding a mounting hole near the hood latch mounting area, which could affect the proper function of the hood latch. To date, no complaints have been reported. |                          |                       |                        |                         |                |
| <b>Sold By</b>             |              | Distributors of aftermarket parts   |                          |                       |                        |                         |                |
| <b>What To Do</b>          |              | Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Tong Yang directly.   |                          |                       |                        |                         |                |