

## PUBLIC SAFETY NOTICE

### Intertek Warns of Potential Safety-Related Issue with Front Bumper Covers Bearing a CAPA Quality Seal

Published: 31 May 2019

The following is a notification from Intertek that the *Tran Hung* front bumper covers identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

<b>Product Description</b>		Bumper Cover, Front					
<b>Make</b>	<b>Model</b>	<b>Years</b>	<b>Details</b>	<b>AM Part Number</b>	<b>OEM Part Number</b>	<b>Partslink Number</b>	<b>Country</b>
Cadillac	XTS	2013	w/DRL, w/PDC, w/Collision, w/o Steering Aid	CD34-9909-WSHWDL	22914024	GM1000937	US
<b>Manufacturer</b>		Tran Hung Int. Co., Ltd.					
<b>Number of Units</b>		75					
<b>Lot Numbers</b>		03/18A					
<b>Potential Hazard</b>		The manufacturer has made unauthorized changes, including, but not limited to alterations to the attachment method for the brackets that retains ADAS sensors. These changes are not comparable to those utilized by the OEM and may not perform in a comparable manner, potentially impacting the functionality of the ADAS system, and which poses a potential safety-related issue.					
<b>Sold By</b>		Distributors of aftermarket parts.					
<b>What To Do</b>		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Tran Hung directly.					