

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with R Driving Lamp Bearing a CAPA Quality Seal

Published: March 8, 2022

The following is a notification from Intertek that the TYC Brother R Driving Lamp identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Lamp, Driving R					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Lexus	IS 200t	2017- 2020	w/o Adaptive Headlamps	12-5409- 00-9	8161053060	LX2563104	US
Lexus	IS 250	2017- 2020	w/o Adaptive Headlamps	12-5409- 00-9	8161053060	LX2563104	US
Lexus	IS 300	2017- 2020	w/o Adaptive Headlamps	12-5409- 00-9	8161053060	LX2563104	US
Lexus	IS 350	2017- 2020	w/o Adaptive Headlamps	12-5409- 00-9	8161053060	LX2563104	US
Manufacturer		TYC Brother Industrial Co., Ltd.					
Number of Units		350					
Lot Numbers		06152010					
		11022010					
		03012110					
		07052110					
Potential Hazard		Park and Daytime Running Lamp functions may become inoperable. If this occurs, vehicle visibility to surrounding drivers will be impaired.					
Sold By		Distributors of aftermarket parts					
What To	Do	Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact TYC Brother directly.					

Page 1 of 1 Public Notice 22-04