

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Radiator Supports Bearing a CAPA Quality Seal

Published: February 23, 2023

The following is a notification from Intertek that the Tong Yang radiator supports identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

| Product Description | | Radiator Support | | | | | |
|---------------------|-------|---|---------------------------------------|-------------------|--------------------|---------------------|---------|
| | | | | | | | |
| Make | Model | Years | Details | AM Part Number | OEM Part Number | PartsLink Number | Country |
| Honda | Civic | 2019- 2020 | Coupe, Front, Touring Model | HD- 03001JQ | 71410TBCA31 | HO1225212 | US |
| Honda | Civic | 2020 | Coupe, Front, Si Model | HD- 03001JQ | 71410TBCA31 | HO1225212 | US |
| Honda | Civic | 2020- 2021 | Front, Sedan, Si, Touring Model | HD- 03001JQ | 71410TBCA31 | HO1225212 | US |
| | | | | | | | |
| Manufacturer | | Tong Yang Industry Co., Ltd. | | | | | |
| | | | | | | | |
| Number of Units | | 110 | | | | | |
| Lot Numbers | | 09/19A, 10/19A | | | | | |
| | | | | | | | |
| Potential Hazard | | Parts may exhibit a separation of metal surrounding a mounting hole near the | | | | | |
| | | hood latch mounting area, which could affect the proper function of the hood | | | | | |
| | | latch. To date, no complaints have been reported. | | | | | |
| Sold By | | Distributors of aftermarket parts | | | | | |
| What To Do | | Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Tong Yang directly. | | | | | |