



WEEKLY PARTS UPDATE August 21, 2009

[Report: P6]
Weekly

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Dodge Full Size Pickup, 06-07	Fender L	DG-10057AQ-LH	Taiwan Kai Yih	55276987AB	CH1240255
Dodge Full Size Pickup, 06-07	Fender L	DGPU06FL1	Gordon	55276987AB	CH1240255
Dodge Full Size Pickup, 06-07	Fender L	S0681F100AS	Jui Li	55276987AB	CH1240255
Dodge R1500 Pickup, 06-08 (New Style)	Fender L	DG-10057AQ-LH	Taiwan Kai Yih	55276987AB	CH1240255
Dodge R1500 Pickup, 06-08 (New Style)	Fender L	DGPU06FL1	Gordon	55276987AB	CH1240255
Dodge R1500 Pickup, 06-08 (New Style)	Fender L	S0681F100AS	Jui Li	55276987AB	CH1240255
Ford Crown Victoria, 98-08	Hood	FDCV98HD1	Gordon	6W7Z16612A	FO1230181
Ford Edge, 07-08	Hood	FD6210150-000C	AP	7T4Z16612A	FO1230262
Mazda CX-7, 07-08	Hood	MZ-20050AQ	Taiwan Kai Yih	EGY15231XC	MA1230163
Mazda CX-7, 07-08	Hood	MZCX07HD1	Gordon	EGY15231XC	MA1230163
Mazda CX-7, 07-08	Hood	S0717H000AS	Jui Li	EGY15231XC	MA1230163
Mercury Grand Marquis, 98-08	Hood	FDCV98HD1	Gordon	6W7Z16612A	FO1230181
Mercury Marauder, 03-08	Hood	FDCV98HD1	Gordon	6W7Z16612A	FO1230181
Toyota Sequoia, 05-07	Fender R	TA18002BRQ	Cobra King	538010C100	TO1241223
Toyota Tundra Double Cab, 05-06, w/fender flare	Fender R	TA18002ARQ	Cobra King	538010C160	TO1241222
Toyota Tundra Double Cab, 05-06, w/o fender flare	Fender R	TA18002RQ	Cobra King	538010C150	TO1241221

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
GMC Sierra, 05-07	Lamp, Fog L	19-5542-90-9	TYC Brother	15776380	GM2592154
Saturn Vue, 02-04	Headlamp Assy, R	20-6421-00-9	TYC Brother	22702946	GM2503228
Saturn Vue, 02-04	Headlamp Assy, L	20-6422-00-9	TYC Brother	22702945	GM2502228

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-20073AQ	Chevrolet Colorado, 04-09	Hood	Taiwan Kai Yih	05/09A	88944095	GM1230319
S0539H000AS	Chevrolet Colorado, 04-09	Hood	Jui Li	05/09A	88944095	GM1230319
CV3300150-000C	Chevrolet Impala, 00-05	Hood	AP	05/09A	19120224	GM1230238
CV-20073AQ	GMC Canyon, 04-09	Hood	Taiwan Kai Yih	05/09A	88944095	GM1230319
S0539H000AS	GMC Canyon, 04-09	Hood	Jui Li	05/09A	88944095	GM1230319
HD-20065AQ	Honda Pilot, 06-08	Hood	Taiwan Kai Yih	07/09A	60100S9VA80ZZ	HO1230151
HD-20065AQ	Honda Pilot, 06-08	Hood	Taiwan Kai Yih	07/08A	60100S9VA80ZZ	HO1230151
HDPL06HD1	Honda Pilot, 06-08	Hood	Gordon	07/08A	60100S9VA80ZZ	HO1230151
HDPL06HD1	Honda Pilot, 06-08	Hood	Gordon	07/09A	60100S9VA80ZZ	HO1230151
S0701H000AS	Honda Pilot, 06-08	Hood	Jui Li	07/08A	60100S9VA80ZZ	HO1230151
S0701H000AS	Honda Pilot, 06-08	Hood	Jui Li	07/09A	60100S9VA80ZZ	HO1230151
S0551H000AS	Mazda 3 Sedan, 04-08	Hood	Jui Li	04/09A	BNYV5231XB	MA1230158



WEEKLY PARTS UPDATE August 21, 2009

[Report: P6]
Weekly

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV6400030-000C	Chevrolet Trailblazer, 02-07	Panel, Front	AP-Procom	05/09A	15831182	GM1221125
Y-CRBP005CA	Dodge Neon Sport, 95-99, w/fog lamps	Bumper Cover, Front	Y.C.C.	07/05A	4741655	CH1000157

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
20-5696-91-9	Ford Mustang, 01-04	Headlamp Assy, L	TYC Brother	05120810	3R3Z13008DA	FO2502177

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NSS6254A	Infiniti I30, 00	Radiator Support	Auto Power	625005Y500	NI1225136
NSS6285A	Infiniti I30, 01	Radiator Support	Auto Power	625005Y501	NI1225148
NSS6285A	Infiniti I35, 02-04	Radiator Support	Auto Power	625005Y501	NI1225148
NSS6254A	Nissan Maxima, 00	Radiator Support	Auto Power	625005Y500	NI1225136
NSS6285A	Nissan Maxima, 01-03	Radiator Support	Auto Power	625005Y501	NI1225148

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
TY-04225BAQ	Toyota Sienna, 04-05, w/o Park Assist Sensors or Radar Cruise Control	Bumper Cover, Front	Tong Yang Plastics	52119AE900	TO1000272
TY-04225BCQ	Toyota Sienna, 04-05, w/o Park Assist Sensors, w/Radar Cruise Control	Bumper Cover, Front	Tong Yang Plastics	52119AE902	TO1000271
TY-04225BDQ	Toyota Sienna, 04-05, w/Park Assist Sensors and Radar Cruise Control	Bumper Cover, Front	Tong Yang Plastics	52119AE903	TO1000269
TY-04225BBQ	Toyota Sienna, 04-05, w/Park Assist Sensors, w/o Radar Cruise Control	Bumper Cover, Front	Tong Yang Plastics	52119AE901	TO1000270

*This report includes all new, decertified and deleted parts from August 10, 2009 through August 14, 2009
All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.
If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org