

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CR3C11HD1	Chrysler 300 Sedan, 11-12	Hood	Gordon	12/14A	68127958AA	CH1230292
CR3C11HD1	Chrysler 300 Sedan, 11-14	Hood	Gordon	12/14A	68127958AB	CH1230292
CR3C11HD1	Chrysler 300 Sedan, 11-14	Hood	Gordon	12/14A	68127958AC	CH1230292
CR3C11HD1	Chrysler 300 Sedan, Limited, 11-14	Hood	Gordon	12/14A	68127958AB	CH1230292
CR3C11HD1	Chrysler 300 Sedan, Limited, 11-14	Hood	Gordon	12/14A	68127958AC	CH1230292
CR3C11HD1	Chrysler 300 Sedan, Limited, 12	Hood	Gordon	12/14A	68127958AA	CH1230292
CR3C11HD1	Chrysler 300 Sedan, S Model, 11-14	Hood	Gordon	12/14A	68127958AB	CH1230292
CR3C11HD1	Chrysler 300 Sedan, S Model, 11-14	Hood	Gordon	12/14A	68127958AC	CH1230292
CR3C11HD1	Chrysler 300 Sedan, S Model, 12	Hood	Gordon	12/14A	68127958AA	CH1230292
CR3C11HD1	Chrysler 300 Sedan, SRT-8, 11-14	Hood	Gordon	12/14A	68127958AB	CH1230292
CR3C11HD1	Chrysler 300 Sedan, SRT-8, 11-14	Hood	Gordon	12/14A	68127958AC	CH1230292
CR3C11HD1	Chrysler 300 Sedan, SRT-8, 12	Hood	Gordon	12/14A	68127958AA	CH1230292
CR3C11HD1	Chrysler 300C Sedan, 11-12	Hood	Gordon	12/14A	68127958AA	CH1230292
CR3C11HD1	Chrysler 300C Sedan, 11-14	Hood	Gordon	12/14A	68127958AB	CH1230292
CR3C11HD1	Chrysler 300C Sedan, 11-14	Hood	Gordon	12/14A	68127958AC	CH1230292
FDP04HD1	Ford F150 Pickup, 04-08 (New Style)	Hood	Gordon	03/15A	4L3Z16612AA	FO1230240
HDS6507A	Honda Accord Sedan, 08-11, (USA)	Radiator Support	Auto Power	07/15A	60400TA5A00ZZ	HO1225156
FDP04HD1	Lincoln Mark LT, 06-08	Hood	Gordon	03/15A	4L3Z16612AA	FO1230240
MZA310F41	Mazda 3 Sedan/Hatchback, 2.0L/2.3L/2.5L Eng, 10-13, w/o Side Signal Lamps, w/Stone Guard	Fender R	Gordon	03/15A	BBM452111B	MA1241163
MZA613FL1	Mazda 6, 14-16	Fender L	Gordon	01/15A	GHP952211A	MA1240171
TYTD07HD1	Toyota Sequoia, 08-10	Hood	Gordon	05/13A	533010C040	TO1230209
TYTD07HD1	Toyota Sequoia, 08-12	Hood	Gordon	05/13A	533010C030	TO1230209
TYTD07HD1	Toyota Tundra, 07-10	Hood	Gordon	05/13A	533010C040	TO1230209
TYTD07HD1	Toyota Tundra, 07-12	Hood	Gordon	05/13A	533010C030	TO1230209

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
BMB025NJQ	BMW 3-Series F30 Sedan, 12-15, w/o M Sport Line, w/o HL Washer, w/o PDC, w/o Park Assist, w/o Camera	Bumper Cover, Front	Pro Fortune	04/15A	51117293011	BM1000266
BMB025NJQ	BMW 3-Series F30H Sedan Hybrid, 13-15, w/o M Sport, w/o H/LW, w/o PDC, w/o Park Assist, w/o Camera	Bumper Cover, Front	Pro Fortune	04/15A	51117293011	BM1000266
BMB025NJQ	BMW 3-Series F31 Wagon, 14-15, w/o M Sport, w/o H/Lamp Washer, w/o PDC, w/o Park Assist, w/o Camera	Bumper Cover, Front	Pro Fortune	04/15A	51117293011	BM1000266
BK3300000-000C	Buick Allure CX, 05-07	Bumper Cover, Front	AP-Procom	08/15A	12336057	GM1000739
BK3300000-000C	Buick LaCrosse CX, 05-07	Bumper Cover, Front	AP-Procom	08/15A	12336057	GM1000739
Y-GMBP340CA	Chevrolet Camaro LS/LT, 10-13	Bumper Cover, Front	Y.C.C.	12/14A	92236548	GM1000906
CLB078NBQ	Chevrolet Sonic Sedan, 12-16	Bumper Cover, Rear	Pro Fortune	07/14A	95460671	GM1100888
DG04068BBQ	Dodge Caravan, 06-07, Code MLU w/o fog lamps	Bumper Cover, Front	TYG Products	15/01/23	5139117AA	CH1000431
DG04068BBQ	Dodge Grand Caravan, 05, w/o fog lamps	Bumper Cover, Front	TYG Products	15/01/23	5139117AA	CH1000431
Y-FDAR416CA	Ford Excursion, 00-04, Platinum	Panel, Valance Front Upper	Y.C.C.	08/15A	1C3Z17626AAC	FO1095176
Y-FDAR416CA	Ford Excursion, 00-04, Platinum	Panel, Valance Front Upper	Y.C.C.	08/15A	1C3Z17626AACCP	FO1095176
Y-FDAR416CA	Ford F-Series Super Duty Pickup, 99-04, w/o King	Panel, Valance Front Upper	Y.C.C.	08/15A	1C3Z17626AAC	FO1095176
Y-FDAR416CA	Ford F-Series Super Duty Pickup, 99-04, w/o King	Panel, Valance Front Upper	Y.C.C.	08/15A	1C3Z17626AACCP	FO1095176
Y-FDBP059CA	Ford Mustang Deluxe/Premium, 05-09	Bumper Cover, Front	Y.C.C.	08/15A	5R3Z17D957AAA	FO1000574
Y-FDGR416CPC	Ford Super Duty Pickup, 01, Chrome, w/o Platinum	Grille	Y.C.C.	08/15A	1C3Z8200BAA	FO1200359
Y-FDGR416CPC	Ford Super Duty Pickup, 02, Chrome	Grille	Y.C.C.	08/15A	1C3Z8200BAA	FO1200359
Y-FDGR416CPC	Ford Super Duty Pickup, 03-04, Chrome, w/o King	Grille	Y.C.C.	08/15A	1C3Z8200BAA	FO1200359
Y-FDGR416CPC	Ford Super Duty Pickup, 99-00, Chrome	Grille	Y.C.C.	08/15A	1C3Z8200BAA	FO1200359
Y-HDBP163CA	Honda CR-V, 07-09	Bumper Cover, Front	Y.C.C.	12/14A	04711SWAA91ZZ	HO1000251

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
Y-HDBP188CA	Honda CR-V, 12-14	Bumper Cover, Front Upper	Y.C.C.	10/14A	04711T0AA90ZZ	HO1014100
HD7200870-000C	Honda Odyssey EX/EX-L/LX, 05-10	Bumper Cover, Rear	AP-Procom	06/14A	04715SHJA92ZZ	HO1100220
HD7200870-000C	Honda Odyssey EX/EX-L/LX, 05-10	Bumper Cover, Rear	AP-Procom	11/14A	04715SHJA92ZZ	HO1100220
HDB090NCQ	Honda Odyssey EX/EX-L/LX, 11-14	Bumper Cover, Rear	Pro Fortune	02/15A	04715TK8A90ZZ	HO1100267
DS-04295BCQ	Infiniti G35 Sedan, 07-08, w/o technology or sport pkg	Bumper Cover, Front	Tong Yang	09/14A	62022JK60H	IN1000234
IN4010000-010C	Infiniti G35 Sedan, 07-08, w/o technology or sport pkg	Bumper Cover, Front	AP-Procom	08/14A	62022JK60H	IN1000234
DS-04295BCQ	Infiniti G35 Sedan, 07-08, w/o technology or sport pkg	Bumper Cover, Front	Tong Yang	09/14A	62022JK60J	IN1000234
IN4010000-010C	Infiniti G35 Sedan, 07-08, w/o technology or sport pkg	Bumper Cover, Front	AP-Procom	08/14A	62022JK60J	IN1000234
DS-04295BCQ	Infiniti G37 Journey Sedan, 09-11/09, w/o technology pkg	Bumper Cover, Front	Tong Yang	09/14A	62022JK60J	IN1000234
IN4010000-010C	Infiniti G37 Journey Sedan, 09-11/09, w/o technology pkg	Bumper Cover, Front	AP-Procom	08/14A	62022JK60J	IN1000234
LSB008NDQ	Lexus IS 250, 06-08, w/o park distance sensors	Bumper Cover, Rear	Pro Fortune	01/15A	5215953905	LX1100129
LSB008NDQ	Lexus IS 350, 06-08, w/o park distance sensors	Bumper Cover, Rear	Pro Fortune	01/15A	5215953905	LX1100129
TY-04354BGQ	Lexus RX 350, 10-12, Canada Built, w/o Premium Pkg, w/o Parking Assist	Bumper Cover, Front	Tong Yang	08/15A	521190E906	LX1000190
Y-DSBP235CA	Nissan Altima Coupe, 10-13	Bumper Cover, Front	Y.C.C.	08/15A	62022ZX10H	NI1000275
DS-04329BBQ	Nissan Maxima, 09-14	Bumper Cover, Rear	Tong Yang	04/15A	850229N00H	NI1100264
SB6610000-010C	Subaru Forester, 09-13	Bumper Cover, Front	AP-Procom	06/15A	57704SC000	SU1000162
SB-04035BBQ	Subaru Outback, 10-14	Bumper Cover, Rear	Tong Yang	05/15B	57704AJ07A	SU1100164
TY-04360BBQ	Toyota 4Runner, 10-13, w/Chrome trim, From 1-10	Bumper Cover, Front	Tong Yang	07/13A	5211935909	TO1000364
Y-TYBP287CA	Toyota Avalon, 11-12	Bumper Cover, Front	Y.C.C.	09/14B	5211907909	TO1000371
TY-04349BCQ	Toyota Camry Base/LE/XLE, 10-11 (USA)	Bumper Cover, Front	Tong Yang	08/15A	5211906958	TO1000356
Y-TYBP269HCA	Toyota Camry Hybrid, 07-09	Bumper Cover, Front	Y.C.C.	10/14A	5211933943	TO1000327
TYB111NBQ	Toyota Camry Hybrid, 12-14	Bumper Cover, Front	Pro Fortune	10/14A	5211906974	TO1000378
TYB111NBQ	Toyota Camry Hybrid, 12-14	Bumper Cover, Front	Pro Fortune	10/15B	5211906974	TO1000378
TYB111NBQ	Toyota Camry Hybrid, 12-14	Bumper Cover, Front	Pro Fortune	12/14A	5211906974	TO1000378
TYB111NBQ	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Pro Fortune	10/14A	5211906974	TO1000378
TYB111NBQ	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Pro Fortune	10/15B	5211906974	TO1000378
TYB111NBQ	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Pro Fortune	12/14A	5211906974	TO1000378
TY-04403BCQ	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	Tong Yang	07/15A	5215906961	TO1100296
TYB112NBQ	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	Pro Fortune	05/15A	5215906961	TO1100296
TYB112NBQ	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	Pro Fortune	07/15B	5215906961	TO1100296
TY-04411BBQ	Toyota Camry SE/SE Sport, 12-14	Bumper Cover, Rear	Tong Yang	12/14B	5215906963	TO1100297
Y-TYBP269HCA	Toyota Camry, 07-09, (Japan)	Bumper Cover, Front	Y.C.C.	10/14A	5211933943	TO1000327
Y-TYBP292CA	Toyota Prius c, 12-14	Bumper Cover, Front	Y.C.C.	04/15A	5211952980	TO1000392
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	08/15A	5215947905	TO1100280
TY-04350BGQ	Toyota Prius, 10-11, w/Halogen H/Lamps, w/o Precollision	Bumper Cover, Front	Tong Yang	04/15B	5211947917	TO1000359
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	08/15A	5215947905	TO1100280
TY7520870-000C	Toyota Sienna, 04-10, w/o Park Assist Sensors	Bumper Cover, Rear	AP-Procom	06/15A	52159AE900	TO1100229

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						



MONTHLY RECALL REPORT February 2016*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CH1002386DSC	Dodge Ram 1500 Pickup, 10-12, w/fog lamps	Bumper, Front	PBSI-DS	15128	68088186AA	CH1002386
NSR2307A	Nissan Sentra, 07-12	Bar, Reinforcement	Auto Power	03/15A	62036ET000	NI1006219

*This report includes all decertifications from January 1, 2016 through January 31, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.