

NEW PARTS CAPA 101 STANDARD - METALS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Buick Encore, 13-15 | Fender R | BKEC13FR1 | Gordon | 95031570 | GM1241382 |
| Buick Encore, 13-15 | Fender L | BKEC13FL1 | Gordon | 95031571 | GM1240382 |
| Ford C-Max Energi/Hybrid, 13-15 | Radiator Support | FDS6785A | Auto Power | CJ5Z8A284A | FO1225216 |
| Ford Escape, 13-15 | Radiator Support | FDS6785A | Auto Power | CJ5Z8A284A | FO1225216 |
| Honda Civic Coupe, 12-13 | Fender R | HD0910160-0R0C | AP | 60211TR6305ZZ | HO1241181 |
| Honda Civic Coupe, 12-13 | Fender L | HD0910160-0L0C | AP | 60261TR6305ZZ | HO1240181 |
| Honda Civic Hybrid, 12-14 | Fender R | HD0910160-0R0C | AP | 60211TR6305ZZ | HO1241181 |
| Honda Civic Hybrid, 12-14 | Fender L | HD0910160-0L0C | AP | 60261TR6305ZZ | HO1240181 |
| Honda Civic Sedan, 12-15 | Fender R | HD0910160-0R0C | AP | 60211TR6305ZZ | HO1241181 |
| Honda Civic Sedan, 12-15 | Fender L | HD0910160-0L0C | AP | 60261TR6305ZZ | HO1240181 |
| Honda Civic, 12-13 | Fender R | HD0910160-0R0C | AP | 60211TR0A90ZZ | HO1241181 |
| Honda Civic, 12-14 | Fender R | HD0910160-0R0C | AP | 60211TR6999ZZ | HO1241181 |
| Honda Civic, 12-15 | Fender L | HD0910160-0L0C | AP | 60261TR3A90ZZ | HO1240181 |
| Honda Civic, 14-15 | Fender L | HD0910160-0L0C | AP | 60261TR6999ZZ | HO1240181 |
| Subaru Legacy, 15-16 | Brace, Cover | CR-318AQ | Chang Jung | 57705AL02A | SU1041100 |
| Subaru Outback, 15-16 | Brace, Cover | CR-318AQ | Chang Jung | 57705AL02A | SU1041100 |

NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|---------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet Equinox, 10-12 | Support Assy, Front Cover | CV5C020Q | Cobra King | 20824645 | GM1041121 |
| Chevrolet Equinox, 10-12 | Support Assy, Front Cover | CV5C020Q | Cobra King | 22802304 | GM1041121 |
| Chevrolet Equinox, 10-12 | Support Assy, Front Cover | CV5C020Q | Cobra King | 25798731 | GM1041121 |
| Chevrolet Equinox, 10-15 | Support Assy, Front Cover | CV5C020Q | Cobra King | 23106653 | GM1041121 |
| Chevrolet Spark, 13-15, w/Sport | Plate, Skid | CLA108NBQ | Pro Fortune | 95961853 | GM1195130 |
| GMC Terrain, 10-12 | Support Assy, Front Cover | CV5C020Q | Cobra King | 20824645 | GM1041121 |
| GMC Terrain, 10-12 | Support Assy, Front Cover | CV5C020Q | Cobra King | 22802304 | GM1041121 |
| GMC Terrain, 10-12 | Support Assy, Front Cover | CV5C020Q | Cobra King | 25798731 | GM1041121 |
| GMC Terrain, 10-15 | Support Assy, Front Cover | CV5C020Q | Cobra King | 23106653 | GM1041121 |
| GMC Terrain, 13-15 | Support Assy, Front Cover | CV5C020Q | Cobra King | 23106653 | GM1041121 |
| Jeep Grand Cherokee Laredo/Limited/Overland, 11-13 | Cover, Tow Hook Opening R | JP52084RQ | Cobra King | 1SJ40RFXAB | CH1029101 |
| Jeep Grand Cherokee Laredo/Limited/Overland, 11-13 | Cover, Tow Hook Opening L | JP52084LQ | Cobra King | 1SJ41RFXAB | CH1029100 |
| Kia Sorento, 14-15, w/o Sport pkg | Grille | KA-07043GAQ | Tong Yang | 863501U500 | KI1200155 |
| Lexus GS 300, 08-11 | Grille, Bumper | LSN044NAQ | Pro Fortune | 5311230310 | LX1036100 |
| Lexus GS 350, 08-11 | Grille, Bumper | LSN044NAQ | Pro Fortune | 5311230310 | LX1036100 |
| Lexus GS 430, 08-11 | Grille, Bumper | LSN044NAQ | Pro Fortune | 5311230310 | LX1036100 |
| Lexus GS 460, 08-11 | Grille, Bumper | LSN044NAQ | Pro Fortune | 5311230310 | LX1036100 |
| Lexus LS 460, 07-09, w/Pre-collision system | Grille | LSG006NBQ | Pro Fortune | 5311250130 | LX1200132 |
| Lexus LS 600H, 08-09 | Grille | LSG006NBQ | Pro Fortune | 5311250130 | LX1200132 |
| Mercedes-Benz S-Class Hybrid, 10-13, w/Sport, w/o Parktronic | Bumper Cover, Rear | BZB038NDQ | Pro Fortune | 2.2188E+13 | MB1100298 |
| Mercedes-Benz S-Class S63, 12-13, w/o Parktronic | Bumper Cover, Rear | BZB040NDQ | Pro Fortune | 2.2188E+13 | MB1100300 |
| Mercedes-Benz S-Class S63, 12-13, w/Parktronic | Bumper Cover, Rear | BZB040NCQ | Pro Fortune | 2.2188E+13 | MB1100299 |
| Subaru Forester, 14, 2.5L Eng | Bumper Cover, Front | SB6620000-000C | AP-Procom | 57704SG000 | SU1000173 |
| Subaru Forester, 14-15, 2.5L Eng, Paint to match | Bumper Cover, Front | SB6620000-000C | AP-Procom | 57704SG001 | SU1000173 |
| Toyota Corolla, 09-10, w/o Fog lamps | Cover, End | TA11083RQ | Cobra King | 8148102090 | TO1039115 |
| Toyota Corolla, 09-10, w/o Fog lamps | Cover, End | TA11083LQ | Cobra King | 8148202080 | TO1038115 |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet Spark, 13-15 | Taillamp L | 335-1960L-AC | DEPO | 95926604 | GM2800256 |
| Chevrolet Spark, 13-15 | Taillamp R | 335-1960R-AC | DEPO | 95926605 | GM2801256 |
| Ford Fiesta Hatchback S/SES/Titanium, 11-13 | Headlamp Assy, R | K30-1149R-AC1 | DEPO | BE8Z13008A | FO2503295 |
| Ford Fiesta Hatchback S/SES/Titanium, 11-13 | Headlamp Assy, L | K30-1149L-AC1 | DEPO | BE8Z13008B | FO2502295 |
| Ford Fiesta Hatchback SE, 11-13, w/o Appearance Pkg | Headlamp Assy, R | K30-1149R-AC1 | DEPO | BE8Z13008A | FO2503295 |
| Ford Fiesta Hatchback SE, 11-13, w/o Appearance Pkg | Headlamp Assy, L | K30-1149L-AC1 | DEPO | BE8Z13008B | FO2502295 |
| Ford Fiesta Sedan S/SEL/Titanium, 11-13 | Headlamp Assy, R | K30-1149R-AC1 | DEPO | BE8Z13008A | FO2503295 |
| Ford Fiesta Sedan S/SEL/Titanium, 11-13 | Headlamp Assy, L | K30-1149L-AC1 | DEPO | BE8Z13008B | FO2502295 |
| Ford Fiesta Sedan SE, 11-13, w/o Appearance Pkg | Headlamp Assy, R | K30-1149R-AC1 | DEPO | BE8Z13008A | FO2503295 |
| Ford Fiesta Sedan SE, 11-13, w/o Appearance Pkg | Headlamp Assy, L | K30-1149L-AC1 | DEPO | BE8Z13008B | FO2502295 |
| Honda Accord Hybrid, 14-15, Halogen | Headlamp Assy, R | 317-1167R-ACN3 | DEPO | 33100T3WA01 | HO2503166 |
| Honda Accord Hybrid, 14-15, Halogen | Headlamp Assy, L | 317-1167L-ACN3 | DEPO | 33150T3WA01 | HO2502166 |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application</u> | <u>Part</u> | <u>Manufacturer</u> | <u>OEM</u> | <u>PartsLink</u> |
|---|--------------------------|---------------------|------------------------|------------------|
| <u>Description</u> | <u>Description</u> | <u>Number</u> | <u>Number</u> | <u>Number</u> |
| Hyundai Santa Fe, 12, Halogen, Clear Reflector, Black Bezel | Headlamp Assy, L | 321-1133L-ACN2C | DEPO 921010W500 | HY2502166 |
| Hyundai Santa Fe, 12, Halogen, Clear Reflector, Black Bezel | Headlamp Assy, R | 321-1133R-ACN2C | DEPO 921020W500 | HY2503166 |
| Hyundai Sonata, 15 | Taillamp, Lens & Body L | 321-1317L-AC | DEPO 92403C2000 | HY2802124 |
| Hyundai Sonata, 15 | Taillamp, Lens & Body R | 321-1317R-AC | DEPO 92404C2000 | HY2803124 |
| Nissan Frontier, 09-13 | Headlamp Assy, L | 20-9080-00-9 | TYC Brother 26060ZL40A | NI2502188 |
| Nissan Frontier, 09-15 | Headlamp Assy, L | 20-9080-00-9 | TYC Brother 26060ZL40B | NI2502188 |
| SAAB 9-3, 03-07 | Headlamp Assy, L | 20-6694-00-9 | TYC Brother 12799348 | SB2502109 |
| SAAB 9-3, 03-07 | Headlamp Assy, R | 20-6693-00-9 | TYC Brother 12799352 | SB2503109 |
| Scion tC, 11-15 | Reflector, Bumper Rear R | 328-2901R-UC | DEPO 8191047010 | TO1185106 |
| Scion tC, 11-15 | Reflector, Bumper Rear L | 328-2901L-UC | DEPO 8192047010 | TO1184106 |
| Subaru Outback, 15 | Headlamp Assy, R | 20-9593-00-9 | TYC Brother 84001AL02A | SU2503149 |
| Subaru Outback, 15 | Headlamp Assy, L | 20-9594-00-9 | TYC Brother 84001AL03A | SU2502149 |
| Toyota Prius V, 12-15 | Reflector, Bumper Rear R | 328-2901R-UC | DEPO 8191047010 | TO1185106 |
| Toyota Prius V, 12-15 | Reflector, Bumper Rear L | 328-2901L-UC | DEPO 8192047010 | TO1184106 |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application</u> | <u>Part</u> | <u>Manufacturer</u> | <u>OEM</u> | <u>PartsLink</u> |
|---|--------------------|---------------------|--------------------------|------------------|
| <u>Description</u> | <u>Description</u> | <u>Number</u> | <u>Number</u> | <u>Number</u> |
| Chrysler 200 Convertible, 11-14 | Absorber, Impact | CR01139A | Auto Power 68082057AB | CH1070823 |
| Chrysler 200 Sedan, 11-14 | Absorber, Impact | CR01139A | Auto Power 68082057AB | CH1070823 |
| Chrysler 300 Sedan, 11-14, w/o SRT-8 | Bar, Reinforcement | DGR3363A | Auto Power 68100209AE | CH1006222 |
| Chrysler 300 Sedan, 12-14, w/SRT-8 | Bar, Reinforcement | DGR3363A | Auto Power 68100209AE | CH1006222 |
| Chrysler 300, 05-10 | Bar, Reinforcement | DGR3363A | Auto Power 68100209AE | CH1006222 |
| Chrysler Magnum, 07-08 | Bar, Reinforcement | DGR3363A | Auto Power 68100209AE | CH1006222 |
| Dodge Avenger, 11-14 | Absorber, Impact | DG01148A | Auto Power 68082056AB | CH1070825 |
| Dodge Charger RT/SE/SXT, 11-14 | Bar, Reinforcement | DGR3363A | Auto Power 68100209AE | CH1006222 |
| Dodge Magnum SRT-8/SRT-8 Super Bee, 12-14 | Bar, Reinforcement | DGR3363A | Auto Power 68100209AE | CH1006222 |
| Ford Fusion Energi, 13-15 | Absorber, Impact | FD01133A | Auto Power DS7Z17E855A | FO1170143 |
| Ford Fusion Hybrid, 13-15 | Absorber, Impact | FD01133A | Auto Power DS7Z17E855A | FO1170143 |
| Ford Fusion, 13-15 | Absorber, Impact | FD01133A | Auto Power DS7Z17E855A | FO1170143 |
| Honda Civic Coupe, 01-05 | Bar, Reinforcement | HOAA1B030C | Forerunner 71130S5DA03ZZ | HO1006156 |
| Honda Civic Hybrid, 03 | Bar, Reinforcement | HOAA1B030C | Forerunner 71130S5DA03ZZ | HO1006156 |
| Honda Civic Sedan, 01-03 | Bar, Reinforcement | HOAA1B030C | Forerunner 71130S5DA03ZZ | HO1006156 |
| Hyundai Santa Fe, 07-09 | Bar, Reinforcement | HY1006125DSC | PBSI-DS 865302B000 | HY1006125 |
| Hyundai Santa Fe, 10-12 | Bar, Reinforcement | HY1006132DSC | PBSI-DS 865300W500 | HY1006132 |
| Nissan Rogue Krom, 10-11 | Absorber, Impact | NS47613Q | Cobra King 85090JM000 | NI1170136 |
| Nissan Rogue S/SL/SV, 08-09, To 11-08 | Absorber, Impact | NS47613Q | Cobra King 85090JM000 | NI1170136 |
| Nissan Versa Sedan, 15 | Absorber, Impact | NS01142A | Auto Power 620909KM0A | NI1070160 |
| Toyota Prius, 04-09 | Absorber, Impact | TA0C124Q | Cobra King 5261147030 | TO1070144 |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

| <u>Manufacturer</u> | <u>Application</u> | <u>Part</u> | <u>OEM</u> | <u>PartsLink</u> |
|---------------------|--------------------|--------------------|---------------|------------------|
| <u>Number</u> | <u>Description</u> | <u>Description</u> | <u>Number</u> | <u>Number</u> |
| NONE | | | | |

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer</u> | <u>Application</u> | <u>Part</u> | <u>OEM</u> | <u>PartsLink</u> |
|---------------------|---|---------------------|----------------------------|------------------|
| <u>Number</u> | <u>Description</u> | <u>Description</u> | <u>Number</u> | <u>Number</u> |
| CR-04053BBQ | Chrysler 300, 05-10, 3.5L Eng, | Bumper Cover, Rear | Tong Yang 4805777AC | CH1100320 |
| HD04103BBQ | Honda Civic Coupe/Sedan, 01-03 | Bumper Cover, Front | TYG Products 04711S5PA90ZZ | HO1000197 |
| INJ1002A1-C | Infiniti JX35, 13, w/o Premium pkg | Bumper Cover, Front | Great Bestcam 08/14A | IN1000251 |
| INJ1002A1-C | Infiniti JX35, 13, w/o Premium pkg | Bumper Cover, Front | Great Bestcam 08/14A | IN1000251 |
| INJ1002A1-C | Infiniti QX60 Hybrid, 14, w/o Object Sensors | Bumper Cover, Front | Great Bestcam 08/14A | IN1000251 |
| INJ1002A1-C | Infiniti QX60 Hybrid, 14-15, w/o Object Sensors | Bumper Cover, Front | Great Bestcam 08/14A | IN1000251 |
| INJ1002A1-C | Infiniti QX60, 14, w/o Object Sensors | Bumper Cover, Front | Great Bestcam 08/14A | IN1000251 |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--|-------------------------|---------------------|------------|-------------------|-------------------------|
| INJ1002A1-C | Infiniti QX60, 14-15, w/o Object Sensors | Bumper Cover, Front | Great Bestcam | 08/14A | 620223JA0H | IN1000251 |
| LX4610000-210C | Lexus RX 350, 10-12, w/o Premium Pkg; w/Parking Assist | Bumper Cover, Front | AP-Procom | 09/15A | 521190E907 | LX1000191 |
| DT3540000-010C | Nissan Maxima, 09-14 | Bumper Cover, Front | AP-Procom | 07/15A | 620229N00H | NI1000258 |
| TY-04330BCQ | Toyota Corolla Base/CE/LE/XLE, 09-10, (USA) | Bumper Cover, Rear | Tong Yang | 06/15A | 5215902963 | TO1100264 |
| TOYSIEN-F11NEW | Toyota Sienna Base/L/LE, 11-15, 3.5L Eng | Bumper Cover, Front | Micro Rim | 10/14B | 5211908904 | TO1000369 |
| TOYSIEN-F11NEW | Toyota Sienna XLE, 11-15, 3.5L Eng., w/o Limited pkg | Bumper Cover, Front | Micro Rim | 10/14B | 5211908904 | TO1000369 |
| TY7520870-000C | Toyota Sienna, 04-10, w/o Park Assist Sensors | Bumper Cover, Rear | AP-Procom | 05/15A | 52159AE900 | TO1100229 |
| TY7520870-000C | Toyota Sienna, 04-10, w/o Park Assist Sensors | Bumper Cover, Rear | AP-Procom | 07/15A | 52159AE900 | TO1100229 |
| TY7520870-100C | Toyota Sienna, 04-10, w/Park Assist Sensor | Bumper Cover, Rear | AP-Procom | 06/15A | 52159AE902 | TO1100228 |
| TOYSIEN-F11NEW | Toyota Sienna, 11-12, 2.7L Eng | Bumper Cover, Front | Micro Rim | 10/14B | 5211908904 | TO1000369 |

CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

DELETED PARTS CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

*This report includes all new, decertified and deleted parts from March 7, 2016 through March 11, 2016.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org