

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
FD-20183CO	Ford Mustang GT, 13-14	Hood	Tong Yang	06/14A	DR3Z16612A	FO1230304
HD2810150-200C	Honda Accord Sedan, 08-09, (6 cyl)	Hood	AP	10/14A	60100TA6A90ZZ	HO1230154
HD2810150-200C	Honda Accord Sedan, 08-09, 6 cyl, USA built	Hood	AP	10/14A	60100TA6A91ZZ	HO1230154
HD2810150-200C	Honda Accord Sedan, 10-12, 6 Cyl	Hood	AP	10/14A	60100TA6A91ZZ	HO1230154
MZA506HD1	Mazda 5, 06-07	Hood	Gordon	09/15A	CCY35231X	MA1230162
MZA506HD1	Mazda 5, 06-07	Hood	Gordon	09/15A	CDY35231X	MA1230162
MZA506HD1	Mazda 5, 06-10	Hood	Gordon	09/15A	CCY35231XA	MA1230162
TYCR03FL1	Toyota Corolla CE/LE, 03-08	Fender L	Gordon	05/15A	5380202060	TO1240183
S0739H000BS	Toyota Tacoma, 05-09, w/scoop	Hood	Jui Li	09/15A	5330104140	TO1230201
TY-20133BQ	Toyota Tacoma, 05-09, w/scoop	Hood	Tong Yang	09/15A	5330104140	TO1230201
S0739H000BS	Toyota Tacoma, 05-11, w/Scoop	Hood	Jui Li	09/15A	5330104150	TO1230201
TY-20133BQ	Toyota Tacoma, 05-11, w/Scoop	Hood	Tong Yang	09/15A	5330104150	TO1230201
S0739H000BS	Toyota Tacoma, 05-11, w/scoop	Hood	Jui Li	09/15A	5330104170	TO1230201
TY-20133BQ	Toyota Tacoma, 05-11, w/scoop	Hood	Tong Yang	09/15A	5330104170	TO1230201

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
ADA405RB1	Audi A4 Sedan, 05-08, w/o Parking aid	Bumper Cover, Rear	Gordon	01/15A	8E5807303BGRU	AU1100164
ADA405RB1	Audi S4 Sedan, 05-08, w/o Parking aid	Bumper Cover, Rear	Gordon	01/15A	8E5807303BGRU	AU1100164
CLB064NCQ	Chevrolet Cruze, 11-15, w/o RS Pkg, w/o Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	09/15A	95016694	GM1100876
Y-GMAR152CA	Chevrolet Pickup, 88-02, w/tow hooks	Deflector, Front Air	Y.C.C.	10/15A	15569430	GM1090105
Y-GMSB444RCA	Chevrolet Silverado 07-13, black w/o fog lamps	Cap, Face Bar R	Y.C.C.	09/15A	15838398	GM1005146
Y-GMSB444LCA	Chevrolet Silverado Hybrid, 09-13, black w/o fog lamps	Cap, Face Bar L	Y.C.C.	09/15A	15838397	GM1004146
Y-GMSB444RCA	Chevrolet Silverado Hybrid, 09-13, black w/o fog lamps	Cap, Face Bar R	Y.C.C.	09/15A	15838398	GM1005146
Y-GMSB444LCA	Chevrolet Silverado, 07-13, black w/o fog lamps	Cap, Face Bar L	Y.C.C.	09/15A	15838397	GM1004146
Y-GMAR152CA	Chevrolet Suburban, 92-99, w/tow hooks	Deflector, Front Air	Y.C.C.	10/15A	15569430	GM1090105
Y-GMAR152CA	Chevrolet Tahoe, 00	Deflector, Front Air	Y.C.C.	10/15A	15569430	GM1090105
Y-GMAR152CA	Chevrolet Tahoe, 92-99, w/tow hooks	Deflector, Front Air	Y.C.C.	10/15A	15569430	GM1090105
CR-07037GAQ	Chrysler 200, 11-13	Grille	Tong Yang	09/15A	68102305AD	CH1200352
CR-07037GAQ	Chrysler 200, 11-14	Grille	Tong Yang	09/15A	68102305AE	CH1200352
Y-CRBP042ACA	Dodge Caliber, 07, w/o fog lamps	Bumper Cover, Front	Y.C.C.	09/15A	5183407AB	CH1000871
Y-CRBP042ACA	Dodge Caliber, 07-10, w/o fog lamps	Bumper Cover, Front	Y.C.C.	09/15A	5183407AC	CH1000871
Y-CRBP042ACA	Dodge Caliber, 07-10, w/o fog lamps	Bumper Cover, Front	Y.C.C.	09/15A	5183407AD	CH1000871
Y-CRBP042ACA	Dodge Caliber, 07-12, w/o fog lamps	Bumper Cover, Front	Y.C.C.	09/15A	5183407AE	CH1000871
Y-FDBP064CA	Ford Expedition XLT, 07-14, black	Bumper Cover, Front Lower	Y.C.C.	10/15A	7L1Z17D957AA	FO1000631
Y-GMAR152CA	GMC Pickup, 88-02, w/Sport Level trim, w/o tow hooks	Deflector, Front Air	Y.C.C.	10/15A	15569430	GM1090105
CV9300000-H00C	GMC Sierra, 03-07, w/fog lamps	Bumper Cover, Front	AP-Procom	11/14A	12335963	GM1000684
Y-HDBP161CA	Honda Accord Sedan, 08-12, (4cyl)	Bumper Cover, Rear	Y.C.C.	10/15A	04715TA0A90ZZ	HO1100246
Y-HDBP161CA	Honda Accord Sedan, 08-12, (4cyl)	Bumper Cover, Rear	Y.C.C.	10/15A	04715TA0A91ZZ	HO1100246
HD-04249BBQ	Honda Accord Sedan, 13-15	Bumper Cover, Front	Tong Yang	02/15A	04711T2AA90ZZ	HO1000288
HD-04125BBQ	Honda Pilot, 03-05	Bumper Cover, Front	Tong Yang	09/15A	04711S9VA90ZZ	HO1000208
DS-04295BCQ	Infiniti G35 Sedan, 07-08, w/o technology or sport pkg	Bumper Cover, Front	Tong Yang	11/14A	62022JK60H	IN1000234
DS-04295BCQ	Infiniti G35 Sedan, 07-08, w/o technology or sport pkg	Bumper Cover, Front	Tong Yang	11/14A	62022JK60J	IN1000234
DS-04295BCQ	Infiniti G37 Journey Sedan, 09-11/09, w/o technology pkg	Bumper Cover, Front	Tong Yang	11/14A	62022JK60J	IN1000234
LX1310000-000C	Lexus ES 350, 07-12	Bumper Cover, Front	AP-Procom	09/15A	5211933945	LX1000167
LX1310870-100C	Lexus ES 350, 07-12, w/o Parking Sensors	Bumper Cover, Rear	AP-Procom	12/14A	5215933922	LX1100149
LX4610000-210C	Lexus RX 350, 10-12, w/o Premium Pkg; w/Parking Assist	Bumper Cover, Front	AP-Procom	01/15A	521190E907	LX1000191
NSB106NBQ	Nissan Rogue S/SL/SV, 08-15	Bumper Cover, Rear	Pro Fortune	08/15A	HEM22JM04H	NI1100260

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Y-DSBP217CA	Nissan Sentra, 07-12, w/fog lamps, 2.0L eng	Bumper Cover, Front	Y.C.C.	11/14A	62022ET32J	NI1000241
Y-TYBP270FCA	Toyota Camry, 07-10, (4 cyl) (Japan)	Bumper Cover, Rear	Y.C.C.	10/15A	5215933918	TO1100247
TYB084NCQ	Toyota Corolla CE/LE, 03-08	Bumper Cover, Rear	Pro Fortune	09/15A	5215902911	TO1100208
TY2120000-000C	Toyota Matrix Base/L/S, 09-14, w/o Sport pkg	Bumper Cover, Front	AP-Procom	06/15A	5211902994	TO1000344
TY2120000-000C	Toyota Matrix, 09-14, w/o fog lamps	Bumper Cover, Front	AP-Procom	06/15A	5211902994	TO1000344
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	03/15A	5215947905	TO1100280
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	12/14A	5215947905	TO1100280
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	03/15A	5215947905	TO1100280
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	12/14A	5215947905	TO1100280
TY-04436BCQ	Toyota Sienna Base/L/LE/XLE/Limited, 11-15, w/o park distance sensors	Bumper Cover, Rear	Tong Yang	09/15A	5215908902	TO1100286
TY04304BDQ	Toyota Sienna, 06-10, w/park assist sensors	Bumper Cover, Front	TYG Products	14/10/29	52119AE906	TO1000324
VWB061NBQ	Volkswagen Beetle Coupe, 12-14	Bumper Cover, Front	Pro Fortune	04/15A	5C5807217AKGRU	VW1000198
VWB061NBQ	Volkswagen Beetle Convertible, 13-14	Bumper Cover, Front	Pro Fortune	04/15A	5C5807217AKGRU	VW1000198
VWB042NBQ	Volkswagen Jetta, 11-14, w/o Parking Assist	Bumper Cover, Rear	Pro Fortune	07/15A	5C6807418AGRU	VW1100186

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
332-1199R-ACN	Chevrolet Impala, 04-05, from 2/6/04	Headlamp Assy, R	DEPO	20150925	10356098	GM2503248

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NSR2538A	Nissan Altima Sedan, 13-15	Bar, Reinforcement	Auto Power	08/14A	620323TA1A	NI1006239

CORRECTION

The following part was listed as decertified on the February, 2016 Monthly Recall Report.
Upon further review, this part was not decertified during the period covered by that report.

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NSR2307A	Nissan Sentra, 07-12	Bar, Reinforcement	Auto Power	03/15A	62036ET000	NI1006219

*This report includes all decertifications from February 1, 2016 through February 29, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.