

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chrysler 200 Sedan, 11-14	Bar, Lower Tie	DG30110AOH	Hui Yih	5076459AJ	CH1225217
Chrysler 300 Sedan, 11-15	Bar, Lower Tie	DGS6390A	Auto Power	5065240AG	CH1225198
Chrysler 300, 05-10	Bar, Lower Tie	DGS6390A	Auto Power	5065240AG	CH1225198
Chrysler Sebring Convertible, 08-10	Bar, Lower Tie	DG30110AOH	Hui Yih	5076459AJ	CH1225217
Chrysler Sebring Sedan, 07-10	Bar, Lower Tie	DG30110AOH	Hui Yih	5076459AJ	CH1225217
Dodge Avenger, 08-14	Bar, Lower Tie	DG30110AOH	Hui Yih	5076459AJ	CH1225217
Dodge Challenger, 08-16	Bar, Lower Tie	DGS6390A	Auto Power	5065240AG	CH1225198
Dodge Charger, 06-16	Bar, Lower Tie	DGS6390A	Auto Power	5065240AG	CH1225198
Dodge Magnum, 05-08	Bar, Lower Tie	DGS6390A	Auto Power	5065240AG	CH1225198
Ford Escape Hybrid, 08-12	Fender Brace, R	FD9F121RQ	Cobra King	8L8Z16A023A	FO1245102
Ford Escape Hybrid, 08-12	Fender Brace, L	FD9F121LQ	Cobra King	8L8Z16A024A	FO1244102
Ford Escape, 08-12	Fender Brace, R	FD9F121RQ	Cobra King	8L8Z16A023A	FO1245102
Ford Escape, 08-12	Fender Brace, L	FD9F121LQ	Cobra King	8L8Z16A024A	FO1244102
Mazda CX-5, 16	Radiator Support	MZ-03010BQ	Tong Yang	KA0M53110	
Mazda CX-5, 16	Radiator Support	MZ-03010BQ	Tong Yang	KD6153110A	
Mercury Mariner Hybrid, 08-11	Fender Brace, R	FD9F121RQ	Cobra King	8L8Z16A023A	FO1245102
Mercury Mariner Hybrid, 08-11	Fender Brace, L	FD9F121LQ	Cobra King	8L8Z16A024A	FO1244102
Mercury Mariner, 08-11	Fender Brace, R	FD9F121RQ	Cobra King	8L8Z16A023A	FO1245102
Mercury Mariner, 08-11	Fender Brace, L	FD9F121LQ	Cobra King	8L8Z16A024A	FO1244102
Toyota Tundra, 14-16	Bracket, Ext Mounting	TY44145AH	Hui Yih	521140C030	TO1041103
Toyota Tundra, 14-16	Retainer, Center	TA6K016Q	Cobra King	525210C070	TO1010103
Toyota Tundra, 14-16	Retainer, Center	TY46145ACH	Hui Yih	525210C070	TO1010103
Toyota Tundra, 14-16	Retainer, Outer R	TA6K016RQ	Cobra King	525370C030	TO1033118
Toyota Tundra, 14-16	Retainer, Outer L	TA6K016LQ	Cobra King	525380C030	TO1032118

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Cadillac CTS-V Coupe, 11-14, w/o Side object sensor	Bumper Cover, Rear	CD34-8509	Tran Hung	25958761	GM1100880
Chevrolet Captiva Sport, 12-15	Grille, Radiator	CV-07267GAQ	Tong Yang	25911316	GM1200664
Chevrolet Malibu Eco, 14	Grille	CV-07273GAQ	Tong Yang	22995188	GM1036160
Chevrolet Malibu, 14-16	Grille	CV-07273GAQ	Tong Yang	22995188	GM1036160
Chrysler 300 Sedan, 12-14, w/SRT-8	Bumper Cover, Front	CRB021NCQ	Pro Fortune	68071976AB	CH1000A03
Chrysler 300 Sedan, 13-14, Type 1, w/o Parking Sensor, w/SRT8	Bumper Cover, Front	CRB021NDQ	Pro Fortune	68212551AA	CH1000A18
Dodge Durango AWD, 14-15, Code MBA	Dam, Air	DGA095NAQ	Pro Fortune	5113682AB	CH1090151
Dodge Durango RWD, 14-15	Dam, Air	DGA095NAQ	Pro Fortune	5113682AB	CH1090151
Ford F150 Pickup, 09-14, w/o Towing pkg	Bumper Pad, Rear	FD58091AH	Hui Yih	9L3Z17B807A	FO1191126
Ford F150 Pickup, 09-14, w/Towing pkg, w/Rear object sensors	Bumper Pad, Rear	FD58091CH	Hui Yih	9L3Z17B807C	FO1191125
Ford F150 Pickup, 09-14, w/Towing pkg, w/o Rear object sensors	Bumper Pad, Rear	FD58091BH	Hui Yih	9L3Z17B807B	FO1191124
Ford F150 SVT Raptor Pickup, 10-14, w/o Rear object sensors	Bumper Pad, Rear	FD58091BH	Hui Yih	9L3Z17B807B	FO1191124
Ford F150 SVT Raptor Pickup, 13-14, w/Rear object sensors	Bumper Pad, Rear	FD58091CH	Hui Yih	9L3Z17B807C	FO1191125
Honda CR-V, 15	Bumper Cover, Rear Lower, R	HD-04287PARQ	Tong Yang	04717T1WA91	HO1117102
Honda CR-V, 15	Bumper Cover, Rear Lower, L	HD-04287PALQ	Tong Yang	04718T1WA91	HO1116102
Hyundai Sonata, 14	Bumper Cover	HN-04151BBQ	Tong Yang	866113Q700	HY1100200
Kia Sorento, 16	Bumper Cover, Front Lower	KA-04096BAQ	Tong Yang	86512C6000	KI1015105
Kia Sorento, 16, w/o Parking assist	Bumper Cover, Rear Upper	KA-04097BBQ	Tong Yang	86611C6000	KI1114103
Kia Sorento, 16, w/Parking assist	Bumper Cover, Rear Upper	KA-04097BDQ	Tong Yang	86650C6000	KI1114104
Lexus IS 250, 11-13, w/Headlamp Washer w/o Park Distance Sensors	Bumper Cover, Front	TY-04519BGQ	Tong Yang	5211953981	LX1000215
Lexus IS 250, 11-13, w/Headlamp Washers; w/Park Distance Sensors	Bumper Cover, Front	TY-04519BHQ	Tong Yang	5211953982	LX1000216



WEEKLY PARTS UPDATE

May 23, 2016

[Report: P6]
Weekly

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Lexus IS 250, 11-13, w/o Headlamp Washer w/o Park Distance Sensors	Bumper Cover, Front	TY-04519BEQ	Tong Yang	5211953979	LX1000212
Lexus IS 250, 11-13, w/o Headlamp Washer w/Park Distance Sensors	Bumper Cover, Front	TY-04519BFQ	Tong Yang	5211953980	LX1000217
Lexus IS 250, 14-15, w/o F sport pkg, From 5-13	Grille	LX2110930-000C	AP-Procom	5311253051	
Lexus IS 350, 11-13, w/Headlamp Washer w/o Park Distance Sensors	Bumper Cover, Front	TY-04519BGQ	Tong Yang	5211953981	LX1000215
Lexus IS 350, 11-13, w/Headlamp Washers; w/Park Distance Sensors	Bumper Cover, Front	TY-04519BHQ	Tong Yang	5211953982	LX1000216
Lexus IS 350, 11-13, w/o Headlamp Washer w/o Park Distance Sensors	Bumper Cover, Front	TY-04519BEQ	Tong Yang	5211953979	LX1000212
Lexus IS 350, 11-13, w/o Headlamp Washer w/Park Distance Sensors	Bumper Cover, Front	TY-04519BFQ	Tong Yang	5211953980	LX1000217
Lexus IS 350, 14-15, w/o F sport pkg, From 5-13	Grille	LX2110930-000C	AP-Procom	5311253051	
Nissan Versa Sedan, 15-16	Bumper Cover, Rear	Y-DSBP264CA	Y.C.C.	HEM229KM0J	NI1100297
Subaru Forester, 14, 2.5L Eng	Bumper Cover, Front	Y-SBBP006CA	Y.C.C.	57704SG000	SU1000173
Subaru Forester, 14-16, 2.5L Eng, Paint to match	Bumper Cover, Front	Y-SBBP006CA	Y.C.C.	57704SG001	SU1000173
Subaru Impreza, 14-16	Moulding, Surround	SB-07051FBQ	Tong Yang	91123FJ080	SU1202101
Toyota Camry Hybrid, 15, Std type	Grille, Lower Cover	TY-07599GAQ	Tong Yang	5311206260	TO1036158
Toyota Camry, 15, Std type	Grille, Lower Cover	TY-07599GAQ	Tong Yang	5311206260	TO1036158
Toyota Corolla, 14-16	Support, Side Cover R	TY56142ARH	Hui Yih	5257502110	TO1133113
Toyota Corolla, 14-16	Support, Side Cover L	TY56142ALH	Hui Yih	5257602110	TO1132113
Volkswagen Golf GTI, 15, w/o Parallel park assist	Bumper Cover, Rear	VW-04215BBQ	Tong Yang	5GM807417GRU	VW1100202
Volkswagen Golf, 15, w/o Parallel park assist	Bumper Cover, Rear	VW-04215BBQ	Tong Yang	5GM807417GRU	VW1100202

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Buick Lucerne CX/CXL, 08-11	Headlamp Assy, L	336-1117L-ACN	DEPO	25974773	GM2502277
Buick Lucerne CX/CXL, 08-11	Headlamp Assy, R	336-1117R-ACN	DEPO	25974774	GM2503277
Buick Lucerne CXL SE, 08-10	Headlamp Assy, L	336-1117L-ACN	DEPO	25974773	GM2502277
Buick Lucerne CXL SE, 08-10	Headlamp Assy, R	336-1117R-ACN	DEPO	25974774	GM2503277
Buick Lucerne CXL SE, 06-08	Headlamp Assy, L	336-1117L-ACN	DEPO	25974773	GM2502277
Buick Lucerne CXL SE, 06-08	Headlamp Assy, R	336-1117R-ACN	DEPO	25974774	GM2503277
Buick Lucerne Super, 08-11	Headlamp Assy, L	336-1117L-ACN	DEPO	25974773	GM2502277
Buick Lucerne Super, 08-11	Headlamp Assy, R	336-1117R-ACN	DEPO	25974774	GM2503277
Buick Lucerne, 06-11	Headlamp Assy, L	336-1117L-ACN	DEPO	25772343	GM2502277
Buick Lucerne, 06-11	Headlamp Assy, R	336-1117R-ACN	DEPO	25772344	GM2503277
Chevrolet Express Van, 03-09	Lamp, Park/Signal L	18-5970-00-9	TYC Brother	15880073	GM2520188
Chevrolet Express Van, 03-09	Lamp, Park/Signal R	18-5969-00-9	TYC Brother	15880074	GM2521188
Chevrolet Express Van, 03-10	Lamp, Park/Signal R	18-5969-00-9	TYC Brother	20772636	GM2521188
Chevrolet Express Van, 03-10	Lamp, Park/Signal L	18-5970-00-9	TYC Brother	20772637	GM2520188
Chevrolet Express Van, 03-15	Lamp, Park/Signal R	18-5969-00-9	TYC Brother	22940754	GM2521188
Chevrolet Express Van, 03-15	Lamp, Park/Signal L	18-5970-00-9	TYC Brother	22940755	GM2520188
Chevrolet Express Van, 03-15	Lamp, Park/Signal L	18-5970-00-9	TYC Brother	23284114	GM2520188
Chevrolet Express Van, 03-15	Lamp, Park/Signal R	18-5969-00-9	TYC Brother	23284115	GM2521188
Ford Fiesta S/SE Hatchback, 14	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008D	FO2502324
Ford Fiesta S/SE Hatchback, 14-15	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008F	FO2502324
Ford Fiesta S/SE Hatchback, 14-16, from 7/8/15	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008J	FO2502324
Ford Fiesta S/SE Sedan, 14	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008D	FO2502324
Ford Fiesta S/SE Sedan, 14-15	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008F	FO2502324
Ford Fiesta S/SE Sedan, 14-16, from 7/8/15	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008J	FO2502324
Ford Fiesta ST, 14	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008D	FO2502324
Ford Fiesta ST, 14-15	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008F	FO2502324
Ford Fiesta ST, 14-16, from 7/8/15	Headlamp Assy, R	20-9531-00-9	TYC Brother	D2BZ13008J	FO2502324



WEEKLY PARTS UPDATE

May 23, 2016

[Report: P6]
Weekly

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Ford Focus Hatchback Titanium, 12-14	Headlamp Assy, R	20-9431-90-9	TYC Brother	BM5Z13008H	FO2503299
Ford Focus Hatchback Titanium, 12-14	Headlamp Assy, L	20-9432-90-9	TYC Brother	BM5Z13008M	FO2502299
Ford Focus Sedan Titanium, 12-14	Headlamp Assy, L	20-9432-90-9	TYC Brother	BM5Z13008M	FO2502299
Ford Focus Titanium Sedan, 12-14	Headlamp Assy, R	20-9431-90-9	TYC Brother	BM5Z13008H	FO2503299
GMC Savana 03-09	Lamp, Park/Signal L	18-5970-00-9	TYC Brother	15880073	GM2520188
GMC Savana, 03-09	Lamp, Park/Signal R	18-5969-00-9	TYC Brother	15880074	GM2521188
GMC Savana, 03-10	Lamp, Park/Signal R	18-5969-00-9	TYC Brother	20772636	GM2521188
GMC Savana, 03-10	Lamp, Park/Signal L	18-5970-00-9	TYC Brother	20772637	GM2520188
GMC Savana, 03-15	Lamp, Park/Signal R	18-5969-00-9	TYC Brother	22940754	GM2521188
GMC Savana, 03-15	Lamp, Park/Signal L	18-5970-00-9	TYC Brother	22940755	GM2520188
GMC Savana, 03-15	Lamp, Park/Signal L	18-5970-00-9	TYC Brother	23284114	GM2520188
GMC Savana, 03-15	Lamp, Park/Signal R	18-5969-00-9	TYC Brother	23284115	GM2521188
Honda CR-V, 15-16, Touring Model	Headlamp Assy, R	317-1173R-AC2	DEPO	33100T1WA21	HO2503170
Honda CR-V, 15-16, Touring Model	Headlamp Assy, L	317-1173L-AC2	DEPO	33150T1WA21	HO2502170
Hyundai Elantra Sedan, 14-16, on luggage lid, Korea Built	Taillamp L	321-1312L-AC	DEPO	924033X200	HY2802126
Infiniti Q50 Hybrid, 14-15, w/o Adaptive Headlamps	Headlamp Assy, R	325-1106R-AC2	DEPO	260104HBOA	IN2503157
Infiniti Q50, 14-15, w/o Adaptive Headlamps	Headlamp Assy, R	325-1106R-AC2	DEPO	260104HBOA	IN2503157
Infiniti Q50, 14-15, w/o Adaptive Headlamps	Headlamp Assy, L	325-1106L-AC2	DEPO	260604HBOA	IN2502157
Kia Optima, 14-15	Taillamp L	17-5532-00-9	TYC Brother	924034C500	KI2802104
Kia Optima, 14-15	Taillamp R	17-5531-00-9	TYC Brother	924044C500	KI2803104
Kia Sedona, 15-16	Taillamp R	17-5545-00-9	TYC Brother	92406A9000	KI2803107
Kia Sedona, 15-16, On liftgate, Bulb type	Taillamp L	17-5546-00-9	TYC Brother	92405A9000	KI2802107
Mazda 3 Hatchback, 14-15, Japan Built, on body	Taillamp R	316-1940R-AC	DEPO	BHP151150B	MA2805115
Mazda 3 Hatchback, 14-15, Japan Built, on body	Taillamp L	316-1940L-AC	DEPO	BHP151160B	MA2804115
Mazda 3 Hatchback, 14-16	Reflector, Bumper Rear R	216-2906R3UC	DEPO	BCW8515L0B	MA1185104
Mazda 3 Hatchback, 14-16	Reflector, Bumper Rear L	216-2906L3UC	DEPO	BCW8515M0B	MA1184104
Mazda 3 Hatchback, 14-16, Japan Built, on body	Taillamp R	316-1940R-AC	DEPO	BHP151150C	MA2805115
Mazda 3 Hatchback, 14-16, Japan Built, on body	Taillamp L	316-1940L-AC	DEPO	BHP151160C	MA2804115
Mazda 3 Hatchback, 14-16, Japan Built, on Liftgate	Taillamp R	316-1309R-AC	DEPO	B45C513F0B	MA2803114
Nissan Infiniti Q50 Hybrid, 14-15, w/o Adaptive Headlamps	Headlamp Assy, L	325-1106L-AC2	DEPO	260604HBOA	IN2502157
Toyota Sienna Base/Limited/LE Standard/XLE, 15	Lamp, Back Up R	17-5543-00-9	TYC Brother	8158008030	TO2803117
Toyota Sienna Base/Limited/LE Standard/XLE, 15	Lamp, Back Up L	17-5544-00-9	TYC Brother	8159008030	TO2802117
Toyota Yaris Hatchback, 09-11	Headlamp Assy, R	20-9123-01-9	TYC Brother	8113052B50	TO2519123
Toyota Yaris Hatchback, 09-11	Headlamp Assy, L	20-9124-01-9	TYC Brother	8117052B40	TO2518123
Volkswagen Passat, 12, From 02/21/11	Headlamp Assy, L	20-12800-00-9	TYC Brother	561941005B	VW2502148
Volkswagen Passat, 12-15, From 3-21-11	Headlamp Assy, L	20-12800-00-9	TYC Brother	561941005D	VW2502148
Volkswagen Passat, 12-15, From 3-21-11	Headlamp Assy, R	20-12799-00-9	TYC Brother	561941006D	VW2503148
Volkswagen, Passat, 12	Headlamp Assy, R	20-12799-00-9	TYC Brother	561941006B	VW2503148

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Chevrolet Impala, 14-16	Absorber, Impact	CV01136A	Auto Power	23489775	GM1170226

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Y-GMBP329CA	Chevrolet Impala, 06-14, w/fog lamps	Bumper Cover, Front	Y.C.C.	11/15A	89025048	GM1000764
HD-04155BBQ	Honda Civic Coupe, 06-11	Bumper Cover, Rear	Tong Yang	05/15C	04715SVAA90ZZ	HO1100234
Y-HYBP005CA	Hyundai Sonata, 02-05	Bumper Cover, Front	Y.C.C.	11/15A	865603D030	HY1000139
Y-HYBP017CA	Hyundai Sonata, 11-14	Bumper Cover, Front	Y.C.C.	11/15A	865113Q000	HY1000183
Y-KABP011HRC	Kia Sorento, 11-13, w/Parking Assistant	Bumper Cover, Rear	Y.C.C.	11/15A	866101U010	KI1100154
TY-04276BCQ	Toyota Camry Base, 08-09, (USA)	Bumper Cover, Front	Tong Yang	12/15A	5211906919	TO1000329
TY-04276BCQ	Toyota Camry CE, 07 (USA)	Bumper Cover, Front	Tong Yang	12/15A	5211906919	TO1000329
TY-04276BCQ	Toyota Camry Hybrid, 07-09 (USA)	Bumper Cover, Front	Tong Yang	12/15A	5211906919	TO1000329
TY-04276BCQ	Toyota Camry LE/XLE, 07-09, (USA)	Bumper Cover, Front	Tong Yang	12/15A	5211906919	TO1000329
Y-TYBP249CA	Toyota Camry SE, 02-04 (USA)	Bumper Cover, Front	Y.C.C.	11/15A	52119AA905	TO1000231
TY-05046VBO	Toyota Camry SE, 10-11 (USA)	Spoiler, Front	Tong Yang	10/15A	7685106906	TO1093120
TYB082NBO	Toyota Camry, 02-06, (USA)	Bumper Cover, Rear	Pro Fortune	12/15A	52159AA903	TO1100203

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
MC860093F-000C	Mercury Mountaineer, 02-05	Cover, Radiator Support	AP-Procom	1L2Z8C299BA	FO1225172

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from May 16, 2016 through May 20, 2016.
All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.
If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org