

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
S0955F200AS	Chevrolet Cruze, 11	Fender R	Jui Li	12/15A	96930972	GM1241370
S0955F200AS	Chevrolet Cruze, 11-15	Fender R	Jui Li	12/15A	95092195	GM1241370
S0589H000AS	Dodge Caliber, 07-09	Hood	Jui Li	07/15A	5074140AF	CH1230249
S0589H000AS	Dodge Caliber, 07-11	Hood	Jui Li	07/15A	5074140AG	CH1230249
S0589H000AS	Dodge Caliber, 07-12	Hood	Jui Li	07/15A	5074140AH	CH1230249
CV9310150-100C	GMC Sierra 1500 Hybrid, 09	Hood	AP	11/15A	25786290	GM1230359
CV9310150-100C	GMC Sierra 1500 Hybrid, 09-10	Hood	AP	11/15A	25848847	GM1230359
CV9310150-100C	GMC Sierra 1500 Hybrid, 09-11	Hood	AP	11/15A	20863104	GM1230359
CV9310150-100C	GMC Sierra, 07-09	Hood	AP	11/15A	25786290	GM1230359
CV9310150-100C	GMC Sierra, 07-10	Hood	AP	11/15A	25848847	GM1230359
CV9310150-100C	GMC Sierra, 07-11	Hood	AP	11/15A	20863104	GM1230359
HD-20056AQ	Honda Odyssey, 05-07	Hood	Tong Yang	01/16A	60100SHJA90ZZ	HO1230146
S0477H000AS	Honda Odyssey, 05-07	Hood	Jui Li	01/16A	60100SHJA90ZZ	HO1230146
HDPL06HD1	Honda Pilot, 06-08	Hood	Gordon	07/15A	60100S9VA80ZZ	HO1230151
KA63002LQ	Kia Optima Hybrid, 11-15	Fender L	Cobra King	02/16A	663112T000	KI1240134
KA63002RQ	Kia Optima Hybrid, 11-15	Fender R	Cobra King	02/16A	663212T000	KI1241134
KA63002LQ	Kia Optima, 11-15	Fender L	Cobra King	02/16A	663112T000	KI1240134
KA63002RQ	Kia Optima, 11-15	Fender R	Cobra King	02/16A	663212T000	KI1241134
LXGS06FR1	Lexus GS 300, 06-09	Fender R	Gordon	06/14A	5380130A30	LX1241112
LXGS06FR1	Lexus GS 300, 06-11	Fender R	Gordon	06/14A	5380130A01	LX1241112
LXGS06FR1	Lexus GS 350, 06-09	Fender R	Gordon	06/14A	5380130A30	LX1241112
LXGS06FR1	Lexus GS 350, 06-11	Fender R	Gordon	06/14A	5380130A01	LX1241112
LXGS06FR1	Lexus GS 430, 06-09	Fender R	Gordon	06/14A	5380130A30	LX1241112
LXGS06FR1	Lexus GS 430, 06-11	Fender R	Gordon	06/14A	5380130A01	LX1241112
LXGS06FR1	Lexus GS 450h, 07-08	Fender R	Gordon	06/14A	5380130A30	LX1241112
LXGS06FR1	Lexus GS 450h, 07-11	Fender R	Gordon	06/14A	5380130A01	LX1241112
LXGS06FR1	Lexus GS 460, 06-09	Fender R	Gordon	06/14A	5380130A30	LX1241112
LXGS06FR1	Lexus GS 460, 06-11	Fender R	Gordon	06/14A	5380130A01	LX1241112
DT1530160-0R0C	Nissan Altima Hybrid, 07-08	Fender R	AP	01/16A	63100JA030	NI1241186
NSKF081AR	Nissan Altima Hybrid, 07-08	Fender R	Auto Power	01/16A	63100JA030	NI1241186
DT1530160-0R0C	Nissan Altima Hybrid, 07-11	Fender R	AP	01/16A	63100ZN55A	NI1241186
NSKF081AR	Nissan Altima Hybrid, 07-11	Fender R	Auto Power	01/16A	63100ZN55A	NI1241186
DT1530160-0R0C	Nissan Altima Sedan, 07-08	Fender R	AP	01/16A	63100JA030	NI1241186
NSKF081AR	Nissan Altima Sedan, 07-08	Fender R	Auto Power	01/16A	63100JA030	NI1241186
DT1530160-0R0C	Nissan Altima Sedan, 07-12	Fender R	AP	01/16A	63100ZN55A	NI1241186
NSKF081AR	Nissan Altima Sedan, 07-12	Fender R	Auto Power	01/16A	63100ZN55A	NI1241186
NS58002RQ	Nissan Altima, 13-15	Fender R	Cobra King	11/15A	631003TA0A	NI1241205

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
Y-ACBP002CA	Acura ILX Hybrid, 13-15	Bumper Cover, Front	Y.C.C.	06/15A	04711TX6A90ZZ	AC1000180
Y-ACBP002CA	Acura ILX, 13-15 w/fog lamps	Bumper Cover, Front	Y.C.C.	06/15A	04711TX6A90ZZ	AC1000180
Y-GMBP340CA	Chevrolet Camaro LS/LT, 10-13	Bumper Cover, Front	Y.C.C.	07/15B	92236548	GM1000906
CV-04185BBQ	Chevrolet Equinox, 10-11	Bumper Cover, Front	Tong Yang	04/15A	20896097	GM1000907
CV-04185BBQ	Chevrolet Equinox, 10-15	Bumper Cover, Front	Tong Yang	04/15A	20983230	GM1000907
Y-CRBP050CA	Chrysler PT Cruiser, 08-09, Code MLN	Bumper Cover, Rear	Y.C.C.	06/15A	ZG96TZZAE	CH1100826
Y-CRBP050CA	Chrysler PT Cruiser, 08-10, Code MLN	Bumper Cover, Rear	Y.C.C.	06/15A	ZG96TZZAF	CH1100826
DG-04112BCQ	Dodge Journey, 11-16, w/Fog Lamps, w/o Headlamp Washer	Fascia, Upper	Tong Yang	02/16A	1TX73TZZAC	CH1000A06
DG-04112BCQ	Dodge Journey, 11-16, w/Fog Lamps, w/o Headlamp Washer	Fascia, Upper	Tong Yang	02/16A	5YB55TZZAB	CH1000A06
FD-04420MAQ	Ford Escape S, 13-16, w/o Towing pkg	Cover, Lower Rear	Tong Yang	11/15A	CJ5Z17K835AA	FO1195129
HD-04257BBQ	Honda Accord Coupe, 13-16, 4 Cyl	Bumper Cover, Rear	Tong Yang	10/15A	04715T3LA90ZZ	HO1100282

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
Y-HDBP141CA	Honda Accord Hybrid, 05	Bumper Cover, Rear	Y.C.C.	01/16B	04715SDAA90ZZ	HO1100208
Y-HDBP141CA	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Y.C.C.	01/16B	04715SDAA90ZZ	HO1100208
Y-HDBP184CA	Honda Civic EX/EX NAVI Sedan, 12, Canada/USA built	Bumper Cover, Front	Y.C.C.	11/15A	04711TR3A80ZZ	HO1000281
Y-HDBP184CA	Honda Civic EX-L/EX-L NAVI/SI/NAVI Sedan, 12	Bumper Cover, Front	Y.C.C.	11/15A	04711TR3A80ZZ	HO1000281
HDB083NBQ	Honda Civic Hybrid, 06-08	Bumper Cover, Front	Pro Fortune	10/15B	04711SNEA90ZZ	HO1000239
HD-04153BBQ	Honda Civic Hybrid, 06-11	Bumper Cover, Rear	Tong Yang	10/15A	04715SNAA90ZZ	HO1100235
HDB083NBQ	Honda Civic Sedan, 06-08, 1.8L eng	Bumper Cover, Front	Pro Fortune	10/15B	04711SNEA90ZZ	HO1000239
HD-04153BBQ	Honda Civic Sedan, 06-11, 1.8L eng	Bumper Cover, Rear	Tong Yang	10/15A	04715SNAA90ZZ	HO1100235
HD04230BDQ	Honda Odyssey Base/Touring/Touring Elite, 11-16	Bumper Cover, Rear	TYG Products	16/03/28	04715TK8A80ZZ	HO1100266
HD04169BCQ	Honda Odyssey EX/EX-L/LX, 05-10	Bumper Cover, Rear	TYG Products	16/02/24	04715SHJA92ZZ	HO1100220
HD7200870-000C	Honda Odyssey EX/EX-L/LX, 05-10	Bumper Cover, Rear	AP-Procom	11/15A	04715SHJA92ZZ	HO1100220
HN-04092BBQ	Hyundai Elantra Sedan, 11-12 (USA)	Bumper Cover, Rear	Tong Yang	01/16B	866113Y000	HY1100180
HN-04092BBQ	Hyundai Elantra, 11-13, From 5-14-12, USA built	Bumper Cover, Rear	Tong Yang	01/16B	866113Y001	HY1100180
IN4010870-000C	Infiniti G35, 07-08, Sedan	Bumper Cover, Rear	AP-Procom	07/15A	85022JK00H	IN1100126
IN4010870-000C	Infiniti G35, 07-08, Sedan	Bumper Cover, Rear	AP-Procom	09/15B	85022JK00H	IN1100126
IN4010870-000C	Infiniti G37, 09, Sedan	Bumper Cover, Rear	AP-Procom	07/15A	85022JK00H	IN1100126
IN4010870-000C	Infiniti G37, 09, Sedan	Bumper Cover, Rear	AP-Procom	09/15B	85022JK00H	IN1100126
Y-KABP010CA	Kia Forte Hatchback, 11-13	Bumper Cover, Front	Y.C.C.	01/16A	865111M000	KI1000145
Y-KABP010CA	Kia Forte Sedan, 10-13	Bumper Cover, Front	Y.C.C.	01/16A	865111M000	KI1000145
Y-KABP013CA	Kia Rio Sedan, 12-16	Bumper Cover, Front	Y.C.C.	10/15A	865111W000	KI1000159
KA-04032BBQ	Kia Sportage, 11-15	Bumper Cover, Front	Tong Yang	12/15B	865113W000	KI1000152
LX2100000-710C	Lexus IS 250, 09-10, w/o Pre-Collision System; w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	04/15A	5211953945	LX1000188
LX2100000-710C	Lexus IS 250, 09-10, w/o Pre-Collision System; w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	09/15A	5211953945	LX1000188
LX2100000-710C	Lexus IS 350, 09-10, w/o Pre-Collision System; w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	04/15A	5211953945	LX1000188
LX2100000-710C	Lexus IS 350, 09-10, w/o Pre-Collision System; w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	09/15A	5211953945	LX1000188
TY-04275BBQ	Lexus RX 350, 04-06	Bumper Cover, Rear	Tong Yang	02/16A	521590E900	LX1100121
TY-04275BBQ	Lexus RX 350, 07-09	Bumper Cover, Rear	Tong Yang	02/16A	521590E900	LX1100121
TY-04275BBQ	Lexus RX 400h, 06-07	Bumper Cover, Rear	Tong Yang	02/16A	521590E900	LX1100121
DS-04333BBQ	Nissan Altima, 13-15	Bumper Cover, Front	Tong Yang	11/15B	620223TA0H	NI1000285
DS-04333BBQ	Nissan Altima, 13-15	Bumper Cover, Front	Tong Yang	12/15A	620223TA0H	NI1000285
DS-04276BBQ	Nissan Maxima, 09-14	Bumper Cover, Front	Tong Yang	12/15A	620229N00H	NI1000258
NSI058RAQ	Nissan Maxima, 09-14	Liner, Fender R	Pro Fortune	09/15A	63842ZX70A	NI1249119
NSI058LAQ	Nissan Maxima, 09-14	Liner, Fender L	Pro Fortune	09/15A	63843ZX70A	NI1248119
DS-04329BBQ	Nissan Maxima, 09-14	Bumper Cover, Rear	Tong Yang	07/15A	850229N00H	NI1100264
DT2010000-200C	Nissan Versa Hatchback, 07-11, w/o Sport	Bumper Cover, Front	AP-Procom	10/15A	FBM22EM30J	NI1000245
DT2010000-200C	Nissan Versa Hatchback, 07-11, w/o Sport	Bumper Cover, Front	AP-Procom	11/15A	FBM22EM30J	NI1000245
DT2010000-200C	Nissan Versa Hatchback, 07-12, w/o Sport	Bumper Cover, Front	AP-Procom	10/15A	FBM229EG0J	NI1000245
DT2010000-200C	Nissan Versa Hatchback, 07-12, w/o Sport	Bumper Cover, Front	AP-Procom	11/15A	FBM229EG0J	NI1000245
DT2010000-200C	Nissan Versa Sedan, 07-11	Bumper Cover, Front	AP-Procom	10/15A	FBM229EG0J	NI1000245
DT2010000-200C	Nissan Versa Sedan, 07-11	Bumper Cover, Front	AP-Procom	11/15A	FBM229EG0J	NI1000245
DT2010000-200C	Nissan Versa Sedan, 07-11	Bumper Cover, Front	AP-Procom	10/15A	FBM22EM30J	NI1000245
DT2010000-200C	Nissan Versa Sedan, 07-11	Bumper Cover, Front	AP-Procom	11/15A	FBM22EM30J	NI1000245
TYB102NBQ	Toyota Avalon, 00-04	Bumper Cover, Rear	Pro Fortune	12/15A	52159AC903	TO1100191
Y-TYBP269HCA	Toyota Camry Hybrid, 07-09	Bumper Cover, Front	Y.C.C.	05/15A	5211933943	TO1000327
TY-04402BBQ	Toyota Camry Hybrid, 12-14	Bumper Cover, Front	Tong Yang	09/15A	5211906974	TO1000378
TY-04402BBQ	Toyota Camry L/LE/XLE, 12-14	Bumper Cover, Front	Tong Yang	09/15A	5211906974	TO1000378
Y-TYBP269HCA	Toyota Camry, 07-09, (Japan)	Bumper Cover, Front	Y.C.C.	05/15A	5211933943	TO1000327
TYB084NCQ	Toyota Corolla CE/LE, 03-08	Bumper Cover, Rear	Pro Fortune	03/16A	5215902911	TO1100208
TY04345BCQ	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	TYG Products	16/02/08	5211902946	TO1000297
TY04345BCQ	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	TYG Products	16/03/07	5211902946	TO1000297

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
TY04345BCQ	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	TYG Products	16/02/08	521190Z938	TO1000297
TY04345BCQ	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	TYG Products	16/03/07	521190Z938	TO1000297
TY-04260BBQ	Toyota Highlander, 04-07	Bumper Cover, Front	Tong Yang	11/15B	5211948917	TO1000278
TY6020000-100C	Toyota Highlander, 11-13	Bumper Cover, Front	AP-Procom	06/14A	521190E914	TO1000374
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	11/15A	5215947905	TO1100280
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	11/15A	5215947905	TO1100280
TY-04442BBQ	Toyota RAV-4, 13-15, North America Built	Bumper Cover, Front	Tong Yang	11/15A	521190R911	TO1014101
TY04225BAQ	Toyota Sienna, 04-05, w/o Park Assist Sensors or Radar Cruise Control	Bumper Cover, Front	TYG Products	15/02/19	52119AE900	TO1000272
TY7520870-000C	Toyota Sienna, 04-10, w/o Park Assist Sensors	Bumper Cover, Rear	AP-Procom	11/15B	52159AE900	TO1100229
TY04304BCQ	Toyota Sienna, 06-10, w/o park assist sensors	Bumper Cover, Front	TYG Products	16/03/01	52119AE904	TO1000323

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
312-1186R-AC7	Toyota Tacoma, 05-11, Type 1	Headlamp Assy, R	DEPO	20150601	8111004173	TO2503181

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
FO1002412DSC	Ford F150 Pickup, 09-12, Chrome, w/o fog lamps	Bumper, Front	PBSI-DS	15362	9L3Z17757A	FO1002412

*This report includes all decertifications from June 1, 2016 through June 30, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.