



MONTHLY RECALL REPORT

August 2016*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
BM3S12HD1	BMW 3-Series Sedan F30, 12-15	Hood	Gordon	02/16A	41007290944	BM1230136
CV6400150-000C	Chevrolet Trailblazer, 02-09	Hood	AP	01/16A	12478013	GM1230264
CVH043A	Chevrolet Trailblazer, 02-09	Hood	Auto Power	01/16A	12478013	GM1230264
CV-20100AQ	Chevrolet Traverse, 09-11	Hood	Tong Yang	10/14A	15939034	GM1230389
CV-20100AQ	Chevrolet Traverse, 09-12	Hood	Tong Yang	10/14A	22807864	GM1230389
FDED03F11	Ford Expedition, 03-06, w/wheel opng mldg	Fender L	Gordon	11/14A	2L1Z16006DA	FO1240230
NS58001Q	Nissan Altima, 13-15	Hood	Cobra King	03/16A	651003TA0A	NI1230189
TYHN11FL1	Toyota Highlander, 11-13, w/o antenna hole	Fender L	Gordon	02/16A	538020E050	TO1240237

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
FD-04347BBQ	Ford Fusion Hybrid, 10-12	Bumper Cover, Front	Tong Yang	01/16A	AE5Z17D957BAPTM	FO1000650
FD-04347BBQ	Ford Fusion, 10-12	Bumper Cover, Front	Tong Yang	01/16A	AE5Z17D957BAPTM	FO1000650
GMCENVO-F02NEW	GMC Envoy SLE/SLT, 02-09	Bumper Cover, Front	Micro Rim	B9716	88937036	GM1000641
Y-HDBP141CA	Honda Accord Hybrid, 05	Bumper Cover, Rear	Y.C.C.	02/16A	04715SDAA90ZZ	HO1100208
Y-HDBP141CA	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Y.C.C.	02/16A	04715SDAA90ZZ	HO1100208
Y-HDBP162HCA	Honda Accord Sedan, 08-09, (6 cyl)	Bumper Cover, Rear	Y.C.C.	12/15A	04715TA1A90ZZ	HO1100245
Y-HDBP162HCA	Honda Accord Sedan, 08-12 (6 cyl)	Bumper Cover, Rear	Y.C.C.	12/15A	04715TA1A91ZZ	HO1100245
DT2010000-200C	Nissan Versa Hatchback, 07-11, w/o Sport	Bumper Cover, Front	AP-Procom	12/15A	FBM22EM30J	NI1000245
DT2010000-200C	Nissan Versa Hatchback, 07-11, w/o Sport	Bumper Cover, Front	AP-Procom	12/15B	FBM22EM30J	NI1000245
DT2010000-200C	Nissan Versa Hatchback, 07-12, w/o Sport	Bumper Cover, Front	AP-Procom	12/15A	FBM229EG0J	NI1000245
DT2010000-200C	Nissan Versa Hatchback, 07-12, w/o Sport	Bumper Cover, Front	AP-Procom	12/15B	FBM229EG0J	NI1000245
DT2010000-200C	Nissan Versa Sedan, 07-11	Bumper Cover, Front	AP-Procom	12/15A	FBM229EG0J	NI1000245
DT2010000-200C	Nissan Versa Sedan, 07-11	Bumper Cover, Front	AP-Procom	12/15B	FBM229EG0J	NI1000245
DT2010000-200C	Nissan Versa Sedan, 07-11	Bumper Cover, Front	AP-Procom	12/15A	FBM22EM30J	NI1000245
DT2010000-200C	Nissan Versa Sedan, 07-11	Bumper Cover, Front	AP-Procom	12/15B	FBM22EM30J	NI1000245
Y-TYBP259CA	Toyota Camry SE, 05-06, (USA)	Bumper Cover, Front	Y.C.C.	11/15A	5211906908	TO1000285
Y-TYBP270HCA	Toyota Camry SE, 07 (USA)	Bumper Cover, Rear	Y.C.C.	11/15B	5215906912	TO1100246
Y-TYBP270HCA	Toyota Camry SE, 07-11, (USA)	Bumper Cover, Rear	Y.C.C.	11/15B	5215906951	TO1100245
TY2810000-000C	Toyota Corolla S/XRS, 09-10, w/spoiler holes	Bumper Cover, Front	AP-Procom	12/15A	5211902989	TO1000342
TYB106NBQ	Toyota Highlander Hybrid, 08-10	Bumper Cover, Rear	Pro Fortune	03/16A	521590E906	TO1100260
TYB106NBQ	Toyota Highlander, 08-10	Bumper Cover, Rear	Pro Fortune	03/16A	521590E906	TO1100260
Y-TYBP263CA	Toyota Prius, 04-09	Bumper Cover, Front	Y.C.C.	03/16A	5211947903	TO1000274
TY20-8517	Toyota Venza Base/LE/XLE, 14-16	Bumper Cover, Rear	Tran Hung	12/15A	521590T900	TO1100277
TY20-8517	Toyota Venza Base/LE/XLE/Limited, 09-13	Bumper Cover, Rear	Tran Hung	12/15A	521590T900	TO1100277

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
20-6436-01-9	Honda Element, 03-06	Headlamp Assy, L	TYC Brother	1111610	33151SCVA01	HO2518106
312-1186R-AC7	Toyota Tacoma, 05-11, Type 1	Headlamp Assy, R	DEPO	20150601	8111004173	TO2503181

CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

*This report includes all decertifications from July 1, 2016 through July 31, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.