

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
S0589H000AS	Dodge Caliber, 07-09	Hood	Jui Li	05/16A	5074140AF	CH1230249
S0589H000AS	Dodge Caliber, 07-11	Hood	Jui Li	05/16A	5074140AG	CH1230249
S0589H000AS	Dodge Caliber, 07-12	Hood	Jui Li	05/16A	5074140AH	CH1230249
DJ-AC98402-RH	Honda Accord Sedan, 98-02	Fender R	Da Juane	03/13B	60211S84A90ZZ	HO1241147
HD2700160-0R0C	Honda Accord Sedan, 98-02	Fender R	AP	03/13B	60211S84A90ZZ	HO1241147
S0337F200AS	Honda Accord Sedan, 98-02	Fender R	Jui Li	03/13B	60211S84A90ZZ	HO1241147
HY12001Q	Hyundai Veloster, 12-13	Hood	Cobra King	05/16A	664002V010	HY1230154
KA5510150-000C	Kia Sorento, 11-15	Hood	AP	04/16S	664001U000	KI1230126
DS-20103AQ	Nissan Altima Coupe, 08-09	Hood	Tong Yang	01/15A	65100JA030	NI1230173
DS-20103AQ	Nissan Altima Coupe, 08-09	Hood	Tong Yang	02/16A	65100JA030	NI1230173
DS-20103AQ	Nissan Altima Coupe, 08-09	Hood	Tong Yang	03/15B	65100JA030	NI1230173
DS-20103AQ	Nissan Altima Hybrid, 07-09	Hood	Tong Yang	01/15A	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Hybrid, 07-09	Hood	Tong Yang	02/16A	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Hybrid, 07-09	Hood	Tong Yang	03/15B	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Sedan, 07-09	Hood	Tong Yang	01/15A	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Sedan, 07-09	Hood	Tong Yang	02/16A	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Sedan, 07-09	Hood	Tong Yang	03/15B	65100JA00D	NI1230173
DS-20103AQ	Nissan Altima Sedan/Hybrid, 07-09	Hood	Tong Yang	01/15A	65100JA030	NI1230173
DS-20103AQ	Nissan Altima Sedan/Hybrid, 07-09	Hood	Tong Yang	02/16A	65100JA030	NI1230173
DS-20103AQ	Nissan Altima Sedan/Hybrid, 07-09	Hood	Tong Yang	03/15B	65100JA030	NI1230173
TY-20192AQ	Scion tC, 11-13	Hood	Tong Yang	06/16A	5330121090	SC1230106
TY-20143AQ	Toyota Camry Hybrid, 07-11	Hood	Tong Yang	04/16A	5330106090	TO1230206
S1077F100AS	Toyota Camry Hybrid, 12-14	Fender L	Jui Li	04/16A	5381206150	TO1240239
TY-20143AQ	Toyota Camry, 07-11	Hood	Tong Yang	04/16A	5330106090	TO1230206
S1077F100AS	Toyota Camry, 12-14	Fender L	Jui Li	04/16A	5381206150	TO1240239
DJ-LA09401	Toyota Corolla, 09-12 (Japan)	Hood	Da Juane	06/16A	5330112A80	TO1230211
DJ-LA09401	Toyota Corolla, 09-13, (USA)	Hood	Da Juane	06/16A	5330102210	TO1230211
TA16002LQ	Toyota Tundra Regular or Access Cab, 00-06, w/o fender flare	Fender L	Cobra King	05/13A	538020C031	TO1240177
TA16002LQ	Toyota Tundra Regular or Access Cab, 00-06, w/o fender flare	Fender L	Cobra King	10/15A	538020C031	TO1240177
TY-20174AQ	Toyota Venza, 09-15	Hood	Tong Yang	04/16A	533010T020	TO1230214
VW-20052AQ	Volkswagen Jetta GLI Sedan, 11-16	Hood	Tong Yang	04/16A	5C6823031D	VW1230142
VW-20052AQ	Volkswagen Jetta Hybrid, 13-16	Hood	Tong Yang	04/16A	5C6823031D	VW1230142
VW-20052AQ	Volkswagen Jetta Sedan, 11	Hood	Tong Yang	04/16A	5C6823031B	VW1230142
VW-20052AQ	Volkswagen Jetta Sedan, 11-12	Hood	Tong Yang	04/16A	5C6823031C	VW1230142

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HD-04174BBQ	Acura MDX, 07-09	Bumper Cover, Front	Tong Yang	11/15A	04711STXA90ZZ	AC1000157
CV04091BBQ	Chevrolet Cavalier, 03-05	Bumper Cover, Front	TYG Products	16/04/25	12335575	GM1000662
Y-GMBP453CA	Chevrolet Equinox, 10-11	Bumper Cover, Front	Y.C.C.	02/16A	20896097	GM1000907
Y-GMBP453CA	Chevrolet Equinox, 10-15	Bumper Cover, Front	Y.C.C.	02/16A	20983230	GM1000907
CV-07199GAQ	Chevrolet Equinox, 10-15	Grille, Lower	Tong Yang	01/15A	25798747	GM1200621
CV-04213BBQ	Chevrolet Traverse, 09-12, w/Single Exhaust, w/o Rear Object Sensor	Bumper Cover, Rear	Tong Yang	09/15A	15930134	GM1100841
CV-04213BBQ	Chevrolet Traverse, 09-13, w/Single Exhaust, w/o Rear Object Sensor	Bumper Cover, Rear	Tong Yang	09/15A	20969815	GM1100841
Y-FDGR064CCA	Ford Expedition, 07-14, Chrome	Grille	Y.C.C.	11/15A	7L1Z8200BA	FO1200494
FD-04416BDQ	Ford Taurus, 13-14, w/Active park assist	Bumper Cover, Front	Tong Yang	10/15B	DG1Z17D957HAPTM	FO1000667
HD-04115BBQ	Honda Accord Coupe, 01-02	Bumper Cover, Rear	Tong Yang	03/14A	04715S82A91ZZ	HO1100198
HD-04256BBQ	Honda Accord Coupe, 13-15	Bumper Cover, Front	Tong Yang	10/15A	71101T3LA01ZZ	HO1000291
HDA1014EL-C	Honda Accord Sedan, 03-07, (USA/Mexico)	Liner, Fender L	Great Bestcam	12/15A	74151SDAA00	HO1248114

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD04086BBQ	Honda Accord Sedan, 98-00	Bumper Cover, Front	TYG Products	15/09/25	04711S84A90ZZ	HO1000178
HD-04256BBQ	Honda Accord, 13-14	Bumper Cover, Front	Tong Yang	10/15A	04711T3LA90ZZ	HO1000291
HD-04237BBQ	Honda Civic Coupe, 12-13, 1.8L eng	Bumper Cover, Rear	Tong Yang	05/16A	04715TS8A90ZZ	HO1100273
HN2720000-000C	Hyundai Elantra Sedan, 11-13 (USA)	Bumper Cover, Front	AP-Procom	01/16A	865113Y000	HY1000185
HYS2014CL-C	Hyundai Santa Fe, 10-12	Liner, Fender L	Great Bestcam	12/15A	868100W200	HY1248123
HYS2014CR-C	Hyundai Santa Fe, 10-12	Liner, Fender R	Great Bestcam	12/15A	868200W200	HY1249123
MZ32014FR-C	Mazda 3 Hatchback, 12-13, 2.0/2.5L Eng	Liner, Fender R	Great Bestcam	01/16A	BFD156130	MA1249139
MZ32014FL-C	Mazda 3 Hatchback, 12-13, 2.0/2.5L Eng	Liner, Fender L	Great Bestcam	01/16A	BFD156140	MA1248139
MZ32014FR-C	Mazda 3 Sedan, 12-13	Liner, Fender R	Great Bestcam	01/16A	BFD156130	MA1249139
MZ32014FL-C	Mazda 3 Sedan, 12-13	Liner, Fender L	Great Bestcam	01/16A	BFD156140	MA1248139
MZ32014FR-C	Mazda 3, 10-11, 2.5L Eng	Liner, Fender R	Great Bestcam	01/16A	BFD156130	MA1249139
MZ32014FL-C	Mazda 3, 10-11, 2.5L Eng	Liner, Fender L	Great Bestcam	01/16A	BFD156140	MA1248139
SB2520000-200C	Subaru XV Crosstrek Hybrid, 14	Bumper Cover, Front	AP-Procom	01/16A	57704FJ011	SU1000172
SB2520000-200C	Subaru XV Crosstrek, 13	Bumper Cover, Front	AP-Procom	01/16A	57704FJ010	SU1000172
SB2520000-200C	Subaru XV Crosstrek, 13-14	Bumper Cover, Front	AP-Procom	01/16A	57704FJ011	SU1000172
Y-TYBP270AHC	Toyota Camry LE/XLE, 07-11, (6 cyl) (USA)	Bumper Cover, Rear	Y.C.C.	02/16A	5215906910	TO1100244
TY6020000-000C	Toyota Highlander Hybrid, 08-09	Bumper Cover, Front	AP-Procom	05/16A	5211948936	TO1000338
TY6020000-000C	Toyota Highlander Hybrid, 08-10	Bumper Cover, Front	AP-Procom	05/16A	521190E911	TO1000338
TY6020000-000C	Toyota Highlander, 08-09	Bumper Cover, Front	AP-Procom	05/16A	5211948936	TO1000338
TY6020000-000C	Toyota Highlander, 08-10	Bumper Cover, Front	AP-Procom	05/16A	521190E911	TO1000338
TY-04391BBQ	Toyota Highlander, 11-13	Bumper Cover, Front	Tong Yang	12/15A	521190E914	TO1000374
TYB119NBQ	Toyota Highlander, 11-13	Bumper Cover, Front	Pro Fortune	04/16A	521190E914	TO1000374
TY8030870-210C	Toyota RAV-4, 09-10, w/Bumper Ext, (USA)	Bumper Cover, Rear	AP-Procom	06/16A	521590R902	TO1100271
TY8030870-210C	Toyota RAV-4, 09-10, w/Bumper Ext, w/Gate Mtd Spare, (Japan)	Bumper Cover, Rear	AP-Procom	06/16A	521590R902	TO1100271
TY8030870-210C	Toyota RAV-4, 11-12, w/Bumper Ext, w/Gate Mtd Spare	Bumper Cover, Rear	AP-Procom	06/16A	521590R902	TO1100271
Y-TYBP255CA	Toyota Sienna, 04-05, w/o Park Assist Sensors, w/Radar Cruise Control	Bumper Cover, Front	Y.C.C.	04/16A	52119AE902	TO1000271
VW0940870-000C	Volkswagen Passat, 12-15	Bumper Cover, Rear	AP-Procom	05/16A	561807421DGRU	VW1100192
VW0940870-000C	Volkswagen Passat, 12-15	Bumper Cover, Rear	AP-Procom	05/16A	561807421GRU	VW1100192

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CVSR07HL4	Chevrolet Silverado Hybrid 1500, 09	Headlamp Assy, L	Gordon	01/15A	25833678	GM2502280
CVSR07HL4	Chevrolet Silverado Hybrid 1500, 09	Headlamp Assy, L	Gordon	01/16A	25833678	GM2502280
CVSR07HL4	Chevrolet Silverado Hybrid 1500, 09	Headlamp Assy, L	Gordon	10/15B	25833678	GM2502280
CVSR07HR4	Chevrolet Silverado Hybrid 1500, 09	Headlamp Assy, R	Gordon	12/15A	25833679	GM2503280
CVSR07HL4	Chevrolet Silverado Hybrid 1500, 09-11	Headlamp Assy, L	Gordon	01/15A	25962804	GM2502280
CVSR07HL4	Chevrolet Silverado Hybrid 1500, 09-11	Headlamp Assy, L	Gordon	01/16A	25962804	GM2502280
CVSR07HL4	Chevrolet Silverado Hybrid 1500, 09-11	Headlamp Assy, L	Gordon	10/15B	25962804	GM2502280
CVSR07HR4	Chevrolet Silverado Hybrid 1500, 09-11	Headlamp Assy, R	Gordon	12/15A	25962805	GM2503280
CVSR07HL4	Chevrolet Silverado, 07-09	Headlamp Assy, L	Gordon	01/15A	25833678	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-09	Headlamp Assy, L	Gordon	01/16A	25833678	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-09	Headlamp Assy, L	Gordon	10/15B	25833678	GM2502280
CVSR07HR4	Chevrolet Silverado, 07-09	Headlamp Assy, R	Gordon	12/15A	25833679	GM2503280
CVSR07HL4	Chevrolet Silverado, 07-10, 2500/3500	Headlamp Assy, L	Gordon	01/15A	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-10, 2500/3500	Headlamp Assy, L	Gordon	01/16A	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-10, 2500/3500	Headlamp Assy, L	Gordon	10/15B	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-11	Headlamp Assy, L	Gordon	01/15A	25962804	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-11	Headlamp Assy, L	Gordon	01/16A	25962804	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-11	Headlamp Assy, L	Gordon	10/15B	25962804	GM2502280

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CVSR07HR4	Chevrolet Silverado, 07-13	Headlamp Assy, R	Gordon	12/15A	22853028	GM2503263
CVSR07HR4	Chevrolet Silverado, 07-13	Headlamp Assy, R	Gordon	12/15A	25962805	GM2503280
CVSR07HL4	Chevrolet Silverado, 07-13, 1500	Headlamp Assy, L	Gordon	01/15A	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-13, 1500	Headlamp Assy, L	Gordon	01/16A	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 07-13, 1500	Headlamp Assy, L	Gordon	10/15B	22853027	GM2502280
CVSR07HR4	Chevrolet Silverado, 09-11	Headlamp Assy, R	Gordon	12/15A	22853028	GM2503263
CVSR07HL4	Chevrolet Silverado, 09-13, Hybrid 1500	Headlamp Assy, L	Gordon	01/15A	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 09-13, Hybrid 1500	Headlamp Assy, L	Gordon	01/16A	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 09-13, Hybrid 1500	Headlamp Assy, L	Gordon	10/15B	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 11-14, 2500/3500 pickup	Headlamp Assy, L	Gordon	01/15A	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 11-14, 2500/3500 pickup	Headlamp Assy, L	Gordon	01/16A	22853027	GM2502280
CVSR07HL4	Chevrolet Silverado, 11-14, 2500/3500 pickup	Headlamp Assy, L	Gordon	10/15B	22853027	GM2502280
20-6362-01-9	Honda Accord Hybrid, 05-07	Headlamp Assy, L	TYC Brother	5251510	33151SDAA01	HO2502120
20-6362-01-9	Honda Accord, 03-07	Headlamp Assy, L	TYC Brother	5251510	33151SDAA01	HO2502120

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CH1096100DSC	Jeep Commander, 06-10	Crossmember, Lower	PBSI-DS	05/14A	5166082AB	CH1096100
CH1096100DSC	Jeep Grand Cherokee, 05-10	Crossmember, Lower	PBSI-DS	05/14A	5166082AB	CH1096100
NI1106177DSC	Nissan Maxima, 09-14	Bar, Reinforcement	PBSI-DS	03/16A	850309N05A	NI1106177
NI1106177DSC	Nissan Maxima, 16	Bar, Reinforcement	PBSI-DS	03/16A	850309N05A	NI1106177

*This report includes all decertifications from September 1, 2016 through September 30, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.