

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-20074AQ	GMC Envoy, 02-09	Hood	Tong Yang	06/16A	12478014	GM1230318
S0447H000AS	GMC Envoy, 02-09	Hood	Jui Li	06/16A	12478014	GM1230318
TYS6488A	Toyota Sequoia, 08	Radiator Support	Auto Power	01/16A	532010C070	TO1225275
TYS6488A	Toyota Sequoia, 08-16	Radiator Support	Auto Power	01/16A	532010C071	TO1225275
TYS6488A	Toyota Tundra, 07-09	Radiator Support	Auto Power	01/16A	532010C070	TO1225275
TYS6488A	Toyota Tundra, 07-10	Radiator Support	Auto Power	01/16A	532010C071	TO1225275

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HD04104BBQ	Honda Civic Hybrid, 03	Bumper Cover, Rear	TYG Products	150925	04715S5AA90ZZ	HO1100200
HD04104BBQ	Honda Civic Hybrid, 03	Bumper Cover, Rear	TYG Products	16/10/14	04715S5AA90ZZ	HO1100200
HD04104BBQ	Honda Civic Sedan, 01-03	Bumper Cover, Rear	TYG Products	150925	04715S5AA90ZZ	HO1100200
HD04104BBQ	Honda Civic Sedan, 01-03	Bumper Cover, Rear	TYG Products	16/10/14	04715S5AA90ZZ	HO1100200
GMCGRAM-F03NEW	Pontiac Grand Am SE, 03-05	Bumper Cover, Front	Micro Rim	B1716	12335576	GM1000675

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
317-19A7L-AC	Honda Civic Sedan, 13-15	Taillamp L	DEPO	20150605	33550TR0A51	HO2804102

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from November 1, 2016 through November 30, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org