

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CR-20019AQ	Chrysler 200 Convertible, 11	Hood	Tong Yang	04/16A	68079056AC	CH1230290
CR-20019AQ	Chrysler 200 Convertible, 11	Hood	Tong Yang	04/16A	68079056AD	CH1230290
CR-20019AQ	Chrysler 200 Convertible, 11-14	Hood	Tong Yang	04/16A	68079056AE	CH1230290
CR-20019AQ	Chrysler 200 Sedan, 11	Hood	Tong Yang	04/16A	68079056AC	CH1230290
CR-20019AQ	Chrysler 200 Sedan, 11	Hood	Tong Yang	04/16A	68079056AD	CH1230290
CR-20019AQ	Chrysler 200 Sedan, 11-12	Hood	Tong Yang	04/16A	68079056AE	CH1230290
DG9310090-000C	Dodge 1500 Pickup, 09	Radiator Support	AP-Procom	03/16A	68050996AA	CH1225219
WL-508AQ	Dodge 1500 Pickup, 09	Radiator Support	William Precision	03/16A	68050996AA	CH1225219
DG9310090-000C	Dodge 1500 Pickup, 09-11	Radiator Support	AP-Procom	03/16A	68050996AC	CH1225219
WL-508AQ	Dodge 1500 Pickup, 09-11	Radiator Support	William Precision	03/16A	68050996AC	CH1225219
DG9310090-000C	Dodge RAM R1500 Pickup, 09-12	Radiator Support	AP-Procom	03/16A	68050996AE	CH1225219
WL-508AQ	Dodge RAM R1500 Pickup, 09-12	Radiator Support	William Precision	03/16A	68050996AE	CH1225219
DG9310090-000C	Dodge RAM R2500 Pickup, 10-12	Radiator Support	AP-Procom	03/16A	68050996AE	CH1225219
WL-508AQ	Dodge RAM R2500 Pickup, 10-12	Radiator Support	William Precision	03/16A	68050996AE	CH1225219
FDMT10HD1	Ford Mustang, 10-12	Hood	Gordon	02/15A	AR3Z16612B	FO1230290
KA-03006AQ	Kia Sorento, 11-12	Radiator Support	Tong Yang	11/15A	641011U000	KI1225152
SB-20029AQ	Subaru Forester, 14-17, 2.0L/2.5L Eng	Hood	Tong Yang	07/16A	57229SG0009P	SU1230144

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
ADA405RB1	Audi A4 Sedan, 05-08, w/o Parking aid	Bumper Cover, Rear	Gordon	03/16A	8E5807303BGRU	AU1100164
ADA409RB1	Audi A4 Sedan, 09-14, w/S-Line pkg, w/o Parking aid	Bumper Cover, Rear	Gordon	04/15A	8K5807303BGRU	AU1100184
ADA405RB1	Audi S4 Sedan, 05-08, w/o Parking aid	Bumper Cover, Rear	Gordon	03/16A	8E5807303BGRU	AU1100164
ADA409RB1	Audi S4 Sedan, 10-14, w/o Parking aid	Bumper Cover, Rear	Gordon	04/15A	8K5807303BGRU	AU1100184
BM-04085BEQ	BMW 5-Series Hybrid F10H 12-13, w/Park Distance Control w/o Side View Camera	Bumper Cover, Front	Tong Yang	01/15A	51117285964	BM1000241
BM-04085BEQ	BMW 5-Series Sedan F10 11-13, w/Park Distance Control, w/o Side View Camera	Bumper Cover, Front	Tong Yang	01/15A	51117285964	BM1000241
CLB064NCQ	Chevrolet Cruze, 11-16, w/o RS Pkg, w/o Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	05/14A	95016694	GM1100876
CV-04185BBQ	Chevrolet Equinox, 10-11	Bumper Cover, Front	Tong Yang	04/16A	20896097	GM1000907
CV-04185BBQ	Chevrolet Equinox, 10-11	Bumper Cover, Front	Tong Yang	07/15C	20896097	GM1000907
CV-04185BBQ	Chevrolet Equinox, 10-11	Bumper Cover, Front	Tong Yang	07/16A	20896097	GM1000907
CV-04185BBQ	Chevrolet Equinox, 10-15	Bumper Cover, Front	Tong Yang	04/16A	20983230	GM1000907
CV-04185BBQ	Chevrolet Equinox, 10-15	Bumper Cover, Front	Tong Yang	07/15C	20983230	GM1000907
CV-04185BBQ	Chevrolet Equinox, 10-15	Bumper Cover, Front	Tong Yang	07/16A	20983230	GM1000907
CV-04120BBQ	Chevrolet HHR, 06-11	Bumper Cover, Front	Tong Yang	02/15A	15269707	GM1000776
CV93005Q	Chevrolet Pickup, 88-02, w/o Sport Level trim or tow hooks	Deflector, Front Air	Cobra King	03/16A	15569428	GM1090108
CV04149BBQ	Chevrolet Silverado 2500/3500, 07-10	Deflector, Front Air	TYG Products	16/03/18	15915505	GM1092202
CV93005Q	Chevrolet Suburban, 92-99, w/o tow hooks	Deflector, Front Air	Cobra King	03/16A	15569428	GM1090108
CV93005Q	Chevrolet Tahoe, 92-99, w/o tow hooks	Deflector, Front Air	Cobra King	03/16A	15569428	GM1090108
Y-CRBP036CA	Dodge Durango, 04-06, w/fog lamps	Bumper Cover, Front	Y.C.C.	07/16A	5HP18TZZAB	CH1000418
DG-05023VAQ	Dodge R1500 Ram Pick-Up, 09-14, w/Sport	Dam, Air	Tong Yang	05/16B	68033135AA	CH1090146
Y-FDBP104CA	Ford Escape, 13-15, w/o Rear Object Sensors	Bumper Cover, Rear	Y.C.C.	08/16A	CJ5Z17K835AB	FO1100690
FD-04373BBQ	Ford Explorer, 11-15, w/o Parking Assist	Bumper Cover, Front Upper	Tong Yang	03/16A	BB5Z17D957APT	FO1014109
Y-FDBP084CA	Ford Focus Sedan, 12-14	Bumper Cover, Rear	Y.C.C.	08/16A	CP9Z17K835BAPT	FO1100677
Y-FDBP109CA	Ford Mustang, 13-14	Bumper Cover, Front	Y.C.C.	06/16A	DR3Z17D957ABPT	FO1000670
Y-FDBP109CA	Ford Mustang, 13-14	Bumper Cover, Front	Y.C.C.	07/16A	DR3Z17D957ABPT	FO1000670

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD2810000-200C	Honda Accord Coupe, 08-10	Bumper Cover, Front	AP-Procom	08/16A	04711TE0A90ZZ	HO1000256
Y-HDBP150CA	Honda Accord Sedan, 06-07	Bumper Cover, Rear	Y.C.C.	08/16A	04715SDBA80ZZ	HO1100233
Y-HDBP155CA	Honda Civic Hybrid, 06-11	Bumper Cover, Rear	Y.C.C.	01/16A	04715SNAA90ZZ	HO1100235
HD0900000-500C	Honda Civic Hybrid, 09-11	Bumper Cover, Front	AP-Procom	07/16A	04711SNAA90ZZ	HO1000266
Y-HDBP155CA	Honda Civic Sedan, 06-11, 1.8L eng	Bumper Cover, Rear	Y.C.C.	01/16A	04715SNAA90ZZ	HO1100235
HD0900000-500C	Honda Civic Sedan, 09-11	Bumper Cover, Front	AP-Procom	07/16A	04711SNAA90ZZ	HO1000266
HDB090NCQ	Honda Odyssey EX/EX-L/LX, 11-16	Bumper Cover, Rear	Pro Fortune	08/16A	04715TK8A90ZZ	HO1100267
HD04229BBQ	Honda Odyssey EX/EX-L/XL, 11-15	Bumper Cover, Front	TYG Products	16/08/09	04711TK8A90ZZ	HO1000276
HD04229BBQ	Honda Odyssey EX/LX/EX-L, 11-16, w/o Parking sensors	Bumper Cover, Front	TYG Products	16/08/09	04711TK8A91ZZ	HO1000276
AM-04053BCQ	Jeep Grand Cherokee Laredo/Limited/Overland/Summit, 14-15, w/o Parking Assist	Bumper Cover, Front Upper	Tong Yang	03/16A	1WL27TZZAC	CH1014105
LSB037NDQ	Lexus RX 350, 13-15, w/o F Sport pkg	Bumper Cover, Front	Pro Fortune	07/16A	521190E916	LX1000248
LSB037NDQ	Lexus RX 450h, 13-15, w/o F Sport pkg, w/Parking assist	Bumper Cover, Front	Pro Fortune	07/16A	521190E916	LX1000248
DS-04276BBQ	Nissan Maxima, 09-14	Bumper Cover, Front	Tong Yang	02/16A	620229N00H	NI1000258
DS-04329BBQ	Nissan Maxima, 09-14	Bumper Cover, Rear	Tong Yang	09/15A	850229N00H	NI1100264
Y-DSBP244CA	Nissan Versa Sedan, 12, (P)	Bumper Cover, Rear	Y.C.C.	05/16A	HEM223AN0H	NI1100284
Y-DSBP244CA	Nissan Versa Sedan, 12-16	Bumper Cover, Rear	Y.C.C.	05/16A	HEM223AN0J	NI1100284
SB-04035BBQ	Subaru Outback, 10-14	Bumper Cover, Rear	Tong Yang	05/16B	57704AJ07A	SU1100164
TY3820870-000C	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	AP-Procom	01/16A	5215906961	TO1100296
Y-TYBP250CA	Toyota Camry, 02-06, (USA)	Bumper Cover, Rear	Y.C.C.	07/16A	52159AA903	TO1100203
TY2810000-100C	Toyota Corolla Base/CE/L, 09-10, w/o spoiler holes	Bumper Cover, Front	AP-Procom	03/16B	5211902990	TO1000343
Y-TYBP257CA	Toyota Corolla S, 05-08	Bumper Cover, Front	Y.C.C.	06/14A	5211902947	TO1000298
Y-TYBP257CA	Toyota Corolla S, 05-08	Bumper Cover, Front	Y.C.C.	06/14A	521190Z939	TO1000298
Y-TYBP257CA	Toyota Corolla XRS, 05-06	Bumper Cover, Front	Y.C.C.	06/14A	5211902947	TO1000298
Y-TYBP257CA	Toyota Corolla XRS, 05-06	Bumper Cover, Front	Y.C.C.	06/14A	521190Z939	TO1000298
TYB106NBQ	Toyota Highlander Hybrid, 08-10	Bumper Cover, Rear Upper	Pro Fortune	04/16A	521590E906	TO1100260
TYB106NBQ	Toyota Highlander, 08-10	Bumper Cover, Rear Upper	Pro Fortune	04/16A	521590E906	TO1100260
TY2120000-000C	Toyota Matrix Base/L/S, 09-14, w/o Sport pkg	Bumper Cover, Front	AP-Procom	03/16A	5211902994	TO1000344
TY2120000-000C	Toyota Matrix, 09-14, w/o fog lamps	Bumper Cover, Front	AP-Procom	03/16A	5211902994	TO1000344
TY04304BDQ	Toyota Sienna, 06-10, w/park assist sensors	Bumper Cover, Front	TYG Products	16/04/06	52119AE906	TO1000324
Y-TYBP272CA	Toyota Venza, 09-13	Bumper Cover, Front	Y.C.C.	07/16A	521190T900	TO1000354
Y-TYBP272CA	Toyota Venza, 14-15, w/o HID Lamps	Bumper Cover, Front	Y.C.C.	07/16A	521190T900	TO1000354
VWB042NBQ	Volkswagen Jetta, 11-15, w/o Parking Assist	Bumper Cover, Rear	Pro Fortune	05/16A	5C6807418AGRU	VW1100186

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CVR3386A	Chevrolet Sonic Hatchback LS/LT/LTZ, 12-16, w/fog lamps	Bar, Impact Lower	Auto Power	03/16A	96696249	GM1006671
CVR3386A	Chevrolet Sonic Hatchback RS, 12-16	Bar, Impact Lower	Auto Power	03/16A	96696249	GM1006671
CVR3386A	Chevrolet Sonic Sedan, 12-16, w/fog lamps	Bar, Impact Lower	Auto Power	03/16A	96696249	GM1006671

*This report includes all decertifications from December 1, 2016 through December 31, 2016.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.