

NEW PARTS CAPA 101 STANDARD - METALS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-----------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Dodge RAM R2500 Pickup, 13-16 | Crossmember, Radiator Upper | DGS005BUK | Sa. Tai - H | 68222830AA | CH1225252 |
| Dodge RAM R2500 Pickup, 13-16 | Crossmember, Radiator Lower | DGS005CWK | Sa. Tai - H | 68222831AA | CH1225262 |
| Dodge RAM R2500 Pickup, 13-16 | Crossmember, Radiator Lower | DGS005BWK | Sa. Tai - H | 68224848AA | CH1225253 |
| Dodge RAM R3500 Pickup, 13-16 | Crossmember, Radiator Lower | DGS005BWK | Sa. Tai - H | 68224848AA | CH1225253 |

NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|---------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Acura RDX, 16-17 | Moulding, Grille | HD-07201FAQ | Tong Yang | 71123TX4A51 | AC1202102 |
| Dodge Challenger, 08-14 | Crossmember, Upper | DGS6908A | Auto Power | 5028743AE | CH1225268 |
| Dodge Durango, 14, Code MBA | Bumper Cover, Front Lower | DGP095NBQ | Pro Fortune | 1XV00TZZAB | CH1015116 |
| Dodge Durango, 14, Code MLH | Fascia, Lower | DGP096NAQ | Pro Fortune | 5113672AB | CH1015118 |
| Honda Fit EV, 13-14 | Cover, Engine Under | HDE011NAQ | Pro Fortune | 74111TX9A00 | HO1228139 |
| Honda Fit, 09-14 | Cover, Engine Under | HDE010NAQ | Pro Fortune | 74111TK6A00 | HO1228125 |
| Hyundai Accent Hatchback, 15-16 | Grille, Bumper | HYN004NAQ | Pro Fortune | 865611R010 | HY1036128 |
| Hyundai Accent Sedan, 14-16, From 10-15-13 | Grille, Bumper | HYN004NAQ | Pro Fortune | 865611R010 | HY1036128 |
| Hyundai Sonata, 15-16, w/o Rear object sensors | Bumper Cover, Rear | HN2420870-100C | AP-Procom | 86611C2000 | HY1100205 |
| Hyundai Tucson, 16 | Plate, Skid | HN-04172MAQ | Tong Yang | 86665D3100 | HY1195113 |
| Jeep Cherokee Latitude/Limited/North/Sport, 14-16, w/o Park Assist | Bumper Cover, Front Upper | CHRCHE-F14NEW | Micro Rim | 5NJ52TZZAB | CH1014112 |
| Jeep Cherokee Latitude/Limited/North/Sport, 14-16, w/o Park Assist | Bumper Cover, Front Upper | CHRCHE-F14NEW | Micro Rim | 5NJ52TZZAC | CH1014112 |
| Jeep Cherokee, 14-17, w/Off Road pkg | Liner, Fender Assy R | AMJ3014CR1-C | Great Bestcam | 68102264AF | CH1249162 |
| Kia Sedona, 15-16, w/o Parking Assist | Bumper Cover, Rear | KA-04109BBQ | Tong Yang | 86611A9000 | KI1100188 |
| Lexus CT 200h, 14-16, w/o F Sport | Grille | TY-07628GAQ | Tong Yang | 5311176020 | LX1200177 |
| Toyota 4Runner, 14-16, w/o Chrome | Bumper Cover, Front Lower | TY-05086VAQ | Tong Yang | 5212935030 | TO1091100 |
| Toyota Yaris Hatchback, 15-17 | Cover, Upper Grille | TYM156TAQ | Pro Fortune | 527190D900 | TO1217100 |
| Toyota Yaris Hatchback, 15-17 | Moulding, Grille | TYM156DEQ | Pro Fortune | 531210D250 | TO1216104 |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|--------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Ford Transit Connect, 10-13 | Taillamp R | 330-1952R-AC | DEPO | 9T1Z13404A | FO2801225 |
| Ford Transit Connect, 10-13 | Taillamp L | 330-1952L-AC | DEPO | 9T1Z13405A | FO2800225 |
| Honda Pilot, 16, w/o Auto Dimming, w/Auto On/Off | Headlamp, R | 317-1174R-ACD2 | DEPO | 33100TG7A12 | HO2503167 |
| Honda Pilot, 16, w/o Auto Dimming, w/Auto On/Off | Headlamp, L | 317-1174L-ACD2 | DEPO | 33150TG7A12 | HO2502167 |
| Hyundai Elantra Coupe, 14, On luggage lid, LED | Taillamp L | 321-1314L-AC | DEPO | 924033X310 | HY2802129 |
| Hyundai Elantra Coupe, 14, On luggage lid, LED | Taillamp R | 321-1314R-AC | DEPO | 924043X310 | HY2803129 |
| Hyundai Elantra Sedan, 11-16, On luggage lid, LED, Korea built | Taillamp L | 321-1314L-AC | DEPO | 924033X310 | HY2802129 |
| Hyundai Elantra Sedan, 11-16, On luggage lid, LED, Korea built | Taillamp R | 321-1314R-AC | DEPO | 924043X310 | HY2803129 |
| Kia Optima SX, 12-13, USA built | Lamp, Daytime Running L | 123-1601L-AC | DEPO | 922072T100 | KI2562100 |
| Kia Optima SX, 12-13, USA built | Lamp, Daytime Running R | 123-1601R-AC | DEPO | 922082T100 | KI2563100 |
| Kia Optima, 12-13, Halogen (USA) | Headlamp Assy, L | 323-1135L-ACN2 | DEPO | 921014C000 | KI2502157 |
| Kia Optima, 12-13, Halogen (USA) | Headlamp Assy, R | 323-1135R-ACN2 | DEPO | 921024C000 | KI2503157 |
| Lexus RX 350, 16 | Reflector, Bumper Rear R | 324-2905R-UC | DEPO | 8191048050 | LX1185103 |
| Lexus RX 350, 16 | Reflector, Bumper Rear L | 324-2905L-UC | DEPO | 8192048050 | LX1184103 |
| Lexus RX 450h, 16 | Reflector, Bumper Rear R | 324-2905R-UC | DEPO | 8191048050 | LX1185103 |
| Lexus RX 450h, 16 | Reflector, Bumper Rear L | 324-2905L-UC | DEPO | 8192048050 | LX1184103 |
| Mazda 5, 06-07 | Headlamp, R | 316-1135R-UC3 | DEPO | CC43510K0C | MA2519137 |
| Mazda 5, 06-07 | Headlamp, L | 316-1135L-UC3 | DEPO | CC43510L0C | MA2518137 |
| Mercedes-Benz C-Class C300/C350/C400/C63 AMG, 15 | Headlamp Assy, L | 340-1146L-AC2 | DEPO | 2058202761 | MB2502220 |
| Mercedes-Benz C-Class C300/C350/C400/C63 AMG, 15 | Headlamp Assy, R | 340-1146R-AC2 | DEPO | 2058202861 | MB2503220 |
| Mercedes-Benz C-Class C300/C350/C400/C63 AMG, 15-16 | Headlamp Assy, L | 340-1146L-AC2 | DEPO | 2059067102 | MB2502220 |
| Mercedes-Benz C-Class C300/C350/C400/C63 AMG, 15-16 | Headlamp Assy, R | 340-1146R-AC2 | DEPO | 2059067202 | MB2503220 |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-----------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Dodge Dart, 13-15 | Bar, Impact | CH1006226DSC | PBSI-DS | 68082361AB | CH1006226 |
| Ford C-Max Energi, 13-16 | Reinforcement, Bumper Front | FD44131AH | Hui Yih | CP9Z17757B | FO1006261 |
| Ford C-Max Hybrid, 13-16 | Reinforcement, Bumper Front | FD44131AH | Hui Yih | CP9Z17757B | FO1006261 |
| Ford Escape, 13-16 | Reinforcement, Bumper Front | FD44131AH | Hui Yih | CP9Z17757B | FO1006261 |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application</u> <u>Description</u> | <u>Part</u> <u>Description</u> | <u>Manufacturer</u> <u>Number</u> | <u>Manufacturer</u> <u>Number</u> | <u>OEM</u> <u>Number</u> | <u>PartsLink</u> <u>Number</u> |
|---|-----------------------------------|--------------------------------------|--------------------------------------|-----------------------------|-----------------------------------|
| Ford Focus Electric, 12-14 | Reinforcement, Bumper Front | FD44131AH | Hui Yih | CP9Z17757B | FO1006261 |
| Lincoln MKC, 15-16, w/o Adaptive Cruise Control | Reinforcement, Bumper Front | FD44131AH | Hui Yih | CP9Z17757B | FO1006261 |
| Subaru Legacy, 10-14 | Reinforcement, Bumper Front | SB44101AH | Hui Yih | 57711AJ00A9P | SU1006147 |
| Subaru Outback, 10-14 | Reinforcement, Bumper Front | SB44101AH | Hui Yih | 57711AJ00A9P | SU1006147 |
| Toyota Tacoma, 05-15, Chrome | Bumper, Rear Face Bar | TO1102240DSC | PBSI-DS | 5215104061 | TO1102240 |
| Toyota Tacoma, 05-15, Prime | Bumper, Rear Face Bar | TO1102241DSC | PBSI-DS | 5215104051 | TO1102241 |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

| <u>Manufacturer</u> <u>Number</u> | <u>Application</u> <u>Description</u> | <u>Part</u> <u>Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM</u> <u>Number</u> | <u>PartsLink</u> <u>Number</u> |
|--------------------------------------|--|-----------------------------------|---------------------|------------|-----------------------------|-----------------------------------|
| FD-20151AQ | Ford F150 Pickup, 09-14 | Hood | Tong Yang | 09/16A | 9L3Z16612A | FO1230274 |
| HDCV12H11 | Honda Civic Coupe, 12-13 | Hood | Gordon | 08/16A | 60100TR3A90ZZ | HO1230166 |
| HDCV12H11 | Honda Civic Sedan, 12-13 (USA/Canada) | Hood | Gordon | 08/16A | 60100TR3A90ZZ | HO1230166 |
| MZA609HD1 | Mazda 6, 09-13 | Hood | Gordon | 08/16A | GS3L52310 | MA1230165 |
| S0851H000AS | Mazda 6, 09-13 | Hood | Jui Li | 08/16A | GS3L52310 | MA1230165 |
| S0989F100AS | Toyota Sienna, 11-14, w/o Antenna | Fender L | Jui Li | 08/16A | 5381208030 | TO1240234 |

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer</u> <u>Number</u> | <u>Application</u> <u>Description</u> | <u>Part</u> <u>Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM</u> <u>Number</u> | <u>PartsLink</u> <u>Number</u> |
|--------------------------------------|--|-----------------------------------|---------------------|------------|-----------------------------|-----------------------------------|
| Y-HDBP141CA | Honda Accord Hybrid, 05 | Bumper Cover, Rear | Y.C.C. | 06/16A | 04715SDAA90ZZ | HO1100208 |
| Y-HDBP141CA | Honda Accord Sedan, 03-05 | Bumper Cover, Rear | Y.C.C. | 06/16A | 04715SDAA90ZZ | HO1100208 |
| Y-HYBP028CA | Hyundai Santa Fe Sport, 13-17, w/o parking assist | Bumper Cover, Front | Y.C.C. | 06/16A | 865114Z000 | HY1014100 |
| Y-MCBP006CA | Mercury Grand Marquis, 03-05 | Bumper Cover, Front | Y.C.C. | 06/16A | 3W3Z17D957BA | FO1000518 |
| MB3350000-500C | Mitsubishi Galant, 09-12, Paint to match | Bumper Cover, Front | AP-Procom | 07/16A | 6400C626 | MI1000325 |
| TY3820870-000C | Toyota Camry L/LE/XLE/Hybrid, 12-14 | Bumper Cover, Rear | AP-Procom | 05/16A | 5215906961 | TO1100296 |
| TY7530000-010C | Toyota Sienna Base/L/LE, 11-15, 3.5L Eng | Bumper Cover, Front | AP-Procom | 02/16A | 5211908904 | TO1000369 |
| TY7530000-010C | Toyota Sienna XLE, 11-15, 3.5L Eng., w/o Limited pkg | Bumper Cover, Front | AP-Procom | 02/16A | 5211908904 | TO1000369 |
| TY7530000-010C | Toyota Sienna, 11-12, 2.7L Eng | Bumper Cover, Front | AP-Procom | 02/16A | 5211908904 | TO1000369 |
| TY-04409BAQ | Toyota Tacoma, 12-15, Base w/o Wheel Opening Flares | Bumper Cover, Front | Tong Yang | 05/16B | 5211904060 | TO1000384 |

CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer</u> <u>Number</u> | <u>Application</u> <u>Description</u> | <u>Part</u> <u>Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM</u> <u>Number</u> | <u>PartsLink</u> <u>Number</u> |
|--------------------------------------|--|-----------------------------------|---------------------|------------|-----------------------------|-----------------------------------|
| NONE | | | | | | |

CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer</u> <u>Number</u> | <u>Application</u> <u>Description</u> | <u>Part</u> <u>Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM</u> <u>Number</u> | <u>PartsLink</u> <u>Number</u> |
|--------------------------------------|--|-----------------------------------|---------------------|------------|-----------------------------|-----------------------------------|
| NONE | | | | | | |

DELETED PARTS CAPA 101 STANDARD - METALS

| <u>Manufacturer</u> <u>Number</u> | <u>Application</u> <u>Description</u> | <u>Part</u> <u>Description</u> | <u>Manufacturer</u> | <u>OEM</u> <u>Number</u> | <u>PartsLink</u> <u>Number</u> |
|--------------------------------------|--|-----------------------------------|---------------------|-----------------------------|-----------------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer</u> <u>Number</u> | <u>Application</u> <u>Description</u> | <u>Part</u> <u>Description</u> | <u>Manufacturer</u> | <u>OEM</u> <u>Number</u> | <u>PartsLink</u> <u>Number</u> |
|--------------------------------------|--|-----------------------------------|---------------------|-----------------------------|-----------------------------------|
| NONE | | | | | |



WEEKLY PARTS UPDATE

February 13, 2017

[Report: P6]
Weekly

DELETED PARTS CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|------------------------------------|-----------------------------|---------------------|-----------------------|-----------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|------------------------------------|-----------------------------|---------------------|-----------------------|-----------------------------|
| NONE | | | | | |

*This report includes all new, decertified and deleted parts from February 6, 2017 through February 10, 2017.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org