

**NEW PARTS CAPA 101 STANDARD - METALS**

| <b>Application<br/>Description</b>          | <b>Part<br/>Description</b> | <b>Manufacturer<br/>Number</b> | <b>Manufacturer</b> | <b>OEM<br/>Number</b> | <b>PartsLink<br/>Number</b> |
|---|-----------------------------|--------------------------------|---------------------|-----------------------|-----------------------------|
| BMW 3-Series F30 Sedan, 12-14               | Fender L                    | BM3410160-0LOC                 | AP                  | 41357298027           | BM1240152                   |
| BMW 3-Series F30 Sedan, 12-16               | Fender L                    | BM3410160-0LOC                 | AP                  | 41007438439           | BM1240152                   |
| BMW 3-Series F30 Sedan, 12-16               | Fender R                    | BM3410160-0R0C                 | AP                  | 41007438440           | BM1241152                   |
| BMW 3-Series Sedan F30, 12-14               | Fender R                    | BM3410160-0R0C                 | AP                  | 41357298028           | BM1241152                   |
| Chevrolet Silverado 1500, 14-15, w/camera   | Tailgate                    | CV-90023AQ                     | Tong Yang           | 23205798              | GM1900128                   |
| Chevrolet Silverado 1500, 14-16, w/camera   | Tailgate                    | CV-90023AQ                     | Tong Yang           | 23418940              | GM1900128                   |
| Chevrolet Silverado 2500/3500, 15, w/camera | Tailgate                    | CV-90023AQ                     | Tong Yang           | 23205798              | GM1900128                   |
| Chevrolet Silverado 2500/3500, 16, w/camera | Tailgate                    | CV-90023AQ                     | Tong Yang           | 23418940              | GM1900128                   |
| Ford Escape Hybrid, 08-12                   | Tie Bar, Lower              | FDS6585A                       | Auto Power          | 8L8Z16138B            | FO1225197                   |
| Ford Escape, 08-12                          | Tie Bar, Lower              | FDS6585A                       | Auto Power          | 8L8Z16138B            | FO1225197                   |
| GMC Sierra 1500, 14-15, w/camera            | Tailgate                    | CV-90023AQ                     | Tong Yang           | 23205798              | GM1900128                   |
| GMC Sierra 1500, 14-16, w/camera            | Tailgate                    | CV-90023AQ                     | Tong Yang           | 23418940              | GM1900128                   |
| GMC Sierra 2500/3500, 15, w/camera          | Tailgate                    | CV-90023AQ                     | Tong Yang           | 23205798              | GM1900128                   |
| GMC Sierra 2500/3500, 15, w/camera          | Tailgate                    | CV-90023AQ                     | Tong Yang           | 23418940              | GM1900128                   |
| Mercedes-Benz CLA-Class, 14-16              | Fender L                    | BZ-10076AQ-LH                  | Tong Yang           | 1178810101            | MB1240146                   |
| Mercedes-Benz CLA-Class, 14-16              | Fender R                    | BZ-10076AQ-RH                  | Tong Yang           | 1178810201            | MB1241146                   |
| Mercury Mariner Hbyrid, 08-11               | Tie Bar, Lower              | FDS6585A                       | Auto Power          | 8L8Z16138B            | FO1225197                   |
| Mercury Mariner, 08-11                      | Tie Bar, Lower              | FDS6585A                       | Auto Power          | 8L8Z16138B            | FO1225197                   |
| Nissan Juke, 11-16                          | Tie Bar, Upper Side R       | NSS6734AR                      | Auto Power          | 625201KA0A            | NI1225201                   |
| Nissan Juke, 11-16                          | Tie Bar, Upper Side L       | NSS6734AL                      | Auto Power          | 625211KA0A            | NI1225202                   |
| Nissan Juke, 15-16                          | Fender R                    | DS-10226AQ-RH                  | Tong Yang           | F31003YMMMA           | NI1241214                   |
| Nissan Juke, 15-16                          | Fender L                    | DS-10226AQ-LH                  | Tong Yang           | F31013YMMMA           | NI1240214                   |

**NEW PARTS CAPA 201 STANDARD - PLASTICS**

| <b>Application<br/>Description</b>  | <b>Part<br/>Description</b> | <b>Manufacturer<br/>Number</b> | <b>Manufacturer</b> | <b>OEM<br/>Number</b> | <b>PartsLink<br/>Number</b> |
|---|-----------------------------|--------------------------------|---------------------|-----------------------|-----------------------------|
| Acura MDX, 14-16, w/Adaptive cruise control   | Bumper Cover, Front         | ACB023NDQ                      | Pro Fortune         | 04711TZ5A80ZZ         | AC1000184                   |
| Acura MDX, 14-16, w/o Adaptive cruise control   | Bumper Cover, Front         | ACB023NCQ                      | Pro Fortune         | 04711TZ5A90ZZ         | AC1000183                   |
| Audi A3, 15-16, Cabrio (A3CA), w/o Parking Aid  | Bumper Cover, Rear          | AU0710870-100C                 | AP-Procom           | 8V5807067GRU          | AU1100215                   |
| Audi A3/S3, 15-16, w/o Parking Aid  | Bumper Cover, Rear          | AU0710870-100C                 | AP-Procom           | 8V5807067GRU          | AU1100215                   |
| Buick Regal Base/Premium, 14-15   | Bumper Cover, Front         | BKB033NBQ                      | Pro Fortune         | 22938366              | GM1000950                   |
| Buick Regal eASSIST, 14-15  | Bumper Cover, Front         | BKB033NBQ                      | Pro Fortune         | 22938366              | GM1000950                   |
| Buick Regal GS, 12-15   | Bumper Cover, Front         | BKB035NBQ                      | Pro Fortune         | 13399053              | GM1000951                   |
| Chrysler 200, 15-16, Sedan, w/ Adaptive Cruise Control                                  | Grille, Lower               | CR-07044GAQ                    | Tong Yang           | 68202989AC            | CH1036135                   |
| Dodge Challenger R/T, R/T Plus, SXT, SXT Plus, 15-16, w/Fog Lamps                       | Dam, Air                    | DG-05030VAQ                    | Tong Yang           | 68258745AB            | CH1090155                   |
| Dodge Challenger, 15-16, 5.7L/6.2L/6.4L Eng, w/o Parking Sensors                        | Bumper Cover, Rear Lower    | DG-05031VAQ                    | Tong Yang           | 68260009AB            | CH1195119                   |
| Dodge Challenger, 15-16, 5.7L/6.2L/6.4L Eng, w/o Parking Sensors                        | Bumper Cover, Rear Lower    | DG-05031VAQ                    | Tong Yang           | 68260009AC            | CH1195119                   |
| Dodge Challenger, 15-16, w/o Adaptive Cruise Control                                    | Bumper Cover, Rear Lower    | DG-05031VBQ                    | Tong Yang           | 68260010AB            | CH1195120                   |
| Dodge Challenger, 15-16, w/o Adaptive Cruise Control                                    | Bumper Cover, Rear Lower    | DG-05031VBQ                    | Tong Yang           | 68260010AC            | CH1195120                   |
| Dodge Durango, 14-15  | Moulding, Bumper Front      | DGM059NEQ                      | Pro Fortune         | 5113729AB             | CH1044114                   |
| Ford Transit Connect Van, 14-15, to 9/11/14   | Bumper Cover, Rear          | FD-04472BAQ                    | Tong Yang           | DT1Z17906B            | FO1100706                   |
| Ford Transit Connect Wagon, 14-15, to 9/11/14   | Bumper Cover, Rear          | FD-04472BAQ                    | Tong Yang           | DT1Z17906B            | FO1100706                   |
| Ford Transit Connect Wagon, 14-16   | Bumper Cover, Rear          | FD-04472BBQ                    | Tong Yang           | DT1Z17906BB           | FO1100705                   |
| Honda CR-V, 15-16   | Bumper Cover, Front         | HDB103NBQ                      | Pro Fortune         | 04711T1WA91ZZ         | HO1014102                   |
| Honda CR-V, 15-16   | Bumper Cover, Rear Lower, R | HDP104RAQ                      | Pro Fortune         | 04717T1WA91           | HO1117102                   |
| Honda CR-V, 15-16   | Bumper Cover, Rear Lower, L | HDP104LAQ                      | Pro Fortune         | 04718T1WA91           | HO1116102                   |
| Jeep Cherokee, 14-17, w/Off Road pkg  | Liner, Fender Assy L        | AMJ3014CL1-C                   | Great Bestcam       | 68102265AF            | CH1248162                   |
| Lexus NX 200t, 15-16, w/o F Sport Pkg; w/o Park Distance Sensors;<br>w/Headlamp Washers | Bumper Cover, Front         | TY-04537BFQ                    | Tong Yang           | 5211978903            | LX1000287                   |
| Lexus NX 200t, 15-16, w/o F Sport Pkg; w/Park Distance Sensors;<br>w/o Headlamp Washers | Bumper Cover, Front         | TY-04537BGQ                    | Tong Yang           | 5211978905            | LX1000288                   |
| Lexus NX 300h, 15-16, w/o Headlamp Washers  | Bumper Cover, Front         | TY-04537BEQ                    | Tong Yang           | 5211978902            | LX1000286                   |
| Nissan Altima Sedan, 13-15  | Bracket, License            | NS58040Q                       | Cobra King          | 962103TA0A            | NI1068115                   |
| Nissan Altima Sedan, 13-16  | Bracket, Bumper Side R      | DS56133ARH                     | Hui Yih             | 852203TA0A            | NI1143102                   |
| Nissan Altima Sedan, 13-16  | Bracket, Bumper Side R      | NS58617RQ                      | Cobra King          | 852203TA0A            | NI1143102                   |
| Nissan Altima Sedan, 13-16  | Bracket, Bumper Side L      | DS56133ALH                     | Hui Yih             | 852213TA0A            | NI1142102                   |
| Nissan Altima Sedan, 13-16  | Bracket, Bumper Side L      | NS58617LQ                      | Cobra King          | 852213TA0A            | NI1142102                   |
| Nissan Rogue, 14-16 (USA)   | Filler, Center Bumper Front | LT-NSB002A                     | Liantuoh            | 626604BA1B            | NI1091104                   |
| Scion xB, 11-15   | Grille                      | TY-07575GAQ                    | Tong Yang           | 5311112C70            | SC1200108                   |

### NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u>    | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|-----------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Toyota Prius c, 15-16             | Bumper Cover, Front     | TY-04546BBO                | Tong Yang           | 5211952996        | TO1000413               |
| Toyota Prius, 16                  | Support, Bumper R       | TY43164ARH                 | Hui Yih             | 5211547050        | TO1043128               |
| Toyota Prius, 16                  | Support, Bumper L       | TY43164ALH                 | Hui Yih             | 5211647050        | TO1042128               |
| Toyota Tacoma, 16, paint to match | Moulding, Fender R      | TY13161ARH                 | Hui Yih             | 7587104900        | TO1291109               |
| Toyota Tacoma, 16, Paint to Match | Moulding, Fender L      | TY13161ALH                 | Hui Yih             | 7587204900        | TO1291109               |
| Toyota Tacoma, 16-17              | Extension, Bumper R     | TY52161ARH                 | Hui Yih             | 5215304010        | TO1105136               |
| Toyota Tacoma, 16-17              | Extension, Bumper L     | TY52161ALH                 | Hui Yih             | 5215404010        | TO1104136               |
| Toyota Tacoma, 16-17, Black       | Moulding, Fender R      | TY13161ARH                 | Hui Yih             | 7587104060        | TO1291109               |
| Toyota Tacoma, 16-17, Black       | Moulding, Fender L      | TY13161ALH                 | Hui Yih             | 7587204060        | TO1291109               |

### NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u>                 | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet Trax, 13-16                          | Taillamp L              | 11-12434-00-9              | TYC Brother         | 42435955          | GM2800272               |
| Chevrolet Trax, 13-16                          | Taillamp R              | 11-12433-00-9              | TYC Brother         | 42435956          | GM2801272               |
| Chevrolet Trax, 13-16                          | Taillamp L              | 11-12434-00-9              | TYC Brother         | 95136720          | GM2800272               |
| Chevrolet Trax, 13-16                          | Taillamp R              | 11-12433-00-9              | TYC Brother         | 95136721          | GM2801272               |
| Honda Civic LX/EX/EX-T/EX-L Sedan, 16, Halogen | Headlamp Assy, R        | 317-1180R-AC2              | DEPO                | 33100TBAA01       | HO2503173               |
| Honda Civic LX/EX/EX-T/EX-L Sedan, 16, Halogen | Headlamp Assy, L        | 317-1180L-AC2              | DEPO                | 33150TBAA01       | HO2502173               |
| Kia Forte LX/EX Sedan, 14-16                   | Lamp, Fog L             | 19-6066-00-9               | TYC Brother         | 92201A7050        | KI2592133               |
| Kia Forte LX/EX Sedan, 14-16                   | Lamp, Fog R             | 19-6065-00-9               | TYC Brother         | 92202A7050        | KI2593133               |
| Kia Forte5 LX/EX, 14-16                        | Lamp, Fog L             | 19-6066-00-9               | TYC Brother         | 92201A7050        | KI2592133               |
| Kia Forte5 LX/EX, 14-16                        | Lamp, Fog R             | 19-6065-00-9               | TYC Brother         | 92202A7050        | KI2593133               |

### NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application Description</u>           | <u>Part Description</u>    | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|----------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet Suburban, 15-16                | Bar, Front Bumper Impact   | GM1006681DSC               | PBSI-DS             | 23195058          | GM1006681               |
| Chevrolet Tahoe, 15-16                   | Bar, Front Bumper Impact   | GM1006681DSC               | PBSI-DS             | 23195058          | GM1006681               |
| Ford Flex, 09-15                         | Bar, Reinforcement         | FO1006255DSC               | PBSI-DS             | DG1Z17757A        | FO1006255               |
| Ford Taurus Police, 13-15                | Bar, Reinforcement         | FO1006255DSC               | PBSI-DS             | DG1Z17757A        | FO1006255               |
| Ford Taurus SE/SEL/Limited, 10-12        | Bar, Reinforcement         | FO1006255DSC               | PBSI-DS             | DG1Z17757A        | FO1006255               |
| Ford Taurus SHO, 10-15                   | Bar, Reinforcement         | FO1006255DSC               | PBSI-DS             | DG1Z17757A        | FO1006255               |
| Kia Forte Sedan, 14-16                   | Reinforcement, Bumper Rear | KAR8059A                   | Auto Power          | 86631A7010        | KI1106130               |
| Lincoln MKS, 10-12, 3.5/3.7L Eng         | Bar, Reinforcement         | FO1006255DSC               | PBSI-DS             | DG1Z17757A        | FO1006255               |
| Lincoln MKT, 10-14                       | Bar, Reinforcement         | FO1006255DSC               | PBSI-DS             | DG1Z17757A        | FO1006255               |
| Toyota Tacoma, 16-17, w/o Parking Assist | Pad, Step                  | TY58161AH                  | Hui Yih             | 5205704020        | TO1191108               |
| Toyota Tacoma, 16-17, w/Parking Assist   | Pad, Step                  | TY58161BH                  | Hui Yih             | 5205704030        | TO1191109               |

### DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

### CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u>  | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|---------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 01/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 01/16B     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 02/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 02/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 03/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 04/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 04/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 05/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 07/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 08/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 08/16A     | CJ5Z8A284A        | FO1225216               |

**DECERTIFICATIONS**

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

**CAPA 101 STANDARD - METALS**

| <u>Manufacturer Number</u> | <u>Application Description</u>  | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|---------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 09/14A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 09/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 09/15B     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 09/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 10/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 10/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 11/14A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 11/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 11/15B     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 12/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford C-Max Energi/Hybrid, 13-16 | Radiator Support        | Tong Yang           | 12/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 01/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 01/16B     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 02/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 02/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 03/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 04/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 04/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 05/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 07/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 08/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 08/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 09/14A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 09/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 09/15B     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 09/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 10/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 10/16A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 11/14A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 11/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 11/15B     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 12/15A     | CJ5Z8A284A        | FO1225216               |
| FD-03033AQ                 | Ford Escape, 13-16              | Radiator Support        | Tong Yang           | 12/16A     | CJ5Z8A284A        | FO1225216               |
| KA-20030AQ                 | Kia Sportage, 11-16             | Hood                    | Tong Yang           | 12/16A     | 664003W000        | K11230129               |

**CAPA 201 STANDARD - PLASTICS**

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE                       |                                |                         |                     |            |                   |                         |

**CAPA 301 STANDARD - LIGHTING**

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE                       |                                |                         |                     |            |                   |                         |

**CAPA 501 STANDARD - BUMPERS**

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE                       |                                |                         |                     |            |                   |                         |



**WEEKLY PARTS UPDATE**  
**February 21, 2017**

[Report: P6]  
 Weekly

**DELETED PARTS CAPA 101 STANDARD - METALS**

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| HD-20016A-RH               | Honda Civic, 96-98             | Fender R                | San Wanpum          | 60211S04A00ZZ     | HO1241143               |

**DELETED PARTS CAPA 201 STANDARD - PLASTICS**

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE                       |                                |                         |                     |                   |                         |

**DELETED PARTS CAPA 301 STANDARD - LIGHTING**

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE                       |                                |                         |                     |                   |                         |

**DELETED PARTS CAPA 501 STANDARD - BUMPERS**

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE                       |                                |                         |                     |                   |                         |

\*This report includes all new, decertified and deleted parts from February 13, 2017 through February 17, 2017.

All CAPA reports including the weekly update are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org)