

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CV-10038AQ-LH	Chevrolet Blazer, 92-94	Fender L	Tong Yang	08/16A	15029229	GM1240132
CV-10038AQ-LH	Chevrolet Full Size Pickup C/K, 88-02, (Old Style)	Fender L	Tong Yang	08/16A	15029229	GM1240132
CV-10038AQ-LH	Chevrolet Suburban, 92-00	Fender L	Tong Yang	08/16A	15029229	GM1240132
CV-10038AQ-LH	Chevrolet Tahoe, 95-00	Fender L	Tong Yang	08/16A	15029229	GM1240132
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	01/15A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	01/17A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	02/15A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	02/16A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	03/15A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	03/16A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	04/15A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	05/16A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	08/16A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	10/16A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	11/16A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	12/15A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-11	Hood	Tong Yang	12/16A	5076777AC	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	01/15A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	01/17A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	02/15A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	02/16A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	03/15A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	03/16A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	04/15A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	05/16A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	08/16A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	10/16A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	11/16A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	12/15A	5076777AE	CH1230282
DG-20055AQ	Dodge Journey, 09-16	Hood	Tong Yang	12/16A	5076777AE	CH1230282
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	01/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	01/16B	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	02/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	02/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	03/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	04/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	04/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	05/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	07/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	08/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	08/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	09/14A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	09/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	09/15B	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	09/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	10/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	10/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	11/14A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	11/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	11/15B	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	12/15A	CJ5Z8A284A	FO1225216

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	12/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Tong Yang	ALL	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	01/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	01/16B	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	02/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	02/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	03/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	04/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	04/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	05/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	07/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	08/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	08/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	09/14A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	09/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	09/15B	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	09/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	10/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	10/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	11/14A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	11/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	11/15B	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	12/15A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	12/16A	CJ5Z8A284A	FO1225216
FD-03033AQ	Ford Escape, 13-16	Radiator Support	Tong Yang	ALL	CJ5Z8A284A	FO1225216
FD-20151AQ	Ford F150 Pickup, 09-14	Hood	Tong Yang	09/16A	9L3Z16612A	FO1230274
CV-10038AQ-LH	GMC Full Size Pickup C/K, 88-02, (Old Style)	Fender L	Tong Yang	08/16A	15029229	GM1240132
CV-10038AQ-LH	GMC Suburban, 92-00	Fender L	Tong Yang	08/16A	15029229	GM1240132
CV-10038AQ-LH	GMC Yukon, 92-99, w/o Denali pkg	Fender L	Tong Yang	08/16A	15029229	GM1240132
HDCV12H11	Honda Civic Coupe, 12-13	Hood	Gordon	08/16A	60100TR3A90ZZ	HO1230166
HDCV12H11	Honda Civic Sedan, 12-13 (USA/Canada)	Hood	Gordon	08/16A	60100TR3A90ZZ	HO1230166
JP8210150-000C	Jeep Grand Cherokee, 11-12	Hood	AP	08/16A	55369587AC	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-12	Hood	AP	09/16A	55369587AC	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-14	Hood	AP	08/16A	55369587AD	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-14	Hood	AP	09/16A	55369587AD	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-16	Hood	AP	08/16A	55369587AG	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-16	Hood	AP	09/16A	55369587AG	CH1230283
KA-20030AQ	Kia Sportage, 11-16	Hood	Tong Yang	12/16A	664003W000	KI1230129
MZA609HD1	Mazda 6, 09-13	Hood	Gordon	08/16A	GS3L52310	MA1230165
S0851H000AS	Mazda 6, 09-13	Hood	Jui Li	08/16A	GS3L52310	MA1230165
S0989F100AS	Toyota Sienna, 11-14, w/o Antenna	Fender L	Jui Li	08/16A	5381208030	TO1240234

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Y-GMBP353HCA	Chevrolet Malibu ECO, 13-15, w/Rear Vision Camera; w/Park Assist	Bumper Cover, Rear	Y.C.C.	09/16A	22827123	GM1100897
Y-GMBP353HCA	Chevrolet Malibu, 13-15, w/Rear Vision Camera; w/Park Assist	Bumper Cover, Rear	Y.C.C.	09/16A	22827123	GM1100897
CV-04173BCQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/o object sensor	Bumper Cover, Rear	Tong Yang	08/16A	25830549	GM1100785

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-04173BCQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/o object sensor	Bumper Cover, Rear	Tong Yang	08/16A	20951794	GM1100785
Y-FDBF422CA	Ford Expedition, 99-02, paint to match	Bumper Pad, Front	Y.C.C.	10/16A	3L3Z17K833AAA	FO1057282
Y-FDBF422CA	Ford F-Series Light Duty Pickup, 99-04, w/o Lightning, paint to match	Bumper Pad, Front	Y.C.C.	10/16A	3L3Z17K833AAA	FO1057282
CV-04173BCQ	GMC Yukon, 07-11, w/o object sensor	Bumper Cover, Rear	Tong Yang	08/16A	25830549	GM1100785
CV-04173BCQ	GMC Yukon, 07-14, w/o object sensor	Bumper Cover, Rear	Tong Yang	08/16A	20951794	GM1100785
Y-HDBP141CA	Honda Accord Hybrid, 05	Bumper Cover, Rear	Y.C.C.	06/16A	04715SDAA90ZZ	HO1100208
Y-HDBP141CA	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Y.C.C.	06/16A	04715SDAA90ZZ	HO1100208
Y-HYBP028CA	Hyundai Santa Fe Sport, 13-17, w/o parking assist	Bumper Cover, Front	Y.C.C.	06/16A	865114Z000	HY1014100
HYS2014CR-C	Hyundai Santa Fe, 10-12	Liner, Fender R	Great Bestcam	06/16A	868200W200	HY1249123
Y-HYAR026RCA	Hyundai Santa Fe, 13-16	Bumper Cover, Front Lower	Y.C.C.	10/16A	86512B8100	HY1015103
Y-LCBP005CA	Lincoln Navigator, 07-08, w/o parking sensors	Bumper Cover, Front	Y.C.C.	10/16A	7L7Z17D957APTM	FO1000619
MZ-04153BBQ	Mazda CX-5, 13-15	Bumper Cover, Rear	Tong Yang	09/16A	KDY75022XDBB	MA1100210
Y-MCBP006CA	Mercury Grand Marquis, 03-05	Bumper Cover, Front	Y.C.C.	06/16A	3W3Z17D957BA	FO1000518
MB3350000-500C	Mitsubishi Galant, 09-12, Paint to match	Bumper Cover, Front	AP-Procom	07/16A	6400C626	MI1000325
TY3820870-000C	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	AP-Procom	05/16A	5215906961	TO1100296
TY-04395BDQ	Toyota Corolla Base/CE/L/LE, 11-13 (NA)	Bumper Cover, Rear	Tong Yang	12/15A	5215902977	TO1100287
TY2810000-400C	Toyota Corolla, 11-13, Base/CE/LE, North American Built	Bumper Cover, Front	AP-Procom	11/15A	5211903901	TO1000372
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	08/16A	5215947905	TO1100280
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	08/16A	5215947916	TO1100280
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	08/16A	5215947905	TO1100280
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	08/16A	5215947916	TO1100280
TY7530000-010C	Toyota Sienna Base/L/LE, 11-15, 3.5L Eng	Bumper Cover, Front	AP-Procom	02/16A	5211908904	TO1000369
TY7530000-010C	Toyota Sienna XLE, 11-15, 3.5L Eng., w/o Limited pkg	Bumper Cover, Front	AP-Procom	02/16A	5211908904	TO1000369
TY7530000-010C	Toyota Sienna, 11-12, 2.7L Eng	Bumper Cover, Front	AP-Procom	02/16A	5211908904	TO1000369
TY-04409BAQ	Toyota Tacoma, 12-15, Base w/o Wheel Opening Flares	Bumper Cover, Front	Tong Yang	05/16B	5211904060	TO1000384
VW-04161BBQ	Volkswagen Passat, 12-15	Bumper Cover, Front	Tong Yang	03/16A	561807217BGRU	VW1000199

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from February 1, 2017 through February 28, 2017.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.