

NEW PARTS CAPA 101 STANDARD - METALS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---------------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Honda HR-V, 16-17 | Fender L | HD-10162AQ-LH | Tong Yang | 60261T7J305ZZ | HO1240190 |
| Hyundai Elantra Sedan, 17 | Fender L | HN-10075AQ-LH | Tong Yang | 66311F2000 | HY1240166 |
| Hyundai Elantra Sedan, 17 | Fender R | HN-10075AQ-RH | Tong Yang | 66321F2000 | HY1241166 |
| Kia Optima, 16 | Hood | KA-20043AQ | Tong Yang | 66400D5000 | KI1230137 |
| Subaru Forester, 14-17, 2.0L/2.5L Eng | Hood | SUFS14HD1 | Gordon | 57229SG0009P | SU1230144 |
| Toyota Corolla, 14-17 | Bar, Upper Tie | TY31142AUH | Hui Yih | 5320502210 | TO1225415 |

NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|--------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet Colorado, 15-16 | Plate, Skid | CV-04321MBO | Tong Yang | 22891697 | GM1000A21 |
| Chevrolet Colorado, 15-17, w/o Tow hook | Plate, Skid | CV-04321MAQ | Tong Yang | 22893870 | GM1095204 |
| Chevrolet Cruze, 15-16, 1.4L Eng | Cover, Grille | CLN133NAQ | Pro Fortune | 42359042 | GM1036171 |
| Dodge Challenger, 15-16, w/o Adaptive Cruise Control | Grille, Lower | DG-07098GAQ | Tong Yang | 68259756AA | CH1036146 |
| Dodge Charger 11-14, R/T/SE/SXT, Factory Installed, Chrome | Grille | DG-07072MBO | Tong Yang | 68092602AA | CH1210109 |
| Dodge Durango, 11-15, w/Parking sensor w/o Blind spot sensor | Bumper Cover, Rear | DGB096NDQ | Pro Fortune | 68092094AB | CH1100959 |
| GMC Sierra 1500, 14-16 | Seal, Radiator | CVS60010A | Auto Power | 23322448 | GM1224142 |
| Honda Pilot, 16, w/o Radar Cruise Control | Grille | HDG059NAQ | Pro Fortune | 71121TG7A01 | HO1200227 |
| Honda Pilot, 16-17 | Cover, Center Grille | HD-07214GAQ | Tong Yang | 71113TG7A00 | HO1036125 |
| Hyundai Tucson, 16, w/Blind Spot Detection | Bumper Cover, Rear Lower | HN-04172BAQ | Tong Yang | 86612D3100 | HY1115112 |
| Infiniti G35 Sedan, 05-06 (AWD) | Bumper Cover, Front | ING1002B4-C | Great Bestcam | 62022AC940 | IN1000133 |
| Infiniti G35 Sedan, 05-06 (RWD) | Bumper Cover, Front | ING1002B3-C | Great Bestcam | 62022AC740 | IN1000132 |
| Lexus ES 300h, 13-15 | Moulding, Bumper Front | LSM023NCQ | Pro Fortune | 5312133050 | LX1210108 |
| Lexus ES 350, 13-15 | Moulding, Bumper Front | LSM023NCQ | Pro Fortune | 5312133050 | LX1210108 |
| Lexus GS 200t, 13-16, w/o Parking sensors | Bumper Cover, Front | LSB031NIQ | Pro Fortune | 521193A944 | LX1000295 |
| Lexus GS 350, 13-16, w/o Parking sensors | Bumper Cover, Front | LSB031NIQ | Pro Fortune | 521193A944 | LX1000295 |
| Lexus GS 450h, 13-16, w/o Parking sensors, w/Headlamp washer | Bumper Cover, Front | LSB031NIQ | Pro Fortune | 521193A944 | LX1000295 |
| Lincoln MKZ Hybrid, 13-16, w/Rear object sensors, w/Active park assist | Bumper Cover, Rear | FMCMKZ-R13PNEW | Micro Rim | EP5Z17K835BPTM | FO1100700 |
| Lincoln MKZ, 13-16, w/Rear object sensors, w/Active park assist | Bumper Cover, Rear | FMCMKZ-R13PNEW | Micro Rim | EP5Z17K835BPTM | FO1100700 |
| Nissan Altima Sedan, 13 from 10/12-15 | Liner, Fender R | LT-NSV002BR | Liantuoh | 638403TA0D | NI1249134 |
| Nissan Altima Sedan, 13, to 10/12 | Liner, Fender Assy R | LT-NSV002AR | Liantuoh | 638403TA0A | NI1249131 |
| Nissan Altima Sedan, 13, to 10/12 | Liner, Fender Assy L | LT-NSV002AL | Liantuoh | 638413TA0A | NI1248131 |
| Nissan Altima Sedan, 2013 from 10/12-15 | Liner, Fender L | LT-NSV002BL | Liantuoh | 638413TA0D | NI1248134 |
| Nissan Maxima, 04-06 | Grille | DS-07254GAQ | Tong Yang | 620707Y00A | NI1200203 |
| Nissan Murano, 15-16 | Bumper Cover, Rear Lower | DT6230810-000C | AP-Procom | 850B25AA0A | NI1115100 |
| Nissan Murano, 15-17 | Bumper Cover, Rear | DT6230870-000C | AP-Procom | 850225AA0H | NI1114101 |
| Nissan Rogue, 14-16 | Liner, Fender Front R | NSR1014BR-C | Great Bestcam | 638426FL0A | NI1249135 |
| Nissan Rogue, 14-16 | Liner, Fender Front L | NSR1014BL-C | Great Bestcam | 638436FL0A | NI1248135 |
| Toyota Camry Hybrid, 15-16, Std type | Grille, Lower Cover | TY382000G-200C | AP-Procom | 5311206260 | TO1036158 |
| Toyota Camry, 15-16, Std type | Grille, Lower Cover | TY382000G-200C | AP-Procom | 5311206260 | TO1036158 |
| Volkswagen Jetta GLI, 15-16, Sedan, w/o Fog Lamps | Plate, End R | VW17003BRQ | Cobra King | 5C68072349B9 | VW1039136 |
| Volkswagen Jetta Hybrid, 15-16, w/Fog Lamps | Plate, End L | VW17003ALQ | Cobra King | 5C6807233A9B9 | VW1038137 |
| Volkswagen Jetta Hybrid, 15-16, w/Fog Lamps | Plate, End R | VW17003ARQ | Cobra King | 5C6807234A9B9 | VW1039137 |
| Volkswagen Jetta Hybrid, 15-16, w/o Fog Lamps | Plate, End L | VW17003BLQ | Cobra King | 5C68072339B9 | VW1038136 |
| Volkswagen Jetta Hybrid, 15-16, w/o Fog Lamps | Plate, End R | VW17003BRQ | Cobra King | 5C68072349B9 | VW1039136 |
| Volkswagen Jetta Sedan, 15-16, w/Fog Lamps | Plate, End L | VW17003ALQ | Cobra King | 5C6807233A9B9 | VW1038137 |
| Volkswagen Jetta Sedan, 15-16, w/Fog Lamps | Plate, End R | VW17003ARQ | Cobra King | 5C6807234A9B9 | VW1039137 |
| Volkswagen Tiguan, 09-11 | Bumper Cover, Front | VW-04228BBQ | Tong Yang | 5N0807421CGRU | VW1100174 |
| Volkswagen Jetta/GLI, 15-16, Sedan, w/o Fog Lamps | Plate, End L | VW17003BLQ | Cobra King | 5C68072339B9 | VW1038136 |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---------------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Hyundai Accent Hatchback/Sedan, 15-16 | Headlamp Assy, R | 321-1154R-AC2 | DEPO | 921021R710 | HY2503192 |
| Toyota Venza, 13-16, On quarter panel | Taillamp R | 11-6485-90-9 | TYC Brother | 815500T020 | TO2801190 |
| Toyota Venza, 13-16, On quarter panel | Taillamp L | 11-6486-90-9 | TYC Brother | 815600T020 | TO2800190 |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet Malibu, 13-16 | Bracket, Bumper R | CVT181AR | Auto Power | 22865540 | GM1067194 |
| Ford 250 Super Duty/350 Super Duty Pickup, 08-12 | Bumper, Rear Assembly | FO1103149DSC | PBSI-DS | FO1103149 | FO1103149 |
| Ford 250 Super Duty/350 Super Duty Pickup, 08-12 | Bumper, Rear Assembly | FO1103150DSC | PBSI-DS | FO1103150 | FO1103150 |
| Ford 250 Super Duty/350 Super Duty Pickup, 08-12 | Bumper, Rear Assembly | FO1103151DSC | PBSI-DS | FO1103151 | FO1103151 |
| Ford Super Duty Pick up, 13-15, w/o Rear object sensors, Paint to match | Bumper Cover, Rear Assy | FO1103174DSC | PBSI-DS | FO1103174 | FO1103174 |
| Ford Super Duty Pickup, 08-16, w/o Rear object sensors, Chrome | Bumper, Rear Assembly | FO1103148DSC | PBSI-DS | FO1103148 | FO1103148 |
| Ford Super Duty Pickup, 13-15, w/o Rear object sensors, Chrome | Bumper, Rear Assembly | FO1103176DSC | PBSI-DS | FO1103176 | FO1103176 |
| Ford Super Duty Pickup, 13-15, w/Rear object sensors, Chrome | Bumper, Rear Assembly | FO1103177DSC | PBSI-DS | FO1103177 | FO1103177 |
| Ford Super Duty Pickup, 13-15, w/Rear object sensors, Paint to match | Bumper, Rear Assembly | FO1103175DSC | PBSI-DS | FO1103175 | FO1103175 |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|---------------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| CV-04185BBQ | Chevrolet Equinox, 10-11 | Bumper Cover, Front | Tong Yang | 12/16A | 20896097 | GM1000907 |
| CV-04185BBQ | Chevrolet Equinox, 10-15 | Bumper Cover, Front | Tong Yang | 12/16A | 20983230 | GM1000907 |
| TY-04349BCQ | Toyota Camry Base/LE/XLE, 10-11 (USA) | Bumper Cover, Front | Tong Yang | 09/16A | 5211906958 | TO1000356 |

CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

DELETED PARTS CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |



WEEKLY PARTS UPDATE

May 1st, 2017

[Report: P6]
Weekly

DELETED PARTS CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|------------------------------------|-----------------------------|---------------------|-----------------------|-----------------------------|
| NONE | | | | | |

*This report includes all new, decertified and deleted parts from April 24, 2017 through April 28, 2017.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org