

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BM-20014AQ	BMW 5-Series Sedan, 04-10	Hood	Tong Yang	05/16A	41617111385	BM1230116
BM-20014AQ	BMW 5-Series Wagon, 06-10	Hood	Tong Yang	05/16A	41617111385	BM1230116
AM-10020AQ-RH	Jeep Wrangler, 07-08	Fender R	Tong Yang	10/15A	68002398AC	CH1241257
AM-10020AQ-RH	Jeep Wrangler, 07-11	Fender R	Tong Yang	10/15A	68002398AD	CH1241257
AM-10020AQ-RH	Jeep Wrangler, 07-12	Fender R	Tong Yang	10/15A	68002398AE	CH1241257
AM-10020AQ-RH	Jeep Wrangler, 07-16	Fender R	Tong Yang	10/15A	68029992AB	CH1241257
MZ-03001AQ	Mazda 3, 04-09	Radiator Support	Tong Yang	08/16A	BP4K53110H	MA1225127
MZ-03001AQ	Mazda 3, 04-09	Radiator Support	Tong Yang	08/16A	BP4K53110J	MA1225127
S0721F200AS	Mazda CX-9, 07-09	Fender R	Jui Li	08/16A	TD1152110D	MA1241159
S0721F200AS	Mazda CX-9, 07-15	Fender R	Jui Li	08/16A	TD1152110E	MA1241159
TYS6612A	Toyota Venza, 09-11	Radiator Support	Auto Power	06/15A	532100T010	TO1225293
TYS6612A	Toyota Venza, 09-11	Radiator Support	Auto Power	06/15A	532100T011	TO1225293
TYS6612A	Toyota Venza, 09-16	Radiator Support	Auto Power	06/15A	532100T012	TO1225293
VW0940090-200C	Volkswagen Passat, 12-15	Radiator Support	AP-Procom	09/16A	561805588B9B9	VW1225138

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-04233BCQ	Chevrolet Cruze, 11-16, w/o RS Pkg, w/o Rear Object Sensor	Bumper Cover, Rear	Tong Yang	11/16A	95016694	GM1100876
CLB094NDQ	Chevrolet Cruze, 11-16, w/RS Pkg, w/Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	01/13A	95217523	GM1100873
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	05/16B	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	07/16A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	08/16A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	05/16B	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	07/16A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	08/16A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	05/16B	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	07/16A	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	08/16A	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	05/16B	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	07/16A	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	08/16A	20951793	GM1100783
CV-04173BDQ	GMC Yukon, 07-11, w/object sensor	Bumper Cover, Rear	Tong Yang	05/16B	25830551	GM1100783
CV-04173BDQ	GMC Yukon, 07-11, w/object sensor	Bumper Cover, Rear	Tong Yang	07/16A	25830551	GM1100783
CV-04173BDQ	GMC Yukon, 07-11, w/object sensor	Bumper Cover, Rear	Tong Yang	08/16A	25830551	GM1100783
CV-04173BDQ	GMC Yukon, 07-14, w/object sensor	Bumper Cover, Rear	Tong Yang	05/16B	20951793	GM1100783
CV-04173BDQ	GMC Yukon, 07-14, w/object sensor	Bumper Cover, Rear	Tong Yang	07/16A	20951793	GM1100783
CV-04173BDQ	GMC Yukon, 07-14, w/object sensor	Bumper Cover, Rear	Tong Yang	08/16A	20951793	GM1100783
Y-HDBP141CA	Honda Accord Hybrid, 05	Bumper Cover, Rear	Y.C.C.	09/16B	04715SDAA90ZZ	HO1100208
Y-HDBP141CA	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Y.C.C.	09/16B	04715SDAA90ZZ	HO1100208
Y-HDBP162HCA	Honda Accord Sedan, 08-09, (6 cyl)	Bumper Cover, Rear	Y.C.C.	11/16A	04715TA1A90ZZ	HO1100245
Y-HDBP162HCA	Honda Accord Sedan, 08-12 (6 cyl)	Bumper Cover, Rear	Y.C.C.	11/16A	04715TA1A91ZZ	HO1100245
HD6710130-100C	Honda CR-V, 15-16	Cover, Lower	AP-Procom	11/16A	04712T1WA91	HO1015111
LX2110870-100C	Lexus IS 200t, 14-16, w/o Park distance sensors	Bumper Cover, Rear	AP-Procom	03/16A	5215953940	LX1100168



MONTHLY RECALL REPORT

July 2017*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
LX2110870-100C	Lexus IS 250 Sedan, 14-16, w/o Park Distance Sensors	Bumper Cover, Rear	AP-Procom	03/16A	5215953940	LX1100168
LX2110870-100C	Lexus IS 300, 14-16, w/o Park distance sensors	Bumper Cover, Rear	AP-Procom	03/16A	5215953940	LX1100168
LX2110870-100C	Lexus IS 350, 14-16, w/o Park distance sensors	Bumper Cover, Rear	AP-Procom	03/16A	5215953940	LX1100168
MZ-04097BBQ	Mazda 3 Sedan STD, 07-09	Bumper Cover, Front	Tong Yang	11/16B	BAN650031CBB	MA1000215
DS-04357BBQ	Nissan Rogue, 14-15	Bumper Cover, Front	Tong Yang	12/15A	620224BA0H	NI1000293
TY04253BBQ	Toyota Camry, 02-06, (USA)	Bumper Cover, Rear	TYG Products	15/02/06	52159AA903	TO1100203
TY04253BBQ	Toyota Camry, 02-06, (USA)	Bumper Cover, Rear	TYG Products	16/07/21	52159AA903	TO1100203
Y-TYBP271ACA	Toyota Corolla Base/CE/L, 09-10, (USA)	Bumper Cover, Rear	Y.C.C.	11/16A	5215902963	TO1100264
Y-TYBP271HCA	Toyota Corolla, 09-10, (Japan)	Bumper Cover, Rear	Y.C.C.	08/16A	5215912934	TO1100268
TYB106NBQ	Toyota Highlander Hybrid, 08-10	Bumper Cover, Rear Upper	Pro Fortune	11/16A	521590E906	TO1100260
TYB106NBQ	Toyota Highlander, 08-10	Bumper Cover, Rear Upper	Pro Fortune	11/16A	521590E906	TO1100260
TY-07482GAQ	Toyota Yaris Hatchback, 12-14	Grille	Tong Yang	09/15A	5311252260	TO1036127
Y-TYBP288CA	Toyota Yaris Hatchback, 12-14, CE/L/LE	Bumper Cover, Front	Y.C.C.	06/15A	5211952965	TO1000381
VW0940870-000C	Volkswagen Passat, 12-15	Bumper Cover, Rear	AP-Procom	10/16A	561807421DGRU	VW1100192
VW0940870-000C	Volkswagen Passat, 12-15	Bumper Cover, Rear	AP-Procom	10/16A	561807421GRU	VW1100192

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from June 1, 2017 through June 30, 2017.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.