

NEW PARTS CAPA 101 STANDARD - METALS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|-----------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Honda Accord, 16-17, Sedan, 4 Cyl | Hood | HD-20115AQ | Tong Yang | 60100T2FA10ZZ | HO1230183 |
| Honda Accord, 16-17, Sedan, 6 Cyl | Hood | HD-20115CQ | Tong Yang | 60100T2GA10ZZ | HO1230184 |
| Nissan Murano, 15-17 | Radiator Support | DS-03021AQ | Tong Yang | 625005AA0A | NI1225249 |
| Nissan Murano, 15-17 | Radiator Support | DS-03021AQ | Tong Yang | 625005AA1A | NI1225249 |
| Volkswagen Passat, 16-17 | Hood | VWPS16HD1 | Gordon | 561823031F | VW1230147 |

NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---|---------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet 1500 Silverado Classic, 05-07 | Cover, Tow Hook L | CV9B084LQ | Cobra King | 10392477 | GM1029114 |
| Chevrolet 1500 Silverado Classic, 05-07 | Cover, Tow Hook R | CV9B084RQ | Cobra King | 10392478 | GM1029113 |
| Chevrolet 2500/3500 Silverado Classic, 05-07 | Cover, Tow Hook L | CV9B084LQ | Cobra King | 10392477 | GM1029114 |
| Chevrolet 2500/3500 Silverado Classic, 05-07 | Cover, Tow Hook R | CV9B084RQ | Cobra King | 10392478 | GM1029113 |
| Chevrolet Avalanche, 02-06, w/o Body cladding | Cover, Tow Hook L | CV9B084LQ | Cobra King | 10392477 | GM1029114 |
| Chevrolet Avalanche, 02-06, w/o Body cladding | Cover, Tow Hook R | CV9B084RQ | Cobra King | 10392478 | GM1029113 |
| Chrysler 200 Sedan, 15-17, w/o Parallel Park assist | Bumper Cover, Front | CHR20015FB1 | Gordon | 1WZ18TZZAD | CH1000A15 |
| Chrysler 200, 15-17, w/Parksense FR & RR w/Stop, Code XH4 | Bumper Cover, Front | CHR20015FB3 | Gordon | 5NH87TZZAD | CH1000A16 |
| GMC Sierra 1500, 14-15 | Panel, Grille Mounting | CV-07289GAQ | Tong Yang | 23322442 | GM1223110 |
| Honda Accord Sedan, 16-17, w/o Parking Sensors | Bumper Cover, Front | HD-04304BCQ | Tong Yang | 71101T2FA50ZZ | HO1000302 |
| Honda Accord Sedan, 16-17, w/Parking Sensors | Bumper Cover, Front | HD-04304BDQ | Tong Yang | 71100T2FA70ZZ | HO1000303 |
| Honda Civic Coupe, 16-17 | Moulding, Grille | HD-07217MAQ | Tong Yang | 71125TBAA01 | HO1210149 |
| Honda Civic Sedan, 16-17 | Moulding, Grille | HD-07217MAQ | Tong Yang | 71125TBAA01 | HO1210149 |
| Honda Civic, 16, Com/Steel, 1.5L Eng | Radiator Support | HDS60023-1A | Auto Power | 71410TBCA01 | HO1225183 |
| Hyundai Tucson, 16 | Bumper Cover, Front | HN-04166BBQ | Tong Yang | 86511D3000 | HY1014101 |
| Kia Optima, 16 | Radiator Support | KA-03025AQ | Tong Yang | 64101D5000 | KI225180 |
| Kia Soul, 14 | Liner, Fender L | KAS6014BL-C | Great Bestcam | 86811B2000 | KI1248130 |
| Kia Soul, 14 | Liner, Fender R | KAS6014BR-C | Great Bestcam | 86812B2000 | KI1249130 |
| Kia Soul, 15-16 | Liner, Fender L | KAS6014CL-C | Great Bestcam | 86811B2100 | KI1248140 |
| Kia Soul, 15-16 | Liner, Fender R | KAS6014CR-C | Great Bestcam | 86812B2100 | KI1249140 |
| Lexus IS 250, 09-10 | Cover, Grille | LSN021NAQ | Pro Fortune | 5311353010 | LX1036105 |
| Lexus IS 350, 09-10 | Cover, Grille | LSN021NAQ | Pro Fortune | 5311353010 | LX1036105 |
| Mercedes-Benz S63 Sedan, 14-16, w/Parktronic | Bumper Cover, Front | BZB073NDQ | Pro Fortune | 222880244780 | MB1000465 |
| Mercedes-Benz S63 Sedan, 14-16, w/Parktronic | Bumper Cover, Front | BZB073NDQ | Pro Fortune | 22288024479999 | MB1000465 |
| Mini Cooper F55 Base Hardtop, 15-17, w/o John Cooper Works | Spoiler, Rear | AT-05010VAQ | Tong Yang | 51127380028 | MC1193105 |
| Mini Cooper F55 Base Hardtop, 15-17, w/o John Cooper Works, w/Park distance control | Spoiler, Rear | AT-05010VBQ | Tong Yang | 51127380030 | MC1193106 |
| Mini Cooper F55 Hardtop 4 Door, 15-17 | Bumper Cover, Front | AT-04039BBQ | Tong Yang | 51117379432 | MC1000117 |
| Mini Cooper F56 Hardtop Hatchback, 14-17 | Bumper Cover, Front | AT-04039BBQ | Tong Yang | 51117379432 | MC1000117 |
| Mini Cooper F57 Convertible, 16 | Bumper Cover, Front | AT-04039BBQ | Tong Yang | 51117379432 | MC1000117 |
| Nissan Altima Sedan, 16-17 | Cover, Engine Under Lower | NSE021NAQ | Pro Fortune | 758909HS0A | NI1228164 |
| Nissan Maxima, 16-17 | Cover, Engine Under Lower | NSE021NAQ | Pro Fortune | 758909HS0A | NI1228164 |
| Nissan Titan Platinum Reserve/Pro-4X, 16-17, w/Tow Hitch | Moulding, Bumper Rear | DS58168BH | Hui Yih | 85078EZ00B | NI1191108 |
| Nissan Titan, 16-17, w/o Tow Hitch | Moulding, Bumper Rear | DS58168AH | Hui Yih | 85078EZ00A | NI1191107 |
| Subaru Impreza Wagon, 12-16 | Bumper Cover, Rear | SB-04061BBQ | Tong Yang | 57704FJ031 | SU1100169 |

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| BMW 3-Series F30 Sedan, 12-15, w/o M Sport | Lamp, Side Marker L | 18-6178-00-9 | TYC Brother | 63147274521 | BM2554102 |
| BMW 3-Series F30 Sedan, 12-15, w/o M Sport | Lamp, Side Marker R | 18-6177-00-9 | TYC Brother | 63147274522 | BM2555102 |
| BMW 3-Series F30H Hybrid Sedan, 13-15, w/o M Sport | Lamp, Side Marker R | 18-6177-00-9 | TYC Brother | 63147274522 | BM2555102 |
| BMW 3-Series F30H Sedan Hybrid, 13-15, w/o M Sport | Lamp, Side Marker L | 18-6178-00-9 | TYC Brother | 63147274521 | BM2554102 |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| BMW 3-Series F31 Wagon, 14-16, w/o M Sport | Lamp, Side Marker L | 18-6178-00-9 | TYC Brother | 63147274521 | BM2554102 |
| BMW 3-Series F31 Wagon, 14-16, w/o M Sport | Lamp, Side Marker R | 18-6177-00-9 | TYC Brother | 63147274522 | BM2555102 |
| Chevrolet Colorado, 15 | Taillamp L | K35-1973L-AC | DEPO | 94776929 | GM2800270 |
| Chevrolet Colorado, 15-16 | Taillamp L | K35-1973L-AC | DEPO | 23283790 | GM2800270 |
| Chevrolet Colorado, 15-16 | Taillamp R | K35-1973R-AC | DEPO | 23283791 | GM2801270 |
| Chevrolet Colorado, 15-16 | Taillamp R | K35-1973R-AC | DEPO | 94776928 | GM2801270 |
| Chevrolet Colorado, 15-17 | Taillamp L | K35-1973L-AC | DEPO | 84169777 | GM2800270 |
| Chevrolet Colorado, 15-17 | Taillamp R | K35-1973R-AC | DEPO | 84169778 | GM2801270 |
| Chevrolet Silverado 2500/3500, 15, Black bezel, Chrome trim | Headlamp, L | 20-9756-00-9 | TYC Brother | 23359896 | GM2502416 |
| Chevrolet Silverado 2500/3500, 15, Black bezel, Chrome trim | Headlamp, R | 20-9755-00-9 | TYC Brother | 23477067 | GM2503416 |
| Chevrolet Silverado 2500/3500, 15-16, Black bezel, Chrome trim | Headlamp, L | 20-9756-00-9 | TYC Brother | 23389970 | GM2502416 |
| Chevrolet Silverado 2500/3500, 15-16, Black bezel, Chrome trim | Headlamp, R | 20-9755-00-9 | TYC Brother | 23389971 | GM2503416 |
| Ford Fusion Energi, 13-16, On body | Taillamp R | K30-1965R-AC | DEPO | DS7Z13404D | FO2805111 |
| Ford Fusion Energi, 13-16, On body | Taillamp L | K30-1965L-AC | DEPO | DS7Z13405D | FO2804111 |
| Ford Fusion Titanium Hybrid, 13-16, On body | Taillamp R | K30-1965R-AC | DEPO | DS7Z13404D | FO2805111 |
| Ford Fusion Titanium Hybrid, 13-16, On body | Taillamp L | K30-1965L-AC | DEPO | DS7Z13405D | FO2804111 |
| Ford Fusion Titanium, 13-16, On body | Taillamp R | K30-1965R-AC | DEPO | DS7Z13404D | FO2805111 |
| Ford Fusion Titanium, 13-16, On body | Taillamp L | K30-1965L-AC | DEPO | DS7Z13405D | FO2804111 |
| Hyundai Tucson, 10-15 | Lamp, Fog L | 221-2031L-AC | DEPO | 922012S000 | HY2592136 |
| Hyundai Tucson, 10-15 | Lamp, Fog R | 221-2031R-AC | DEPO | 922022S000 | HY2593136 |
| Mazda CX-3, 16, Halogen | Headlamp Assy, R | 20-9751-01-9 | TYC Brother | DB4G510K0 | MA2519173 |
| Mazda CX-3, 16-17 | Lamp, Signal Assy R | 216-1626R-AC | DEPO | DB4G51350A | MA2531120 |
| Mazda CX-3, 16-17 | Lamp, Signal Assy L | 216-1626L-AC | DEPO | DB4G51360A | MA2530120 |
| Mazda CX-3, 16-17, Halogen | Headlamp Assy, L | 20-9752-01-9 | TYC Brother | DB4G510L0 | MA2518173 |
| Mazda CX-3, 16-17, Halogen | Headlamp Assy, R | 20-9751-01-9 | TYC Brother | DB4N510K0 | MA2519173 |
| Mazda CX-3, 16-17, Halogen | Headlamp Assy, L | 20-9752-01-9 | TYC Brother | DB4N510L0 | MA2518173 |
| Nissan Murano, 15 | Headlamp Assy, R | 315-1198R-AC | DEPO | 260105AA0A | NI2503232 |
| Nissan Murano, 15 | Headlamp Assy, L | 315-1198L-AC | DEPO | 260605AA0A | NI2502232 |
| Nissan Murano, 15 | Headlamp Assy, L | 315-1198L-AC | DEPO | 260605AA0B | NI2502232 |
| Nissan Murano, 15-16 | Headlamp Assy, R | 315-1198R-AC | DEPO | 260105AA0B | NI2503232 |
| Nissan Murano, 15-16 | Headlamp Assy, R | 315-1198R-AC | DEPO | 260105AA0D | NI2503232 |
| Nissan Murano, 15-16 | Headlamp Assy, L | 315-1198L-AC | DEPO | 260605AA0D | NI2502232 |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Chevrolet Captiva Sport, 12-15 | Absorber, Energy | CV3C124BQ | Cobra King | 25880598 | GM1070292 |
| Chevrolet Captiva Sport, 12-15 | Absorber, Energy | CV3C124Q | Cobra King | 96660549 | GM1070290 |
| Ford Econoline Van, 07-14, w/Rear object sensors | Bar, Face | FO1102363DSC | PBSI-DS | 7C2Z17906B | FO1102363 |
| Ford Econoline Van, 05-07 | Bar, Face | FO1102362DSC | PBSI-DS | 7C2Z17906F | GO1102362 |
| Ford Econoline Van, 08-14, w/o Rear object sensors | Bar, Face | FO1102362DSC | PBSI-DS | 7C2Z17906F | GO1102362 |
| Ford Econoline Van, 08-14, w/o Rear object sensors, Paint to match | Bar, Face | FO1102301DSC | PBSI-DS | 7C2Z17906EPTM | FO1102301 |
| Ford Econoline Van, 94-07 | Bar, Face | FO1102301DSC | PBSI-DS | 7C2Z17906EPTM | FO1102301 |
| Ford F150 Pickup, 06-08, (New Style), w/o Rear Object Sensors | Bumper, Rear Assembly | FO1103137DSC | PBSI-DS | FO1103137 | FO1103137 |
| Ford F150 Pickup, 06-08, (New Style), w/o Rear Object Sensors, from 8-9-05 | Bumper, Rear Assembly | FO1103136DSC | PBSI-DS | FO1103136 | FO1103136 |
| Ford F150 Pickup, 06-08, (New Style), w/o Rear Object Sensors, from 8-9-05 | Bumper, Rear Assembly | FO1103140DSC | PBSI-DS | FO1103140 | FO1103140 |
| Ford F150 Pickup, 06-08, (New Style), w/o Rear Object Sensors, from 8-9-05 | Bumper, Rear Assembly | FO1103141DSC | PBSI-DS | FO1103141 | FO1103141 |
| Ford F150 Pickup, 06-08, (New Style), w/o Rear Object Sensors, from 8-9-05 | Bumper, Rear Assembly | FO1103143DSC | PBSI-DS | FO1103143 | FO1103143 |
| Ford F150 Pickup, 08, (New Style), w/o Rear Object Sensors | Bumper, Rear Assembly | FO1103142DSC | PBSI-DS | FO1103142 | FO1103142 |
| Ford F150 Pickup, 08, w/Rear Object Sensors | Bumper, Rear Assembly | FO1103138DSC | PBSI-DS | FO1103138 | FO1103138 |
| Ford F150, 06-08, (New Style), w/Rear Object Sensors, from 8-9-05 | Bumper, Rear Assembly | FO1103139DSC | PBSI-DS | FO1103139 | FO1103139 |
| GMC Terrain, 16-17 | Absorber, Energy | CV4T124Q | Cobra King | 23305982 | GM1070295 |
| Honda CR-V, 02-06 | Bar, Reinforcement | HO1006162DSC | PBSI-DS | 71130S9A010ZZ | HO1006162 |
| Honda CR-V, 02-06 | Bar, Reinforcement | HO1006172DSC | PBSI-DS | 71130S9A900ZZ | 71130S9A90 |
| Hyundai Sonata, 15-16 | Bar, Reinforcement | HY1006141DSC | PBSI-DS | 86530C2000 | HY1006141 |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|---|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| Hyundai Sonata, 15-16 | Bar, Reinforcement | HY1006142DSC | PBSI-DS | 86530C2010 | HY1006142 |
| Lincoln Mark LT, 06-08 | Bumper, Rear Assembly | FO1103140DSC | PBSI-DS | FO1103140 | FO1103140 |
| Lincoln Mark LT, 06-08, w/o Rear Object Sensors | Bumper, Rear Assembly | FO1103137DSC | PBSI-DS | FO1103137 | FO1103137 |
| Lincoln Mark LT, 06-08, w/o Rear Object Sensors | Bumper, Rear Assembly | FO1103141DSC | PBSI-DS | FO1103141 | FO1103141 |
| Lincoln Mark LT, 06-08, w/o Rear Object Sensors | Bumper, Rear Assembly | FO1103143DSC | PBSI-DS | FO1103143 | FO1103143 |
| Lincoln Mark LT, 06-08, w/Rear Object Sensors | Bumper, Rear Assembly | FO1103139DSC | PBSI-DS | FO1103139 | FO1103139 |
| Lincoln Mark T, 06-08, w/o Rear Object Sensors | Bumper, Rear Assembly | FO1103136DSC | PBSI-DS | FO1103136 | FO1103136 |
| Ram ProMaster City Cargo Van, 15-16 | Absorber, Energy | DG87124Q | Cobra King | 68259424AA | CH1070838 |
| Ram ProMaster City Passenger Van, 15-16 | Absorber, Energy | DG87124Q | Cobra King | 68259424AA | CH1070838 |
| Saturn Vue Hybrid, 09 | Absorber, Energy | CV3C124BQ | Cobra King | 25880598 | GM1070292 |
| Saturn Vue Hybrid, 09 | Absorber, Energy | CV3C124Q | Cobra King | 96660549 | GM1070290 |
| Saturn Vue XE/XR, 08-10 | Absorber, Energy | CV3C124Q | Cobra King | 96660549 | GM1070290 |
| Saturn Vue, 08-10 | Absorber, Energy | CV3C124BQ | Cobra King | 25880598 | GM1070292 |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--|-------------------------|---------------------|------------|-------------------|-------------------------|
| HD0900000-500C | Honda Civic Hybrid, 09-11 | Bumper Cover, Front | AP-Procom | 08/16A | 04711SNAA90ZZ | HO1000266 |
| HD0900000-500C | Honda Civic Hybrid, 09-11 | Bumper Cover, Front | AP-Procom | 10/16A | 04711SNAA90ZZ | HO1000266 |
| HD0900000-500C | Honda Civic Sedan, 09-11 | Bumper Cover, Front | AP-Procom | 08/16A | 04711SNAA90ZZ | HO1000266 |
| HD0900000-500C | Honda Civic Sedan, 09-11 | Bumper Cover, Front | AP-Procom | 10/16A | 04711SNAA90ZZ | HO1000266 |
| Y-MZBP151CA | Mazda CX-5, 13-15 | Bumper Cover, Front | Y.C.C. | 03/16A | KD4550031BB | MA1000236 |
| Y-DSBP254CA | Nissan Versa Note, 14-16 | Bumper Cover, Rear | Y.C.C. | 01/17A | HEM223VY0J | NI1100294 |
| TYB084NCQ | Toyota Corolla CE/LE, 03-08 | Bumper Cover, Rear | Pro Fortune | 04/16A | 5215902911 | TO1100208 |
| TY04548BBQ | Toyota Sienna Base/L/LE, 11-17, 3.5L Eng | Bumper Cover, Front | TYG Products | 16/12/21 | 5211908904 | TO1000369 |
| TY04548BBQ | Toyota Sienna Base/L/LE, 11-17, 3.5L Eng | Bumper Cover, Front | TYG Products | 17/06/23 | 5211908904 | TO1000369 |
| TY04548BBQ | Toyota Sienna XLE, 11-17, 3.5L Eng., w/o Limited pkg | Bumper Cover, Front | TYG Products | 16/12/21 | 5211908904 | TO1000369 |
| TY04548BBQ | Toyota Sienna XLE, 11-17, 3.5L Eng., w/o Limited pkg | Bumper Cover, Front | TYG Products | 17/06/23 | 5211908904 | TO1000369 |
| TY04548BBQ | Toyota Sienna, 11-13, 2.7L Eng | Bumper Cover, Front | TYG Products | 16/12/21 | 5211908904 | TO1000369 |
| TY04548BBQ | Toyota Sienna, 11-13, 2.7L Eng | Bumper Cover, Front | TYG Products | 17/06/23 | 5211908904 | TO1000369 |

CAPA 202 STANDARD - NON-WOVEN FABRICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| 20-5124-00-9 | Chevrolet Venture, 97-05 | Headlamp Assy, L | TYC Brother | 11171410 | 10368389 | GM2502175 |
| 317-19A4R-AC | Honda Accord, 13-15, on body | Taillamp R | DEPO | 20161111 | 33500T2AA01 | HO2805101 |
| 317-19A4R-AC | Honda Accord, 13-15, on body | Taillamp R | DEPO | 20170324 | 33500T2AA01 | HO2805101 |
| 11-6282-00-9 | Jeep Grand Cherokee, 07-10 | Taillamp L | TYC Brother | 10201410 | 55079013AC | CH2800172 |
| 20-5124-00-9 | Oldsmobile Silhouette, 97-04 | Headlamp Assy, L | TYC Brother | 11171410 | 10368389 | GM2502175 |
| 20-5124-00-9 | Pontiac Montana, 99-05 | Headlamp Assy, L | TYC Brother | 11171410 | 10368389 | GM2502175 |
| 20-5124-00-9 | Pontiac Trans Sport, 97-98 | Headlamp Assy, L | TYC Brother | 11171410 | 10368389 | GM2502175 |

CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--|-------------------------|---------------------|------------|-------------------|-------------------------|
| GM1103177DSC | Chevrolet Silverado 1500, 14-16, Black | Bumper, Rear Assembly | PBSI-DS | 12/16A | GM1103177 | GM1103177 |

DELETED PARTS CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

*This report includes all new, decertified and deleted parts from August 21, 2017 through August 25, 2017.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org