

### RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

#### CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD-10082BQ-LH	Acura TL, 05-08, From VIN 5A073159	Fender L	Tong Yang	06/15A	04630SEPA91ZZ	AC1240118
S0807F100BS	Acura TL, 05-08, From VIN 5A073159	Fender L	Jui Li	06/15A	04630SEPA91ZZ	AC1240118

#### CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CLB094NDQ	Chevrolet Cruze, 11-16, w/RS Pkg, w/Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	11/16A	95217523	GM1100873
Y-CRBP054PGC	Dodge Caravan, 04-05	Bumper Cover, Front	Y.C.C.	01/16A	1AK392S2AA	CH1000449
Y-CRBP054PGC	Dodge Caravan, 05 (to 05/04)	Bumper Cover, Front	Y.C.C.	01/16A	1AK392B8AA	CH1000908
Y-CRBP054PGC	Dodge Caravan, 06-07, Code MLD	Bumper Cover, Front	Y.C.C.	01/16A	1AK392S2AA	CH1000449
DG-04112BCQ	Dodge Journey, 11-16, w/Fog Lamps, w/o Headlamp Washer	Fascia, Upper	Tong Yang	10/16A	1TX73TZZAC	CH1000A06
DG-04112BCQ	Dodge Journey, 11-16, w/Fog Lamps, w/o Headlamp Washer	Fascia, Upper	Tong Yang	10/16A	5YB55TZZAB	CH1000A06
FD-04286BBQ	Ford Expedition Eddie Bauer/Limited, 07-11	Bumper Cover, Front Lower	Tong Yang	01/17A	7L1Z17D957CPTM	FO1000630
FD-04286BBQ	Ford Expedition XLT, 07-11, w/appearance pkg	Bumper Cover, Front Lower	Tong Yang	01/17A	7L1Z17D957CPTM	FO1000630
FD-04286BBQ	Ford Expedition, 07-14, Paint to match	Bumper Cover, Front Lower	Tong Yang	01/17A	CL1Z17D957BPTM	FO1000630
HDB088NBQ	Honda Civic Hybrid, 12	Bumper Cover, Rear	Pro Fortune	09/16A	04715TR3A90ZZ	HO1100272
HDB088NBQ	Honda Civic Hybrid, 12	Bumper Cover, Rear	Pro Fortune	11/16A	04715TR3A90ZZ	HO1100272
HDB088NBQ	Honda Civic Sedan, 12, 1.8L eng (USA, Canada, Japan)	Bumper Cover, Rear	Pro Fortune	09/16A	04715TR3A90ZZ	HO1100272
HDB088NBQ	Honda Civic Sedan, 12, 1.8L eng (USA, Canada, Japan)	Bumper Cover, Rear	Pro Fortune	11/16A	04715TR3A90ZZ	HO1100272
HD7200870-000C	Honda Odyssey EX/EX-L/LX, 05-10	Bumper Cover, Rear	AP-Procom	10/16A	04715SHJA92ZZ	HO1100220
HD04229BBQ	Honda Odyssey EX/EX-L/XL, 11-15	Bumper Cover, Front	TYG Products	16/12/20	04711TK8A90ZZ	HO1000276
HD04229BBQ	Honda Odyssey EX/LX/EX-L, 11-16, w/o Parking sensors	Bumper Cover, Front	TYG Products	16/12/20	04711TK8A91ZZ	HO1000276
DS-04276BBQ	Nissan Maxima, 09-14	Bumper Cover, Front	Tong Yang	09/16B	620229N00H	NI1000258
DT6220000-010C	Nissan Murano, 09	Bumper Cover, Front	AP-Procom	01/16A	FBM221AA0H	NI1000257
DT6220000-010C	Nissan Murano, 09	Bumper Cover, Front	AP-Procom	08/16A	FBM221AA0H	NI1000257
DT6220000-010C	Nissan Murano, 09-10	Bumper Cover, Front	AP-Procom	01/16A	FBM221AA0J	NI1000257
DT6220000-010C	Nissan Murano, 09-10	Bumper Cover, Front	AP-Procom	08/16A	FBM221AA0J	NI1000257
Y-TYBP259CA	Toyota Camry SE, 05-06, (USA)	Bumper Cover, Front	Y.C.C.	07/15A	5211906908	TO1000285
VG-04152BBQ	Volkswagen Jetta Hybrid, 13-15	Bumper Cover, Front	Tong Yang	02/17A	5C6807217DGRU	VW1000190
VG-04152BBQ	Volkswagen Jetta Sedan, 11-14, w/o Headlamp Washer, w/o Parking Assist	Bumper Cover, Front	Tong Yang	02/17A	5C6807217DGRU	VW1000190
VG-04152BBQ	Volkswagen Jetta Sedan, 11-14, w/o Headlamp Washer, w/o Parking Assist	Bumper Cover, Front	Tong Yang	02/17A	5C6807217GRU	VW1000190
VG-05041VAQ	Volkswagen Tiguan, 12-16	Spoiler, Lower	Tong Yang	06/16A	5N0805903K9B9	VW1094116

#### CAPA 202 STANDARD - NON-WOVEN FABRICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

#### CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
18-5931-01-9	Chevrolet Colorado, 04-08, w/o Xtreme	Lamp, Park/Signal R	TYC Brother	5181510	15851203	GM2521189
18-5931-01-9	Chevrolet Colorado, 04-10, w/o Xtreme	Lamp, Park/Signal R	TYC Brother	5181510	25942428	GM2521189
18-5931-01-9	Chevrolet Colorado, 04-12, w/o Xtreme	Lamp, Park/Signal R	TYC Brother	5181510	19328955	GM2521189
18-5931-01-9	Chevrolet Colorado, 04-12, w/o Xtreme	Lamp, Park/Signal R	TYC Brother	5181510	20936078	GM2521189
18-5931-01-9	Chevrolet Colorado, 04-12, w/o Xtreme	Lamp, Park/Signal R	TYC Brother	5181510	22876078	GM2521189
18-5931-01-9	GMC Canyon, 04-08	Lamp, Park/Signal R	TYC Brother	5181510	15851203	GM2521189



# MONTHLY RECALL REPORT

## August 2017\*

[Report: P8]  
Monthly

### RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

#### CAPA 301 STANDARD - LIGHTING

Manufacturer <u>Number</u>	Application <u>Description</u>	Part <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	OEM <u>Number</u>	PartsLink <u>Number</u>
18-5931-01-9	GMC Canyon, 04-10	Lamp, Park/Signal R	TYC Brother	5181510	25942428	GM2521189
18-5931-01-9	GMC Canyon, 04-11	Lamp, Park/Signal R	TYC Brother	5181510	20936078	GM2521189
18-5931-01-9	GMC Canyon, 04-11	Lamp, Park/Signal R	TYC Brother	5181510	22876078	GM2521189
18-5931-01-9	GMC Canyon, 04-12	Lamp, Park/Signal R	TYC Brother	5181510	19328955	GM2521189

#### CAPA 501 STANDARD - BUMPER PARTS

Manufacturer <u>Number</u>	Application <u>Description</u>	Part <u>Description</u>	<u>Manufacturer</u>	<u>Lot</u>	OEM <u>Number</u>	PartsLink <u>Number</u>
NONE						

\*This report includes all decertifications from July 1, 2017 through July 31, 2017.

All CAPA Reports including the recall report are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org).