

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Lexus RX 350, 16, Canada built	Fender R	LXR16FR1	Gordon	538010E150	LX1241138
Lexus RX 350, 16, Canada built	Fender L	LXR16FL1	Gordon	538020E060	LX1240138
Lexus RX 450h, 16	Fender R	LXR16FR1	Gordon	538010E150	LX1241138
Lexus RX 450h, 16	Fender L	LXR16FL1	Gordon	538020E060	LX1240138

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Buick LaCrosse, 14-16, w/ Adaptive Cruise Control	Bumper Cover, Front	BK-04056BDQ	Tong Yang	90904906	GM1000953
Chevrolet Tahoe, 15	Bumper Cover, Rear	CV9410870-100C	AP-Procom	23142968	GM1100942
Chevrolet Tahoe, 15-17	Bumper Cover, Rear	CV9410870-100C	AP-Procom	23324503	GM1100942
Dodge Dart, 13-16, w/Parking sensors	Bumper Cover, Rear	Y-CRBP064CA	Y.C.C.	68172075AA	CH1100976
Ford C-Max Energi, 13-17, w/o Front tow hook	Bumper Cover, Front	Y-FDBP101CA	Y.C.C.	DM5Z17D957APTM	FO1000689
Ford C-Max Hybrid, 13-17, w/o Front tow hook	Bumper Cover, Front	Y-FDBP101CA	Y.C.C.	DM5Z17D957APTM	FO1000689
GMC Sierra 1500, 14-15	Bezel, Fog Lamp L	CV9N083LQ	Cobra King	22902334	GM1038169
GMC Sierra 1500, 14-15	Bezel, Fog Lamp R	CV9N083RQ	Cobra King	22902335	GM1039169
Honda Accord EX-L Sedan, 16-17, 6 cyl	Bumper Cover, Rear	HDB114NCQ	Pro Fortune	71501T2FA60ZZ	HO1100291
Honda Accord SE/Sport/Sport Special Edition Sedan, 16-17	Bumper Cover, Rear	HDB114NCQ	Pro Fortune	71501T2FA60ZZ	HO1100291
Honda Accord Sedan, 16-17, w/o Parking Sensors	Bumper Cover, Front	HDB113NCQ	Pro Fortune	71101T2FA50ZZ	HO1000302
Honda Accord Sedan, 16-17, w/Parking Sensors	Bumper Cover, Front	HDB113NDQ	Pro Fortune	71100T2FA70ZZ	HO1000303
Honda Accord Touring Sedan, 16-17, 6cyl	Bumper Cover, Rear	HDB114NDQ	Pro Fortune	71500T2FA80ZZ	HO1100293
Hyundai Sonata, 15-16	Liner, Fender L	HYS1014EL-C	Great Bestcam	86811C2000	HY1248154
Hyundai Sonata, 15-16	Liner, Fender R	HYS1014ER-C	Great Bestcam	86812C2000	HY1249154
Lexus ES 300h, 13, w/Parking sensors	Bumper Cover, Front	Y-LXBP003CA	Y.C.C.	5211933993	LX1000242
Lexus ES 300h, 13-15, w/Parking sensors	Bumper Cover, Front	Y-LXBP003CA	Y.C.C.	521193T912	LX1000242
Lexus ES 350, 13, w/Parking sensors	Bumper Cover, Front	Y-LXBP003CA	Y.C.C.	5211933993	LX1000242
Lexus ES 350, 13-15, w/Parking Sensors	Bumper Cover, Front	Y-LXBP003CA	Y.C.C.	521193T912	LX1000242
Lexus NX 200t, 15-17, w/o F Sport Pkg; w/o Headlamp Washers, w/o Park Distance Sensors	Bumper Cover, Front	LSB059NCQ	Pro Fortune	5211978902	LX1000286
Lexus NX 200t, 15-17, w/o F Sport Pkg; w/o Park Distance Sensors; w/Headlamp Washers	Bumper Cover, Front	LSB059NDQ	Pro Fortune	5211978903	LX1000287
Lexus NX 200t, 15-17, w/o F Sport Pkg; w/Park Distance Sensors; w/Headlamp Washers	Bumper Cover, Front	LSB059NFQ	Pro Fortune	5211978907	LX1000289
Lexus NX 200t, 15-17, w/o F Sport Pkg; w/Park Distance Sensors; w/o Headlamp Washers	Bumper Cover, Front	LSB059NEQ	Pro Fortune	5211978905	LX1000288
Lexus NX 300h, 15-17, w/Headlamp Washers, w/o Park Distance Sensors	Bumper Cover, Front	LSB059NDQ	Pro Fortune	5211978903	LX1000287
Lexus NX 300h, 15-17, w/o Headlamp Washers	Bumper Cover, Front	LSB059NCQ	Pro Fortune	5211978902	LX1000286
Lexus NX 300h, 15-17, w/o Headlamp Washers, w/Park Distance Sensors	Bumper Cover, Front	LSB059NEQ	Pro Fortune	5211978905	LX1000288
Lexus NX 300h, 15-17, w/Park Distance Sensors; w/Headlamp Washers	Bumper Cover, Front	LSB059NFQ	Pro Fortune	5211978907	LX1000289
Nissan Altima Sedan, 16-17, w/Distance Sensors	Bumper Cover, Front	DT1540000-100C	AP-Procom	620229HS2H	NI1000312
Nissan Altima Sedan, 16-17, w/Distance Sensors	Bumper Cover, Front	Y-DSBP248CA	Y.C.C.	620229HS2H	NI1000312
Nissan Altima Sedan, 16-17, w/o Distance sensors	Bumper Cover, Front	DT1540000-200C	AP-Procom	620229HS0H	NI1000311
Nissan Altima Sedan, 16-17, w/o Distance sensors	Bumper Cover, Front	Y-DSBP248ACA	Y.C.C.	620229HS0H	NI1000311
Subaru Legacy, 15-16	Bumper Cover, Rear	SB-04059BBQ	Tong Yang	57704AL10A	SU1100174
Subaru Legacy, 15-17	Bumper Cover, Rear	SB-04059BBQ	Tong Yang	57704AL10B	SU1100174
Toyota Camry Hybrid, 15-17, w/o Park Assist	Bumper Cover, Rear	Y-TYBP311CA	Y.C.C.	5215906989	TO1100315
Toyota Camry, 15-17, w/o Park Assist	Bumper Cover, Rear	Y-TYBP311CA	Y.C.C.	5215906989	TO1100315
Toyota Corolla, 14-17	Support, Side Upper R	TA1S617BRQ	Cobra King	5256202210	TO1143118
Toyota Corolla, 14-17	Support, Side Upper L	TA1S617BLQ	Cobra King	5256302210	TO1142118
Toyota RAV-4 Hybrid, LE+/XLE/Limited, 16-17	Grille, Assy	TY-07650GAQ	Tong Yang	531010R120	TO1200406
Toyota RAV-4 LE/XLE/Limited/Platinum, 16-17	Grille, Assy	TY-07650GAQ	Tong Yang	531010R120	TO1200406
Toyota RAV-4, 16-17, North American Built	Bumper Cover, Rear	Y-TYBP322CA	Y.C.C.	521590R914	TO1114102
Toyota Sienna SE, 11-17, w/o Park Assist	Bumper Cover, Rear	TYB158NBQ	Pro Fortune	5215908905	TO1100284
Toyota Tacoma, 16-17	Insert, Cover	TA8C121RQ	Cobra King	5211504070	TO1043130
Toyota Tacoma, 16-17	Insert, Cover	TA8C121LQ	Cobra King	5211604070	TO1042130
Toyota Tacoma, 16-17	Seal, Upper Rad Supt	TA8C099Q	Cobra King	5329204030	TO1224114

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Ford Taurus SHO, 10-12, HID	Headlamp Assy, R	K30-1147R-UCH	DEPO	AG1Z13008C	FO2503283
Ford Taurus SHO, 10-12, HID	Headlamp Assy, L	K30-1147L-UCH	DEPO	AG1Z13008D	FO2502283
Ford Taurus SHO, 10-12, HID	Headlamp Assy, R	K30-1147R-UCH	DEPO	AG1Z13008G	FO2503283
Ford Taurus SHO, 10-12, HID	Headlamp Assy, L	K30-1147L-UCH	DEPO	AG1Z13008H	FO2502283
Nissan Quest, 12, To 4-12	Headlamp Assy, R	315-1183R-AC6	DEPO	260101JA0B	NI2503229
Nissan Quest, 12, To 4-12	Headlamp Assy, L	315-1183L-AC6	DEPO	260601JA0B	NI2502229
Scion iA, 16	Headlamp Assy, R	20-9743-01-9	TYC Brother	81130WB001	SC2503106
Scion iA, 16	Headlamp Assy, L	20-9744-01-9	TYC Brother	81170WB001	SC2502106
Toyota Tacoma, 17, w/Black bezel	Taillamp R	312-19ACR-AC2C	DEPO	8155004200	TO2801201
Toyota Tacoma, 17, w/Black bezel	Taillamp L	312-19ACL-AC2C	DEPO	8156004200	TO2800201
Toyota Yaris iA, 16-17	Headlamp Assy, R	20-9743-01-9	TYC Brother	81130WB001	SC2503106
Toyota Yaris iA, 16-17	Headlamp Assy, L	20-9744-01-9	TYC Brother	81170WB001	SC2502106

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Honda Accord Coupe, 13-17	Bar, Reinforcement	HO1006188DSC	PBSI-DS	71130T2FA00ZZ	HO1006188
Honda Accord Hybrid, 14-17	Bar, Reinforcement	HO1006188DSC	PBSI-DS	71130T2FA00ZZ	HO1006188
Honda Accord Sedan, 13-17	Bar, Reinforcement	HO1006188DSC	PBSI-DS	71130T2FA00ZZ	HO1006188
Hyundai Accent Sedan, 12-17	Reinf, Bumper Cover	HY1006136DSC	PBSI-DS	865301R300	HY1006136
Hyundai Accent Sedan, 12-17	Reinf, Bumper Cover	HY1006136DSC	PBSI-DS	865301R300	HY1006136
Nissan Altima, 10-13; Sedan	Absorber, Energy	NS59613RQ	Cobra King	850923TB1B	NI1173103
Nissan Altima, 10-13; Sedan	Absorber, Energy	NS59613LQ	Cobra King	850933TB1B	NI1172103
Nissan Altima, 15-17; Sedan	Absorber, Energy	NS59613LQ	Cobra King	850933TB1B	NI1172103
Nissan Altima, 15-17; Sedan	Absorber, Energy	NS59613RQ	Cobra King	850923TB1B	NI1173103
Nissan Sentra, 16-17	Absorber, Energy	NS30124Q	Cobra King	620903YU0A	NI1070175

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HN-03012AQ	Hyundai Elantra Sedan, 14-16, Korea built, From 11-1-13	Radiator Support	Tong Yang	11/16B	641013X003	HY1225180
HN-03012AQ	Hyundai Elantra, 10-13	Radiator Support	Tong Yang	11/16B	641013X000	HY1225169

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
HD04103BBO	Honda Civic Coupe/Sedan, 01-03	Bumper Cover, Front	TYG Products	16/07/18	04711S5PA90ZZ	HO1000197

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
MB-10028BQ-LH	Eagle Talon, 95-96, w/Turbo	Fender L	Tong Yang	MB959375	MI1240131
MB-10028BQ-RH	Eagle Talon, 95-96, w/Turbo	Fender R	Tong Yang	MB959376	MI1241131
MB-10028BQ-LH	Mitsubishi Eclipse, 95-99, w/side air dam	Fender L	Tong Yang	MB959375	MI1240131
MB-10028BQ-RH	Mitsubishi Eclipse, 95-99, w/side air dam	Fender R	Tong Yang	MB959376	MI1241131

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CHRJEEP-F11NEW	Jeep Grand Cherokee, 11, w/o Headlamp Washer	Bumper Cover, Front Upper	Micro Rim	68078268AA	CH1000979
CHRJEEP-F11NEW	Jeep Grand Cherokee, 11-13, w/o Headlamp Washer	Bumper Cover, Front Upper	Micro Rim	68078268AB	CH1000979

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all new, decertified and deleted parts from October 2, 2017 through October 6, 2017.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org