

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
S0579H000AS	Ford Super Duty Pickup, 08-10	Hood	Jui Li	01/17A	8C3Z16612A	FO1230268
S0579H000AS	Ford Super Duty Pickup, 08-10	Hood	Jui Li	12/16A	8C3Z16612A	FO1230268
DJ-CV13401	Honda Civic Hybrid, 13	Hood	Da Juane	12/16A	60100TR3A80ZZ	HO1230171
DJ-CV13401	Honda Civic Hybrid, 13-15	Hood	Da Juane	12/16A	60100TR3A50ZZ	HO1230171
DJ-CV13401	Honda Civic Sedan, 13	Hood	Da Juane	12/16A	60100TR3A80ZZ	HO1230171
DJ-CV13401	Honda Civic Sedan, 13-15	Hood	Da Juane	12/16A	60100TR3A50ZZ	HO1230171
HYSF13HD1	Hyundai Santa Fe Sport, 13-17	Hood	Gordon	12/16A	664004Z000	HY1230157
HYSN10H11	Hyundai Sonata Hybrid, 11-15	Hood	Gordon	02/17A	664003S000	HY1230149
HYSN06HD1	Hyundai Sonata, 06-10	Hood	Gordon	11/16A	664000A000	HY1230134
HYSN06HD1	Hyundai Sonata, 06-10	Hood	Gordon	11/16A	664003K010	HY1230134
HYSN10H11	Hyundai Sonata, 11-13	Hood	Gordon	02/17A	664003Q000	HY1230147
HYSN10H11	Hyundai Sonata, 11-14	Hood	Gordon	02/17A	664003S000	HY1230149
DT2910150-000C	Nissan Sentra, 13-15	Hood	AP	02/17A	F51003SGMA	NI1230193
SCTC11HD1	Scion iC, 11-13	Hood	Gordon	01/17A	5330121090	SC1230106
TY-20230AQ	Toyota Corolla, 14-17	Hood	Tong Yang	02/17A	5330102270	TO1230232

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
AU2600000-200C	Audi A4 Cabrio, 07-09, w/o S-Line Pkg, w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	12/16A	8E0807105NGRU	AU1000142
AU2600000-200C	Audi A4 Sedan/Wagon, 05-08, w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	12/16A	8E0807105NGRU	AU1000142
AU2600000-200C	Audi S4 Cabrio, 07-09, w/o S-Line Pkg, w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	12/16A	8E0807105NGRU	AU1000142
AU2600000-200C	Audi S4 Sedan, 05-08, w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	12/16A	8E0807105NGRU	AU1000142
BKB034NDQ	Buick Regal, 14-15, w/Parking sensors	Bumper Cover, Rear	Pro Fortune	04/16A	22938368	GM1100948
CV-07150MAQ	Chevrolet Cobalt LTZ, 06-07	Grille	Tong Yang	12/15A	15247433	GM1202100
CV-07150MAQ	Chevrolet Cobalt, 06-10, w/chrome pkg	Grille	Tong Yang	12/15A	15247433	GM1202100
CR-04068BFQ	Chrysler 200, 15-17, Sedan, w/o Parallel Park Assist, w/ Parking Sensors	Bumper Cover, Front	Tong Yang	10/16A	5SH88TZZAA	CH1000A17
CR-04068BFQ	Chrysler 200, 15-17, Sedan, w/Parallel & Perp Park Assist, w/Stop, Code XH5	Bumper Cover, Front	Tong Yang	10/16A	5SH88TZZAB	CH1000A17
CR4730000-100C	Chrysler 200, 15-17, w/Parksense FR & RR w/Stop, Code XH4	Bumper Cover, Front	AP-Procom	07/17A	5NH87TZZAD	CH1000A16
CRB015NCQ	Chrysler 300 Sedan, 11-14, Type 2, w/o SRT-8, w/o Parking Sensor	Bumper Cover, Front	Pro Fortune	05/17A	68127938AE	CH1000A00
CRB015NCQ	Chrysler 300 Sedan, 11-12, w/o Parking Sensor	Bumper Cover, Front	Pro Fortune	05/17A	68127938AA	CH1000A00
CRB015NCQ	Chrysler 300 Sedan, 11-12, w/o Parking Sensor	Bumper Cover, Front	Pro Fortune	05/17A	68127938AD	CH1000A00
S0195H000AP	Ford Mustang Base/GT, 99-04, w/o 35th Anniversary pkg or air scoop	Hood	Jui Li	02/16A	XR3Z16612AA	FO1230176
CV-04095BDQ	GMC Sierra, 03-07, w/fog lamps	Bumper Cover, Front	Tong Yang	03/17A	12335963	GM1000684
HD04210BBQ	Honda Accord Sedan, 08-10 (4cyl)	Bumper Cover, Front	TYG Products	17/02/21	04711TA0A90ZZ	HO1000254
HD04193BBQ	Honda Civic Hybrid, 06-08	Bumper Cover, Front	TYG Products	16/10/24	04711SNEA90ZZ	HO1000239
HDB096NBQ	Honda Civic Hybrid, 13-15	Bumper Cover, Rear Upper	Pro Fortune	10/15A	04715TR3A50ZZ	HO1100278
HDB096NBQ	Honda Civic Hybrid, 13-15	Bumper Cover, Rear Upper	Pro Fortune	10/15A	04715TR3A80ZZ	HO1100278
HD04193BBQ	Honda Civic Sedan, 06-08, 1.8L eng	Bumper Cover, Front	TYG Products	16/10/24	04711SNEA90ZZ	HO1000239
HDB096NBQ	Honda Civic Sedan, 13-15, 1.8L Eng	Bumper Cover, Rear Upper	Pro Fortune	10/15A	04715TR3A50ZZ	HO1100278
HDB096NBQ	Honda Civic Sedan, 13-15, 1.8L Eng	Bumper Cover, Rear Upper	Pro Fortune	10/15A	04715TR3A80ZZ	HO1100278
HD-04168BAQ	Honda CR-V, 07-09	Bumper Cover, Rear	Tong Yang	06/17A	04715SWAA90	HO1100241
HN-04060BBQ	Hyundai Santa Fe, 07-09, w/2 Tone Color	Bumper Cover, Front	Tong Yang	08/16A	865112B020	HY1000165
HN-04060BBQ	Hyundai Santa Fe, 07-09, w/2 Tone Color	Bumper Cover, Front	Tong Yang	11/16A	865112B020	HY1000165

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Y-HYBP024HCA	Hyundai Sonata, 11-13, Dual Exhaust	Bumper Cover, Rear	Y.C.C.	05/17A	866103Q100	HY1100176
MZ-04112BBQ	Mazda 6, 09-10	Bumper Cover, Front	Tong Yang	10/16B	GSYL50031A	MA1000222
MZ-04112BBQ	Mazda 6, 09-10	Bumper Cover, Front	Tong Yang	10/16B	GSYL50031B	MA1000222
MZ-04112BBQ	Mazda 6, 09-10	Bumper Cover, Front	Tong Yang	10/16B	GSYL50031BBB	MA1000222
MZ-04112BBQ	Mazda 6, 09-13	Bumper Cover, Front	Tong Yang	10/16B	GSYL50031CBB	MA1000222
MZ5300870-000C	Mazda CX-5, 13-16	Bumper Cover, Rear	AP-Procom	04/17A	KDY75022XDBB	MA1100210
DS-04333BBQ	Nissan Altima, 13-15	Bumper Cover, Front	Tong Yang	02/17B	620223TA0H	NI1000285
Y-DSBP249CA	Nissan Rogue, 14-16	Bumper Cover, Front	Y.C.C.	03/17A	620224BA0H	NI1000293
SB1800000-000C	Subaru Legacy, 05-07	Bumper Cover, Front	AP-Procom	07/16A	57704AG02A	SU1000149
SB-04034BBQ	Subaru Outback, 10-12	Bumper Cover, Front	Tong Yang	07/16A	57704AJ09A	SU1000165
TY-04484BBQ	Toyota 4Runner, 14-16, w/Chrome	Bumper Cover, Front	Tong Yang	02/16A	5211935913	TO1000407
TY-04261BCQ	Toyota Avalon XL, 05-06	Bumper Cover, Front	Tong Yang	04/17A	52119AC912	TO1000308
Y-TYBP290CA	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	Y.C.C.	04/17A	5215906961	TO1100296
TYB116NCQ	Toyota Corolla Base/CE/L/LE, 11-13 (NA)	Bumper Cover, Rear	Pro Fortune	05/17A	5215902977	TO1100287
TYB116NCQ	Toyota Corolla Base/CE/L/LE, 11-13 (NA)	Bumper Cover, Rear	Pro Fortune	06/17A	5215902977	TO1100287
Y-TYBP299CA	Toyota Corolla S, 14-16	Bumper Cover, Front	Y.C.C.	12/16A	5211903906	TO1000400
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	10/16B	5215947905	TO1100280
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	10/16B	5215947916	TO1100280
Y-TYBP265CA	Toyota Prius, 04-09	Bumper Cover, Rear	Y.C.C.	06/17A	5215947903	TO1100239
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	10/16B	5215947905	TO1100280
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	10/16B	5215947916	TO1100280
TY8030870-210C	Toyota RAV-4, 09-10, w/Bumper Ext, (USA)	Bumper Cover, Rear	AP-Procom	02/17A	521590R902	TO1100271
TY8030870-210C	Toyota RAV-4, 09-10, w/Bumper Ext, w/Gate Mtd Spare, (Japan)	Bumper Cover, Rear	AP-Procom	02/17A	521590R902	TO1100271
TY8030870-210C	Toyota RAV-4, 11-12, w/Bumper Ext, w/Gate Mtd Spare	Bumper Cover, Rear	AP-Procom	02/17A	521590R902	TO1100271

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
KI1006131DSC	Kia Sorento, 11-13, w/o Sport pkg	Bar, Reinforcement	PBSI-DS	01/17B	865301U000	KI1006131

*This report includes all decertifications from September 1, 2017 through September 30, 2017.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.