

### RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

### CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
FT-10035BQ-LH	Fiat 500 HB, 12	Fender L	Tong Yang	12/16A	68070509AB	F11240100
FT-10035BQ-LH	Fiat 500 HB, 12-15	Fender L	Tong Yang	12/16A	68070509AC	F11240100
HD2820150-000C	Honda Accord Sedan, 13-14, 4 Cyl	Hood	AP	04/17A	60100T2AA90ZZ	HO1230169
HD2820150-000C	Honda Accord Sedan, 13-16, 4 Cyl	Hood	AP	04/17A	60100T2FA90ZZ	HO1230169
HN-03012AQ	Hyundai Elantra Sedan, 14-16, Korea built, From 11-1-13	Radiator Support	Tong Yang	11/16B	641013X003	HY1225180
HN-20030AQ	Hyundai Elantra, 07-10	Hood	Tong Yang	03/17A	664002H010	HY1230136
HN-03012AQ	Hyundai Elantra, 10-13	Radiator Support	Tong Yang	11/16B	641013X000	HY1225169
HYGN10HD1	Hyundai Genesis Coupe, 10-12	Hood	Gordon	03/17A	664002M000	HY1230145
KASL10HD1	Kia Soul, 10-11	Hood	Gordon	04/17A	664002K010	KI1230124
S0551H000AS	Mazda 3 Sedan, 04-09	Hood	Jui Li	02/17A	BNYV5231X	MA1230158
S0551H000AS	Mazda 3 Sedan, 04-09	Hood	Jui Li	02/17A	BNYV5231XA	MA1230158
S0551H000AS	Mazda 3 Sedan, 04-09	Hood	Jui Li	02/17A	BNYV5231XB	MA1230158
TY2800150-M00C	Toyota Corolla, 03-08	Hood	AP	03/17A	5330102110	TO1230185
TA8B001Q	Toyota Tacoma, 12-15, w/o Scoop	Hood	Cobra King	03/17A	5330104200	TO1230224
S0845H000AS	Toyota Venza, 09-16	Hood	Jui Li	03/17A	533010T020	TO1230214
VG1710160-0R0C	Volkswagen GLI Sedan, 11-15	Fender R	AP	03/16A	5C6821106	VW1241142
VG1710160-0R0C	Volkswagen GLI Sedan, 11-17	Fender R	AP	03/16A	5C6821106A	VW1241142
VG1710160-0R0C	Volkswagen Jetta Hybrid, 13-15	Fender R	AP	03/16A	5C6821106	VW1241142
VG1710160-0R0C	Volkswagen Jetta Hybrid, 13-17	Fender R	AP	03/16A	5C6821106A	VW1241142
VG1710160-0R0C	Volkswagen Jetta Sedan, 11-15	Fender R	AP	03/16A	5C6821106	VW1241142
VG1710160-0R0C	Volkswagen Jetta Sedan, 11-17	Fender R	AP	03/16A	5C6821106A	VW1241142

### CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
BM33-9939-WSH	BMW 7-Series F04/F02 Hybrid, 11-12, w/Park distance control w/o Side view camera w/o M pkg	Bumper Cover, Front	Tran Hung	09/16A	51117251632	BM1000231
BM33-9939-WSH	BMW 7-Series, 09-12, w/Park distance control w/o Side view	Bumper Cover, Front	Tran Hung	09/16A	51117251632	BM1000231
CLB064NCQ	Chevrolet Cruze, 11-16, w/o RS Pkg, w/o Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	05/17A	95016694	GM1100876
FDB128NBQ	Ford Escape Hybrid, 08-12, Thermoplastic	Bumper Cover, Rear	Pro Fortune	05/17A	8L8Z17K835APTM	FO1100629
FDB128NBQ	Ford Escape, 08-12, Thermoplastic	Bumper Cover, Rear	Pro Fortune	05/17A	8L8Z17K835APTM	FO1100629
FD-04437BCQ	Ford Flex, 10-12, 3.5L Turbo Eng., w/o Towing pkg	Bumper Cover, Rear	Tong Yang	08/16A	DA8Z17K835SPTM	FO1100658
FD-04437BCQ	Ford Flex, 13-14, From 3-15-13, To 3-15-13, w/o Towing pkg	Bumper Cover, Rear	Tong Yang	08/16A	DA8Z17K835SPTM	FO1100658
Y-FDBP100CA	Ford Flex, 13-14, w/o Active Park Assist	Bumper Cover, Front	Y.C.C.	03/17A	DA8Z17D957APTM	FO1000685
HD-04236BBQ	Honda Civic Coupe, 12-13	Bumper Cover, Front	Tong Yang	03/17A	04711TS8A90ZZ	HO1000282
HD04103BBQ	Honda Civic Coupe/Sedan, 01-03	Bumper Cover, Front	TYG Products	16/07/18	04711S5PA90ZZ	HO1000197
HD04229BBQ	Honda Odyssey EX/EX-L/XL, 11-15	Bumper Cover, Front	TYG Products	17/01/13	04711TK8A90ZZ	HO1000276
HD04229BBQ	Honda Odyssey EX/LX/EX-L, 11-16, w/o Parking sensors	Bumper Cover, Front	TYG Products	17/01/13	04711TK8A91ZZ	HO1000276
Y-HYBP029CA	Hyundai Accent Hatchback, 14-16	Bumper Cover, Front	Y.C.C.	02/17A	865111R010	HY1000201
Y-HYBP029CA	Hyundai Accent Sedan, 14-16	Bumper Cover, Front	Y.C.C.	02/17A	865111R010	HY1000201
Y-HYBP026CA	Hyundai Santa Fe, 13-16	Bumper Cover, Front	Y.C.C.	04/17A	86511B8000	HY1000199
Y-HYBP024HCA	Hyundai Sonata, 11-13, Dual Exhaust	Bumper Cover, Rear	Y.C.C.	07/16A	866103Q100	HY1100176
IFB003NDQ	Infiniti FX35, 12-13, w/o Premium pkg	Bumper Cover, Front Upper	Pro Fortune	06/14A	FBM223EV0H	IN1000255
IFB003NDQ	Infiniti FX37, 12-13, w/o Premium pkg	Bumper Cover, Front Upper	Pro Fortune	06/14A	FBM223EV0H	IN1000255
IFB003NDQ	Infiniti QX70, 14-15, w/o Parking sensors	Bumper Cover, Front Upper	Pro Fortune	06/14A	FBM223EV0H	IN1000255
Y-AMBPO16CA	Jeep Compass, 11-15	Bumper Cover, Front Upper	Y.C.C.	02/17A	68109861AC	CH1014104
AM04077BBQ	Jeep Grand Cherokee Laredo/Laredo Limited, 08-10	Bumper Cover, Front	TYG Products	17/07/07	68033744AB	CH1000932
AM04077BBQ	Jeep Grand Cherokee North, 10	Bumper Cover, Front	TYG Products	17/07/07	68033744AB	CH1000932
AM04077BBQ	Jeep Grand Cherokee Overland, 08-09	Bumper Cover, Front	TYG Products	17/07/07	68033744AB	CH1000932
Y-AMBPO11CA	Jeep Grand Cherokee, 05-07, w/o STR-8, w/o chrome	Bumper Cover, Front	Y.C.C.	09/16A	5159130AA	CH1000451

### RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

#### CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
LX1310870-100C	Lexus ES 350, 07-12, w/o Parking Sensors	Bumper Cover, Rear	AP-Procom	10/16B	5215933922	LX1100149
MB-04146BBQ	Mitsubishi Lancer, 08-17, w/o Turbo	Bumper Cover, Rear	Tong Yang	04/17B	6410B832	MI1100287
TYB116NCQ	Toyota Corolla Base/CE/L/LE, 11-13 (NA)	Bumper Cover, Rear	Pro Fortune	02/17A	5215902977	TO1100287

#### CAPA 202 STANDARD - NON-WOVEN FABRICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

#### CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
340-1130L-ACN	Mercedes-Benz C-Class, 08-11	Headlamp Assy, L	DEPO	20170731	2048208761	MB2502163
340-1130R-ACN	Mercedes-Benz C-Class, 08-11	Headlamp Assy, R	DEPO	20170731	2048208861	MB2503163
340-1130L-ACN	Mercedes-Benz C-Class, 08-11	Headlamp Assy, L	DEPO	20170731	2049065503	MB2502163
340-1130R-ACN	Mercedes-Benz C-Class, 08-11	Headlamp Assy, R	DEPO	20170731	2049065603	MB2503163

#### CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
GM1102558DSC	Chevrolet Silverado 1500/2500 HD, 14-16, w/Corner step, w/o Parking aid sensors, Chrome	Bumper, Rear Face Bar	PBSI-DS	01/17A	23108142	GM1102558
GM1102558DSC	GMC Sierra 1500, 14-16, w/Corner step, w/o Parking aid sensors, Chrome	Bumper, Rear Face Bar	PBSI-DS	01/17A	23108142	GM1102558
GM1102558DSC	GMC Sierra 2500 HD/3500 HD, 15-16, w/Corner step, w/o Parking aid sensors, Chrome	Bumper, Rear Face Bar	PBSI-DS	01/17A	23108142	GM1102558
TOOA2G020C	Lexus ES 300, 02-06	Bar, Reinforcement	Forerunner	12/16A	52171AA040	TO1106169
TOOA2B030C	Toyota Camry, 02-04, USA built	Bar, Reinforcement	Forerunner	03/17A	52021AA020	TO1006186
TOOA2G020C	Toyota Camry, 02-06	Bar, Reinforcement	Forerunner	12/16A	52171AA040	TO1106169
TOAA3B030C	Toyota Corolla, 03-08	Reinf., Bumper Front	Forerunner	01/17A	5202102060	TO1006188

\*This report includes all decertifications from October 1, 2017 through October 31, 2017.

All CAPA Reports including the recall report are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [debbie@capacertified.org](mailto:debbie@capacertified.org).