

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
FDS6785A	Ford C-Max Energi/Hybrid, 13-16	Radiator Support	Auto Power	05/17A	CJ5Z8A284A	FO1225216
FDS6785A	Ford Escape, 13-17	Radiator Support	Auto Power	05/17A	CJ5Z8A284A	FO1225216
HD-20076AQ	Honda Accord Coupe, 08-09	Hood	Tong Yang	06/17A	60100TE0A90ZZ	HO1230156
HD-20076AQ	Honda Accord Coupe, 08-12	Hood	Tong Yang	06/17A	60100TE0A91ZZ	HO1230156
DJ-AC98401	Honda Accord Sedan, 98-00	Hood	Da Juane	04/17A	60100S87A90ZZ	HO1230127
HD2700150-000C	Honda Accord Sedan, 98-00	Hood	AP	04/17A	60100S87A90ZZ	HO1230127
S0337H000AS	Honda Accord Sedan, 98-00	Hood	Jui Li	04/17A	60100S87A90ZZ	HO1230127
DJ-CV06401	Honda Civic Hybrid, 06-08	Hood	Da Juane	08/17A	60100SNEA90ZZ	HO1230148
DJ-CV06401	Honda Civic Hybrid, 06-11	Hood	Da Juane	08/17A	60100SNEA91ZZ	HO1230148
HD-10101AQ-RH	Honda Civic Hybrid, 06-11	Fender R	Tong Yang	02/17A	60211SNA90ZZ	HO1241168
DJ-CV06401	Honda Civic Sedan, 06-10	Hood	Da Juane	08/17A	60100SNEA90ZZ	HO1230148
DJ-CV06401	Honda Civic Sedan, 06-11	Hood	Da Juane	08/17A	60100SNEA91ZZ	HO1230148
HD-10101AQ-RH	Honda Civic Sedan, 06-11	Fender R	Tong Yang	02/17A	60211SNA90ZZ	HO1241168
DJ-AT12401	Hyundai Accent Hatchback, 12-17	Hood	Da Juane	06/17A	664001R120	HY1230153
DJ-AT12401	Hyundai Accent Sedan, 12-17	Hood	Da Juane	06/17A	664001R120	HY1230153
DJ-AT12401	Hyundai Accent Sedan/Hatchback, 12	Hood	Da Juane	06/17A	664001R110	HY1230153
MD0710150-000C	Mercedes-Benz C-Class C230/C300/C350, 08-10	Hood	AP	09/16A	2048800657	MB1230123
MD0710150-000C	Mercedes-Benz C-Class C230/C300/C350, 08-11	Hood	AP	09/16A	2048801057	MB1230123
CR-201AQ	Mitsubishi Outlander Sport, 11-15	Hood	Chang Jung	07/17A	5900A748	MI1230220
MB3D001Q	Mitsubishi Outlander Sport, 11-15	Hood	Cobra King	07/17A	5900A748	MI1230220
TY5030150-000C	Toyota Avalon, 05-10	Hood	AP	07/17A	53301AC040	TO1230202
S0989H000AS	Toyota Sienna, 11-16	Hood	Jui Li	05/17A	5330108040	TO1230220
TYI07H11	Toyota Yaris Hatchback, 07-11	Hood	Gordon	08/17A	5330152240	TO1230208
TY-20206AQ	Toyota Yaris Hatchback, 12-14, Japan built	Hood	Tong Yang	05/17A	5330152320	TO1230227
TY-20206AQ	Toyota Yaris Hatchback, 14-17, France built	Hood	Tong Yang	05/17A	5330152320	TO1230227

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
AD-04048BCQ	Audi A4 Sedan, 13-15	Bumper Cover, Rear	Tong Yang	09/15B	8K5807067GRU	AU1100206
BM-04124BCQ	BMW X1 E84, 13-15, w/o M sport line, w/o Headlamp washer	Bumper Cover, Front	Tong Yang	02/17A	51117345031	BM1000322
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	03/17A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-11, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	03/17A	25830551	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/o Off Road pkg, w/object sensor	Bumper Cover, Rear	Tong Yang	03/17A	20951793	GM1100783
CV-04173BDQ	Chevrolet Tahoe, 07-14, w/Off Road pkg, (RPO-BPH)	Bumper Cover, Rear	Tong Yang	03/17A	20951793	GM1100783
Y-CRBP024CA	Dodge Caravan ES/Sport, 01-04, w/fog lamps	Bumper Cover, Front	Y.C.C.	08/17A	5018609AA	CH1000328
Y-CRBP024CA	Dodge Grand Caravan ES/Sport, 01-04, w/fog lamps	Bumper Cover, Front	Y.C.C.	08/17A	5018609AA	CH1000328
Y-CRBP065CA	Dodge Ram Pickup R1500, 13 (1 piece)	Bumper Cover, Front	Y.C.C.	08/17A	68197698AA	CH1000A10
Y-CRBP065CA	Dodge Ram Pickup R1500, 14-16, w/o Parking sensors (1 piece)	Bumper Cover, Front	Y.C.C.	08/17A	68197698AA	CH1000A10
DG-07086GAO	Dodge Ram R1500 Pick-Up, 13-16, Code MFD	Grille	Tong Yang	03/17A	68093446AC	CH1200368
FD-04398BBQ	Ford Focus Sedan, 12-14	Bumper Cover, Rear	Tong Yang	07/17A	CP9Z17K835BAPTM	FO1100677
Y-FDBP037ACA	Ford Mustang Base, 99-04	Bumper Cover, Front	Y.C.C.	08/17A	YR3Z17D957EA	FO1000437
Y-FDBP037ACA	Ford Mustang Base, 99-04	Bumper Cover, Front	Y.C.C.	08/17A	YR3Z17D957EC	FO1000437
Y-FDBP037ACA	Ford Mustang Base, 99-04	Bumper Cover, Front	Y.C.C.	08/17A	YR3Z17D957ECCP	FO1000437
FD-04248BBQ	Ford Mustang Deluxe/Premium, 05-09	Bumper Cover, Rear	Tong Yang	05/17A	5R3Z17K835AAA	FO1100387
Y-FDGR416CPC	Ford Super Duty Pickup, 01, Chrome, w/o Platinum Edition	Grille	Y.C.C.	05/17A	1C3Z8200BAA	FO1200359
Y-FDGR416CPC	Ford Super Duty Pickup, 02, Chrome	Grille	Y.C.C.	05/17A	1C3Z8200BAA	FO1200359
Y-FDGR416CPC	Ford Super Duty Pickup, 03-04, Chrome, w/o King Ranch	Grille	Y.C.C.	05/17A	1C3Z8200BAA	FO1200359
Y-FDGR416CPC	Ford Super Duty Pickup, 99-00, Chrome	Grille	Y.C.C.	05/17A	1C3Z8200BAA	FO1200359
CV-04173BDQ	GMC Yukon, 07-11, w/object sensor	Bumper Cover, Rear	Tong Yang	03/17A	25830551	GM1100783
CV-04173BDQ	GMC Yukon, 07-14, w/object sensor	Bumper Cover, Rear	Tong Yang	03/17A	20951793	GM1100783

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CV-04303BBQ	GMC Yukon, 15	Bumper Cover, Front	Tong Yang	08/17A	23142977	GM1000975
CV-04303BBQ	GMC Yukon/XL/Denali, 15-17	Bumper Cover, Front	Tong Yang	08/17A	23320621	GM1000975
HD-04117BBQ	Honda Accord Hybrid, 05	Bumper Cover, Rear	Tong Yang	01/17A	04715SDAA90ZZ	HO1100208
HD-04117BBQ	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Tong Yang	01/17A	04715SDAA90ZZ	HO1100208
HN-04071BBQ	Hyundai Santa Fe, 07-09	Bumper Cover, Rear	Tong Yang	01/17A	866112B020	HY1100153
Y-INBP501CA	Infiniti G25 Base/Journey Sedan, 11-12	Bumper Cover, Front	Y.C.C.	04/16B	620221NF0H	IN1000246
Y-INBP501CA	Infiniti G25 Base/Journey Sedan, 11-12	Bumper Cover, Front	Y.C.C.	04/16B	FBM221NF0H	IN1000246
Y-INBP501CA	Infiniti G37 Base/Journey Sedan, 09-13	Bumper Cover, Front	Y.C.C.	04/16B	FBM221NF0H	IN1000246
Y-INBP501CA	Infiniti G37 Base/Journey Sedan, 10-13	Bumper Cover, Front	Y.C.C.	04/16B	620221NF0H	IN1000246
Y-INBP501CA	Infiniti Q40, 15	Bumper Cover, Front	Y.C.C.	04/16B	FBM221NF0H	IN1000246
LX1300000-110C	Lexus ES 300, 05-06	Bumper Cover, Front	AP-Procom	07/17A	5211933929	LX1000150
LX1300000-110C	Lexus ES 330, 05-06	Bumper Cover, Front	AP-Procom	07/17A	5211933929	LX1000150
LX2100000-710C	Lexus IS 250, 09-10, w/o Pre-Collision System; w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	03/17B	5211953945	LX1000188
LX2100000-710C	Lexus IS 350, 09-10, w/o Pre-Collision System; w/o Headlamp Washer	Bumper Cover, Front	AP-Procom	03/17B	5211953945	LX1000188
Y-LCBP006ACA	Lincoln MKZ Hybrid, 13-15, w/o Tow hook, w/o Front object sensors	Bumper Cover, Front	Y.C.C.	08/17A	DP5Z17D957ABPTM	FO1000691
Y-LCBP006ACA	Lincoln MKZ, 13-15, w/o Tow hook, w/o Front object sensors	Bumper Cover, Front	Y.C.C.	08/17A	DP5Z17D957ABPTM	FO1000691
MZ1430000-A00C	Mazda 3 H/B 5 Door, 04-06	Bumper Cover, Front	AP-Procom	09/17A	BN8F50031DBB	MA1000195
MZ1450870-100C	Mazda 3 Sedan, 14	Bumper Cover, Rear	AP-Procom	06/17A	BHN150221ABB	MA1100215
MZB052NBQ	Mazda 3 Sedan, 14	Bumper Cover, Rear	Pro Fortune	08/17A	BHN150221ABB	MA1100215
MZ1450870-100C	Mazda 3 Sedan, 14-16	Bumper Cover, Rear	AP-Procom	06/17A	BJS750221ABB	MA1100215
MZB052NBQ	Mazda 3 Sedan, 14-16	Bumper Cover, Rear	Pro Fortune	08/17A	BJS750221ABB	MA1100215
MZB044NBQ	Mazda 6, 09-13, 2.5L Eng	Bumper Cover, Rear	Pro Fortune	09/17A	GSYL50221BBB	MA1100195
Y-DSBP254CA	Nissan Versa Note, 14-16	Bumper Cover, Rear	Y.C.C.	07/17A	HEM223VY0J	NI1100294
Y-SCBP401CA	Scion tC, 05-10	Bumper Cover, Front	Y.C.C.	09/17A	5211921906	SC1000103
Y-TYBP290CA	Toyota Camry L/LE/XLE/Hybrid, 12-14	Bumper Cover, Rear	Y.C.C.	11/16A	5215906961	TO1100296
TY-04329BBQ	Toyota Corolla Base/CE/L, 09-10, w/o spoiler holes	Bumper Cover, Front	Tong Yang	03/17A	5211902990	TO1000343
Y-TYBP299CA	Toyota Corolla S, 14-16	Bumper Cover, Front	Y.C.C.	09/17A	5211903906	TO1000400
TY-04063BAQ	Toyota Corolla Sedan, 93-97	Bumper Cover, Rear	Tong Yang	05/17A	5215902902	TO1100174
TY-04391BBQ	Toyota Highlander, 11-13	Bumper Cover, Front	Tong Yang	08/14A	521190E914	TO1000374
Y-TYBP273ACA	Toyota Prius, 10-11, w/Halogen H/Lamps, w/o Precollision	Bumper Cover, Front	Y.C.C.	06/17B	5211947917	TO1000359

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
FO1002416DSC	Ford F250/F350 Super Duty Pickup, 11-16, Chrome	Bumper, Front	PBSI-DS	17048	BC3Z17757B	FO1002416
FO1002416DSC	Ford F450 Super Duty Pickup, 11-16, w/o Bumper end caps, Chrome	Bumper, Front	PBSI-DS	17048	BC3Z17757B	FO1002416
TYR2149A	Toyota Corolla, 03-08	Reinf., Bumper Front	Auto Power	08/17A	5202102060	TO1006188



MONTHLY RECALL REPORT January 2018*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all decertifications from December 1, 2017 through December 31, 2017.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.