

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
ADA508HD1	Audi A5 Cabrio, 10-11	Hood	Gordon	04/16A	8T0823029D	AU1230122
ADA508HD1	Audi A5 Coupe, 08-11	Hood	Gordon	04/16A	8T0823029D	AU1230122
ADA508HD1	Audi S5 Cabrio, 10-11	Hood	Gordon	04/16A	8T0823029D	AU1230122
ADA508HD1	Audi S5 Coupe, 08-11	Hood	Gordon	04/16A	8T0823029D	AU1230122
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09	Fender R	Tong Yang	05/17A	68054338AA	CH1241269
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09-11	Fender R	Tong Yang	05/17A	68054338AB	CH1241269
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09-12	Fender R	Tong Yang	05/17A	68054338AC	CH1241269
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09-12	Fender R	Tong Yang	05/17A	68054338AD	CH1241269
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09-13	Fender R	Tong Yang	05/17A	68054338AE	CH1241269
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09-15	Fender R	Tong Yang	05/17A	68054338AF	CH1241269
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09-15	Fender R	Tong Yang	05/17A	68054338AG	CH1241269
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09-15	Fender R	Tong Yang	05/17A	68054338AH	CH1241269
DG-10060AQ-RH	Dodge Ram R1500 Pickup, 09-17	Fender R	Tong Yang	05/17A	68054338AI	CH1241269
FDS6989A	Ford C-Max Energi, 13-17	Radiator Support, Lwr	Auto Power	08/17A	FV6Z5810812A	FO1225221
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang	09/17A	CP9Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang	11/16A	CP9Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang	09/17A	CM5Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang	11/16A	CM5Z8A284A	FO1225214
FDS6977A	Ford Transit Connect Wagon, 14-17	Radiator Support, Lwr	Auto Power	07/17A	AV6Z5810812C	FO1225225
HDCV12FR1	Honda Civic Coupe, 12-13	Fender R	Gordon	09/16A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic Hybrid, 12-14	Fender R	Gordon	09/16A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic Sedan, 12-15	Fender R	Gordon	09/16A	60211TR6305ZZ	HO1241181
HDCV12FR1	Honda Civic, 12-13	Fender R	Gordon	09/16A	60211TR0A90ZZ	HO1241181
HDCV12FR1	Honda Civic, 12-14	Fender R	Gordon	09/16A	60211TR6999ZZ	HO1241181
DJ-FT09401	Honda Fit, 09, Sayama Built	Hood	Da Juane	02/17A	60100TK6A91ZZ	HO1230159
DJ-FT09401	Honda Fit, 09, Suzuka Built from VIN 9S005261	Hood	Da Juane	02/17A	60100TK6A91ZZ	HO1230159
DJ-FT09401	Honda Fit, 09, Suzuka Built, to VIN 9S005260	Hood	Da Juane	02/17A	60100TK6305ZZ	HO1230159
DJ-FT09401	Honda Fit, 09-14, Suzuka Built, to VIN 9S005260	Hood	Da Juane	02/17A	60100TK6A92ZZ	HO1230159
DJ-FT09401	Honda Fit, 10-13	Hood	Da Juane	02/17A	60100TK6A91ZZ	HO1230159
HN-03012AQ	Hyundai Elantra Sedan, 14-16, Korea built, From 11-1-13	Radiator Support	Tong Yang	05/17A	641013X003	HY1225180
HN-03012AQ	Hyundai Elantra, 10-13	Radiator Support	Tong Yang	05/17A	641013X000	HY1225169
TA16002ALQ	Toyota Tundra Regular or Access Cab, 00-06, w/fender flare	Fender L	Cobra King	01/17A	538020C041	TO1240176
VWPS12FL1	Volkswagen Passat, 12-15	Fender L	Gordon	01/17A	561821021	VW1240145

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD-04117BBQ	Honda Accord Hybrid, 05	Bumper Cover, Rear	Tong Yang	10/17A	04715SDAA90ZZ	HO1100208
Y-HDBP141CA	Honda Accord Hybrid, 05	Bumper Cover, Rear	Y.C.C.	02/17A	04715SDAA90ZZ	HO1100208
HD-04117BBQ	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Tong Yang	10/17A	04715SDAA90ZZ	HO1100208
Y-HDBP141CA	Honda Accord Sedan, 03-05	Bumper Cover, Rear	Y.C.C.	02/17A	04715SDAA90ZZ	HO1100208
HDB083NBQ	Honda Civic Hybrid, 06-08	Bumper Cover, Front	Pro Fortune	01/16A	04711SNEA90ZZ	HO1000239
HDB083NBQ	Honda Civic Sedan, 06-08, 1.8L eng	Bumper Cover, Front	Pro Fortune	01/16A	04711SNEA90ZZ	HO1000239
TY-04238BEQ	Lexus RX 350, 07-09, w/o laser cruise control w/H/Lamp washer cover assy	Bumper Cover, Front	Tong Yang	04/15A	5211948935	LX1000198
LSB018NCQ	Lexus RX 350, 10-15, w/Parking Sensors	Bumper Cover, Rear	Pro Fortune	11/17A	521050E903	LX1100143
LSB037NDQ	Lexus RX 350, 13-15, w/o F Sport pkg	Bumper Cover, Front	Pro Fortune	11/16A	521190E916	LX1000248
LSB018NCQ	Lexus RX 450h, 10-15, w/Parking Sensors	Bumper Cover, Rear	Pro Fortune	11/17A	521050E903	LX1100143
LSB037NDQ	Lexus RX 450h, 13-15, w/o F Sport pkg, w/Parking assist	Bumper Cover, Front	Pro Fortune	11/16A	521190E916	LX1000248
TYB138NBQ	Toyota 4Runner Limited, 14-16, 4.0L Eng, w/Chrome	Bumper Cover, Rear	Pro Fortune	08/17A	5215935919	TO1100283
TYB138NBQ	Toyota 4Runner SR5, 14-15, 4.0L Eng, w/Chrome	Bumper Cover, Rear	Pro Fortune	08/17A	5215935919	TO1100283
TY-04518BBQ	Toyota FJ Cruiser, 07-10, w/Rear Object Sensors	Bumper Cover, Rear	Tong Yang	06/17A	5215935220	TO1100250



MONTHLY RECALL REPORT

March 2018*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
TY-04332BBQ	Toyota Highlander Hybrid, 06-07	Bumper Cover, Rear	Tong Yang	11/17A	5215948904	TO1100231
TY-04332BBQ	Toyota Highlander, 04-07	Bumper Cover, Rear	Tong Yang	11/17A	5215948904	TO1100231
TY-04399BBQ	Toyota Yaris Hatchback, 09-11	Bumper Cover, Front	Tong Yang	02/17B	5211952961	TO1000352

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from February 1, 2018 through February 28, 2018.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com.