



# MONTHLY RECALL REPORT

## April 2018\*

[Report: P8]  
Monthly

### RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

### CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CVQN10HD1	Chevrolet Equinox, 10-16	Hood	Gordon	05/17A	25942545	GM1230394
CVQN10HD1	Chevrolet Equinox, 10-17	Hood	Gordon	05/17A	23393270	GM1230394
DG-10060AQ-LH	Dodge Ram R1500 Pickup, 09	Fender L	Tong Yang	03/17A	68054339AA	CH1240269
DG-10060AQ-LH	Dodge Ram R1500 Pickup, 09-11	Fender L	Tong Yang	03/17A	68054339AB	CH1240269
DG-10060AQ-LH	Dodge Ram R1500 Pickup, 09-12	Fender L	Tong Yang	03/17A	68054339AC	CH1240269
DG-10060AQ-LH	Dodge Ram R1500 Pickup, 09-12	Fender L	Tong Yang	03/17A	68054339AD	CH1240269
DG-10060AQ-LH	Dodge Ram R1500 Pickup, 09-13	Fender L	Tong Yang	03/17A	68054339AE	CH1240269
DG-10060AQ-LH	Dodge Ram R1500 Pickup, 09-15	Fender L	Tong Yang	03/17A	68054339AF	CH1240269
DG-10060AQ-LH	Dodge Ram R1500 Pickup, 09-15	Fender L	Tong Yang	03/17A	68054339AG	CH1240269
DG-10060AQ-LH	Dodge Ram R1500 Pickup, 09-17	Fender L	Tong Yang	03/17A	68054339AI	CH1240269
HD-10119AQ-RH	Honda Pilot, 09-15	Fender R	Tong Yang	08/16A	60211SZAA90ZZ	HO1241175
HN-20043AQ	Hyundai Sonata Hybrid, 11-15	Hood	Tong Yang	03/17B	664003S000	HY1230149
HN-20043AQ	Hyundai Sonata Hybrid, 11-15	Hood	Tong Yang	10/17A	664003S000	HY1230149
HN-20043AQ	Hyundai Sonata Hybrid, 11-15	Hood	Tong Yang	12/16A	664003S000	HY1230149
HN-20043AQ	Hyundai Sonata, 11-13	Hood	Tong Yang	03/17B	664003Q000	HY1230147
HN-20043AQ	Hyundai Sonata, 11-13	Hood	Tong Yang	10/17A	664003Q000	HY1230147
HN-20043AQ	Hyundai Sonata, 11-13	Hood	Tong Yang	12/16A	664003Q000	HY1230147
HN-20043AQ	Hyundai Sonata, 11-14	Hood	Tong Yang	03/17B	664003S000	HY1230149
HN-20043AQ	Hyundai Sonata, 11-14	Hood	Tong Yang	10/17A	664003S000	HY1230149
HN-20043AQ	Hyundai Sonata, 11-14	Hood	Tong Yang	12/16A	664003S000	HY1230149
JP8210150-000C	Jeep Grand Cherokee, 11-12	Hood	AP	10/16A	55369587AC	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-12	Hood	AP	11/17A	55369587AC	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-14	Hood	AP	10/16A	55369587AD	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-14	Hood	AP	11/17A	55369587AD	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-17	Hood	AP	10/16A	55369587AG	CH1230283
JP8210150-000C	Jeep Grand Cherokee, 11-17	Hood	AP	11/17A	55369587AG	CH1230283
S0751F100AS	Lexus RX 330, 04-06	Fender L	Jui Li	03/17A	538020E010	LX1240110
TY-10176AQ-LH	Lexus RX 330, 04-06	Fender L	Tong Yang	03/17A	538020E010	LX1240110
S0751F100AS	Lexus RX 350, 07-09	Fender L	Jui Li	03/17A	538020E010	LX1240110
TY-10176AQ-LH	Lexus RX 350, 07-09	Fender L	Tong Yang	03/17A	538020E010	LX1240110
LE08002LQ	Lexus RX 350, 10-15, Canada built	Fender L	Cobra King	04/17A	538120E050	LX1240115
S0751F100AS	Lexus RX 400h, 06-08	Fender L	Jui Li	03/17A	538020E010	LX1240110
TY-10176AQ-LH	Lexus RX 400h, 06-08	Fender L	Tong Yang	03/17A	538020E010	LX1240110
LE08002LQ	Lexus RX 450h, 15, Canada built	Fender L	Cobra King	04/17A	538120E050	LX1240115
NS58002LQ	Nissan Altima, 13-16	Fender L	Cobra King	03/17A	631013TA0A	NI1240205
DS-10179AQ-LH	Nissan Maxima, 09	Fender L	Tong Yang	05/16A	F31019N0MA	NI1240194
DS-10179AQ-LH	Nissan Maxima, 09-14	Fender L	Tong Yang	05/16A	631019N15A	NI1240194
DS-20120AQ	Nissan Maxima, 09-14, Aluminum	Hood	Tong Yang	12/16A	F51009N0MA	NI1230179
TY-20035AQ	Toyota 4Runner, 90-95	Hood	Tong Yang	03/17A	5330189124	TO1230104
TYCR03FR1	Toyota Corolla CE/LE, 03-08	Fender R	Gordon	05/17A	5380102060	TO1241183
TY-20035AQ	Toyota Pickup, 89-95	Hood	Tong Yang	03/17A	5330189124	TO1230104

### CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
FD-07333GAQ	Ford Focus S Sedan, 12-14	Grille	Tong Yang	06/17A	BM5Z8200A	FO1200536
FD-07333GAQ	Ford Focus SE Sedan/Hatchback, 12-14, w/o Sport Pkg	Grille	Tong Yang	06/17A	BM5Z8200A	FO1200536
FD-07333GAQ	Ford Focus, 12-14, S; Sedan	Grille	Tong Yang	06/17A	BM5Z8200BCP	FO1200536
FD-07333GAQ	Ford Focus, 12-14, SE; Sedan/Hatchback; w/o Sport Pkg	Grille	Tong Yang	06/17A	BM5Z8200BCP	FO1200536
HD04210BBQ	Honda Accord Sedan, 08-10 (4cyl)	Bumper Cover, Front	TYG Products	17/10/24	04711TA0A90ZZ	HO1000254



# MONTHLY RECALL REPORT

## April 2018\*

[Report: P8]  
Monthly

### RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

#### CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD-04243BAQ	Honda CR-V, 12-14	Bumper Cover, Rear Lower	Tong Yang	09/17B	04715T0AA90	HO1115102
KA4120000-000C	Kia Forte 5 EX/LX, 14-16	Bumper Cover, Front	AP-Procom	10/17A	86511A7000	KI1000163
KA4120000-000C	Kia Forte Sedan, 14-16	Bumper Cover, Front	AP-Procom	10/17A	86511A7000	KI1000163
MZ-04089BCQ	Mazda 3 Sedan, 04-06, 3i; w/o Sport; prime	Bumper Cover, Rear	Tong Yang	08/17A	BN8P50221HBB	MA1100174
MZB052NBQ	Mazda 3 Sedan, 14	Bumper Cover, Rear	Pro Fortune	06/17A	BHN150221ABB	MA1100215
MZB052NBQ	Mazda 3 Sedan, 14-18	Bumper Cover, Rear	Pro Fortune	06/17A	BJS750221ABB	MA1100215
MZ-04089BCQ	Mazda 3, 04-06	Bumper Cover, Rear	Tong Yang	08/17A	BN8P50221HAA	MA1100174
NSB113NBQ	Nissan Altima, 13-15	Bumper Cover, Front	Pro Fortune	09/17A	620223TA0H	NI1000285
SB6610000-010C	Subaru Forester, 09-13	Bumper Cover, Front	AP-Procom	07/17A	57704SC000	SU1000162
SB-04047BBQ	Subaru Forester, 14	Bumper Cover, Rear	Tong Yang	11/17B	57704SG010	SU1100172
SB-04047BBQ	Subaru Forester, 14-18	Bumper Cover, Rear	Tong Yang	11/17B	57704SG012	SU1100172
TY-05084VAQ	Toyota Camry Hybrid SE, 15-17	Bumper Cover, Rear Lower	Tong Yang	12/16A	5216906020	TO1195106
TY-05084VAQ	Toyota Camry SE/Special Edition/XSE, 15-17	Bumper Cover, Rear Lower	Tong Yang	12/16A	5216906020	TO1195106
Y-TYBP305CA	Toyota Highlander Hybrid, 14-16	Bumper Cover, Front	Y.C.C.	10/17A	521190E925	TO1014102
Y-TYBP306CA	Toyota Highlander Hybrid, 14-18, w/o Rear Object Sensors	Bumper Cover, Rear Upper	Y.C.C.	10/17A	521590E911	TO1114100
Y-TYBP305CA	Toyota Highlander, 14-16	Bumper Cover, Front	Y.C.C.	10/17A	521190E925	TO1014102
Y-TYBP306CA	Toyota Highlander, 14-18. w/o Rear Object Sensors	Bumper Cover, Rear Upper	Y.C.C.	10/17A	521590E911	TO1114100
TYR1014DAL-C	Toyota RAV-4 Hybrid, 16-17	Liner, Fender L	Great Bestcam	12/16A	538760R060	TO1248171
TY8040870-000C	Toyota RAV-4, 13-15, w/Parking sensors	Bumper Cover, Rear	AP-Procom	08/17A	521500R120	TO1100308
TYR1014DAL-C	Toyota RAV-4, 13-17	Liner, Fender L	Great Bestcam	12/16A	538760R060	TO1248171
VG0940870-000C	Volkswagen Passat, 12-15	Bumper Cover, Rear	AP-Procom	06/17A	561807421DGRU	VW1100192
VG0940870-000C	Volkswagen Passat, 12-15	Bumper Cover, Rear	AP-Procom	06/17A	561807421GRU	VW1100192

#### CAPA 202 STANDARD - NON-WOVEN FABRICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

#### CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
20-9028-00-9	Dodge Ram 1500 Pickup, 09-10	Headlamp Assy, L	TYC Brother	10161710	55277409AD	CH2502217
20-9028-00-9	Dodge Ram 1500 Pickup, 09-12	Headlamp Assy, L	TYC Brother	10161710	55277409AE	CH2502217
20-9028-00-9	Dodge Ram 1500 Pickup, 09-12	Headlamp Assy, L	TYC Brother	10161710	55277409AF	CH2502217
20-9028-00-9	Dodge Ram 2500 Pickup, 10	Headlamp Assy, L	TYC Brother	10161710	55277409AD	CH2502217
20-9028-00-9	Dodge Ram 2500 Pickup, 10-12	Headlamp Assy, L	TYC Brother	10161710	55277409AE	CH2502217
20-9028-00-9	Dodge Ram 2500 Pickup, 10-12	Headlamp Assy, L	TYC Brother	10161710	55277409AF	CH2502217
324-1603R-AC	Lexus IS 250, 14	Lamp, Daytime Running R	DEPO	20150731	8161053030	LX2563100
324-1603R-AC	Lexus IS 250, 14-16	Lamp, Daytime Running R	DEPO	20150731	8161053031	LX2563100
324-1603R-AC	Lexus IS 350, 14	Lamp, Daytime Running R	DEPO	20150731	8161053030	LX2563100
324-1603R-AC	Lexus IS 350, 14-16	Lamp, Daytime Running R	DEPO	20150731	8161053031	LX2563100



# MONTHLY RECALL REPORT April 2018\*

[Report: P8]  
Monthly

## RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

### CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

### CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

\*This report includes all decertifications from March 1, 2018 through March 31, 2018.

All CAPA Reports including the recall report are available on the CAPA website at [www.capacertified.org](http://www.capacertified.org).

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at [jillian.rahal@intertek.com](mailto:jillian.rahal@intertek.com).