

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
DGDN11FR1	Dodge Durango, 11	Fender R	Gordon	11/17A	55369734AA	CH1241273
DGDN11FR1	Dodge Durango, 11-13	Fender R	Gordon	11/17A	55369734AC	CH1241273
DGDN11FL1	Dodge Durango, 11-13	Fender L	Gordon	02/17A	55369735AA	CH1240273
DGDN11FR1	Dodge Durango, 11-15	Fender R	Gordon	11/17A	55369734AB	CH1241273
DGDN11FL1	Dodge Durango, 11-17	Fender L	Gordon	02/17A	55369735AB	CH1240273
DGDN11FL1	Dodge Durango, 11-17	Fender L	Gordon	02/17A	55369735AC	CH1240273
DGDN11FR1	Dodge Durango, 14-18	Fender R	Gordon	11/17A	55369734AC	CH1241273
FDS6785A	Ford C-Max, 13-17, Energi	Radiator Support	Auto Power	01/18A	CJ5Z8A284A	FO1225216
FDS6785A	Ford C-Max, 13-17, Energi	Radiator Support	Auto Power	11/17A	CJ5Z8A284A	FO1225216
FDS6785A	Ford C-Max, 13-18, Hybrid	Radiator Support	Auto Power	01/18A	CJ5Z8A284A	FO1225216
FDS6785A	Ford C-Max, 13-18, Hybrid	Radiator Support	Auto Power	11/17A	CJ5Z8A284A	FO1225216
FDS6785A	Ford Escape, 13-18	Radiator Support	Auto Power	01/18A	CJ5Z8A284A	FO1225216
FDS6785A	Ford Escape, 13-18	Radiator Support	Auto Power	11/17A	CJ5Z8A284A	FO1225216
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang	08/17A	CP9Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang	08/17A	CM5Z8A284A	FO1225214
FDF008HD1	Ford Focus, 08-11	Hood	Gordon	09/17A	8S4Z16612A	FO1230272
FD-03031AQ	Ford Focus, 14-18	Radiator Support	Tong Yang	08/17A	CM5Z8A284ACP	FO1225214
FD-03031AQ	Ford Focus, 14-18, Hybrid	Radiator Support	Tong Yang	08/17A	CM5Z8A284ACP	FO1225214
DJ-IS10403-LH	Honda Insight, 10-14	Fender L	Da Juane	07/17A	60261TM8A90ZZ	HO1240177
HD3510160-OL0C	Honda Insight, 10-14	Fender L	AP	07/17A	60261TM8A90ZZ	HO1240177
S1101F100AS	Honda Insight, 10-14	Fender L	Jui Li	07/17A	60261TM8A90ZZ	HO1240177
WL-458AQ-LH	Jeep Wrangler, 07-08	Fender L	William Precision	03/17A	68002399AC	CH1240257
AM-03002AQ	Jeep Wrangler, 07-11	Radiator Support	Tong Yang	08/16A	55077976AC	CH1225213
AM-03002AQ	Jeep Wrangler, 07-11	Radiator Support	Tong Yang	08/16A	55077976AD	CH1225213
WL-458AQ-LH	Jeep Wrangler, 07-11	Fender L	William Precision	03/17A	68002399AD	CH1240257
WL-458AQ-LH	Jeep Wrangler, 07-12	Fender L	William Precision	03/17A	68002399AE	CH1240257
AM-03002AQ	Jeep Wrangler, 07-14	Radiator Support	Tong Yang	08/16A	55077976AE	CH1225213
AM-03002AQ	Jeep Wrangler, 07-16	Radiator Support	Tong Yang	08/16A	55077976AF	CH1225213
WL-458AQ-LH	Jeep Wrangler, 07-17	Fender L	William Precision	03/17A	68029993AB	CH1240257

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
BK-04050BDQ	Buick Verano, 12, w/o Rear object sensor	Bumper Cover, Rear	Tong Yang	09/17A	22998262	GM1100892
BK-04050BDQ	Buick Verano, 13-15, w/o Rear view camera	Bumper Cover, Rear	Tong Yang	09/17A	22998262	GM1100892
DG-07072MAQ	Dodge Charger R/T/SE/SXT, 11-14, black w/o chrome	Grille, Radiator	Tong Yang	05/16A	68104033AA	CH1210108
DGB096NDQ	Dodge Durango, 11-15, w/Parking sensor w/o Blind spot sensor	Bumper Cover, Rear	Pro Fortune	05/17A	68092094AB	CH1100959
DG-04088BAQ	Dodge Nitro, 07-09, Black w/o fog lamps	Bumper Cover, Front	Tong Yang	10/16A	1FU08CD7AA	CH1000886
FD-07325MAQ	Ford Edge, 11-14	Bumper Cover, Front Lower	Tong Yang	12/16A	BT4Z8200EPTM	FO1087131
FD-04424MAQ	Ford Escape, 13-17, w/Towing pkg	Cover, Lower Rear	Tong Yang	09/17A	CJ5Z17K835BA	FO1195128
FD-04424MAQ	Ford Escape SE/SEL/Titanium, 13-17, w/o Towing pkg	Cover, Lower Rear	Tong Yang	09/17A	CJ5Z17K835BA	FO1195128
Y-FDBP099CA	Ford Explorer, 11-15	Bumper Cover, Rear Upper	Y.C.C.	11/17A	BB5Z17K835APT	FO1114102
Y-GMAR426CA	GMC Sierra SLE/SLT, 99-02	Cap, Face Bar Trim	Y.C.C.	08/17A	12477935	GM1051104
Y-GMAR426CA	GMC Sierra SLE/SLT, 99-02	Cap, Face Bar Trim	Y.C.C.	08/17A	89026801	GM1051104
Y-GMAR426CA	GMC Yukon, 00-06, paint to match	Cap, Face Bar Trim	Y.C.C.	08/17A	12477935	GM1051104
Y-GMAR426CA	GMC Yukon, 00-06, paint to match	Cap, Face Bar Trim	Y.C.C.	08/17A	89026801	GM1051104
HD-04183BBQ	Honda Accord Coupe, 08-12	Bumper Cover, Rear	Tong Yang	10/17A	04715TE0A90ZZ	HO1100247

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD04225BBQ	Honda Accord Sedan, 08-09, (6 cyl)	Bumper Cover, Rear	TYG Products	17/09/12	04715TA1A90ZZ	HO1100245
HD04225BBQ	Honda Accord Sedan, 08-09, (6 cyl)	Bumper Cover, Rear	TYG Products	17/12/04	04715TA1A90ZZ	HO1100245
HD04225BBQ	Honda Accord Sedan, 08-12 (6 cyl)	Bumper Cover, Rear	TYG Products	17/09/12	04715TA1A91ZZ	HO1100245
HD04225BBQ	Honda Accord Sedan, 08-12 (6 cyl)	Bumper Cover, Rear	TYG Products	17/12/04	04715TA1A91ZZ	HO1100245
HDB088NBQ	Honda Civic Hybrid, 12	Bumper Cover, Rear	Pro Fortune	08/17A	04715TR3A90ZZ	HO1100272
HDB088NBQ	Honda Civic Sedan, 12, 1.8L eng (USA, Canada, Japan)	Bumper Cover, Rear	Pro Fortune	08/17A	04715TR3A90ZZ	HO1100272
HN-04101BAQ	Hyundai Tucson, 10-13	Bumper Cover, Rear Lower	Tong Yang	08/17C	866102S000	HY1115101
HN-04101BAQ	Hyundai Tucson, 10-15	Bumper Cover, Rear Lower	Tong Yang	08/17C	866902S000	HY1115101
KA-04067BBQ	Kia Forte 5 EX/LX, 14-16	Bumper Cover, Front	Tong Yang	07/17A	86511A7000	KI1000163
KA-04067BBQ	Kia Forte Sedan, 14-16	Bumper Cover, Front	Tong Yang	07/17A	86511A7000	KI1000163
LX20-8509-OH	Lexus IS 250, 09-13, w/o Park Distance Sensors	Bumper Cover, Rear	Tran Hung	05/16A	5215953929	LX1100140
LX20-8509-OH	Lexus IS 350, 09-13, w/o Park Distance Sensors	Bumper Cover, Rear	Tran Hung	05/16A	5215953929	LX1100140
DS-04329BBQ	Nissan Maxima, 09-14	Bumper Cover, Rear	Tong Yang	07/17A	850229N00H	NI1100264
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	05/17A	5215947905	TO1100280
TY-04383BBQ	Toyota Prius Plug In, 12-15	Bumper Cover, Rear	Tong Yang	05/17A	5215947916	TO1100280
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	05/17A	5215947905	TO1100280
TY-04383BBQ	Toyota Prius, 10-15	Bumper Cover, Rear	Tong Yang	05/17A	5215947916	TO1100280
TY04548BDQ	Toyota Sienna Limited, 11-15, 3.5L Eng	Bumper Cover, Front	TYG Products	18/01/22	5211908902	TO1000368
TY04548BDQ	Toyota Sienna XLE, 11-15, w/Limited pkg 3.5L Eng	Bumper Cover, Front	TYG Products	18/01/22	5211908902	TO1000368
TY04179BAQ	Toyota Sienna, 01-03, Gray	Bumper Cover, Front	TYG Products	17/09/27	5211908030B0	TO1000219
VGB052NBQ	Volkswagen GTI, 10-14 w/o Parking Assist	Bumper Cover, Rear	Pro Fortune	12/16A	5K6807417GGRU	VW1100182

CAPA 202 STANDARD - NON-WOVEN FABRICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CVR3375A	Buick Verano, 12-14	Bar, Impact	Auto Power	08/17A	13426894	GM1006667
CVR3375A	Chevrolet Cruze, 11-16	Bar, Impact	Auto Power	08/17A	13426894	GM1006667
CH1002387DSC	Dodge Ram R1500 Pickup, 10-12, w/o Sport pkg, w/o fog	Bumper, Front	PBSI-DS	17117	68088188AA	CH1002387
FO1002412DSC	Ford F150 Pickup, 09-12, Chrome, w/o fog lamps	Bumper, Front	PBSI-DS	17202	9L3Z17757A	FO1002412
FD58091AH	Ford F150 Pickup, 09-14, w/o Towing pkg	Bumper Pad, Rear	Hui Yih	07/17A	9L3Z17B807A	FO1191126
FO1002412DSC	Ford Pickup, 09-14, F150	Bumper, Front	PBSI-DS	17202	9L3Z17757ACP	FO1002412

CAPA 601 STANDARD - RADIATORS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

*This report includes all decertifications from April 1, 2018 through April 30, 2018.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com.