

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CDCT08HD1	Cadillac CTS Coupe/Wagon, 11-14	Hood	Gordon	06/16A	22789395	GM1230383
CDCT08HD1	Cadillac CTS Sedan, 08-03/31/09	Hood	Gordon	06/16A	25885609	GM1230383
CDCT08HD1	Cadillac CTS Sedan, 08-13	Hood	Gordon	06/16A	22789395	GM1230383
CVTH15FL1	Chevrolet Tahoe, 15-16	Fender L	Gordon	01/17A	22756423	GM1240388
CVTH15FL1	Chevrolet Tahoe, 15-16	Fender L	Gordon	01/17A	23272194	GM1240388
CVTH15FL1	Chevrolet Tahoe, 15-17	Fender L	Gordon	01/17A	84216909	GM1240388
FDS6785A	Ford C-Max, 13-17, Energi	Radiator Support	Auto Power	03/18A	CJ5Z8A284A	FO1225216
FDS6785A	Ford C-Max, 13-18, Hybrid	Radiator Support	Auto Power	03/18A	CJ5Z8A284A	FO1225216
FDS6785A	Ford Escape, 13-18	Radiator Support	Auto Power	03/18A	CJ5Z8A284A	FO1225216
FDFU09T11	Ford F-150 Pickup, 09-14, Styleside w/Tailgate Step	Tailgate	Gordon	08/17A	BL3Z9940700D	FO1900123
FDFU09T11	Ford F-150 Styleside Pickup, 09-12, Step	Tailgate	Gordon	08/17A	AL3Z9940700A	FO1900123
FDFU09T11	Ford F-150 SVT Raptor Pickup, 10-12, w/Tailgate Step	Tailgate	Gordon	08/17A	BL3Z9940700D	FO1900123
FDFU09T11	Ford F-150 SVT Raptor Pickup, 10-12, Step	Tailgate	Gordon	08/17A	AL3Z9940700A	FO1900123
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang	02/18A	CP9Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-14	Radiator Support	Tong Yang	06/18A	CP9Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang	02/18A	CM5Z8A284A	FO1225214
FD-03031AQ	Ford Focus Sedan/Hatchback, 12-16	Radiator Support	Tong Yang	06/18A	CM5Z8A284A	FO1225214
FD-03031AQ	Ford Focus, 14-18	Radiator Support	Tong Yang	02/18A	CM5Z8A284ACP	FO1225214
FD-03031AQ	Ford Focus, 14-18	Radiator Support	Tong Yang	06/18A	CM5Z8A284ACP	FO1225214
FD-03031AQ	Ford Focus, 14-18, Hybrid	Radiator Support	Tong Yang	02/18A	CM5Z8A284ACP	FO1225214
FD-03031AQ	Ford Focus, 14-18, Hybrid	Radiator Support	Tong Yang	06/18A	CM5Z8A284ACP	FO1225214
CV-20092AQ	GMC Sierra 1500 Hybrid, 09	Hood	Tong Yang	09/17A	25786290	GM1230359
CV-20092AQ	GMC Sierra 1500 Hybrid, 09-10	Hood	Tong Yang	09/17A	25848847	GM1230359
CV-20092AQ	GMC Sierra 1500 Hybrid, 09-11	Hood	Tong Yang	09/17A	20863104	GM1230359
CV-20092AQ	GMC Sierra, 07-09	Hood	Tong Yang	09/17A	25786290	GM1230359
CV-20092AQ	GMC Sierra, 07-10	Hood	Tong Yang	09/17A	25848847	GM1230359
CV-20092AQ	GMC Sierra, 07-11	Hood	Tong Yang	09/17A	20863104	GM1230359
HD-20081AQ	Honda Fit, 09, Sayama Built	Hood	Tong Yang	04/17A	60100TK6A91ZZ	HO1230159
HDFI09HD1	Honda Fit, 09, Sayama Built	Hood	Gordon	04/17A	60100TK6A91ZZ	HO1230159
HD-20081AQ	Honda Fit, 09, Suzuka Built from VIN 9S005261	Hood	Tong Yang	04/17A	60100TK6A91ZZ	HO1230159
HDFI09HD1	Honda Fit, 09, Suzuka Built from VIN 9S005261	Hood	Gordon	04/17A	60100TK6A91ZZ	HO1230159
HD-20081AQ	Honda Fit, 09, Suzuka Built, to VIN 9S005260	Hood	Tong Yang	04/17A	60100TK6305ZZ	HO1230159
HDFI09HD1	Honda Fit, 09, Suzuka Built, to VIN 9S005260	Hood	Gordon	04/17A	60100TK6305ZZ	HO1230159
HD-20081AQ	Honda Fit, 09-14, Suzuka Built, to VIN 9S005260	Hood	Tong Yang	04/17A	60100TK6A92ZZ	HO1230159
HDFI09HD1	Honda Fit, 09-14, Suzuka Built, to VIN 9S005260	Hood	Gordon	04/17A	60100TK6A92ZZ	HO1230159
HD-20081AQ	Honda Fit, 10-13	Hood	Tong Yang	04/17A	60100TK6A91ZZ	HO1230159
HDFI09HD1	Honda Fit, 10-13	Hood	Gordon	04/17A	60100TK6A91ZZ	HO1230159
HD-20078AQ	Honda Pilot, 09-15	Hood	Tong Yang	11/16A	60100SZA090ZZ	HO1230157
SUFS14HD1	Subaru Forester, 14-17, 2.0L/2.5L Eng	Hood	Gordon	06/17A	57229SG0009P	SU1230144
SUFS14HD1	Subaru Forester, 14-17, 2.0L/2.5L Eng	Hood	Gordon	10/17B	57229SG0009P	SU1230144
SUFS14HD1	Subaru Forester, 14-17, 2.0L/2.5L Eng	Hood	Gordon	11/17A	57229SG0009P	SU1230144
SUFS14HD1	Subaru Forester, 14-17, 2.0L/2.5L Eng	Hood	Gordon	ALL	57229SG0009P	SU1230144
TAOL001AQ	Toyota Prius c, 12-16	Hood	Cobra King	11/17A	5330152370	TO1230228

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
HD-04173BBQ	Acura MDX, 04-06	Bumper Cover, Front	Tong Yang	11/17A	04711S3VA80ZZ	AC1000150
CV-04106BAQ	Chevrolet Avalanche, 02	Bumper Cover, Front	Tong Yang	01/18A	88944057	GM1000648
CV-04241PALQ	Chevrolet Silverado, 12-13, w/o Fog lamps, Chrome	Cap, Face Bar L	Tong Yang	08/16A	22796186	GM1004157
DGB068NCQ	Dodge Charger, 11, w/o Parking Sensor	Bumper Cover, Rear	Pro Fortune	12/16A	68092608AA	CH1100962

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
DGB068NCQ	Dodge Charger, 11-14, w/o Parking Sensor	Bumper Cover, Rear	Pro Fortune	12/16A	68092608AB	CH1100962
DGB068NCQ	Dodge Charger, 12-14, Type 1 w/o parking sensor	Bumper Cover, Rear	Pro Fortune	12/16A	68092608AA	CH1100962
DGB068NCQ	Dodge Charger, 12-14, Type 1, w/o Parking sensor	Bumper Cover, Rear	Pro Fortune	12/16A	68092608AB	CH1100962
FD-04395BDQ	Ford Edge, 11-14, w/Rear Object Sensors	Bumper Cover, Rear	Tong Yang	03/18A	BT4Z17810BPTM	FO1114101
FD-07354GAQ	Ford Taurus, 13-15	Grille	Tong Yang	07/17A	DG1Z8200BCP	FO1210115
FD-07354GAQ	Ford Taurus, 13-15	Grille	Tong Yang	07/17A	DG1Z8200BPTM	FO1210115
HDB084NBQ	Honda Civic Hybrid, 06-11	Bumper Cover, Rear	Pro Fortune	02/18A	04715SNAA90ZZ	HO1100235
HDB084NBQ	Honda Civic Sedan, 06-11, 1.8L eng	Bumper Cover, Rear	Pro Fortune	02/18A	04715SNAA90ZZ	HO1100235
Y-HDBP147ACA	Honda Odyssey EX/EX-L/LX, 05-07	Bumper Cover, Front	Y.C.C.	07/17B	04711SHJA90ZZ	HO1000222
Y-HYBP023CA	Hyundai Genesis Coupe, 13-15	Bumper Cover, Front	Y.C.C.	05/17A	865112M300	HY1000197
HN2420000-000C	Hyundai Sonata, 15-17, Sport Type	Bumper Cover, Front	AP-Procom	01/18A	86511C2300	HY1000211
KIB006NCQ	Kia Sedona EX/LX, 06-08, w/Back-up Sensor	Bumper Cover, Rear	Pro Fortune	11/17A	866114D011	KI1100132
LX4610000-310C	Lexus RX 350, 10-12, Canada Built, w/o Premium Pkg, w/o Parking Assist	Bumper Cover, Front	AP-Procom	11/17A	521190E906	LX1000190
LSB018NCQ	Lexus RX 350, 10-15, w/Parking Sensors	Bumper Cover, Rear	Pro Fortune	01/18A	521050E903	LX1100143
LSB018NCQ	Lexus RX 350, 10-15, w/Parking Sensors	Bumper Cover, Rear	Pro Fortune	01/18A	5210548903	LX1100143
LSB018NCQ	Lexus RX 400h, 10-15, w/Parking Sensors	Bumper Cover, Rear	Pro Fortune	01/18A	5210548903	LX1100143
LSB018NCQ	Lexus RX 450h, 10-15, w/Parking Sensors	Bumper Cover, Rear	Pro Fortune	01/18A	521050E903	LX1100143
Y-MZBP007CA	Mazda 3 Hatchback, 14-16	Bumper Cover, Front	Y.C.C.	11/17A	BJS750031ABB	MA1000239
MZ-04098BBQ	Mazda 3 Sedan, 07-09	Bumper Cover, Rear	Tong Yang	04/18A	BS4N50221CBB	MA1100192
Y-MZBP007CA	Mazda 3 Sedan, 14-16	Bumper Cover, Front	Y.C.C.	11/17A	BJS750031ABB	MA1000239
Y-MZBP007CA	Mazda 3, 14	Bumper Cover, Front	Y.C.C.	11/17A	BHN150031ABB	MA1000239
Y-MZBP151CA	Mazda CX-5, 13-15	Bumper Cover, Front	Y.C.C.	01/18A	KD4550031BB	MA1000236
DS-04400BBQ	Nissan Altima Sedan, 16-17, w/o Distance sensors	Bumper Cover, Front	Tong Yang	03/18A	620229HSH0H	NI1000311
Y-DSBP234CA	Nissan Maxima, 09-14	Bumper Cover, Front	Y.C.C.	01/18A	620229N00H	NI1000258
Y-DSBP234CA	Nissan Maxima, 09-14	Bumper Cover, Front	Y.C.C.	01/18B	620229N00H	NI1000258
DS-04329BBQ	Nissan Maxima, 09-14	Bumper Cover, Rear	Tong Yang	11/17B	850229N00H	NI1100264
DS-04306BBQ	Nissan Rogue S/SL/SV, 11-15	Bumper Cover, Front	Tong Yang	01/18B	620221VK0H	NI1000277
DS-04354BBQ	Nissan Versa Note, 14-15	Bumper Cover, Front	Tong Yang	02/18A	FBM223VY0J	NI1000292
SBG004NCQ	Subaru Forester, 11-13	Grille	Pro Fortune	09/17A	91121SC040	SU1200149
TYB137NBQ	Toyota 4Runner, 14-17, w/Chrome	Bumper Cover, Front	Pro Fortune	03/18A	5211935913	TO1000407
TY2810000-100C	Toyota Corolla Base/CE/L, 09-10, w/o spoiler holes	Bumper Cover, Front	AP-Procom	11/17A	5211902990	TO1000343
Y-TYBP267ACA	Toyota Corolla Base/CE/L, 09-10, w/o spoiler holes	Bumper Cover, Front	Y.C.C.	12/17A	5211902990	TO1000343
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	01/17A	5211902946	TO1000297
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	12/17A	5211902946	TO1000297
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	01/17A	521190Z938	TO1000297
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	12/17A	521190Z938	TO1000297
TYB130NBQ	Toyota Corolla, 14-16	Bumper Cover, Rear	Pro Fortune	12/17B	5215903901	TO1100309
TY-04285BBQ	Toyota Matrix Base, 05-08	Bumper Cover, Front	Tong Yang	10/17A	5211902953	TO1000294
TY-04285BBQ	Toyota Matrix XR, 05-08, w/o Spoiler	Bumper Cover, Front	Tong Yang	10/17A	5211902953	TO1000294
TY-04285BBQ	Toyota Matrix XRS, 05-06, w/o Spoiler	Bumper Cover, Front	Tong Yang	10/17A	5211902953	TO1000294
TY8040870-100C	Toyota RAV-4, 13-15, w/o Parking sensors	Bumper Cover, Rear	AP-Procom	09/17A	521500R110	TO1100306
TY04592BDQ	Toyota Sienna Base/L/LE/XLE/Limited, 11-17, w/park	Bumper Cover, Rear	TYG Products	18/02/10	5215908903	TO1100285
TAA1016RQ	Toyota Tacoma, 05-11, Matte Black/Paint to Match	Bumper Cover, Front Ext. R	Cobra King	04/17A	5211204020	TO1005170

CAPA 202 STANDARD - NON-WOVEN FABRICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
335-1161R-AC2	GMC Terrain Denali, 13-15	Headlamp Assy, R	DEPO	20170814	22915383	GM2503381
335-1161R-AC2	GMC Terrain Denali, 13-15	Headlamp Assy, R	DEPO	20171002	22915383	GM2503381
335-1161R-AC2	GMC Terrain Denali, 13-15	Headlamp Assy, R	DEPO	20180305	22915383	GM2503381
335-1161R-AC2	GMC Terrain Denali, 13-15	Headlamp Assy, R	DEPO	20170814	23319182	GM2503381
335-1161R-AC2	GMC Terrain Denali, 13-15	Headlamp Assy, R	DEPO	20171002	23319182	GM2503381
335-1161R-AC2	GMC Terrain Denali, 13-15	Headlamp Assy, R	DEPO	20180305	23319182	GM2503381
11-11705-00-9	Kia Sorento, 11-13	Taillamp R	TYC Brother	08141710	924021U000	KI2805103

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
FO1002412DSC	Ford F150 Pickup, 09-12, Chrome, w/o fog lamps	Bumper, Front	PBSI-DS	17172	9L3Z17757A	FO1002412
FD58091BH	Ford F150 Pickup, 09-14, w/Towring pkg, w/o Rear object sensors	Bumper Pad, Rear	Hui Yih	09/17A	9L3Z17B807B	FO1191124
FD58091BH	Ford F150 SVT Raptor Pickup, 10-14, w/o Rear object sensors	Bumper Pad, Rear	Hui Yih	09/17A	9L3Z17B807B	FO1191124
FO1002412DSC	Ford Pickup, 09-14, F150	Bumper, Front	PBSI-DS	17172	9L3Z17757ACP	FO1002412

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

*This report includes all decertifications from June 1, 2018 through June 30, 2018.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com.