

NEW PARTS CAPA 101 STANDARD - METALS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>	
101	Chevrolet Colorado, 15-17	Fender L	CV9710160-0L0C	AP	23354494	GM1240404
101	Chevrolet Colorado, 15-17	Fender R	CV9710160-0R0C	AP	23373629	GM1241404
101	Chevrolet Impala Limited, 14-16	Radiator Support	CVS6822A	Auto Power	22844490	GM1225297
101	Chevrolet Impala, 12-13	Radiator Support	CVS6822A	Auto Power	22844490	GM1225297
101	Dodge Ram Promaster Cargo Van, 14-18	Hood	DG5500-02A-CP	Hornig Ling	68095724AA	CH1230316
101	Honda Odyssey, 18	Fender R	HDOD18FR1	Gordon	60211THRA00ZZ	HO1241194
101	Honda Odyssey, 18	Fender L	HDOD18FL1	Gordon	60261THRA00ZZ	HO1240194
101	Honda Odyssey, 18-18	Fender R	HDOD18FR1	Gordon	60211THR305ZZ	HO1241194
101	Honda Odyssey, 18-18	Fender L	HDOD18FL1	Gordon	60261THR305ZZ	HO1240194
101	Kia, Sportage, 17-18,	Hood	KA8120150-000C	AP	66400D9000	KI1230138

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>	
201	BMW 3-Series E92, 07-13, Coupe, 3.0L Eng	Fender L	BM33-4102-LH	Tran Hung	41357168987	BM1240142
201	BMW 3-Series E92, 07-13, Coupe, 3.0L Eng	Fender R	BM33-4102-RH	Tran Hung	41357168988	BM1241142
201	BMW 3-Series E93, 07-13, Convertible, 3.0L Eng	Fender L	BM33-4102-LH	Tran Hung	41357168987	BM1240142
201	BMW 3-Series E93, 07-13, Convertible, 3.0L Eng	Fender R	BM33-4102-RH	Tran Hung	41357168988	BM1241142
201	Chrysler 300, 15-18, Sedan	Shield, Sight	CHR30015FU1	Gordon	68227211AC	CH1224103
201	Chrysler Pacifica Hybrid, 17	Radiator Support	CRS60108A	Auto Power	68292241AB	CH1225287
201	Chrysler Pacifica, 17	Radiator Support	CRS60108A	Auto Power	68292241AB	CH1225287
201	Dodge RAM R1500 Pick-Up, 14-18, w/Parking sensors	Bumper Cover, Front	Y-CRBP065HCA	Y.C.C.	68239435AA	CH1000A12
201	Ford Explorer, 16-16, w/o Active Park Assist, w/o Camera, w/Parking Aid, w/Tow Hook, Prime	Bumper Cover, Front	FDB145NDQ	Pro Fortune	FB5Z17D957DPT	FO1000726
201	Ford Explorer, 16-16, w/o Active Park Assist, w/o Camera, w/Parking Aid, w/Tow Hook, Prime	Bumper Cover, Front	Y-FDBP121AHC	Y.C.C.	FB5Z17D957DPT	FO1000726
201	Ford Explorer, 16-17, Police Model, w/Front Tow Hook	Bumper Cover, Front	FDB145NCQ	Pro Fortune	FB5Z17D957EB	FO1000723
201	Ford Explorer, 16-17, Police Model, w/Front Tow Hook	Bumper Cover, Front	Y-FDBP121ACA	Y.C.C.	FB5Z17D957EB	FO1000723
201	Ford Explorer, 16-17, w/Active Park Assist, w/Front Tow Hook	Bumper Cover, Front	FDB145NFQ	Pro Fortune	FB5Z17D957FA	FO1000728
201	Ford Explorer, 16-17, w/Active Park Assist, w/Front Tow Hook	Bumper Cover, Front	Y-FDBP121HCA	Y.C.C.	FB5Z17D957FA	FO1000728
201	Ford Explorer, 16-17, w/o Active Park Assist, w/Camera, w/Parking Aid, w/Tow Hook, Prime	Bumper Cover, Front	FDB145NEQ	Pro Fortune	FB5Z17D957EA	FO1000734
201	Ford Explorer, 16-17, w/o Active Park Assist, w/Camera, w/Parking Aid, w/Tow Hook, Prime	Bumper Cover, Front	Y-FDBP121CA	Y.C.C.	FB5Z17D957EA	FO1000734
201	Ford Explorer, 16-17, w/o Active Park Assist, w/Front View Camera, w/Front Tow Hook	Bumper Cover, Front	FDB145NEQ	Pro Fortune	FB5Z17D957ECP	FO1000734
201	Ford Explorer, 16-17, w/o Active Park Assist, w/Front View Camera, w/Front Tow Hook	Bumper Cover, Front	Y-FDBP121CA	Y.C.C.	FB5Z17D957ECP	FO1000734
201	Ford Explorer, 16-17, w/o Active Park Assist, w/o Front View Camera, w/Front Parking Aid, w/Front Tow Hook	Bumper Cover, Front	FDB145NDQ	Pro Fortune	FB5Z17D957DAP	FO1000726
201	Ford Explorer, 16-17, w/o Active Park Assist, w/o Front View Camera, w/Front Parking Aid, w/Front Tow Hook	Bumper Cover, Front	Y-FDBP121AHC	Y.C.C.	FB5Z17D957DAP	FO1000726
201	Ford Pickup, 09-10, 2010, 5.4L Eng, 4.6L Eng	Deflector, Upper Air	FD7E099AQ	Cobra King	9L3Z19E525A	FO1224124
201	Ford Pickup, 10, SVT Raptor	Deflector, Upper Air	FD7E099AQ	Cobra King	9L3Z19E525A	FO1224124
201	Ford, Explorer, 16-16,	Bumper Cover, Front	FDB145NEQ	Pro Fortune	FB5Z17D957GPT	FO1000734
201	Ford, Explorer, 16-16,	Bumper Cover, Front	Y-FDBP121CA	Y.C.C.	FB5Z17D957GPT	FO1000734
201	Hyundai Genesis Sedan, 15, 3.8L Eng, w/o Front object sensors, w/Headlamp washers	Bumper Cover, Front	HN-04180BFQ	Tong Yang	86511B1100	HY1000207
201	Hyundai Genesis Sedan, 15, 5.0L Eng, w/Front object sensors	Bumper Cover, Front	HN-04180BGQ	Tong Yang	86540B1400	HY1000209
201	Hyundai Genesis Sedan, 15-16, 3.8L Eng, w/Front object sensors	Bumper Cover, Front	HN-04180BHQ	Tong Yang	86540B1200	HY1000208

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
201 Hyundai Genesis Sedan, 15-16, 3.8L Eng, w/o Front object sensors, w/o Headlamp washers	Bumper Cover, Front	HN-04180BEQ	Tong Yang	86511B1000	HY1000206
201 Kia Sorento, 16-18, EX, L, LX Model, w/Fog Lamps	Insert, Front Bumper	LKA74083ALQ	Cobra King	86525C6020	KI1038123
201 Kia Sorento, 16-18, EX, L, LX Model, w/Fog Lamps	Insert, Front Bumper	FKA74083ARQ	Cobra King	86526C6020	KI1039123
201 Kia Sorento, 16-18, EX, L, LX Model, w/o Fog Lamps	Insert, Front Bumper	LKA74083LQ	Cobra King	86525C6000	KI1038129
201 Kia Sorento, 16-18, EX, L, LX Model, w/o Fog Lamps	Insert, Front Bumper	FKA74083RQ	Cobra King	86526C6000	KI1039129
201 Lexus IS 200t, 17, w/F Sport Pkg	Bumper Cover, Front	LX20-9962-OHOS	Tran Hung	521195E939	LX1000333
201 Lexus IS 200t, 17, w/F Sport Pkg, w/Headlamp Washers, w/o Park Sensors, prime	Bumper Cover, Front	LX20-9962-WHOS	Tran Hung	521195E937	LX1000334
201 Lexus IS 250, 17, w/F Sport Pkg	Bumper Cover, Front	LX20-9962-OHOS	Tran Hung	521195E939	LX1000333
201 Lexus IS 300, 17, w/F Sport Pkg	Bumper Cover, Front	LX20-9962-OHOS	Tran Hung	521195E939	LX1000333
201 Lexus IS 300, 17, w/F Sport Pkg, w/Headlamp Washers, w/o Park Sensors, prime	Bumper Cover, Front	LX20-9962-WHOS	Tran Hung	521195E937	LX1000334
201 Lexus IS 350, 17, w/F Sport Pkg	Bumper Cover, Front	LX20-9962-OHOS	Tran Hung	521195E939	LX1000333
201 Lexus IS 350, 17, w/F Sport Pkg, w/Headlamp Washers, w/o Park Sensors, Prime	Bumper Cover, Front	LX20-9962-WHOS	Tran Hung	521195E937	LX1000334
201 Lexus LS 460, 13-17	Grille, Lower	LSN043NAQ	Pro Fortune	5311250300	LX1036113
201 Lexus LS 600H, 13-16	Grille, Lower	LSN043NAQ	Pro Fortune	5311250300	LX1036113
201 Lincoln MKC, 15-17	Bumper Cover, Rear	LC-04024BAQ	Tong Yang	EJ7Z17K835AD	FO1115108
201 Lincoln, MKC, 15-17,	Bumper Cover, Rear	LC-04024BAQ	Tong Yang	EJ7Z17K835AC	FO1115108
201 Mazda CX-5, 13-16	Cover, Engine Under	ILT-MZB005A	Liantuoh	KD535611YA	MA1228117
201 Toyota Camry, 18, Hybrid	Seal, Upper	TY39181AH	Hui Yih	5329506190	TO1224119
201 Toyota Camry, 18, Japan Built	Seal, Upper	TY39181AH	Hui Yih	5329506190	TO1224119
201 Toyota Camry, 18, North America Built	Seal, Upper	TY39181AH	Hui Yih	5329506190	TO1224119
201 Toyota RAV-4, 16-17, Hybrid	Retainer Upper Cover	TA5J617BRQ	Cobra King	525620R050	TO1133124
201 Toyota RAV-4, 16-17, Hybrid	Retainer Upper Cover	TA5J617BLQ	Cobra King	525630R050	TO1132124
201 Toyota RAV-4, 16-18	Retainer Upper Cover	TA5J617BRQ	Cobra King	525620R050	TO1133124
201 Toyota RAV-4, 16-18	Retainer Upper Cover	TA5J617BLQ	Cobra King	525630R050	TO1132124
201 Toyota Sequoia SR5, 08-17, w/o Parking Sensors	Bumper Cover, Rear	LG-70-176C	CHL	521590C910	TO1100269
201 Toyota Sequoia, 08-14, w/Parking Sensors	Bumper Cover, Rear	LG-70-177C	CHL	521590C909	TO1100262
201 Toyota Sequoia, 15-17, w/Parking sensors	Bumper Cover, Rear	LG-70-178C	CHL	521590C911	TO1100324

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
301 Chevrolet Traverse, 13-15	Lamp, Park L	12-5306-00-9	TYC Brother	20956917	GM2530135
301 Chevrolet Traverse, 13-15	Lamp, Park R	12-5305-00-9	TYC Brother	20956918	GM2531135
301 Chevrolet Traverse, 13-17	Lamp, Park L	12-5306-00-9	TYC Brother	23305608	GM2530135
301 Chevrolet Traverse, 13-17	Lamp, Park R	12-5305-00-9	TYC Brother	23305609	GM2531135
301 Ford Transit Cargo Van, 16-17, from 9/2/15, w/o Chrome trim	Headlamp Assy, R	20-9945-90-9	TYC Brother	CK4Z13008E	FO2503356
301 Ford Transit Cargo Van, 16-17, from 9/2/15, w/o Chrome trim	Headlamp Assy, L	20-9946-90-9	TYC Brother	CK4Z13008H	FO2502356
301 Ford Transit Passenger Van, 16-17, from 9/2/15, w/o Chrome trim	Headlamp Assy, R	20-9945-90-9	TYC Brother	CK4Z13008E	FO2503356
301 Ford Transit Passenger Van, 16-17, from 9/2/15, w/o Chrome trim	Headlamp Assy, L	20-9946-90-9	TYC Brother	CK4Z13008H	FO2502356
301 Mercedes-Benz GLA-Class, 15-18	Headlamp Assy, L	340-1153L-AC2	DEPO	1569062900	MB2502235

NEW PARTS CAPA 301 STANDARD - LIGHTING

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
301 Mercedes-Benz GLA-Class, 15-18	Headlamp Assy, R	340-1153R-AC2	DEPO	1569063000	MB2503235
301 Nissan Maxima, 16	Lamp, Fog R	19-6157-00-9	TYC Brother	261504RA0A	NI2593134
301 Nissan Maxima, 16	Lamp, Fog L	19-6158-00-9	TYC Brother	261554RA0A	NI2592134
301 Nissan Maxima, 16-18	Lamp, Fog R	19-6157-00-9	TYC Brother	261504RA0B	NI2593134
301 Nissan Maxima, 16-18	Lamp, Fog L	19-6158-00-9	TYC Brother	261554RA0B	NI2592134

NEW PARTS CAPA 501 STANDARD - BUMPERS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
501 Chrysler 200, 15-17, Sedan	Absorber, Energy	CH1070839DSC	Grand HB	68096064AB	CH1070839
501 Ford F150 Pickup, 15-17, w/Towing Pkg Medium Duty Towing, Hvy Duty Towing	Bar, Reinforcement	FD54151AH	Hui Yih	FL3Z17D826B	FO1106375
501 Ford F150 Pickup, 15-17, Crew Cab, w/Towing Pkg Medium Duty Towing, Hvy Duty Towing	Bar, Reinforcement	FD54151AH	Hui Yih	FL3Z17D826B	FO1106375
501 Ford F150 Pickup, 15-17, Extended Cab, w/Towing Pkg w/o Max Trailer Towing Pkg	Bar, Reinforcement	FD54151AH	Hui Yih	FL3Z17D826B	FO1106375
501 Ford Pickup, 15-17, F150 Crew Cab, w/Towing Pkg Medium Duty Towing, Hvy Duty Towing	Bar, Reinforcement	FD54151AH	Hui Yih	HL3Z17D826G	FO1106375
501 Ford Pickup, 15-17, F150 Extended Cab, w/Towing Pkg w/o Max Trailer Towing Pkg	Bar, Reinforcement	FD54151AH	Hui Yih	HL3Z17D826G	FO1106375
501 Ford Pickup, 15-17, F150 Regular Cab, w/Towing Pkg Medium Duty Towing, Hvy Duty Towing	Bar, Reinforcement	FD54151AH	Hui Yih	HL3Z17D826G	FO1106375
501 GMC 1500 Sierra, 14-15, w/o Park Assist	Bumper, Front	CVB7099ACH	Auto Power	22902307	GM1002848
501 GMC 1500 Sierra, 14-15, w/Park Assist	Bumper, Front	CVB7099-1APT	Auto Power	22902310	GM1002859
501 GMC 1500 Sierra, 14-15, w/Park Assist, w/o Z71 Pkg	Bumper, Front	CVB7099-1ACH	Auto Power	22902308	GM1002847
501 Honda Civic, 13, Coupe	Bracket, Front Bump	HD45141ARH	Hui Yih	71150TR3A00ZZ	HO1067117
501 Honda Civic, 13, Coupe	Bracket, Front Bump	HD45141ALH	Hui Yih	71160TR3A00ZZ	HO1066117
501 Honda Civic, 13-15, Hybrid	Bracket, Front Bump	HD45141ARH	Hui Yih	71150TR3A00ZZ	HO1067117
501 Honda Civic, 13-15, Hybrid	Bracket, Front Bump	HD45141ALH	Hui Yih	71160TR3A00ZZ	HO1066117
501 Honda Civic, 13-15, Sedan	Bracket, Front Bump	HD45141ARH	Hui Yih	71150TR3A00ZZ	HO1067117
501 Honda Civic, 13-15, Sedan	Bracket, Front Bump	HD45141ALH	Hui Yih	71160TR3A00ZZ	HO1066117
501 Kia Sorento, 14-15	Reinf., Bumper Front	KAR2592A	Auto Power	865301U500	KI1006138
501 Toyota Camry, 18, Hybrid, LE, XLE Model	Bar, Reinforcement	TYR2691A	Auto Power	5217106170	TO1106231
501 Toyota Camry, 18, Hybrid, SE Model	Bar, Reinforcement	TYR2691A	Auto Power	5217106170	TO1106231
501 Toyota Camry, 18, L, LE, XLE Model	Bar, Reinforcement	TYR2691A	Auto Power	5217106170	TO1106231
501 Toyota Camry, 18, SE, SXE Model	Bar, Reinforcement	TYR2691A	Auto Power	5217106170	TO1106231

NEW PARTS CAPA 601 STANDARD - RADIATORS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
LSB028NCQ	Lexus CT 200H, 11-13, w/o Parking Aid Sensors	Bumper Cover, Rear	Pro Fortune	11/17A	5215976900	LX1100152

CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						

DELETED PARTS CAPA 101 STANDARD - METALS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 501 STANDARD - BUMPERS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

DELETED PARTS CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

CORRECTION

The following parts were listed as certified on the February 21, 2017 Weekly Parts Update. Upon further review, there parts were not certified during the period covered by that report.

NEW PARTS CAPA 201 STANDARD - PLASTICS

<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Number</u>	<u>Manufacturer</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
Lexus NX 200t, 15-16, w/o F Sport Pkg; w/o Park Distance Sensors; w/Headlamp Washers	Bumper Cover, Front	TY-04537BFQ	Tong Yang	5211978903	LX1000287
Lexus NX 200t, 15-16, w/o F Sport Pkg; w/Park Distance Sensors; w/o Headlamp Washers	Bumper Cover, Front	TY-04537BGQ	Tong Yang	5211978905	LX1000288
Lexus NX 300h, 15-16, w/o Headlamp Washers	Bumper Cover, Front	TY-04537BEQ	Tong Yang	5211978902	LX1000286

*This report includes all new, decertified and deleted parts from July 30, 2018 through August 03, 2018.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahall@intertek.com