

NEW PARTS CAPA 101 STANDARD - METALS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> | |
|--------------------------------|--------------------------------|----------------------------|---------------------|-------------------|-------------------------|-----------|
| 101 | Honda CR-V, 17 | Radiator Support | HDS60220A | Auto Power | 71411TLAA01 | HO1225193 |
| 101 | Honda CR-V, 17, 1.5L Turbo | Radiator Support | HDS60220-1A | Auto Power | 71411TLAA51 | HO1225192 |
| 101 | Honda CR-V, 17, 1.5L Turbo Eng | Radiator Support | HDS60220-1A | Auto Power | 71411TLAA52 | HO1225192 |
| 101 | Honda CR-V, 17-17 | Radiator Support | HDS60220A | Auto Power | 71411TLAA02 | HO1225193 |
| 101 | Mazda CX-9, 16-18, (HSS) | Support, Side R | MZS60234AR | Auto Power | TK4853140 | MA1225163 |
| 101 | Mazda CX-9, 16-18, (HSS) | Support, Side L | MZS60234AL | Auto Power | TK4854140 | MA1225164 |

NEW PARTS CAPA 201 STANDARD - PLASTICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> | |
|--------------------------------|---------------------------------------------------------------------------------------------------------|----------------------------|---------------------|-------------------|-------------------------|-----------|
| 201 | Ford Edge SE/SEL/Titanium, 15-16 | Panel, Valance Lower | FD-04474MBQ | Tong Yang | FT4Z8419APTM | FO1095254 |
| 201 | Honda Accord Sedan, 13-15 | Bumper Cover, Front | HD04335BBQ | TYG Products | 04711T2AA90ZZ | HO1000288 |
| 201 | Jeep Renegade, 15-16 | Support, Upper Radial | JPS6985A | Auto Power | 68256097AA | CH1225282 |
| 201 | Buick LaCrosse, 17 | Cover, Engine Under | BKE003NAQ | Pro Fortune | 23174967 | GM1228162 |
| 201 | Buick LaCrosse, 17-18 | Cover, Engine Under | BKE003NAQ | Pro Fortune | 84164882 | GM1228162 |
| 201 | Cadillac CTS, 08-13, Sedan | Deflector, Front Air | CDE002NAQ | Pro Fortune | 15263372 | GM1228127 |
| 201 | Cadillac CTS, 10-14, Wagon | Deflector, Front Air | CDE002NAQ | Pro Fortune | 15263372 | GM1228127 |
| 201 | Dodge Challenger, 15-17, SRT Hellcat, w/o Fog Lamps | Bumper Cover, Front | DGCLR15FB3 | Gordon | 68260156AC | CH1091108 |
| 201 | Dodge Challenger, 15-17, SRT Demon, w/o Fog Lamps | Bumper Cover, Front | DGCLR15FB3 | Gordon | 68260156AC | CH1091108 |
| 201 | Ford Explorer, 16-17, Police Model, 3.5L Turbo Eng. | Cover, Lower | FD-04500BAQ | Tong Yang | FB5Z17F828A | FO1115121 |
| 201 | Ford Explorer, 16-17, w/Active Park Assist, w/Towing Pkg | Cover, Lower | FD-04500BBQ | Tong Yang | FB5Z17K835BA | FO1115122 |
| 201 | Ford Explorer, 16-17, w/o Active Park Assist, w/Towing Pkg | Cover, Lower | FD-04500BAQ | Tong Yang | FB5Z17F828A | FO1115121 |
| 201 | Kia Sorento, 16-18, Limited | Cover, Upper Bumper | KA-04106BBQ | Tong Yang | 86511C6200 | KI1000174 |
| 201 | Kia Sorento, 16-18, SX Limited | Cover, Upper Bumper | KA-04106BBQ | Tong Yang | 86511C6200 | KI1000174 |
| 201 | Kia Sorento, 16-18, SX Model | Cover, Upper Bumper | KA-04106BBQ | Tong Yang | 86511C6200 | KI1000174 |
| 201 | Mercedes-Benz E-Class, 17, Sedan, w/o Active Park Assist | Bumper Cover, Front | BZ-04226BAQ | Tong Yang | 21388526009999 | BM1000534 |
| 201 | Mercedes-Benz E-Class, 17, Wagon, w/o Active Park Assist | Bumper Cover, Front | BZ-04226BAQ | Tong Yang | 21388526009999 | BM1000534 |
| 201 | Mercedes-Benz E-Class, 17-18, Sedan, w/ Active Park Assist | Bumper Cover, Front | BZ-04226BBQ | Tong Yang | 21388527009999 | BM1000533 |
| 201 | Mercedes-Benz E-Class, 17-18, Wagon, w/ Active Park Assist | Bumper Cover, Front | BZ-04226BBQ | Tong Yang | 21388527009999 | BM1000533 |
| 201 | Mercedes-Benz GLE-SUV, 16-17, (166), Plug-In, w/o Surround View | Grille | BZ-07172GAQ | Tong Yang | 1668880260 | MB1200196 |
| 201 | Mercedes-Benz GLE-SUV, 16-18, (166), GLE300d, GLE350, GLE350d, GLE400, GLE550, w/o Surround View Camera | Grille | BZ-07172GAQ | Tong Yang | 1668880260 | MB1200196 |
| 201 | Mercedes-Benz GLE-SUV, 16-18, (166), GLE43, GLE450, w/o Surround View Camera | Grille | BZ-07172GAQ | Tong Yang | 1668880260 | MB1200196 |
| 201 | Mercedes-Benz, E-Class, 17-18, Sedan, E300 RWD w/o Luxury Pkg | Cover, Engine Under | IBZE001NAQ | Pro Fortune | 2135200900 | MB1228174 |
| 201 | Mercedes-Benz, E-Class, 17-18, Sedan, E300 RWD w/o Luxury Pkg | Cover, Outer L | BZE002LAQ | Pro Fortune | 2135202500 | MB1228172 |
| 201 | Mercedes-Benz, E-Class, 17-18, Sedan, E300, w/o Luxury Pkg, w/Active Park Assist | Bumper Cover, Rear | BZB082NDQ | Pro Fortune | 21388508019999 | MB1100402 |
| 201 | Mercedes-Benz, E-Class, 17-18, Sedan, E300, w/o Luxury Pkg, w/o Active Park Assist | Bumper Cover, Rear | BZB082NCQ | Pro Fortune | 21388506019999 | MB1100401 |
| 201 | Mercedes-Benz, E-Class, 17-18, Sedan, E300 RWD w/o Luxury Pkg | Cover, Outer R | BZE002RAQ | Pro Fortune | 2135202600 | MB1228173 |
| 201 | Nissan Frontier, 02-06 | Bumper Cover, Front | DS-04225BAQ | Tong Yang | 62022VK300 | |
| 201 | Nissan Frontier, 02-06, FWD | Bumper Cover, Front | DS-04225BAQ | Tong Yang | 62022VK325 | |
| 201 | Nissan Pathfinder, 17-18 | Bumper Cover, Front | NI1000314 | Micro Rim | 620229PF0H | NI1000314 |
| 201 | Toyota Corolla, 17-19, CE, L, LE, LE Eco, XLE Model | Grille, Bumper | TYN161NBQ | Pro Fortune | 5311202730 | TO1036170 |

NEW PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

NEW PARTS CAPA 301 STANDARD - LIGHTING

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| 301 GMC Terrain Denali, 13-16 | Taillamp L | 335-1961L-AC | DEPO | 20987298 | GM2804114 |
| 301 GMC Terrain Denali, 13-16 | Taillamp R | 335-1961R-AC | DEPO | 20987299 | GM2805114 |
| 301 GMC Terrain, 13-17, Denali | Taillamp L | 335-1961L-AC | DEPO | 23389935 | GM2804114 |
| 301 GMC Terrain, 13-17, Denali | Taillamp R | 335-1961R-AC | DEPO | 23389936 | GM2805114 |
| 301 Toyota Camry XSE Model, LED, 15-17 | Headlamp Assy, R | 312-11F6RMACM7 | DEPO | 8111006C80 | TO2502228 |
| 301 Toyota Camry XSE Model, LED, 15-17 | Headlamp Assy, L | 312-11F6LMACM7 | DEPO | 8115006C80 | TO2503228 |
| 301 Audi Q5, 18-18 | Reflector, Side Marker | 346-1405L-UC | DEPO | 80A945071 | |
| 301 Audi Q5, 18-18 | Reflector, Side Marker | 346-1405R-UC | DEPO | 80A945072 | |
| 301 Audi SQ5, 18-18 | Reflector, Side Marker | 346-1405L-UC | DEPO | 80A945071 | |
| 301 Audi SQ5, 18-18 | Reflector, Side Marker | 346-1405R-UC | DEPO | 80A945072 | |
| 301 Chevrolet Silverado, 16-17 | Taillamp L | 11-6700-90-9 | TYC Brother | 23295938 | GM2800293 |
| 301 Chevrolet Silverado, 16-17 | Taillamp L | 11-6700-90-9 | TYC Brother | 84019503 | GM2800293 |
| 301 Chevrolet Silverado, 16-18 | Taillamp R | 11-6699-90-9 | TYC Brother | 23295939 | GM2801293 |
| 301 Chevrolet Silverado, 16-18 | Taillamp L | 11-6700-90-9 | TYC Brother | 84288722 | GM2800293 |
| 301 Chevrolet Silverado, 16-18 | Taillamp R | 11-6699-90-9 | TYC Brother | 84288723 | GM2801293 |

NEW PARTS CAPA 301 STANDARD - LIGHTING (EMC TESTED)

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

NEW PARTS CAPA 501 STANDARD - BUMPERS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| 501 BMW 2-Series, 14-18 | Bracket, Impact Bar L | BM45128LLH | Hui Yih | 51117266195 | BM1066110 |
| 501 BMW 2-Series, 14-18 | Bracket, Impact Bar R | BM45128LRH | Hui Yih | 51117266196 | BM1067110 |
| 501 BMW 3-Series, 13-15 | Bracket, Impact Bar L | BM45128LLH | Hui Yih | 51117266195 | BM1066110 |
| 501 BMW 3-Series, 13-18 | Bracket, Impact Bar R | BM45128LRH | Hui Yih | 51117266196 | BM1067110 |
| 501 BMW 4 Series, 14-18 | Bracket, Impact Bar L | BM45128LLH | Hui Yih | 51117266195 | BM1066110 |
| 501 BMW 4 Series, 14-18 | Bracket, Impact Bar R | BM45128LRH | Hui Yih | 51117266196 | BM1067110 |
| 501 Toyota C-HR, 18 | Absorber, Energy | TA1R124AQ | Cobra King | 52611F4020 | TO1070214 |

NEW PARTS CAPA 601 STANDARD - RADIATORS

| <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer Number</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|--------------------------------|-------------------------|----------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DECERTIFICATIONS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| DGDN11FR1 | Dodge Durango, 11 | Fender R | Gordon | 07/16A | 55369734AA | CH1241273 |
| DGDN11FR1 | Dodge Durango, 11-15 | Fender R | Gordon | 07/16A | 55369734AB | CH1241273 |
| DGDN11FR1 | Dodge Durango, 11-18 | Fender R | Gordon | 07/16A | 55369734AC | CH1241273 |
| HD-20099AQ | Honda CR-V, 12-16 | Hood | Tong Yang | 10/17A | 60100T0JA91ZZ | HO1230177 |

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|-------------------------------------------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| FD-04426BEQ | Ford Fusion Energi, 13-16, w/o Towing hook w/o Active park assist | Bumper Cover, Front | Tong Yang | 03/18B | DS7Z17D957AAP | FO1000680 |



**WEEKLY PARTS UPDATE
August 20, 2018**

[Report: P6]
Weekly

CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|----------------------------------------------------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| FD-04426BEQ | Ford Fusion Hybrid, 13-16, w/o Towing hook w/o Active park assist | Bumper Cover, Front | Tong Yang | 03/18B | DS7Z17D957AAP | FO1000680 |
| FD-04426BEQ | Ford Fusion, 13-16, Hybrid, w/o Towing Hook, w/o Active Park Assist, Prime | Bumper Cover, Front | Tong Yang | 03/18B | DS7Z17D957AACI | FO1000680 |
| FD-04426BEQ | Ford Fusion, 13-16, w/o Towing hook w/o Active park assist | Bumper Cover, Front | Tong Yang | 03/18B | DS7Z17D957AAP | FO1000680 |
| FD-04426BEQ | Ford Fusion, 13-16, w/o Towing Hook, w/o Active Park Assist, Prime | Bumper Cover, Front | Tong Yang | 03/18B | DS7Z17D957AACI | FO1000680 |

CAPA 202 STANDARD - NON-WOVEN FABRICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

CAPA 601 STANDARD - RADIATORS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|------------|-------------------|-------------------------|
| NONE | | | | | | |

DELETED PARTS CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|-----------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| S0295F200AS | Jeep Grand Cherokee, 93-98 | Fender R | Jui Li | 55031834 | CH1241202 |
| S0295F100AS | Jeep Grand Cherokee, 93-98 | Fender L | Jui Li | 55031835 | CH1240202 |
| S0629H000AS | Jeep Liberty Limited/Sport, 02-07 | Hood | Jui Li | 55177200AF | CH1230247 |
| S0229H000AS | Jeep Liberty, 02 | Hood | Jui Li | 55177200AB | CH1230220 |
| S0229H000AS | Jeep Liberty, 02-03 | Hood | Jui Li | 55177200AC | CH1230220 |
| S0229F200AS | Jeep Liberty, 02-04 | Fender R | Jui Li | 55177100AD | CH1241231 |
| S0229F200AS | Jeep Liberty, 02-04 | Fender R | Jui Li | 55177100AE | CH1241231 |
| S0229F100AS | Jeep Liberty, 02-04 | Fender L | Jui Li | 55177101AD | CH1240231 |
| S0229F100AS | Jeep Liberty, 02-04 | Fender L | Jui Li | 55177101AE | CH1240231 |
| S0229H000AS | Jeep Liberty, 02-07 | Hood | Jui Li | 55177200AD | CH1230220 |

DELETED PARTS CAPA 201 STANDARD - PLASTICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 202 STANDARD - NON-WOVEN FABRICS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 301 STANDARD - LIGHTING

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 501 STANDARD - BUMPERS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

DELETED PARTS CAPA 601 STANDARD - RADIATORS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|-------------------------|---------------------|-------------------|-------------------------|
| NONE | | | | | |

CORRECTION

The following parts were listed as deleted on the August 13, 2018 Weekly Parts Update.
Upon further review, these parts were not deleted during the period covered by that report.

DELETED PARTS CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|---------------------------------|---------------------|-------------------|-------------------------|
| 101 | FD-10126AQ-RH | Ford Escape, 01-07, w Fender R | Tong Yang | YL8Z16005BA | FO1241219 |
| 101 | FD-10126AQ-LH | Ford Escape, 01-07, w Fender L | Tong Yang | YL8Z16006BA | FO1240219 |
| 101 | FD-10126BQ-RH | Ford Escape, 01-07, w Fender R | Tong Yang | YL8Z16005DA | FO1241215 |
| 101 | FD-10126BQ-LH | Ford Escape, 01-07, w Fender L | Tong Yang | YL8Z16006DA | FO1240215 |
| 101 | FD-10105BQ-RH | Ford Focus, 00-04 Fender R | Tong Yang | YS4Z16005CA | FO1241207 |
| 101 | FD-10105BQ-LH | Ford Focus, 00-04 Fender L | Tong Yang | YS4Z16006CA | FO1240207 |
| 101 | FD-10126DQ-RH | Mercury Mariner HEV, Fender R | Tong Yang | 5E6Z16005AA | FO1241253 |
| 101 | FD-10126DQ-LH | Mercury Mariner HEV, Fender L | Tong Yang | 5E6Z16006AB | FO1240253 |
| 101 | FD-10126DQ-RH | Mercury Mariner, 05-0 Fender R | Tong Yang | 5E6Z16005AA | FO1241253 |
| 101 | FD-10126DQ-LH | Mercury Mariner, 05-0 Fender L | Tong Yang | 5E6Z16006AB | FO1240253 |
| 101 | MB-10045BQ-LH | Mitsubishi Eclipse GT/ Fender L | Tong Yang | MR392631 | MI1240142 |
| 101 | DS-10116AQ-RH | Nissan Altima, 02-06 Fender R | Tong Yang | 631128J030 | NI1241171 |
| 101 | DS-10116AQ-LH | Nissan Altima, 02-06 Fender L | Tong Yang | 631138J030 | NI1240171 |
| 101 | CV-10096AQ-LH | Pontiac G5, 07-09 Fender L | Tong Yang | 15793419 | GM1240324 |
| 101 | CV-10096AQ-RH | Pontiac G5, 07-09 Fender R | Tong Yang | 22693944 | GM1241324 |
| 101 | CV-10096AQ-LH | Pontiac G5, 07-09 Fender L | Tong Yang | 22693945 | GM1240324 |
| 101 | CV-10096AQ-RH | Pontiac G5, 07-10 Fender R | Tong Yang | 15793420 | GM1241324 |
| 101 | PT-10025AQ-RH | Pontiac Grand Prix Ba Fender R | Tong Yang | 89023494 | GM1241298 |

The following part lot was listed as decertified on the August 13, 2018 Weekly Parts Update.
Upon further review, this part lot was not decertified during the period covered by that report.

CAPA 101 STANDARD - METALS

| <u>Manufacturer Number</u> | <u>Application Description</u> | <u>Part Description</u> | <u>Manufacturer</u> | <u>Lot</u> | <u>OEM Number</u> | <u>PartsLink Number</u> |
|----------------------------|--------------------------------|--------------------------|---------------------|------------|-------------------|-------------------------|
| 101 | HDOD08HD1 | Honda Odyssey, 08-11Hood | Gordon | 04/18A | 60100SHJA9 | HO1230161 |

*This report includes all new, decertified and deleted parts from August 13, 2018 through August 17, 2018.

All CAPA reports including the weekly update are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com