

DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations, regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Decertification Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Decertified Part Reimbursement Program 4700 Broadmoor SE, Suite 200, Kentwood, MI 49512 or FAX (616) 245.5347.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
DGDN11FR1	Dodge Durango, 11-18	Fender R	Gordon	07/16A	55369734AC	CH1241273
DGPU09TG1	Dodge Ram R3500/R2500 Pick-up, 10-14	Tailgate	Gordon	11/16A	68105727AE	CH1900129
HD-20099AQ	Honda CR-V, 12-16	Hood	Tong Yang	10/17A	60100T0JA91ZZ	HO1230177
MZA609FL1	Mazda 6, 09-13	Fender L	Gordon	06/17A	GS3L52210A	MA1240160
S0851F100AS	Mazda 6, 09-13	Fender L	Jui Li	06/17A	GS3L52210A	MA1240160
S0721H000AS	Mazda CX-9, 07-14	Hood	Jui Li	04/18A	TDY15231XE	MA1230164
MD0720160-0LOC	Mercedes-Benz C-Class Sedan, 15-16	Fender L	AP	05/17B	2058800118	MB1240150
MB2450150-000C	Mitsubishi Lancer, 08-11, 16-17	Hood	AP	03/18A	5900A209	MI1230213
MION10HD1	Mitsubishi Outlander, 10-13	Hood	Gordon	03/18A	5900A393	MI1230216
DT2010150-100C	Nissan Versa Hatchback/Sedan, 07-09	Hood	AP	04/18A	F5100EL030	NI1230174
TA4H001Q	Toyota Camry, 12-14	Hood	Cobra King	02/18A	5330106150	TO1230225
DJ-LA09401	Toyota Corolla, 09-13, (USA)	Hood	Da Juane	03/18B	5330102210	TO1230211
S0489H000AS	Toyota Sienna, 04-10	Hood	Jui Li	02/18A	53301AE020	TO1230194
TY-20115AQ	Toyota Sienna, 04-10	Hood	Tong Yang	02/18A	53301AE020	TO1230194
TYSN10F21	Toyota Sienna, 11-14, w/antenna	Fender R	Gordon	05/17A	5381108050	TO1241235

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
AU0710870-000C	Audi A3, 15-16, Sedan, w/Parking Aid, w/o Parallel Park Assist	Bumper Cover, Rear Assy	AP-Procom	10/17A	8V5807067AGRU	AU1100216
FDS6821A	Ford Fusion, 13-16	Reinf, Front Panel	Auto Power	06/18A	DS7Z8A284ACP	FO1227103
FD-04426BEQ	Ford Fusion, 13-16, w/o Towing Hook, w/o Active Park Assist, Prime	Bumper Cover, Front	Tong Yang	03/18B	DS7Z17D957AACP	FO1000680
Y-HDBP147ACA	Honda Odyssey EX/EX-L/LX, 05-07	Bumper Cover, Front	Y.C.C.	04/18A	04711SHJA90ZZ	HO1000222
HD04146BDQ	Honda Odyssey Touring, 05-07	Bumper Cover, Front	TYG Products	17/12/07	04711SHJA80ZZ	HO1000223
MB-04146BBQ	Mitsubishi Lancer, 08-17, w/o Turbo	Bumper Cover, Rear	Tong Yang	01/18B	6410B832	MI1100287
Y-DSBP248ACA	Nissan Altima Sedan, 16-18, w/o Distance sensors	Bumper Cover, Front	Y.C.C.	01/18A	620229HS0H	NI1000311
DS-04232BBQ	Nissan Versa Sedan, 07-11	Bumper Cover, Front	Tong Yang	06/16A	FBM229EG0J	NI1000245
Y-TYBP321ACA	Toyota RAV-4, 16-17, North America built, w/o Parking sensors	Bumper Cover, Front	Y.C.C.	05/18A	521190R914	TO1014105
TY-04251BCQ	Toyota Tacoma, 05-11, 2.7L eng., w/o SR5/Pre-Runner	Bumper Cover, Front	Tong Yang	10/17A	5211904040	TO1000302

CAPA 202 STANDARD - NON-WOVEN FABRICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
FO1002422DSC	Ford Pickup F150, 15-17, Crew Cab, Argent w/o Fog Lamps	Beam, Bumper	PBSI-DS	18054	FL3Z17757ACP	FO1002423



MONTHLY DECERTIFICATION REPORT September 2018*

[Report: P8]
Monthly

DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations, regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Decertification Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Decertified Part Reimbursement Program 4700 Broadmoor SE, Suite 200, Kentwood, MI 49512 or FAX (616) 245.5347.

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all decertifications from August 1, 2018 through August 31, 2018.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahal@intertek.com.