

DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations, regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Decertification Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Decertified Part Reimbursement Program 4700 Broadmoor SE, Suite 200, Kentwood, MI 49512 or FAX (616) 245.5347.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CDCT08HD1	Cadillac CTS, 08-13, Sedan, Aluminium	Hood	Gordon	08/17A	19354897	GM1230383
CV9K001Q	Chevrolet Silverado 1500, 07-13	Hood	Cobra King	02/18A	20863101	GM1230365
CVSR07HD1	Chevrolet Silverado 1500, 07-13	Hood	Gordon	04/18A	20863101	GM1230365
WL-458AQ-LH	Jeep Wrangler, 07-17	Fender L	William	01/17A	68029993AB	CH1240257
WL-458AQ-LH	Jeep Wrangler, 07-17	Fender L	William	01/18A	68029993AB	CH1240257

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
AM-04032BCQ	Jeep Liberty, 08-12, w/o Chrome Insert	Bumper Cover, Front	Tong Yang	05/18A	68033628AC	CH1000936
DG-04109BBQ	Dodge Avenger, 11-14	Bumper Cover, Rear	Tong Yang	06/18A	68081863AC	CH1100961
DG-04130BCQ	Dodge Journey, 09-16, w/o Chrome w/o Parking Sensors	Fascia, Upper	Tong Yang	06/18A	1TY37TZZAF	CH1114102
DS-04329BBQ	Nissan Maxima, 09-14	Bumper Cover, Rear	Tong Yang	03/18B	850229N00H	NI1100264
DS-04343BBQ	Nissan Pathfinder, 13-16	Bumper Cover, Front	Tong Yang	01/18A	620223KA0H	NI1000288
DT2010000-200C	Nissan Versa Hatchback, 07-12, w/o Sport	Bumper Cover, Front	AP-Procom	11/17A	FBM229EG0J	NI1000245
FD-04417BDQ	Ford Taurus Police Model, 13-15, w/Rear object sensors	Bumper Cover, Rear	Tong Yang	11/17A	DG1Z17K835GAPT	FO1100685
FDB128NBQ	Ford Escape, 08-12, Hybrid, w/o Rear Object Sensor, w/o Towing Pkg, Prime	Bumper Cover, Rear	Pro Fortune	01/18B	8L8Z17K835ACP	FO1100629
SBB014NBQ	Subaru Outback, 15-17	Bumper Cover, Rear	Pro Fortune	06/18A	57704AL11B	SU1100175
Y-CRBP061CA	Dodge Charger, 11-14, w/o SRT & w/o adaptive speed control	Bumper Cover, Front	Y.C.C.	01/18A	68092596AA	CH1000992
Y-GMBP453CA	Chevrolet Equinox, 10-15	Bumper Cover, Front	Y.C.C.	10/17A	20983230	GM1000907

CAPA 202 STANDARD - NON-WOVEN FABRICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
NONE						

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
K35-1963L-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp L	DEPO	20160621	84247728	GM2804116
K35-1963L-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp L	DEPO	20160913	84247728	GM2804116
K35-1963L-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp L	DEPO	20170825	84247728	GM2804116
K35-1963L-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp L	DEPO	20180104	84247728	GM2804116
K35-1963L-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp L	DEPO	20180330	84247728	GM2804116
K35-1963L-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp L	DEPO	20180608	84247728	GM2804116
K35-1963R-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp R	DEPO	20160621	84247727	GM2805116
K35-1963R-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp R	DEPO	20160913	84247727	GM2805116
K35-1963R-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp R	DEPO	20170825	84247727	GM2805116
K35-1963R-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp R	DEPO	20180104	84247727	GM2805116
K35-1963R-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp R	DEPO	20180330	84247727	GM2805116
K35-1963R-AC	Chevrolet Impala, 14-14, ECO, 1st/2nd Design, On body	Taillamp R	DEPO	20180608	84247727	GM2805116

CAPA 501 STANDARD - BUMPER PARTS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
TY54142AH	Toyota Corolla, 14-18	Bar, Reinforcement	Hui Yih	04/18A	5217102230	TO1106218



MONTHLY DECERTIFICATION REPORT October 2018*

[Report: P8]
Monthly

DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations, regardless of the significance. Your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Decertification Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Decertified Part Reimbursement Program 4700 Broadmoor SE, Suite 200, Kentwood, MI 49512 or FAX (616) 245.5347.

CAPA 601 STANDARD - RADIATORS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE					

*This report includes all decertifications from September 1, 2018 through September 30, 2018.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at jillian.rahall@intertek.com.