

## PUBLIC SAFETY NOTICE

### Intertek Warns of Potential Safety-Related Issue with Reinforcement Bar Bearing a CAPA Quality Seal

Published: April 20, 2022

The following is a notification from Intertek that the Auto Power Reinforcement Bar identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

<b>Product Description</b>		Bar, Reinforcement					
<b>Make</b>	<b>Model</b>	<b>Years</b>	<b>Details</b>	<b>AM Part Number</b>	<b>OEM Part Number</b>	<b>PartsLink Number</b>	<b>Country</b>
Kia	Soul	2020	1.6L Turbo Eng	KAR2734-1A	64900K0150	KI1006172	US
<b>Manufacturer</b>		Auto Power Enterprise Co., Ltd.					
<b>Number of Units</b>		183					
<b>Lot Numbers</b>		12/20A					
<b>Potential Hazard</b>		The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					
<b>Sold By</b>		Distributors of aftermarket parts					
<b>What To Do</b>		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Auto Power directly.					