

**PUBLIC SAFETY NOTICE**

**Intertek Warns of Potential Safety-Related Issue with Tie Bar, Upper Bearing a CAPA Quality Seal**

Published: October 26, 2022

The following is a notification from Intertek that the Tong Yang Tie Bar, Upper identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

<b>Product Description</b>		Tie Bar, Upper					
<b>Make</b>	<b>Model</b>	<b>Years</b>	<b>Details</b>	<b>AM Part Number</b>	<b>OEM Part Number</b>	<b>PartsLink Number</b>	<b>Country</b>
Mercedes-Benz	E-Class	2018-2022	Coupe	BZ-03011AQ	2136206300	MB1225189	US
Mercedes-Benz	E-Class	2017-2022	Sedan; E300, E350, E400, E450, E43, E53	BZ-03011AQ	2136206300	MB1225189	US
Mercedes-Benz	E-Class	2017-2021	Wagon; E400, E450, E53	BZ-03011AQ	2136206300	MB1225189	US
Mercedes-Benz	E-Class	2018-2022	Convertible	BZ-03011AQ	2136206300	MB1225189	US
Mercedes-Benz	CLS	2019-2022	N/A	BZ-03011AQ	2136206300	MB1225189	US
<b>Manufacturer</b>		Tong Yang					
<b>Number of Units</b>		128					
<b>Lot Numbers</b>		06/18A, 11/19A, 09/21A					
<b>Potential Hazard</b>		Mounting features too large for proper part installation in vehicle					
<b>Sold By</b>		Distributors of aftermarket parts					
<b>What To Do</b>		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Tong Yang directly.					