

**PUBLIC SAFETY NOTICE**

**Intertek Warns of Potential Safety-Related Issue with Radiator Supports Bearing a CAPA Quality Seal**

Published: February 23, 2023

The following is a notification from Intertek that the Tong Yang radiator supports identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

<b>Product Description</b>		Radiator Support					
<b>Make</b>	<b>Model</b>	<b>Years</b>	<b>Details</b>	<b>AM Part Number</b>	<b>OEM Part Number</b>	<b>PartsLink Number</b>	<b>Country</b>
Honda	Civic	2018-2019	Coupe, Front, Si Model	HD-03001DQ	71410TBFA11	HO1225201	US
<b>Manufacturer</b>		Tong Yang Industry Co., Ltd.					
<b>Number of Units</b>		180					
<b>Lot Numbers</b>		09/19A, 09/20A, 08/21A, 11/21A, 06/22A, 12/22A					
<b>Potential Hazard</b>		Parts may exhibit a separation of metal surrounding a mounting hole near the hood latch mounting area, which could affect the proper function of the hood latch. To date, no complaints have been reported.					
<b>Sold By</b>		Distributors of aftermarket parts					
<b>What To Do</b>		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Tong Yang directly.					