



## PUBLIC SAFETY NOTICE

### Intertek Warns of Potential Safety-Related Issue with Right Headlamp Assembly Bearing a CAPA Quality Seal

Published: November 07, 2023

Revised: June 03, 2024

The following is a notification from Intertek that the TYC headlamp identified below bearing the CAPA certification mark (CAPA Quality Seal) has been determined to pose a potential safety hazard.

<b>Product Description</b>		Headlamp Assembly, R					
<b>Make</b>	<b>Model</b>	<b>Years</b>	<b>Details</b>	<b>AM Part Number</b>	<b>OEM Part Number</b>	<b>PartsLink Number</b>	<b>Country</b>
Jeep	Compass	17-21		20-9981-00-9	55112706AF	CH2503295	US
<b>Manufacturer</b>		TYC Brother Industrial Co., Ltd.					
<b>Number of Units</b>		6,953					
<b>Lot Numbers</b>		04272010, 10052010, 11162010, 12142010, 02082110, 03152110, 03292110, 04052110, 04122110, 04192110, 08302110, 09202110, 10042110, 11012110, 01032210, 02142210, 03072210, 04042210, 05022210, 05162210, 06132210, 07042210, 07252210, 08082210, 09122210, 09262210, 10102210, 10242210, 11072210, 11142210, 11282210, 12052210, 12122210, 01162310, 02062310, 02132310, 02202310, 02272310, 03062310, 03272310, 04102310, 05292310, 06192310					
<b>Potential Hazard</b>		The low beam function may become inoperable. If this were to occur, driver and oncoming traffic visibility would be impaired.  To date, 4 complaints have been received.					
<b>Sold By</b>		Distributors of aftermarket parts					
<b>What To Do</b>		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact TYC directly.					