

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Radiator Supports Bearing a CAPA Quality Seal

Published: January 12, 2023

The following is a notification from Intertek that the Tong Yang radiator supports identified below bearing the CAPA certification mark (CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Radiator Support					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Honda	Civic	2016-2019	2.0L Eng, Sedan	HD-03001AQ	71410TBAA01	HO1225183	US
Honda	Civic	2016-2017	Coupe, LX, LX-P	HD-03001AQ	71410TBAA01	HO1225183	US
Manufacturer		Tong Yang Industry Co., Ltd.					
Number of Units		7,904					
Lot Numbers		05/17A, 07/17A, 08/17A, 12/17A, 03/18A, 04/18A, 05/18A, 05/18B, 06/18A, 07/18A, 08/18A, 10/18A, 11/18A, 12/18A, 12/18B, 01/19A, 02/19A, 03/19A, 04/19A, 04/19B, 05/19A, 07/19A, 08/19A, 09/19A, 09/19B, 10/19A, 10/19B, 11/19A, 12/19A, 01/20A, 01/20B, 02/20A, 02/20B, 03/20A, 07/20A, 07/20B, 08/20A, 09/20A, 09/20B, 10/20A, 10/20B, 11/20A, 12/20A, 01/21A, 02/21A, 03/21A, 03/21B, 04/21A, 06/21A, 06/21B, 07/21A, 07/21B, 07/21C, 09/21A, 09/21B, 10/21A, 11/21A, 11/21B, 11/21C, 12/21A, 12/21B, 01/22A, 02/22A, 03/22A, 04/22A, 05/22A, 06/22A, 07/22A, 08/22A, 09/22A, 09/22B, 10/22A, 10/22B, 12/22A, 12/22B					
Potential Hazard		Parts may exhibit a separation of metal surrounding a mounting hole near the hood latch mounting area, which could affect the proper function of the hood latch. To date, no complaints have been reported.					
Sold By		Distributors of aftermarket parts					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Tong Yang directly.					