

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Rear Bumper Assemblies Bearing a CAPA Quality Seal

Published: March 18, 2019

The following is a notification from Intertek that the *Hui Yih* rear bumper assemblies identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Bumper, Rear Assembly					
Make	Model	Years	Details	AM Part Number	OEM Part Number	PartsLink Number	Country
Ford	F150 Pickup	2015-2018	w/Rear Parking Aid; w/Towing Pkg, w/o Max Towing, Chrome	FD50151GH	N/A	FO1103189	US
Manufacturer		Hui Yih Industrial Co., Ltd.					
Number of Units		≤ 30					
Lot Numbers		Any assembly which includes rear bumper bar reinforcement, AM Part Number FD54151AH, lot number 03/18B.					
Potential Hazard		The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					
Sold By		Distributors of aftermarket parts.					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Hui Yih directly.					