

**PUBLIC SAFETY NOTICE**

**Intertek Warns of Potential Safety-Related Issue with Rear Bumper Reinforcements (Rebars) Bearing a CAPA Quality Seal**

Published: March 13, 2019

The following is a notification from Intertek that the *Hui Yih* rear bumper reinforcements (rebars) identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

<b>Product Description</b>		Reinforcement, Bumper Rear					
<b>Make</b>	<b>Model</b>	<b>Years</b>	<b>Details</b>	<b>AM Part Number</b>	<b>OEM Part Number</b>	<b>PartsLink Number</b>	<b>Country</b>
Toyota	Tundra	2014-2017		TY54145AH	520230C122	TO1106222	US
<b>Manufacturer</b>		Hui Yih Industrial Co., Ltd.					
<b>Number of Units</b>		135					
<b>Lot Numbers</b>		01/18A, 08/18A					
<b>Potential Hazard</b>		The material used to produce certified products may not be the same material used when certification was achieved. In instances where the same materials are not used, it may result in a product that does not meet CAPA requirements for comparable performance to the car company brand counterpart. To date, no complaints have been reported.					
<b>Sold By</b>		Distributors of aftermarket parts.					
<b>What To Do</b>		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Hui Yih directly.					