

PUBLIC SAFETY NOTICE

Intertek Warns of Potential Safety-Related Issue with Rear Bumper Covers Bearing a CAPA Quality Seal

Published: 31 May 2019

The following is a notification from Intertek that the Y.C.C. rear bumper covers identified below bearing the CAPA Certification Mark (i.e., CAPA Quality Seal) have been determined to pose a potential safety hazard.

Product Description		Bumper Cover, Rear					
Make	Model	Years	Details	AM Part Number	OEM Part Number	Partslink Number	Country
Chrysler	200 Sedan	2015-2017	w/Exhaust opening, w/o Park assist	Y-CRBP074ACA	5NH89TZZAD	CH1100994	US
Manufacturer		Y.C.C. Parts Manufacturing Co., Ltd.					
Number of Units		135					
Lot Numbers		09/17A					
Potential Hazard		The manufacturer has made unauthorized changes, including, but not limited to alterations to the attachment method for the brackets that retains ADAS sensors. These changes are not comparable to those utilized by the OEM and may not perform in a comparable manner, potentially impacting the functionality of the ADAS system, and which poses a potential safety-related issue.					
Sold By		Distributors of aftermarket parts.					
What To Do		Installers of the part may contact the distributor who sold the part for advisement. Distributors holding parts may contact Y.C.C. directly.					