

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 101 STANDARD - METALS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
CV-10077AQ-LH	Chevrolet Impala, 00-05	Fender L	Tong Yang	12/13A	89025179	GM1240273
S0317F100AS	Chevrolet Impala, 00-05	Fender L	Jui Li	12/13A	89025179	GM1240273
CV6400150-000C	Chevrolet Trailblazer, 02-09	Hood	AP	01/15A	12478013	GM1230264
CVH043A	Chevrolet Trailblazer, 02-09	Hood	Auto Power	01/15A	12478013	GM1230264
CV-20058AQ	GMC Sierra, 99-07	Hood	Tong Yang	02/15A	12477699	GM1230236
CV-20058AQ	GMC Sierra, 99-07	Hood	Tong Yang	10/14A	12477699	GM1230236
CV-20058AQ	GMC Yukon XL/Denali, 01-06	Hood	Tong Yang	02/15A	12477699	GM1230236
CV-20058AQ	GMC Yukon XL/Denali, 01-06	Hood	Tong Yang	10/14A	12477699	GM1230236
HD6710150-000C	Honda CR-V, 12-13	Hood	AP	12/14A	60100T0AA90ZZ	HO1230168
HD6710150-000C	Honda CR-V, 12-14	Hood	AP	12/14A	60100T0JA90ZZ	HO1230168
HD-20048AQ	Honda Element, 03-08	Hood	Tong Yang	01/15A	60100SCVA90ZZ	HO1230142
S0411H000AS	Honda Element, 03-08	Hood	Jui Li	01/15A	60100SCVA90ZZ	HO1230142
KA63001Q	Kia Optima Hybrid, 11-12	Hood	Cobra King	01/15A	664002T000	KI1230128
KA63001Q	Kia Optima Hybrid, 11-12	Hood	Cobra King	12/14A	664002T000	KI1230128
KA63001Q	Kia Optima Hybrid, 11-15	Hood	Cobra King	01/15A	664002T010	KI1230128
KA63001Q	Kia Optima Hybrid, 11-15	Hood	Cobra King	12/14A	664002T010	KI1230128
KA63001Q	Kia Optima, 11-13	Hood	Cobra King	01/15A	664002T000	KI1230128
KA63001Q	Kia Optima, 11-13	Hood	Cobra King	12/14A	664002T000	KI1230128
KA63001Q	Kia Optima, 11-15	Hood	Cobra King	01/15A	664002T010	KI1230128
KA63001Q	Kia Optima, 11-15	Hood	Cobra King	12/14A	664002T010	KI1230128
S0737F200AS	Lexus IS 250, 06-10	Fender R	Jui Li	08/13A	5380153070	LX1241111
S0737F100AS	Lexus IS 250, 06-10	Fender L	Jui Li	12/13A	5380253071	LX1240111
S0737F200AS	Lexus IS 250, 11-13, w/o Sport pkg	Fender R	Jui Li	08/13A	5380153070	LX1241111
S0737F100AS	Lexus IS 250, 11-13, w/o Sport pkg	Fender L	Jui Li	12/13A	5380253071	LX1240111
S0737F200AS	Lexus IS 350, 06-10	Fender R	Jui Li	08/13A	5380153070	LX1241111
S0737F100AS	Lexus IS 350, 06-10	Fender L	Jui Li	12/13A	5380253071	LX1240111
S0737F200AS	Lexus IS 350, 11-13, w/o Sport pkg	Fender R	Jui Li	08/13A	5380153070	LX1241111
S0737F100AS	Lexus IS 350, 11-13, w/o Sport pkg	Fender L	Jui Li	12/13A	5380253071	LX1240111
MZA506FL1	Mazda 5, 06-07, w/o Rocker mldg	Fender L	Gordon	02/13A	C23552211B	MA1240157
MZA506FL1	Mazda 5, 06-10, w/o Rocker mldg	Fender L	Gordon	02/13A	C23552211C	MA1240157
DS-10160AQ-RH	Nissan Altima Hybrid, 07-08	Fender R	Tong Yang	03/14A	63100JA030	NI1241186
DS-10160AQ-RH	Nissan Altima Hybrid, 07-11	Fender R	Tong Yang	03/14A	63100ZN55A	NI1241186
DS-10160AQ-RH	Nissan Altima Sedan, 07-08	Fender R	Tong Yang	03/14A	63100JA030	NI1241186
DS-10160AQ-RH	Nissan Altima Sedan, 07-12	Fender R	Tong Yang	03/14A	63100ZN55A	NI1241186
DS-10116AQ-RH	Nissan Altima, 02-06	Fender R	Tong Yang	10/14A	631128J030	NI1241171
S0261F200AS	Nissan Altima, 02-06	Fender R	Jui Li	10/14A	631128J030	NI1241171
SBS6681A	Subaru Legacy, 05-09	Tie Bar, Upper	Auto Power	06/14A	53060AG00A9P	SU1225142
SBS6681A	Subaru Legacy, 05-09	Tie Bar, Upper	Auto Power	07/13A	53060AG00A9P	SU1225142
SBS6681A	Subaru Outback, 05-09	Tie Bar, Upper	Auto Power	06/14A	53060AG00A9P	SU1225142
SBS6681A	Subaru Outback, 05-09	Tie Bar, Upper	Auto Power	07/13A	53060AG00A9P	SU1225142
TY7510150-000C	Toyota Sienna, 98-03	Hood	AP	12/14A	5330108020	TO1230174

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
BKB026NCQ	Buick LaCrosse CX, 06-09, w/Chrome Pkg	Bumper Cover, Rear	Pro Fortune	05/14A	19120176	GM1100708
BKB026NCQ	Buick LaCrosse CXL, 05-09, w/Chrome Pkg, w/o Object Sensor	Bumper Cover, Rear	Pro Fortune	05/14A	19120176	GM1100708

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
BKB026NCQ	Buick LaCrosse CXS, 05-08, w/Chrome Pkg, w/o Object Sensor	Bumper Cover, Rear	Pro Fortune	05/14A	19120176	GM1100708
CDB006NDQ	Cadillac CTS, 08-13, w/o Object Sensors	Bumper Cover, Rear	Pro Fortune	06/14A	15896232	GM1100813
CDB006NDQ	Cadillac CTS, 08-13, w/o Object Sensors	Bumper Cover, Rear	Pro Fortune	06/14B	15896232	GM1100813
GMCIMPA-R06DNEW	Chevrolet Impala LS/LT, 12-15	Bumper Cover, Rear	Micro Rim	H3614	19120961	GM1100736
GMCIMPA-R06DNEW	Chevrolet Impala LTZ, 06-13	Bumper Cover, Rear	Micro Rim	H3614	19120961	GM1100736
GMCIMPA-R06DNEW	Chevrolet Impala SS, 06-09	Bumper Cover, Rear	Micro Rim	H3614	19120961	GM1100736
GMCIMPA-R06DNEW	Chevrolet Impala, 06-13, Police Model	Bumper Cover, Rear	Micro Rim	H3614	19120961	GM1100736
CV-04238BDQ	Chevrolet Malibu Eco, 13-15, w/o Rear Vision Camera; w/o Park Assist	Bumper Cover, Rear	Tong Yang	10/14A	22827126	GM1100894
CV-04238BDQ	Chevrolet Malibu, 13-15, w/o Rear Vision Camera, w/o Park Assist	Bumper Cover, Rear	Tong Yang	10/14A	22827126	GM1100894
Y-CRBP061CA	Dodge Charger, 11-14, w/o SRT & w/o adaptive speed control	Bumper Cover, Front	Y.C.C.	02/15A	68092596AA	CH1000992
Y-CRBP041CA	Dodge Dakota, 05, w/o Chrome, Paint to Match	Bumper Cover, Front	Y.C.C.	01/15A	5JL35TZZAD	CH1000444
Y-CRBP041CA	Dodge Dakota, 05-06, w/o Chrome, Paint to Match	Bumper Cover, Front	Y.C.C.	01/15A	5JL35TZZAE	CH1000444
Y-CRBP041CA	Dodge Dakota, 05-07, w/o Chrome, Paint to Match	Bumper Cover, Front	Y.C.C.	01/15A	5JL35TZZAF	CH1000444
DG04082BBQ	Dodge Pickup (New Style), 06-08, w/o Chrome, w/Bright Insert	Bumper Cover, Front	TYG Products	14/02/05	68001358AA	CH1000872
FD-04286BBQ	Ford Expedition Eddie Bauer/Limited, 07-11	Bumper Cover, Front Lower	Tong Yang	06/14A	7L1Z17D957CPTM	FO1000630
FD-04286BBQ	Ford Expedition XLT, 07-11, w/appearance pkg	Bumper Cover, Front Lower	Tong Yang	06/14A	7L1Z17D957CPTM	FO1000630
FD-04286BBQ	Ford Expedition, 07-14, Paint to match	Bumper Cover, Front Lower	Tong Yang	06/14A	CL1Z17D957BPTM	FO1000630
FD-04204PFQ	Ford F150 Pickup, 05-08, w/o wheel opng	Bumper Cover, Front	Tong Yang	08/14A	6L3Z17D957AAPT	FO1000616
Y-FDBP083CA	Ford Focus Hatchback/Sedan, 12-14	Bumper Cover, Front	Y.C.C.	02/15A	BM5Z17D957CAPTM	FO1000664
Y-FDAR447RCA	Ford F-Series Super Duty Pickup, 11-14, 2WD	Panel, Valance	Y.C.C.	01/15A	BC3Z17626AA	FO1095241
Y-FDAR446RCA	Ford F-Series Super Duty Pickup, 11-14, 4WD	Panel, Valance	Y.C.C.	01/15A	BC3Z17626BA	FO1095242
Y-FDBP081CA	Ford Fusion Hybrid, 10-12	Bumper Cover, Rear	Y.C.C.	10/14A	AE5Z17K835AAPT	FO1100649
FD-04301BBQ	Ford Fusion, 08-09, 2.3L eng	Bumper Cover, Rear	Tong Yang	09/14A	8E5Z17K835GACP	FO1100592
FD-04301BBQ	Ford Fusion, 08-09, 2.3L eng	Bumper Cover, Rear	Tong Yang	09/14A	8E5Z17K835GAPT	FO1100592
FD-04302BBQ	Ford Fusion, 08-09, 3.0L eng	Bumper Cover, Rear	Tong Yang	08/14A	8E5Z17K835HAPT	FO1100593
Y-FDBP081CA	Ford Fusion, 10-12	Bumper Cover, Rear	Y.C.C.	10/14A	AE5Z17K835AAPT	FO1100649
Y-FDBP086CA	Ford Taurus, 10-11	Bumper Cover, Front	Y.C.C.	04/14A	AG1Z17D957AAPT	FO1000651
HD-04097BBQ	Honda Civic Coupe/Sedan, 99-00	Bumper Cover, Rear	Tong Yang	12/13B	04715S01A01ZZ	HO1100190
HDB084NBQ	Honda Civic Hybrid, 06-11	Bumper Cover, Rear	Pro Fortune	08/14B	04715SNAA9OZZ	HO1100235
Y-HDBP155CA	Honda Civic Hybrid, 06-11	Bumper Cover, Rear	Y.C.C.	01/14A	04715SNAA9OZZ	HO1100235
HDB084NBQ	Honda Civic Sedan, 06-11, 1.8L eng	Bumper Cover, Rear	Pro Fortune	08/14B	04715SNAA9OZZ	HO1100235
Y-HDBP155CA	Honda Civic Sedan, 06-11, 1.8L eng	Bumper Cover, Rear	Y.C.C.	01/14A	04715SNAA9OZZ	HO1100235

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
Y-HYBP020CA	Hyundai Elantra Sedan, 11-13 (USA)	Bumper Cover, Front	Y.C.C.	02/15A	865113Y000	HY1000185
Y-HYBP004CA	Hyundai Santa Fe, 01-06	Bumper Cover, Front	Y.C.C.	01/15A	8651026910	HY1000136
Y-HYBP013CA	Hyundai Santa Fe, 05-06	Bumper Cover, Rear	Y.C.C.	05/14A	8661026800	HY1100143
Y-KABP011HRC	Kia Sorento, 11-13, w/Parking Assistant	Bumper Cover, Rear	Y.C.C.	09/14B	866101U010	KI1100154
LSB032NCQ	Lexus GS 350, 13, w/o Park Assist	Bumper Cover, Rear	Pro Fortune	01/14A	5215930955	LX1100159
LX2100870-100C	Lexus IS 250, 06-08, w/o park distance	Bumper Cover, Rear	AP-Procom	11/14A	5215953905	LX1100129
LX2100870-100C	Lexus IS 350, 06-08, w/o park distance	Bumper Cover, Rear	AP-Procom	11/14A	5215953905	LX1100129
TY-04155BBQ	Lexus RX 300, 99-03	Bumper Cover, Front	Tong Yang	12/13B	5211948901	LX1000117
TY-04238BCQ	Lexus RX 330, 04-06, w/o H/Lamp washers, w/o cruise control (Japan)	Bumper Cover, Front	Tong Yang	07/14A	5211948934	LX1000144
TY-04238BCQ	Lexus RX 350, 07-09, w/o H/Lamp washers, w/o cruise control (Japan)	Bumper Cover, Front	Tong Yang	07/14A	5211948934	LX1000144
MZ-04089BDQ	Mazda 3 Sport, 04-06	Bumper Cover, Rear	Tong Yang	04/14A	BN9C50221HAA	MA1100175
MZ-04089BDQ	Mazda 3 Sport, 04-06	Bumper Cover, Rear	Tong Yang	04/14A	BN9C50221HBB	MA1100175
DS-04228BBQ	Nissan Altima Hybrid, 07-11	Bumper Cover, Rear	Tong Yang	08/14A	85022JA040	NI1100248
DS-04228BBQ	Nissan Altima Hybrid, 07-11	Bumper Cover, Rear	Tong Yang	08/14B	85022JA040	NI1100248
DS-04228BBQ	Nissan Altima Hybrid, 07-11	Bumper Cover, Rear	Tong Yang	09/14C	85022JA040	NI1100248
DS-04228BBQ	Nissan Altima Hybrid, 07-11	Bumper Cover, Rear	Tong Yang	10/14A	85022JA040	NI1100248
DS-04228BBQ	Nissan Altima Sedan, 07-12	Bumper Cover, Rear	Tong Yang	08/14A	85022JA040	NI1100248
DS-04228BBQ	Nissan Altima Sedan, 07-12	Bumper Cover, Rear	Tong Yang	08/14B	85022JA040	NI1100248
DS-04228BBQ	Nissan Altima Sedan, 07-12	Bumper Cover, Rear	Tong Yang	09/14C	85022JA040	NI1100248
DS-04228BBQ	Nissan Altima Sedan, 07-12	Bumper Cover, Rear	Tong Yang	10/14A	85022JA040	NI1100248
Y-DSBP245CA	Nissan Altima Sedan, 13-15	Bumper Cover, Rear	Y.C.C.	10/14B	850223TA0H	NI1100287
Y-DSBP213CA	Nissan Altima, 05-06	Bumper Cover, Front	Y.C.C.	05/14A	62022ZB000	NI1000219
Y-DSBP213CA	Nissan Altima, 05-06	Bumper Cover, Front	Y.C.C.	07/14A	62022ZB000	NI1000219
Y-DSBP226HCA	Nissan Maxima, 07-08, w/Parking Assist	Bumper Cover, Rear	Y.C.C.	05/14A	85022ZK40B	NI1100245
DS-04291BDQ	Nissan Sentra SL, 10-12, 2.0L Eng.	Bumper Cover, Front	Tong Yang	07/12A	62022ZT50J	NI1000278
Y-DSBP223CA	Nissan Versa Hatchback, 07-11, w/o Sport	Bumper Cover, Front	Y.C.C.	12/13A	FBM22EM30J	NI1000245
Y-DSBP223CA	Nissan Versa Hatchback, 07-11, w/o Sport	Bumper Cover, Front	Y.C.C.	12/13A	FBM22EM30J	NI1000245
Y-DSBP223CA	Nissan Versa Hatchback, 07-12, w/o Sport	Bumper Cover, Front	Y.C.C.	12/13A	FBM229EG0J	NI1000245
Y-DSBP223CA	Nissan Versa Hatchback, 07-12, w/o Sport	Bumper Cover, Front	Y.C.C.	12/13A	FBM229EG0J	NI1000245
Y-DSBP223CA	Nissan Versa Sedan, 07-11	Bumper Cover, Front	Y.C.C.	12/13A	FBM229EG0J	NI1000245
Y-DSBP223CA	Nissan Versa Sedan, 07-11	Bumper Cover, Front	Y.C.C.	12/13A	FBM229EG0J	NI1000245
Y-DSBP223CA	Nissan Versa Sedan, 07-11	Bumper Cover, Front	Y.C.C.	12/13A	FBM22EM30J	NI1000245
Y-DSBP223CA	Nissan Versa Sedan, 07-11	Bumper Cover, Front	Y.C.C.	12/13A	FBM22EM30J	NI1000245
TY-04259BBQ	Scion tC, 05-10	Bumper Cover, Front	Tong Yang	08/14A	5211921906	SC1000103
TY-04259BBQ	Scion tC, 05-10	Bumper Cover, Front	Tong Yang	08/14B	5211921906	SC1000103
Y-TYBP269ACA	Toyota Camry Base, 08-09, (USA)	Bumper Cover, Front	Y.C.C.	06/14A	5211906919	TO1000329
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	07/14A	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	07/14A	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry Base, 08-10, (USA)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906950	TO1100243
TY-04349BCQ	Toyota Camry Base/LE/XLE, 10-11 (USA)	Bumper Cover, Front	Tong Yang	04/14A	5211906958	TO1000356

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 201 STANDARD - PLASTICS

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
TY-04349BCQ	Toyota Camry Base/LE/XLE, 10-11 (USA)	Bumper Cover, Front	Tong Yang	05/14B	5211906958	TO1000356
TY-04349BCQ	Toyota Camry Base/LE/XLE, 10-11 (USA)	Bumper Cover, Front	Tong Yang	09/14A	5211906958	TO1000356
TY-04349BCQ	Toyota Camry Base/LE/XLE, 10-11 (USA)	Bumper Cover, Front	Tong Yang	11/14A	5211906958	TO1000356
Y-TYBP270CA	Toyota Camry Base/LE/XLE, 11, 2.5L eng (USA)	Bumper Cover, Rear	Y.C.C.	07/14A	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry Base/LE/XLE, 11, 2.5L eng (USA)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry Base/LE/XLE, 11, 2.5L eng (USA)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry Base/LE/XLE, 11, 2.5L eng (USA)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry Base/LE/XLE, 11, 2.5L eng (USA)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906950	TO1100243
Y-TYBP269ACA	Toyota Camry CE, 07 (USA)	Bumper Cover, Front	Y.C.C.	06/14A	5211906919	TO1000329
Y-TYBP270CA	Toyota Camry CE, 07, USA built	Bumper Cover, Rear	Y.C.C.	07/14A	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry CE, 07, USA built	Bumper Cover, Rear	Y.C.C.	08/14B	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry CE, 07, USA built	Bumper Cover, Rear	Y.C.C.	08/14B	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry CE, 07, USA built	Bumper Cover, Rear	Y.C.C.	10/14A	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry CE, 07, USA built	Bumper Cover, Rear	Y.C.C.	10/14A	5215906950	TO1100243
Y-TYBP269ACA	Toyota Camry Hybrid, 07-09 (USA)	Bumper Cover, Front	Y.C.C.	06/14A	5211906919	TO1000329
Y-TYBP270HAC	Toyota Camry Hybrid, 07-11, (USA)	Bumper Cover, Rear	Y.C.C.	07/14B	5215906952	TO1100274
Y-TYBP269ACA	Toyota Camry LE/XLE, 07-09, (USA)	Bumper Cover, Front	Y.C.C.	06/14A	5211906919	TO1000329
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	07/14A	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906909	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	07/14A	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	08/14B	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906950	TO1100243
Y-TYBP270CA	Toyota Camry LE/XLE, 07-10, (4 cyl.)	Bumper Cover, Rear	Y.C.C.	10/14A	5215906950	TO1100243
Y-TYBP279CA	Toyota Camry SE, 10-11 (USA)	Bumper Cover, Front	Y.C.C.	10/14A	5211906959	TO1000355
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	08/14A	5211902946	TO1000297
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	09/14A	5211902946	TO1000297
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	08/14A	5211902938	TO1000297
Y-TYBP257ACA	Toyota Corolla CE/LE, 05-08	Bumper Cover, Front	Y.C.C.	09/14A	5211902938	TO1000297
Y-TYBP277HCA	Toyota Corolla, 11-13, (Japan)	Bumper Cover, Front	Y.C.C.	03/14A	5211912963	TO1000380
TY-04393BBQ	Toyota Highlander, 11-13	Bumper Cover, Rear	Tong Yang	06/14A	521590E907	TO1100289
		Upper				
Y-TYAR421CA	Toyota Tacoma PreRunner, 01-04, (2WD)	Panel, Valance	Y.C.C.	02/15A	53901AD030	TO1095196
Y-TYAR421CA	Toyota Tacoma, 01-04, (4WD)	Panel, Valance	Y.C.C.	02/15A	53901AD030	TO1095196
TY-04284BBQ	Toyota Yaris Sedan, 07-12	Bumper Cover, Rear	Tong Yang	03/14A	5215952929	TO1100249

CAPA 301 STANDARD - LIGHTING

Manufacturer Number	Application Description	Part Description	Manufacturer	Lot	OEM Number	PartsLink Number
DGCV01HR4	Chrysler Town & Country, 01-05	Headlamp Assy, R	Gordon	01/15B	4857700AB	CH2503129
DGCV01HL4	Chrysler Town & Country, 01-05	Headlamp Assy, L	Gordon	01/15B	4857701AB	CH2502129

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CAPA 301 STANDARD - LIGHTING

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
DGCV01HR4	Chrysler Town & Country, 01-07, w/113" WB	Headlamp Assy, R	Gordon	01/15B	4857700AC	CH2503129
DGCV01HL4	Chrysler Town & Country, 01-07, w/113" WB	Headlamp Assy, L	Gordon	01/15B	4857701AC	CH2502129
DGCV01HR4	Dodge Caravan, 01-05	Headlamp Assy, R	Gordon	01/15B	4857700AB	CH2503129
DGCV01HL4	Dodge Caravan, 01-05	Headlamp Assy, L	Gordon	01/15B	4857701AB	CH2502129
DGCV01HR4	Dodge Caravan, 01-07	Headlamp Assy, R	Gordon	01/15B	4857700AC	CH2503129
DGCV01HL4	Dodge Caravan, 01-07	Headlamp Assy, L	Gordon	01/15B	4857701AC	CH2502129
DGCV01HR4	Dodge Grand Caravan, 01-07	Headlamp Assy, R	Gordon	01/15B	4857700AC	CH2503129
DGCV01HL4	Dodge Grand Caravan, 01-07	Headlamp Assy, L	Gordon	01/15B	4857701AC	CH2502129
317-1131R-UC	Honda Accord Hybrid, 05-07	Headlamp Assy, R	DEPO	20141110	33101SDAA01	HO2503120
317-1131L-UC	Honda Accord Hybrid, 05-07	Headlamp Assy, L	DEPO	20140113	33151SDAA01	HO2502120
317-1131L-UC	Honda Accord Hybrid, 05-07	Headlamp Assy, L	DEPO	20141110	33151SDAA01	HO2502120
317-1131R-UC	Honda Accord, 03-07	Headlamp Assy, R	DEPO	20141110	33101SDAA01	HO2503120
317-1131L-UC	Honda Accord, 03-07	Headlamp Assy, L	DEPO	20140113	33151SDAA01	HO2502120
317-1131L-UC	Honda Accord, 03-07	Headlamp Assy, L	DEPO	20141110	33151SDAA01	HO2502120
DGCV01HR4	Plymouth Voyager, 01-04	Headlamp Assy, R	Gordon	01/15B	4857700AB	CH2503129
DGCV01HR4	Plymouth Voyager, 01-04	Headlamp Assy, R	Gordon	01/15B	4857700AC	CH2503129
DGCV01HL4	Plymouth Voyager, 01-04	Headlamp Assy, L	Gordon	01/15B	4857701AB	CH2502129
DGCV01HL4	Plymouth Voyager, 01-04	Headlamp Assy, L	Gordon	01/15B	4857701AC	CH2502129
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	03021510	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	03091510	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	04271510	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	06231410	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	07071410	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	07141410	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	07281410	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	10131410	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	12151410	8111002E60	TO2503216
20-9493-00-9	Toyota Corolla, 14-15	Headlamp Assy, R	TYC Brother	12221410	8111002E60	TO2503216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	01051510	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	03021510	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	03091510	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	04271510	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	06231410	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	07071410	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	07141410	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	07281410	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	10061410	8115002E60	TO2502216
20-9494-00-9	Toyota Corolla, 14-15	Headlamp Assy, L	TYC Brother	12081410	8115002E60	TO2502216

CAPA 501 STANDARD - BUMPER PARTS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
NONE						



MONTHLY RECALL REPORT

June 2015*

[Report: P8]
Monthly

RECALLED DECERTIFIED LOTS

In cooperation with repairers, insurers, distributors, and part manufacturers, CAPA continuously monitors and reviews the quality of parts certified to meet or exceed CAPA standards. The following list includes parts that no longer meet the CAPA standards to which they were originally certified and therefore the following parts have been decertified. CAPA would like to thank you for your support in reporting non-compliance variations regardless of the significance. your assistance assures repairers and consumers they can continue to expect quality collision replacement parts when they see the CAPA seal.

Part lots are expressed in dates. Distributors holding decertified CAPA parts are entitled to a refund, replacement part or credit from the applicable Participant. They can receive one of the above (the Participant decides which) by cutting out the section of the part (a coupon) bearing the CAPA Quality Seal and submitting the coupon(s) to CAPA Headquarters with a completed Recall Reimbursement Form within ninety (90) days of public notice of decertification to CAPA at Recall Report 1000 Vermont Avenue, N.W., Suite 1010, Washington, D.C. 20005 or FAX (202) 737-2214.

CORRECTION

The following lots were listed as decertified on May 2015 Weekly Parts Update Reports.

Upon further review, these lots should remain certified.

CAPA 201 STANDARD - PLASTICS

<u>Manufacturer Number</u>	<u>Application Description</u>	<u>Part Description</u>	<u>Manufacturer</u>	<u>Lot</u>	<u>OEM Number</u>	<u>PartsLink Number</u>
CLB064NCQ	Chevrolet Cruze, 11-15, w/o RS Pkg, w/o Rear Object Sensor	Bumper Cover, Rear	Pro Fortune	11/14B	95016694	GM1100876
DG-05006VAQ	Dodge Pickup, 02 (New Style)	Front Air Dam, Lower	Tong Yang	01/15A	55077337AB	CH1090125
DG-05006VAQ	Dodge Pickup, 02-08, w/o Sport pkg	Front Air Dam, Lower	Tong Yang	01/15A	55077337AD	CH1090125
KA5510000-010C	Kia Sorento, 11-13, w/o Sport Pkg	Bumper Cover, Front Upper	AP-Procom	11/14A	865111U000	KI1000149
LX2100870-000C	Lexus IS 250, 06-08, w/park distance sensors	Bumper Cover, Rear	AP-Procom	11/14A	5215953906	LX1100128
LX2100870-000C	Lexus IS 350, 06-08, w/park distance sensors	Bumper Cover, Rear	AP-Procom	11/14A	5215953906	LX1100128
TY-04193BCQ	Toyota Corolla CE/LE, 03-04	Bumper Cover, Front	Tong Yang	11/14B	5211902915	TO1000240

*This report includes all decertifications from May 1, 2015 through May 31, 2015.

All CAPA Reports including the recall report are available on the CAPA website at www.capacertified.org.

If you would like to download this report directly from the website and wish to be removed from this distribution list, please contact CAPA at debbie@capacertified.org.